

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 28 Feb 2018

Preliminary Advice

Insured Vehicle No : FBB9861M

TP Vehicle No : SBU788B

Make : PORSCHE 911

Date of Inspection : 27/02/2018

Inspection At : STUTTGART AUTO PTE LTD

Accident Date : 13/02/2018

Assignment Date : 27/02/2018

Est. Duration of Repair : 3/Days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...O/S Rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,950.77
Revised Amount	:S\$	4,161.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,161.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :We have not authorized repairs.