

Surveyor:

Tan fien

DOI:

ASSIGNMENT

Date / Time:

26/2/18

Registered in Merimen:

22/2/18 by AP

P assign / CCU / FTE



Insured Vehicle No.:

SLS 5670R

Claim No.:

C0471172

Name of Insured:

Pay Swee Hoon

Policy No.:

P1996600

Insured Tel No.:

HP:

97556777

Make / Model:

T. Hawer.

Excess Sec II :SS

D.O.A.:

21/2/18

Place of Accident:

Tampines Grande 9P

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKA 94 T



INSRS:

WSP:

Tel:

Liability:

RMKS:

pml



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

EMAIL 9/3/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

* Pls ensure consistency & do check the labour costs & reasonable.

5/3/18 @ 4.35

CALLED OI CONFIRMED ACCIDENT. OI HIT PARKED TP KAREN EXPLAIN THE LIM. INFORM TP CLAIM ADVISED TO SERVE AND ANSWER ABOUT NCD ISSUE.

Email Rep Liability Clear.

3.5.18 THE PING TO TPAT TO PREPARE REPORT.

RECEIVED 14 DEC 2018

RECEIVED 31 MAY 2018

PRELIMINARY ADVICE Date/Time:

1/3/18

Sent By:

pml

FINALIZATION

Date/Time: 8.5.18

Confirm with: CAED/AR

Confirm by: MTH

Repair Cost:

PR

S\$7,742.43

(4 days)

Reduction:

31 %

Email

Call

FINAL SETTLEMENT

Date/Time: 28.6.18

Confirm with: CAED/AR

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 25

If NO or B 28, Ass. Lia:

Repair Cost:

olika

S\$8,337.90

OI HIT PARKED TP.

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 400.00

(\$100 x 4 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

→ 350

Total:

S\$8,137.90

Global Sum S\$:

FINAL PAYMENT

Date/Time: 28.6.18

Confirm with: CAED/AR

Email

Call

Payee 1:

S\$8,137.90

Name 1:

PERFORMANCE MOTOR LIMITED.

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/AXA18003584/R1ea3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 26-02-2018		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLS 5670R	Veh. Inspected	SKA 94T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	26/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/02/2018	Inspection Date	27/02/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 1974015394 GST Reg. No M2-0020081-X

301, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747779

360, Hongkong Arang Road
East Coast Centre
Singapore 438166
Tel: 63190869 (AfterSales)
Fax: 63449773

119, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

22 FEB 2018

Estimate No. : b1 46006
Date Estimated : 22/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Yong Wai Lai
94 Bridport Avenue

Singapore 559384

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA94T	E493335	28/09/2010	Z4 sDrive23i	0

DESCRIPTION

To replace front bumper assembly and attachments including knock out dent area cause by accident.

1275 ✓ 2,550.00
1147.50

Painting on front bumper assembly, front bonnet & front right side panel ✓

2102 3,221.00
1,891.80

To check electrical wiring systems at the front section for proper function.

150 ✓ 177.00
135

To replace right headlight including program and conduct tests for proper function.

45L ✓ 531.00
405.90

Sundries. *See*

? 150.00
80.00 ✓

Total Labour 1: 6,629.00

DESCRIPTION

Cover nozzle right
FRT BUMPER RH MOUNT BKT
FRT BUMPER CTR GRID
COVERING RIGHT
FRT BUMPER RH TRIM GRILLE
FINISHER ROD RH
CLOSED GRID RH
FRT BUMPER TOW HOOK COVER
FRT BUMPER (PDC)
FRT EMBLEM (D=70MM)
PLAQUE BMW
FRT RH FENDER INNER COVERING
FRT RH FENDER INNER COVERING
RH BI-XENON HEADLIGHT
DECOUPLING RING PDC TORQUE CONVERTE

QTY PRIC

1 94.70
1 36.60
1 55.15
1 36.75
1 15.70
1 10.25
1 55.50
1 42.20
1 1,081.00
1 69.60
1 69.50
1 121.35
1 121.35
1 2,485.90
4 5.05

VALUE

mis ✓ 94.70
mt ✓ 36.60
x 55.15
x 36.75
x 15.70
x 10.25
x 55.50
x 42.20
de ✓ 1,081.00
mt ✓ 69.50
mt ✓ 69.50
mt ✓ 121.35
mt ✓ 121.35
cm ✓ 2,485.90
mt ✓ 20.20

Total Parts : 4,315.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197451559W GST Reg. No. M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747772

280, Kepong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190448 (AfterSales)
Fax. 63449772

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64794601 (AfterSales)
64794604 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46006
Date Estimated : 22/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA94T	E493335	28/09/2010	Z4 sDrive23i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Checked by / 27/02/18 / 27/02/18 / 27/02/18

Repairer: Tanpin WP

Approved by: WP

3 4 days

Labour 1	:	6,629.00
Parts	:	4,315.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	766.13
Grand Total	:	11,710.78

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401589W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46006
Date Estimated : 22/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

#REPAIR FOR -
Yong Wai Lai
94 Bridport Avenue

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 559384

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKA94T	E493335	28/09/2010	24 sDrive23i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT BUMPER SHOCK ABSORBER *	59.00	1.00	3.00	57.23 <i>de</i> ✓
# COVER SPRAY NOZZLE PRIMED RH *	42.20	1.00	3.00	40.93 <i>de</i> ✓
# UNIVERSAL SOCKET HOUSING MLK UNCODE *	27.75	1.00	3.00	26.92 <i>de</i> ✓
# BUMPER PDC SENSOR (SCHWARZ)- ELBOW *	236.85	1.00	3.00	229.74 <i>de</i> ✓

Total Labour :	
Total Parts :	354.82
Total Labour & Parts :	354.82



FINAL REPORT

Estimate No. : b1 46006
Date Estimated : 22/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

#REPAIR FOR -
Yong Wai Lai
94 Bridport Avenue

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 559384

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKA94T	E493335	28/09/2010	Z4 sDrive23i	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments include making good the bonnet and knocking out dented areas caused by the accident		1275.00	10.00	1,147.50
To spray paint front bumper and bonnet		2102.00	10.00	1,891.80
To check electrical wiring systems at the front section for proper function include adjustment of headlights		150.00	10.00	135.00
To replace RH bi xenon headlight include programming and conducting tests for proper function		451.00	10.00	405.90
Sundries.		80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT BUMPER SHOCK ABSORBER *	59.00	1.00	3.00	57.23
FRT BUMPER RH MOUNT BKT	36.60	1.00	3.00	35.50
# COVER SPRAY NOZZLE PRIMED RH *	42.20	1.00	3.00	40.93
FRT BUMPER PANEL PRIMED (M/PDC)	1,297.20	1.00	3.00	1,258.28
FRT EMBLEM (D=70MM)	69.49	1.00	3.00	67.41
# UNIVERSAL SOCKET HOUSING MLK UNCODE *	27.75	1.00	3.00	26.92
RH BI-XENON HEADLIGHT	2,485.90	1.00	3.00	2,411.32
DECOUPLING RING PDC TORQUE CONVERTE	5.05	1.00	3.00	4.90
# BUMPER PDC SENSOR (SCHWARZ)- ELBOW *	236.85	1.00	3.00	229.74

SUPPLEMENTARY ITEMS

Total Labour :	3,660.20
Total Parts :	4,132.23
Total Labour & Parts :	7,792.43
Deduction for Excess :	0.00
Total Repair Costs less Excess:	7,792.43
GST @7%:	545.47
Grand Total :	8,337.90

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Winnie Ho

Date: 01 Mar 2018

Preliminary Advice

Insured Vehicle No	: SLS5670R	Accident Date	: 21/02/2018
TP Vehicle No	: SKA94T	Assignment Date	: 26/02/2018
Make	: BMW 230i	Est. Duration of Repair	: 4 days
Date of Inspection	: 27/02/2018		
Inspection At	: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesfront O/S... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,944.65
Revised Amount	:S\$	7,765.90
Check Items (Estimated)	:S\$	389.55
Total	:S\$	8,155.45

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Monday, 5 March 2018 2:12 PM
To: 'PBSP'
Cc: Admin A; Vic (LKKAuto)
Subject: RE: REQ FOR DIRECT SETTLEMENT - SKA94T & SLS5670R (AXA) ON 21.02.2018

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents for us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Monday, 5 March 2018 10:00 AM
To: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Fw: REQ FOR DIRECT SETTLEMENT - SKA94T & SLS5670R (AXA) ON 21.02.2018

Dear Motor Claims,

Please let us have your reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Thursday, 1 March 2018 10:17 AM
To: motor.survey@axa.com.sg; motor.doc@axa.com.sg
Subject: Re: REQ FOR DIRECT SETTLEMENT - SKA94T & SLS5670R ON 21.02.2018

Dear Motor Claims,

Please let us have your reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Monday, 26 February 2018 6:08:44 PM
To: motor.survey@axa.com.sg; motor.doc@axa.com.sg
Subject: Re: REQ FOR DIRECT SETTLEMENT - SKA94T & SLS5670R ON 21.02.2018

Dear Motor Claims,

Please let us have your reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Thursday, 22 February 2018 6:38:01 PM
To: motor.survey@axa.com.sg; motor.doc@axa.com.sg
Subject: REQ FOR DIRECT SETTLEMENT - SKA94T & SL55670R ON 21.02.2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

Print Sent Message

This mail is associated with :

***SKA94T (C0471172)**
[SLS5670R]

TP
YONG WAI LAI
Feb 21 2018 9:00AM
[PAY, SWEE HOON]
Performance Motors Limited

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 11/06/2018 15:21 PM.
To cynthia.loh@axa.com.sg; winnie.ho@axa.com.sg
CC AXA_SG; ashersng@lkkauto.com
Subject Re: TP settlement - C0471172/P1996600

Hi Sir,

We refer to the above matter.

The accident occurred when our insured collided into third party parked vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer at \$ 8,737.90 (all-in).

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AXA_SG

To: LKK_HQ;sur@lkkauto.com;assignments@lkkauto.com

CC: AXA_SG

Sent On: 02/03/2018 08:50 AM

Subject: TP settlement - C0471172/P1996600

Dear MOHD RASUL,

Please proceed for direct settlement if damages consistent.

Regards,

Winnie Ho

Print Received Message

This mail is associated with :

***SKA94T (C0471172)**
[SLS5670R]

TP
YONG WAI LAI
Feb 21 2018 9:00AM
[PAY, SWEE HOON]
Performance Motors Limited

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 18/06/2018 11:05 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$8737.90) - SKA94T - Claim Handler: Winnie Ho

Approved:8737.90:OFFER @ \$7800 (ALL IN)



redefining / insurance

AXA Insurance Singapore Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

account number
 00321

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
 -Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	YONG WAI LAI	Certificate number	GA083076 / 1
Cover	Comprehensive	Chassis number	WBALM32050E493335
Plan name	Flexi	Engine number	10107443N52B25AF
NCD applicable	50%		
Vehicle registration number	SKA94T		
Period of Insurance	from 25/05/2016 to 27/05/2017 (both dates inclusive)		
Finance loan company	MERCEDES-BENZ FINANCIAL SERVICES SINGAPORE LTD		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 500.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Singapore Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait photo of Kung Malcolm Gregory

Licence Number: **S1279022H**

Name: **KUNG MALCOLM GREGORY**

Birth Date: **11 Apr 1957**

Issue Date: **28 Aug 2003**

Barcode: 0007787410

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1279022H**

Portrait photo of Kung Malcolm Gregory

Name: **KUNG MALCOLM GREGORY**

Race: **CHINESE**

Date of Birth: **11-04-1957**

Country of Birth: **SINGAPORE**

Sex: **M**

Fingerprint

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	05 Oct 1977

Licence No: **S1279022H**

NP 426A

113682

Barcode

NRIC No: **S1279022H**

Fingerprint

Blood Group: **O+**

Date of issue: **24-07-1993**

94 BRIDPORT AVENUE
SINGAPORE 559384

NRIC No: **S1279022H**

Date: **19/03/2013**

No: **7246453**



AXA Insurance Pte Ltd
8 Shenton Way
#27-01
Singapore 068811
Attention: Motor Claims

"Without Prejudice"

Your Ref:

Our Ref:

Date:

Subject:

23 May 2018

ACCIDENT INVOLVING VEHICLES SKA94T & SLS5670R ON 21.02.2017

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	8337.90
Loss of use	:	S\$	400.00 (S\$ 100.00 x 4 days)
Total	:	S\$	8737.90

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)
www.pml.com.sg

303 Alexandra Road
Sima Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales:
6319 0111
Fax 6474 7770

315 Alexandra Road
401-01
Sima Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales:
6319 0527
Fax 6479 6634

280
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel AfterSales:
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No.
197401559W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@simedarby.com.sg.

Yours sincerely

Teng Wei Khan
Customer Service Manager, Body & Paint

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 9 March 2018 2:32 PM
To: 'swhoon09@gmail.com'
Subject: ACCIDENT INVOLVING SLS 5670R AND SKA 94T ALONG TAMPINES GRANDE CAR PARK ON 21/02/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

09 MAR 2018

PAY SWEE HOON

Dear Sir/ Mdm

OUR REF : CC4/AXA18003584/R1ea3

YOUR REF : SLS 5670R

ACCIDENT INVOLVING SLS 5670R AND SKA 94T ALONG TAMPINES GRANDE CAR PARK ON 21/02/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s PERFORMANCE MOTORS LTD acting on behalf of the owner of SKA 94T against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided the Third Party parked vehicle SKA 94T. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ashersng@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at ashersng@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

LETTER OF AUTHORISATION

ACCIDENT INVOLVING SKA 94T & SLS 56TOR ON 21/2/18.

I, Yong Wai Lai owner of Vehicle Registration No. SKA 94T
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all
documents whatsoever in relation to this matter and to accept and receive any payment due
to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement
amount in respect of such claim shall constitute the full discharge of my claim in respect of
such loss and damage.

Signed by:

Name:

NRIC No.:

Yong Wai Lai

(Date)

27/2/18

S1403524J

In the presence of:

Name:

NRIC No.:

Kevin Leong

(Date)

27/2/18



redefining / insurance

CLAIM REF : C0471172
INSURED : PAY SWEE HOON

DISCHARGE VOUCHER

We/I [YONG WAI LAI, NRIC NO. S1403554J] hereby agree to accept the sum of dollars [EIGHT THOUSAND SEVEN HUNDRED THIRTY SEVEN AND CENTS NINETY ONLY.] [S\$8,737.90] paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. [SLS 5670R] as a result of an accident along [CARPARK 9 TAMPINES GRANDE] on [21/02/2018] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [SKA 94T].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [SLS 5670R] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SLS 5670R].

Dated this 12 day of Dec 2018

Claimant's Signature : [Signature]

NRIC no./ Company Stamp : S1403554J

Occupation/ Business : SALES

Address : 94 BRIDPORT AVE S(559384)

Telephone No. : _____

Witness's Name : PERFORMANCE MOTORS LIMITED

Witness's Signature : [Signature]

Witness's NRIC No. : _____

AXA Insurance Pte Ltd (Company Reg. No. 199903512M)
8 Shenton Way, #24-01 AXA Tower, Singapore 068811
Customer Centre #B1-01
Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197481559W GST Reg. No M2-8028881-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63198100 (Sales & Admin)
63198111 (AfterSales)
Fax: 64747770

188, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63198888 (AfterSales)
Fax: 63449773

110, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63198538 (AfterSales)
63198533/830 (Motorrad)
Fax: 64796601 (AfterSales)
64796634 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1248483	Page No. : 1 of 2
Date IN : 06/03/2018	Invoice Number : 1963650 / WSB
Cust. Svc. Advisor: Kevin Leong Wai Kit	Invoice Date : 11/05/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mdm Yong Wai Lai
94 Bridport Avenue

Singapore 559384

- INVOICE TO - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO. SKA94T	CHASSIS NO. E493335	REGN. DATE 28/09/2010	MODEL Z4 SDRIVE23I	MILEAGE 79183
----------------------------	-------------------------------	---------------------------------	------------------------------	-------------------------

- - - - LABOUR 1 - - - -

To replace front bumper and attachments including to
remove and install body parts in order to carry out painting
job.

To respray front bumper and front bonnet.

To check electrical wiring systems at the front section
for proper function.

To replace right Bi-Xenon headlight including program
and conduct tests for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 21.2.2018. 3RD PARTY CAR : SLS5670R,
YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO
CONSULTANTS PTE LTD ON 27.2.2018. AUTHORISED REPAIR
BY MS ASHER SNG FROM LKK ON 5.3.2018 VIA E-MAIL.

PROPOSE LOSS OF USE = \$100X4. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

Retail

Price

DISC%

NETT

1,275.00

10.00

1,147.50

2,102.00

10.00

1,891.80

150.00

10.00

135.00

451.00

10.00

405.90

80.00

0.00

80.00

0.00

0.00

0.00

0.00

0.00

0.00

Total Labour 1: **3,660.20**

- - - - PARTS - - - -

RH BI-XENON HEADLIGHT

FRT EMBLEM (D=70MM)

DECOUPLING RING PDC TORQUE CONVERTE

BUMPER PDC SENSOR (SCHWARZ)- ELBOW

FRT BUMPER SHOCK ABSORBER

UNIVERSAL SOCKET HOUSING MLK UNCODE

FRT BUMPER RH MOUNT BKT

FRT BUMPER PANEL PRIMED (M/PDC)

COVER SPRAY NOZZLE PRIMED RH

Retail

Price

DISC%

NETT

Qty

2,485.90

3.00

2,411.32

1

69.50

3.00

67.41

1

5.05

3.00

4.90

1

236.85

3.00

229.74

1

59.00

3.00

57.23

1

27.75

3.00

26.92

1

36.60

3.00

35.50

1

1,297.20

3.00

1,258.28

1

42.20

3.00

40.93

Total Parts : **4,132.23**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1248483	Page No. : 2 of 2
Date IN : 06/03/2018	Invoice Number : 1963650 / WSB
Cust. Svc. Advisor: Kevin Leong Wai Kit	Invoice Date : 11/05/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

Labour Charges : 3,580.20	Total Labour & Parts Charges : S\$ 7,792.43
Parts Charges : 4,132.23	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 80.00	Invoice Total Amount Exclude GST : S\$ 7,792.43
	GST @ 7% : S\$ 545.47
	Invoice Total Amount Include GST : S\$ 8,337.90

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 8,337.90**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Feb 2018		26 Feb 2018 09:43 Edit Adj Rpt	S\$7,792.43 Edit Estimates	S\$7,792.43 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PAY, SWEE HOON, ID: S6831755Z, Tel: +6597556277								
Main Claimant:	YONG WAI LAI, ID: S1403554J								
Vehicle Reg. No.:	SKA94T	Date of Loss:	21/02/2018 09:00 - :59 [88 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0471172	Policy/Cover Note No.:	P1996600 (Comprehensive) Coverage: 28/09/2017 - 27/09/2019						
Vehicle Reg. No. (Insured):	SL55670R	Policy No. (Claimant):	GA063076/1						
		Excess:	S\$0.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Winnie Ho - 6880 4833]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 07/03/2018]								
Driver/Custodian (Insured):	PAY, SWEE HOON (), NRIC: S6831755Z, Tel: +6597556277								
Adj Asg. Remarks:	PLS ENSURE CONSISTENCE AND DO CHECK THE LABOUR COSTS IS REASONABLE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (18/06/2018): Alert - Adj Mandate Approved (S\$8737.90) - SKA94T - Claim Handler: Winnie Ho AXA_SG (13/06/2018): TP settlement - C0471172/P1996600 AXA_SG (13/06/2018): Alert - Adj Mandate Approved (S\$7800.00) - SKA94T - Claim Handler: Winnie Ho AXA_SG (13/06/2018): Alert - Adj Mandate Approved (S\$8400.00) - SKA94T - Claim Handler: Winnie Ho AXA_SG (02/03/2018): TP settlement - C0471172/P1996600 AXA_SG (02/03/2018): Re: Direct Settlement - Accident Involving SL55670R (OI : AXA - C0471172) and SK... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKA94T (C0471172)
[SLS5670R]
TP
YONG WAI LAI
Feb 21 2018 9:00AM
[PAY, SWEE HOON]
Performance Motors Limited

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/18 17:51	Adjuster Immediate Advice		Load HTM

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/05/18 09:54	LKK Survey Photo		Load PDF
2	08/05/18 09:54	LKK Resurvey Photo		Load PDF

Documentation

1 per page

No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	23/02/18 08:58	EMAIL_ABS		Load PDF
2	23/02/18 08:58	ESTIMATE_ABS		Load PDF
3	23/02/18 08:58	SKA94T TP GIA_ABS		Load PDF
4	23/02/18 08:58	SLS5670R INS GIA		Load PDF
5	23/02/18 13:48	GIA SKA94T TP		Load PDF
6	23/02/18 13:48	ESTIMATE		Load PDF

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/03/18 08:43	TP ESTIMATE - MARKED		Load PDF
2	05/06/18 10:53	LETTER TO OI		Load PDF
3	11/06/18 15:19	Immediate Advice with Mandate		Load PDF
4	11/06/18 15:19	LTA PARF COE Rebate Details		Load PDF
5	17/12/18 07:48	WORKSHOP INVOICE		Load PDF
6	17/12/18 07:48	AUTHORISATION TO ACT FORM		Load PDF
7	17/12/18 07:48	DISCHARGE VOUCHER		Load PDF
8	17/12/18 07:48	LOD		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

TEAM

Vehicle No:	SLS5670R (Insd veh)	Model:	BMW 230i 2.0 HID NAV SR D/AB (A)
	SKA94T (TP veh)		
Date of Accident:	21/02/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	12,280.12
Final Repair Cost	:	\$	8,337.90
Loss of Use	:	\$	400.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	8,737.90

4.00 days at \$100.00 per day

days

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 23

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	\$	8,737.90
2)		\$	

17 Dec
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18003584/T1EA3Q2

Date: 17/12/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1996600

Claimant Vehicle
No : SKA94T

Insured Vehicle No :

SLS5670R

Date of Loss: 21/02/2018

Nature of Claim:

TP

Claim No: C0471172

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA94T

Make & Model: BMW 230i, 2.0 HID NAV SR D/AB (A)

Engine No: 10107443N52B25AF

Reg. Date: 28/09/2010 (Man. Year: 2010)

Chassis No: WBALM32050E493335

Colour: White

Odometer: 79180 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,997.75	4,212.23	785.52	15.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,479.00	3,580.20	2,898.80	44.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,476.75	7,792.43	3,684.32	32.10
+ GST 7.00/7.00% (S\$)	803.37	545.47	257.90	32.10
Nett Amount (S\$)	12,280.12	8,337.90	3,942.22	32.10
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
	Nett Liability (S\$)	8,737.90		

INSPECTION

Date of Assignment: 26/02/2018

Date Inspected: 27/02/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2018)
Parts:	M1-COUPE	BMW 230I 2.0 HID NAV SR D/AB (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA94T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES (CONSISTENT)	Necessary	150.00 FS	*80.00 FS
2	1		*COVER NOZZLE RIGHT (CONSISTENT)	Not Necessary	94.70 FS	*- FS
3	1		*FRT BUMPER RH MOUNT BKT (CONSISTENT)	Necessary	36.60 FS	*35.50 FS
4	1		*FRT BUMPER CTR GRID (CONSISTENT)	Not Necessary	55.15 FS	*- FS
5	1		*COVERING RIGHT (CONSISTENT)	Not Necessary	36.75 FS	*- FS
6	1		*FRT BUMPER RH TRIM GRILLE (CONSISTENT)	Not Necessary	15.70 FS	*- FS
7	1		*FINISHER ROD RH (CONSISTENT)	Not Necessary	10.25 FS	*- FS
8	1		*CLOSED GRID RH (CONSISTENT)	Not Necessary	55.50 FS	*- FS
9	1		*FRT BUMPER TOW HOOK COVER (CONSISTENT)	Not Necessary	42.20 FS	*- FS
10	1		*FRT BUMPER (PDC) (CONSISTENT)	Deformed	1,258.28 FS	*1,258.28 FS
11	1		*FRT EMBLEM (D=70MM) (CONSISTENT)	Necessary	69.50 FS	*67.41 FS
12	1		*PLAQUE BMW (CONSISTENT)	Not Necessary	69.50 FS	*- FS
13	1		*FRT RH FENDER INNER COVERING (CONSISTENT)	Not Necessary	121.35 FS	*- FS
14	1		*FRT RH FENDER INNER COVERING (CONSISTENT)	Not Necessary	121.35 FS	*- FS
15	1		*RH BI-XENON HEADLIGHT (CONSISTENT)	Cracked	2,485.90 FS	*2,411.32 FS
16	1		*DECOUPLING RING PDC TORQUE CONVERTE (CONSISTENT) (4 PCS)	Necessary (1 PCS ONLY)	20.20 FS	*4.90 FS
17	1		*FRT BUMPER SHOCK ABSORBER (CONSISTENT)	Deformed	57.23 FS	*57.23 FS
18	1		*COVER SPRAY NOZZLE PRIMED RH (CONSISTENT)	Missing	40.93 FS	*40.93 FS
19	1		*UNIVERSAL SOCKET HOUSING MLK UNCODE (CONSISTENT)	Distorted	26.92 FS	*26.92 FS
20	1		*BUMPER PDC SENSOR (SCHWARZ) -ELBOW (CONSISTENT)	Distorted	229.74 FS	*229.74 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,997.75** **4,212.23**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BUMPER ASSEMBLY AND ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSE BY ACCIDENT	New	2,550.00	1,147.50
2	PAINTING ON FRONT BUMPER ASSEMBLY ,FRONT BONNET & FRONT RIGHT SIDE PANEL	New	3,221.00	1,891.80
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION	New	177.00	135.00
4	TO REPLACE RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	531.00	405.90
Gross Labour Cost (\$\$)			6,479.00	3,580.20

Report was unsubmitted during this print-out.

< END OF ESTIMATES >