

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

22 FEB 2018

Estimate No. : b1 46006
Date Estimated : 22/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Yong Wai Lai
94 Bridport Avenue

Singapore 559384

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA94T	E493335	28/09/2010	Z4 sDrive23i	0

DESCRIPTION

To replace front bumper assembly and attachments
including knock out dent area cause by accident.

1275 2,550.00

Painting on front bumper assembly, front bonnet & front
right side panel

2102 3,221.00

To check electrical wiring systems at the front section
for proper function.

150 177.00

To replace right headlight including program and conduct
tests for proper function.

451 531.00

Sundries.

? 150.00

Total Labour 1: 6,629.00

DESCRIPTION

Cover nozzle right
FRT BUMPER RH MOUNT BKT
FRT BUMPER CTR GRID
COVERING RIGHT
FRT BUMPER RH TRIM GRILLE
FINISHER ROD RH
CLOSED GRID RH
FRT BUMPER TOW HOOK COVER
FRT BUMPER (PDC)
FRT EMBLEM (D=70MM)
PLAQUE BMW
FRT RH FENDER INNER COVERING
FRT RH FENDER INNER COVERING
RH BI-XENON HEADLIGHT
DECOUPLING RING PDC TORQUE CONVERTE

QTY	PRIC
1	94.70
1	36.60
1	55.15
1	36.75
1	15.70
1	10.25
1	55.50
1	42.20
1	1,081.00
1	69.50
1	69.50
1	121.35
1	121.35
1	2,485.90
4	5.05

VALUE
m/s 94.70
nh 36.60
x 55.15
7 36.75
? 15.70
? 10.25
? 55.50
x 42.20
de 1,081.00
nh 69.50
x 69.50
x 121.35
? 121.35
one 2,485.90
nh 20.20

Total Parts : 4,315.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46006
Date Estimated : 22/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA94T	E493335	28/09/2010	Z4 sDrive23i	0

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/02/18 Excess S\$ _____Surveyor's Name Tan Jia Sign [Signature]Surveyor's Tel 9749547 Authorised Yes / No _____Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____

Surveyor's E-mail tanjia@lkkauto.comNo. of Working Days Recommended 3 4 days

Labour 1	:	6,629.00
Parts	:	4,315.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	766.13
Grand Total	:	11,710.78

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **