

INS. CASE OWNER:

CC 3 UR / AIG 1800 3585, Symbz

LKK: IDAC:

Surveyor:

YWF

DOI:

ASSIGNMENT

Date / Time:

21/2/18

Registered in Merimen:

26/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLF 4846B

Name of Insured:

UR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

20/2/18

Is driver the owner? (YES / NO)

Nature of Accident:

Claim No.:

8D1383646154

Policy No.:

Make / Model:

Place of Accident:

If NO. Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SHB 52284



INSRS: WSP: Tel: Liability: RMKS:

SMART



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time

11/2/18

Joy

SHB 52284 - X

SLF 4846B - Y

LOR non reporting

STAGE

DATE / PIC

Non-Reporting ltr (1st):

-5-3-18

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Joy 9-4-18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PIR

Confirm by:

Email  Call

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Repair Cost:

SS

Confirm with:

FINAL SETTLEMENT

Date/Time:

Final Liability:

%

Repair Cost:

SS

Loss of Rental (LOR):

SS

Loss of Use (LOU):

SS

Loss of Income (LOI):

SS

LOR only  LOU only

GIA/LTA Search

Medical:

Disbursement:

Legal Cost

Total:

FINAL PAYMENT

Payee 1:

Payee 2: (Strike if N.A.)

Payee 3: (Strike if N.A.)

Global Sum SS:

Confirm with:

Name 1:

Name 2:

Name 3:

Email  Call

If NO or B 28. Ass. Lia: 100

014148 LAST

✓ BY: JOY  
JIB 17-5-18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Email  Call

SMRT TAXIS PTE LTD

X

RECEIVED 17 MAY 2018  
RECEIVED 12 APR 2018

Signature

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHB 52284 Yr Regn: 12/7/2012

Type: M. Car / M. Cycle / Bus / Van / Lorry /  Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Chevrolet Epica c.c. 1791

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 676554 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: FL1LA69RJBB 129605

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fallen

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 20/2/18 D.O.I. 22/2/18

Survey held at SMA

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time | Action / Instruction

4/5 \$10,600/

TAX/02/18/2014

LKK  
AIG

SLR 48468

R ( \$14,586.86 / 58%)

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

1) Date/Time, File Return to?

2) \_\_\_\_\_

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Techn. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

) S + RS. \$ \_\_\_\_\_

) Photo

) Copies

TOTAL



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/LCR18003585/Sjb3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGSINGAPORE 079120		Date : 26-02-2018	
		Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLF 4846B	Veh. Inspected	SHB 5228Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/02/2018	Inspection Date	22/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



3-3-18 / 11:24  
Guan 3-3-18 / 15:24

22-2-18 / 15:28

### SMRT Accident Vehicle Repair Estimates

**Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre**


Reg. No : SHB5228Y  
 Ref. No : TAXI02/18/2114  
 Reg. Date : 12/07/2012  
 Vehicle Type : TAXI  
 Make : CHEVROLET EPICA 2.0 VCDI  
 Model : EPICA-2.0  
 Name of Driver : CHUA HOCK GUAN  
 Type of Accident : CHAIN COLLISION  
 Date / Time of Accident : 20/02/2018 09:24:00 AM  
 Accident Reported Date / Time : 20/02/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : Sebastian  
 Vehicle is Towed Back? : Yes ✓  
 Towed Back Date/Time : 20/02/2018  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024094666  
 Special Instruction to ARC, if any :



SLF4846B / TOWED IN *ALG HC*  
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121  
 LUMPSUM REPAIR

Prepared Date : 20/02/2018 02:26:57 PM

Recording Camera    
 Radio Antenna    
 1<sup>st</sup> witness *QC* Date *22-2-18*  
 2<sup>nd</sup> witness \_\_\_\_\_ Date \_\_\_\_\_



*QC 2/3/18 16:20/2955*

Vehicle to Wagon Date In: *20/2/18* Towing:   
 Time In: \_\_\_\_\_ Driver: \_\_\_\_\_  
 Wagon Job No: *02/0142*  
 Vehicle sent to SMART Date In: *2/3/18* Towing: \_\_\_\_\_  
 Time In: *1430* Driver: *QC*  
 Received by (SMART): \_\_\_\_\_

Chassis No : KL1LA69RJBB129605 Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,690.00	1,200.00
Total Spray Painting Charges	2,952.00	1,400.00
Total Material Charges	8,479.77	7,283.06
Other Charges	1,620.00	700.00
<b>TOTAL</b>	<b>14,741.77</b>	<b>10,583.06</b>
Lum Sum Total	14,750.00	10,600.00
No. of Repair Days	10.00	8.00
Prepared / Adjusted By		SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	21/02/2018 11:05:10 AM	22/02/2018 02:28:18 PM

P

LICK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/02/2018 11:05:10 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : *QA-1803-025-0* Invoice No :  
 Quotation Date : *13/3* Invoice Date :  
 Invoice Amount : Prepared Date :

*9103.82 / -20%*

*7283.06 /  
+ 1200.00 /  
+ 2100.00 /*

*Sebastian  
19/3/18*

*10,583.06 /  
LIS \$10,600/- /*

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,690.00 ✓	1,200.00 ✓
<b>Total Labour</b>	<b>1,690.00</b>	<b>1,200.00</b>

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00 ✓	200.00 ✓
TO RESPRAY REAR PANEL	180.00 ✓	200.00 ✓
TO RESPRAY REAR SPARE TYRE PANEL	180.00 ✓	100.00 ✓
TO RESPRAY REAR CHASSIS LH	180.00 ✓	50.00 ✓
TO RESPRAY REAR CHASSIS RH	180.00 ✓	50.00 ✓
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00 ✓	100.00 ✓
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00 ✓	100.00 ✓
TO RESPRAY REAR BOOT LID	378.00 ✓	200.00 ✓
TO RESPRAY TAIL LAMP PANEL LH	180.00 ✗	0.00
TO RESPRAY TAIL LAMP PANEL RH	180.00 ✗	0.00
TO RESPRAY REAR FENDER RH	378.00 ✓	200.00 ✓
TO RESPRAY REAR FENDER LH	378.00 ✓	200.00 ✓
<b>Total Spray Painting &amp; Panel Beating</b>	<b>2,952.00</b>	<b>1,400.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	80.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	60.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 ✓
TO ALIGN CHASSIS	350.00	200.00 ✓
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60.00 ✓
TO REMOVE AND REFIT WIRE HARDESS	150.00	30.00 ✓
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	110.00 ✓
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 ✓
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 ✓
TO REPLACE SUNDRY PARTS	100.00	20.00 ✓
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>1,620.00</b>	<b>700.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
93745100	REAR	6504589	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace	No	CRK
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace	No	BT
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace	No	CRK
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace	No	BT
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace	No	BT
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No	CRK
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00 264	10.00	237.60	Replace	Replace	No	CRK
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace	No	CRK
96873820	REAR		COVER TOWING EYE RR	1	21.00	100.00	0.00	Replace	Repair	No	R
96647117	COMMON		W/HARNES RR BPR	1	227.34	10.00	204.61	Replace	Check	No	X
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace	No	BT
	COMMON	4006314	SEALANT SIKAFLEX	2	37.00 34	0.00	74.00	Replace	Replace	No	NCC
96418400			MUFFLER A-EXH,RR	1	2,909.00	100.00	0.00	Replace	Repair	No	R
			EXHAUST PIPE MOUNTING, REAR	2	4.40 8.80	10.00	7.92	Replace	Replace	No	BT
96515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Replace	No	BT
	BODY		CHASSIS MEMBER RR LH	1	525.38	100.00	0.00	Replace	Repair	No	R
	BODY		PNL SIDE LH SPARE TYRE	1	650.00	100.00	0.00	Replace	Repair	No	R
	BODY		CHASSIS MEMBER RR RH	1	525.38	100.00	0.00	Replace	Repair	No	R
	BODY		PNL SIDE RH SPARE TYRE	1	650.00	100.00	0.00	Replace	Repair	No	R
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace	No	BT
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace	No	Jay
96327155	REAR		REAR BOOT ACTUATOR LOCK	1	75.00	10.00	67.50	Replace	Check	No	X
96993921	REAR	6504578	TRIM TAIL LID	0	71.00	10.00	0.00	Replace	Not given	No	X
96976171	REAR	6504635	REAR BOOT REFLECTOR	0	165.00	10.00	0.00	Replace	Not given	No	X
96851765	REAR	6504566	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace	No	CRK
96851766	REAR	6504583	LAMP BACK UP RH	0	122.00	10.00	0.00	Replace	Not given	No	X
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace	No	
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace	No	
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace	No	
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No	
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No	
	COMMON		NUMBER PLATE	0	15.00	0.00	0.00	Replace	Not given	No	X

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	COMMON		NUMBER PLATE FRAME	0	12.00	0.00	0.00	Replace	Not given	No X
96190751	REAR		LAMP LICENSE	2	56.00 <sup>112</sup>	10.00	100.80	Replace	Check	No X
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace	No /
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Check	No X
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace	No /
			TRIM REAR BOOT, LH	1	125.00	10.00	112.50	Replace	Replace	No /
			TRIM REAR BOOT, RH	1	125.00	10.00	112.50	Replace	Replace	No /
94503739			CLIP, TRIM	10	1.00 <sup>10</sup>	10.00	9.00	Replace	Replace	No /
96932979			COVER BAORD SPARE TYRE	1	661.00	10.00	594.90	Replace	Check	No X
			INSULATOR SHEET	2	41.48 <sup>82.96</sup>	10.00	74.66	Replace	Check	No X
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No /
			JACK FOAM COVER	1	35.00	10.00	31.50	Replace	Check	No X
96406718			SIGN WARNING TRIANGLE	1	68.00	10.00	61.20	Replace	Check	No X
			PANEL TAIL LAMP, LH	1	143.40	10.00	129.06	Replace	Check	No X
			PANEL TAIL LAMP, RH	1	143.40	10.00	129.06	Replace	Check	No X
96851763	REAR	6504583	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace	No /
96851764	REAR	6504511	LAMP RR COMBINATION RH	1	415.00	10.00	373.50	Replace	Replace	No /
96632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	10.00	1,071.90	Replace	Replace	No /
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No /
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No /
96633557	REAR	6504575	LINER LH REAR FENDER ( PROTECTOR )	1	201.00	10.00	180.90	Replace	Replace	No /
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	100.00	0.00	Replace	Repair	No /
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No /
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No /
			LINER RH REAR FENDER (PROTECTOR)	0	65.00	10.00	0.00	Replace	Not given	No X
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace	No /
	COMMON		SEALANT W/SCREEN	2	37.00 <sup>74</sup>	0.00	74.00	Replace	Replace	No /
<b>TOTAL MATERIALS</b>								<b>10,599.71</b>	<b>9,103.82</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>8,479.77</b>	<b>7,283.06</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

25186.86

## SMRT Accident Vehicle Repair Estimates

A19

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5228Y  
 Ref. No : TAX/02/18/2114  
 Reg. Date : 12/07/2012  
 Vehicle Type : TAXI  
 Make : CHEVROLET EPICA 2.0 VCDI  
 Model : EPICA-2.0  
 Name of Driver : CHUA HOCK GUAN  
 Type of Accident : CHAIN COLLISION  
 Date / Time of Accident : 20/02/2018 09:24:00 AM  
 Accident Reported Date / Time : 20/02/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : Yes  
 Towed Back Date/Time : 20/02/2018  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024094666  
 Special Instruction to ARC, if any :  
 SLF4846B / TOWED IN  
 Prepared Date : 20/02/2018 02:26:57 PM



*Sebastian  
 22/2/18  
 - Loop Sun Repair  
 - Question Mark Iron  
 Photo  
 - Photo After Paint*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : KL1LA69RJBB129605

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Total Labour Charges	: 1,690.00	0.00
Total Spray Painting Charges	: 2,952.00	0.00
Total Material Charges	: 13,664.31	13,664.31
Other Charges	: 1,620.00	0.00
<b>TOTAL</b>	<b>: 19,926.31</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 19,950.00</b>	<b>0.00</b>
No. of Repair Days	: 10.00	0.00
Prepared / Adjusted By	:	<i>8 days</i>
Arc / Surveyor Sing Off Date	: 21/02/2018 11:05:10 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/02/2018 11:05:10 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,690.00	0.00 1200
<b>Total Labour</b>	<b>1,690.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 200
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 100
TO RESPRAY REAR CHASSIS LH	180.00	0.00 50
TO RESPRAY REAR CHASSIS RH	180.00	0.00 50
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00 100
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00 100
TO RESPRAY REAR BOOT LID	378.00	0.00 200
TO RESPRAY TAIL LAMP PANEL LH	180.00	0.00 ?
TO RESPRAY TAIL LAMP PANEL RH	180.00	0.00 ?
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
<b>Total Spray Painting &amp; Panel Beating</b>	<b>2,952.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO ALIGN CHASSIS	350.00	0.00 200
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 60
TO REMOVE AND REFIT WIRE HARDESS	150.00	0.00 30
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 110
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>1,620.00</b>	<b>0.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace ✓	No <del>CRK</del>
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace ✓	No <del>BT</del>
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace ✓	No <del>CRK</del>
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace ✓	No <del>BT</del>
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace ✓	No <del>BT</del>
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ✓	No <del>DMG</del>
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace ✓	No <del>CRK</del>
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace ✓	No <del>CRK</del>
96873820	REAR		COVER TOWING EYE RR	1	21.00	10.00	18.90	Replace	Replace R	No
96647117	COMMON		W/HARNESS RR BPR	1	227.34	10.00	204.61	Replace	Replace ?	No
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace ✓	No <del>Defou</del>
	COMMON	4006314	SEALANT SIKAFLEX	2	37.00	0.00	74.00	Replace	Replace ✓	No <del>NEC</del>
96418400			MUFFLER A-EXH,RR	1	2,909.00	10.00	2,618.10	Replace	Replace R	No
			EXHAUST PIPE MOUNTING, REAR	2	4.40	10.00	7.92	Replace	Replace ✓	No <del>MS</del>
96515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Replace ✓	No <del>Defou</del>
	BODY		CHASSIS MEMBER RR LH	1	525.38	10.00	472.84	Replace	Replace R	No
	BODY		PNL SIDE LH SPARE TYRE	1	650.00	10.00	585.00	Replace	Replace R	No
	BODY		CHASSIS MEMBER RR RH	1	525.38	10.00	472.84	Replace	Replace R	No
	BODY		PNL SIDE RH SPARE TYRE	1	650.00	10.00	585.00	Replace	Replace R	No
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace ✓	No <del>BT</del>
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace ✓	No <del>JM</del>
96327155	REAR		REAR BOOT ACTUATOR LOCK	1	75.00	10.00	67.50	Replace	Replace ?	No
96993921	REAR	6504578	TRIM TAIL LID	1	71.00	10.00	63.90	Replace	Replace X	No
96976171	REAR	6504635	REAR BOOT REFLECTOR	1	165.00	10.00	148.50	Replace	Replace <del>SM</del>	No <del>CRK</del>
96851765	REAR	6504566	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace ✓	No <del>CRK</del>
96851766	REAR	6504583	LAMP BACK UP RH	1	122.00	10.00	109.80	Replace	Replace <del>SM</del>	No <del>DEF</del>
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace ✓	No <del>NEC</del>
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace ✓	No <del>NEC</del>
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace ✓	No <del>NEC</del>
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No <del>NEC</del>
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No <del>NEC</del>
	COMMON		NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace X	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
	COMMON		NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace X	No
96190751	REAR		LAMP LICENSE	2	56.00	10.00	100.80	Replace	Replace ?	No
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace ✓	No Defect
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace ?	No
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace ✓	No NEC
			TRIM REAR BOOT, LH	1	125.00	10.00	112.50	Replace	Replace ✓	No Defect
			TRIM REAR BOOT, RH	1	125.00	10.00	112.50	Replace	Replace ✓	No Defect
94503739			CLIP,TRIM	10	1.00	10.00	9.00	Replace	Replace ✓	No NEC
96932979			COVER BAORD SPARE TYRE	1	661.00	10.00	594.90	Replace	Replace ?	No
			INSULATOR SHEET	2	41.48	10.00	74.66	Replace	Replace ?	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ✓	No NEC
			JACK FOAM COVER	1	35.00	10.00	31.50	Replace	Replace ?	No
96406718			SIGN WARNING TRIANGLE	1	68.00	10.00	61.20	Replace	Replace ?	No
			PANEL TAIL LAMP, LH	1	143.40	10.00	129.06	Replace	Replace ?	No
			PANEL TAIL LAMP, RH	1	143.40	10.00	129.06	Replace	Replace ?	No
96851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace ✓	No BI
96851764	REAR	6504511	LAMP RR COMBINATION RH	1	415.00	10.00	373.50	Replace	Replace ✓	No BI
96632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	10.00	1,071.90	Replace	Replace ✓	No Defect
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No NEC
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No NEC
96633557	REAR	6504575	LINER LH REAR FENDER ( PROTECTOR )	1	201.00	10.00	180.90	Replace	Replace ✓	No CRK
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	10.00	1,320.30	Replace	Replace R	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No NEC
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No NEC
			LINER RH REAR FENDER (PROTECTOR)	1	65.00	10.00	58.50	Replace	Replace X	No
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace ✓	No NEC
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace ✓	No NEC
<b>TOTAL MATERIALS</b>							<b>17,080.39</b>	<b>17,080.39</b>		
<b>TOTAL MATERIALS(Discounted)</b>							<b>13,664.31</b>	<b>13,664.31</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

## View Received Message

This mail is associated with :

**\*SHB5228Y (8013836461SG)**  
**[SLF4846B]**

TP  
SMRT TAXIS PTE LTD  
Feb 26 2018 12:00AM  
[LCRF Pte Ltd]  
SMRT Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 28/02/2018 15:49 PM.  
**To** LKK\_HQ  
**Subject** No OI GIA Report

Hi

Pls be advice that no OI GIA report received  
Pls find OI details below for your further actions

LCRF PTE LTD  
60 Anson Road  
#11-01 Mapletree Anson  
Singapore 077914  
Office :(+65) 31584255

Thank you.

Regards,  
Darshene

### DOCUMENTS SUMMARY

There are no documents.



### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	22/02/2018 10:40
Date Of Accident	20/02/2018 09:30
Exact Location Of Accident	ALONG CTE BEFORE HAVELOCK RD EXIT
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF4846B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201604597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

#### Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE HIRE

#### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

#### Driver

Name of Driver	AZMAN BIN MOHAMED
NRIC No	S1425099I
Date Of Birth	21/04/1960
Occupation	OUTDOOR
Date Of Driving Pass	26/01/1984
Driving Experience	34 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address NOADDRESS  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured PAID DRIVER ✓  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR ✓  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 3

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name TRAFFIC POLICE DIVISION HQ  
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 65470000 - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO POLICE REPORT & SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: VIDEO OVERWRITTEN  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHB5228Y  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category TAXI  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

SKETCH PLAN

CHE TUNNEL BEFORE HAVE TO CC EXIT.

A - SLF 48469  
B - S118 52284

Sketch Plan #2

Describe Circumstances of the Accident

A KINDLY REFER TO POLICE REPORT.

Declaration

We declare the foregoing particulars are true in every respect.

   
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



**SINGAPORE  
POLICE FORCE**



T/20180221/2060

1 of 4

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180221/2060

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 21/02/2018 12:39	Vide Report No.: E/20180220/0048	Station Diary No.:
--	-------------------------------------	--------------------

**Informant's Particulars**

Name of Informant: AZMAN BIN MOHAMED		Address:	
ID Type / ID No.: NRIC NO / S1425099I		Contact No.:	Mobile:
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 57	Date of Birth: 21/04/1960	Type of Informant: Driver
Race: Malay		Language: English	Institution / School Name:
Occupation: UBER DRIVER		Driving Licence Information: Class: 2B,2A,3,4	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 20/02/2018 09:30	Type of Location:
Location: Along Road 1 CENTRAL EXPRESSWAY TUNNEL BEFORE HAVELOCK ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB5228Y	Car				Slightly Damaged	0
SLF4846B	Car				Seriously Damaged	2

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

## Sketch Plan #4



**SINGAPORE  
POLICE FORCE**



T/20180221/2060

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 4

Report No. T/20180221/2060

## CONTINUATION OF REPORT

Driver			
Name	CHUA HOCK CHUAN	ID No.	S1765491H
Related Vehicle	SHB5228Y (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	AZMAN BIN MOHAMED	ID No.	S1425099I
Related Vehicle	SLF4846B (Car)	Contact No.	82473981
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3,4 Date of Expiry: NIL
Date Treatment	20/02/2018	Date Discharge	20/02/2018
No. of Days granted Medical Leave	30	Degree of Injury	NIL
Passenger			
Name	ABDUL RAHMAN BIN ABU BAKAR	ID No.	S1803516B
Related Vehicle	SLF4846B (Car)	Contact No.	NIL
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	20/02/2018	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	NORAIN BINTE ABU BAKAR	ID No.	S7203745D
Related Vehicle	SLF4846B (Car)	Contact No.	NIL
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	20/02/2018	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE  
POLICE FORCE**



T/20180221/2060

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 4  
Report No. T/20180221/2060



CONTINUATION OF REPORT

**Brief Details.**

ON THE ABOVE MENTIONED DATE AND TIME

I WAS TRAVELLING ALONG LANE 1 OF CTE BEHIND A TAXI(SHB5228Y) WHEN SUDDENLY THE TAXI JAM BRAKED. I JAM BRAKED ALSO BUT I LOST CONTROL OF MY CAR AND IT WENT FORWARD AND HIT THE TAXI INFRONT OF ME. DURING THAT TIME I HAD TWO PASSENGERS WITH ME AND ONE OF THEM CALLED FOR THE AMBULANCE. POLICE AND AMBULANCE CAME. MY TWO PASSENGERS AND MYSELF WAS CONVEYED TO SINGAPORE GENERAL HOSPITAL BY THE AMBULANCE. I WAS NOT HOSPITALISED BUT WAS GIVEN 30-DAYS MC. I DO NOT KNOW ABOUT MY TWO PASSENGERS.

Sketch Plan #6



Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE

**IMPORTANT NOTE** : Please submit the completed Addendum form to the same Authorised Reporting Centre whom you submitted the Original Report.

**ADDENDUM**


**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : MVA118025519      Vehicle Registration No : S1FA846E  
Name(as shown in NRIC) : Azman Bin Mohamed  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
NRIC/Passport No : \_\_\_\_\_  
Address : \_\_\_\_\_  
Contact (Tel) : \_\_\_\_\_      (H/P) : \_\_\_\_\_  
(Email) : \_\_\_\_\_  
Date of Accident : 20/04/2018      Time of Accident : 0930Hrs  
Place of Accident : Along CTE before Havelock Exit  
Insurance Company : AI G

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information the following amendments:

Convert to OD



**...CLAIM SUBFOLDER...(Pending for Survey Report)**

Express

**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Feb 2018 <a href="#">Edit Reg</a>		22 Feb 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$10,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$10,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)**CLAIM SUBFOLDER DETAILS**[\[Created by adjuster\]](#)

Insured:	<b>LCRF Pte Ltd</b> , Co. Reg. No.: NA		
Main Claimant:	<b>SMRT TAXIS PTE LTD</b> , Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	<b>SHB5228Y</b>	Date of Loss:	20/02/2018 09:00 - :59 [67 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 7683834721SG</b>	Policy/Cover Note No.:	999995174 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SLF4846B</b>	Policy No. (Claimant):	D-17087562MFSH
		Excess:	
Repairer:	<b>SMRT Automotive Services Pte Ltd (Woodlands)</b> 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Gan, Angie-GL</b> ] Anlegeokling.Gan@aig.com		
Claimant's Insurer:	<b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Sebastian Yeang Wai Keen</b> ] ... [Final Rpt due 07/03/2018]		
Driver/Custodian (Insured):	AZMAN BIN MOHAMED (), NRIC: S1425099I		

**ASSOCIATED MAIL RECEIVED**[View All](#)[Compose Case Mail](#)

- AIG\_SG\_EXPRESS (14/05/2018): **Alert - Adj Mandate Approved (S\$12168.69) - SHB5228Y - Claim Handler: Gan, Angie...**
- AIG\_SG (28/02/2018): **No OI GIA Report**

**ALL ASSOCIATED TASKS**[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SHB5228Y (7683834721SG)  
[SLF4846B]**

**TP**

**SMRT TAXIS PTE LTD**

**Feb 20 2018 9:30AM**

**[LCRF Pte Ltd]**

**SMRT Automotive Services Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)
View [View in Browser](#) ▼

### Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	<b>Third Party Express Settlement - Payment Breakdown</b>	 Edit	<input type="checkbox"/>

### Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
30	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
31	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
32	09/04/18 12:11	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
34	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
35	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
36	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
37	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
38	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
39	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
40	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
41	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
42	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
43	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
44	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
45	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
46	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
47	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
48	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
49	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
50	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
51	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
52	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
53	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
54	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
55	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
56	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
57	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
58	09/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
59	09/04/18 13:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	09/04/18 13:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	09/04/18 13:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	09/04/18 13:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	09/04/18 13:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/18 18:15	TP ESTIMATE- MARKED	 Load PDF	
2	27/02/18 20:00	TP GIA REPORT	 Load PDF	
3	05/03/18 14:06	LETTER TO OI TO REPORT	 Load PDF	
4	09/04/18 12:09	LETTER TO LCRF	 Load PDF	
5	09/05/18 10:41	LTA SEARCH	 Load PDF	
6	09/05/18 10:41	RENTAL RECEIPT	 Load PDF	
7	17/05/18 15:03	AUTHORISATION TO ACT	 Load PDF	
8	17/05/18 15:03	RELEASE VOUCHER	 Load PDF	
9	17/05/18 15:03	WORKSHOP INVOICE	 Load PDF	
10	17/05/18 15:03	PIR	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLF4846B (Insd veh)	Model:	CHEVROLET EPICA 2.0 VCDI (A)
	SHB5228Y (TP veh)		
Date of Accident:	20/02/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	25,186.86
Final Repair Cost	:	\$	12,168.00
Loss of Use	:	\$	7.00 days at \$60.00 per day
Rental (if any)	:	\$	11 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	12,168.00
<b>Is Third Party Workshop GIA Registered?</b> <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
<b>A) For Non GIA Registered Workshop:</b>		Agreed Liability _____ 100 _____ (%)	
<b>B) For GIA Registered Workshop:</b>		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	:	\$ 12,168.00
2)		:	\$
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

17 May  
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/LCR18003585/SJB3S2  
**Date:** 17/05/2018

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	999995174
<b>Claimant Vehicle No :</b>	SHB5228Y	<b>Insured Vehicle No :</b>	SLF4846B
Date of Loss:	20/02/2018	Nature of Claim:	TP
		Claim No:	7683834721SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB5228Y</b>	Engine No:	Z20S14663350K
Make & Model:	CHEVROLET EPICA, 2.0 VCDI (A)	Chassis No:	KL1LA69RJBB129605
Reg. Date:	12/07/2012 (Man. Year: 2012)	Odometer:	676554 km
Colour:	Maroon		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	205/55R15	Rear Tyre Size:	205/55R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,924.86	9,103.82	9,821.04	51.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,262.00	3,300.00	2,962.00	47.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>25,186.86</b>	<b>12,403.82</b>	<b>12,783.04</b>	<b>50.75</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>10,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>25,186.86</b>	<b>10,600.00</b>	<b>14,586.86</b>	<b>57.91</b>
		420.00		
<b>+ Loss of Use (7.0 x S\$60.00/day) (S\$)</b>		1,141.69		
<b>+ Car Rental (11.0 x S\$103.79/day) (S\$)</b>		7.00		
<b>+ Doc/Search Fee (S\$)</b>				
		<b>12,168.69</b>		
<b>Nett Liability (S\$)</b>		<b>12,168.69</b>		
<b>Global Sum Settlement (S\$)</b>		<b>12,168.00</b>		

### INSPECTION

Date of Assignment:	22/02/2018		
Date Inspected:	22/02/2018	Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	8.0 days		

---

**Adjuster:** Sebastian Yeang Wai Keen

**Manager:** Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER RR (DISC 10%)	Cracked	1,238.00 F	*1,114.20 F
2	1		*BEAM RR BUMPER IMPACT (DISC 10%)	Bent	1,221.00 F	*1,098.90 F
3	1		*ABSORBER ENGY RR BUMPER (DISC 10%)	Cracked	70.00 F	*63.00 F
4	1		*BRACKET RR BUMPER SIDE LH (DISC 10%)	Bent	49.00 F	*44.10 F
5	1		*BRACKET RR BUMPER SIDE RH (DISC 10%)	Bent	49.00 F	*44.10 F
6	1		*REFLECTOR REFLEX RR LH (DISC 10%)	Cracked	264.00 F	*237.60 F
7	1		*REFLECTOR REFLEX RR RH (DISC 10%)	Cracked	264.00 F	*237.60 F
8	1		*PANEL END REAR (DISC 10%)	Deformed	255.00 F	*229.50 F
9	2		*EXHAUST PIPE MOUNTING, REAR (DISC 10%)	Missing	8.80 F	*7.92 F
10	1		*PANEL SPARE TYRE (DISC 10%)	Deformed	2,299.00 F	*2,069.10 F
11	1		*REAR BOOT LID (DISC 10%)	Bent	974.00 F	*876.60 F
12	1		*REAR BOOT LOCK (DISC 10%)	Jammed	77.00 F	*69.30 F
13	1		*LAMP BACK UP LH (DISC 10%)	Cracked	151.00 F	*135.90 F
14	1		*EMBLEM REAR (DISC 10%)	Necessary	44.00 F	*39.60 F
15	1		*LETTERING: CHEVROLET (DISC 10%)	Necessary	29.00 F	*26.10 F
16	1		*LETTERING: EPICA LT (DISC 10%)	Necessary	28.00 F	*25.20 F
17	1		*REAR BOOT WEATHERSTRIP (DISC 10%)	Deformed	49.00 F	*44.10 F
18	1		*REAR BOOT STRIKER (DISC 10%)	Necessary	15.00 F	*13.50 F
19	1		*TRIM REAR BOOT, LH (DISC 10%)	Deformed	125.00 F	*112.50 F
20	1		*TRIM REAR BOOT, RH (DISC 10%)	Deformed	125.00 F	*112.50 F
21	10		*CLIP, TRIM (DISC 10%)	Necessary	10.00 F	*9.00 F
22	1		*LAMP RR COMBINATION LH (DISC 10%)	Bent	415.00 F	*373.50 F
23	1		*LAMP RR COMBINATION RH (DISC 10%)	Bent	415.00 F	*373.50 F
24	1		*FENDER LH REAR (DISC 10%)	Deformed	1,191.00 F	*1,071.90 F
25	1		*LINER LH REAR FENDER (PROTECTOR) (DISC 10%)	Cracked	201.00 F	*180.90 F
26	1		*MOLDING WINDSCREEN REAR (DISC 10%)	Necessary	45.00 F	*40.50 F
27	1		*SENSOR REVERSE (SN)	Damaged	180.00 F	*180.00 F
28	2		*SEALANT SIKAFLEX (SN)	Necessary	74.00 F	*74.00 F
29	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
30	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
31	1		*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F
32	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
33	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
34	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
35	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
36	2		*SEALANT W/SCREEN (SN)	Necessary	74.00 F	*74.00 F
37	1		*W/HARNESS RR BPR	Not Necessary	227.34 F	*- F
38	1		*REAR BOOT ACTUATOR LOCK	Not Necessary	75.00 F	*- F
39	1		*TRIM TAIL LID	Not Necessary	71.00 F	*- F
40	1		*REAR BOOT REFLECTOR	Not Necessary	165.00 F	*- F
41	1		*LAMP BACK UP RH	Not Necessary	122.00 F	*- F
42	1		*NUMBER PLATE	Not Necessary	15.00 F	*- F
43	1		*NUMBER PLATE FRAME	Not Necessary	12.00 F	*- F
44	2		*LAMP LICENSE	Not Necessary	112.00 F	*- F
45	1		*TRIM REAR END PANEL	Not Necessary	114.00 F	*- F
46	1		*COVER BOARD SPARE TYRE	Not Necessary	661.00 F	*- F
47	2		*INSULATOR SHEET	Not Necessary	82.96 F	*- F
48	1		*JACK FOAM COVER	Not Necessary	35.00 F	*- F
49	1		*SIGN WARNING TRIANGLE	Not Necessary	68.00 F	*- F
50	1		*PANEL TAIL LAMP, LH	Not Necessary	143.40 F	*- F
51	1		*PANEL TAIL LAMP, RH	Not Necessary	143.40 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*LINER RH REAR FENDER (PROTECTOR)	Not Necessary	65.00 F	*- F
53	1		*COVER TOWING EYE RR	Repair	21.00 F	*- F
54	1		*MUFFLER A-EXH,RR	Repair	2,909.00 F	*- F
55	1		*CHASSIS MEMBER RR LH	Repair	525.38 F	*- F
56	1		*PNL SIDE LH SPARE TYRE	Repair	650.00 F	*- F
57	1		*CHASSIS MEMBER RR RH	Repair	525.38 F	*- F
58	1		*PNL SIDE RH SPARE TYRE	Repair	650.00 F	*- F
59	1		*FENDER RH REAR	Repair	1,467.00 F	*- F
<b>Total Parts (S\$)</b>					<b>18,924.86</b>	<b>9,103.82</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODYWORK.	New	1,690.00	1,200.00
2	SPRAY PAINT.	New	2,952.00	1,400.00
3	TOWING CHARGE.	New	80.00	80.00
4	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	30.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	200.00	60.00
6	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	30.00
7	TO ALIGN CHASSIS.	New	350.00	200.00
8	TO TRANSFER REAR TAILGATE MECHANISM.	New	120.00	60.00
9	TO REMOVE AND REFIT WIRE HARDESS.	New	150.00	30.00
10	TO REMOVE AND REFIX REAR WINDSCREEN.	New	120.00	110.00
11	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	New	120.00	30.00
12	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	New	120.00	50.00
13	TO REPLACE SUNDRY PARTS.	New	100.00	20.00
14	TO WASH AND VACUUM.	New	60.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>6,262.00</b>	<b>3,300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >