

## SMRT Accident Vehicle Repair Estimates

A19

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5228Y  
 Ref. No : TAX/02/18/2114  
 Reg. Date : 12/07/2012  
 Vehicle Type : TAXI  
 Make : CHEVROLET EPICA 2.0 VCDI  
 Model : EPICA-2.0  
 Name of Driver : CHUA HOCK GUAN  
 Type of Accident : CHAIN COLLISION  
 Date / Time of Accident : 20/02/2018 09:24:00 AM  
 Accident Reported Date / Time : 20/02/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : Yes  
 Towed Back Date/Time : 20/02/2018  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024094666  
 Special Instruction to ARC, if any :  
 SLF4846B / TOWED IN  
 Prepared Date : 20/02/2018 02:26:57 PM



Sebastian  
22/2/18

- Lump Sum Repair.
- Question Mark Item Photo
- Photo After Paint

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : KL1LA69RJBB129605

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Total Labour Charges	: 1,690.00	0.00
Total Spray Painting Charges	: 2,952.00	0.00
Total Material Charges	: 13,664.31	13,664.31
Other Charges	: 1,620.00	0.00
<b>TOTAL</b>	<b>: 19,926.31</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 19,950.00</b>	<b>0.00</b>
No. of Repair Days	: 10.00	0.00
Prepared / Adjusted By	:	8 days
Arc / Surveyor Sing Off Date	: 21/02/2018 11:05:10 AM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/02/2018 11:05:10 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : Invoice No :  
Quotation Date : Invoice Date :  
Invoice Amount : Prepared Date :

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,690.00	0.00 1200
<b>Total Labour</b>	<b>1,690.00</b>	<b>0.00</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 200
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 100
TO RESPRAY REAR CHASSIS LH	180.00	0.00 50
TO RESPRAY REAR CHASSIS RH	180.00	0.00 50
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00 100
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00 100
TO RESPRAY REAR BOOT LID	378.00	0.00 200
TO RESPRAY TAIL LAMP PANEL LH	180.00	0.00 ?
TO RESPRAY TAIL LAMP PANEL RH	180.00	0.00 ?
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
<b>Total Spray Painting &amp; Panel Beating</b>	<b>2,952.00</b>	<b>0.00</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO ALIGN CHASSIS	350.00	0.00 200
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 60
TO REMOVE AND REFIT WIRE HARDESS	150.00	0.00 30
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 110
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>1,620.00</b>	<b>0.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace ✓	No CRK
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace ✓	No BT
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace ✓	No CRK
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace ✓	No BT
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace ✓	No BT
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ✓	No DMG
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace ✓	No CRK
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace ✓	No CRK
96873820	REAR		COVER TOWING EYE RR	1	21.00	10.00	18.90	Replace	Replace R	No
96647117	COMMON		W/HARNES RR BPR	1	227.34	10.00	204.61	Replace	Replace ?	No
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace ✓	No Defon
	COMMON	4006314	SEALANT SIKAFLEX	2	37.00	0.00	74.00	Replace	Replace ✓	No NEC
96418400			MUFFLER A-EXH,RR	1	2,909.00	10.00	2,618.10	Replace	Replace R	No
			EXHAUST PIPE MOUNTING, REAR	2	4.40	10.00	7.92	Replace	Replace ✓	No MS
96515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Replace ✓	No Defon
	BODY		CHASSIS MEMBER RR LH	1	525.38	10.00	472.84	Replace	Replace R	No
	BODY		PNL SIDE LH SPARE TYRE	1	650.00	10.00	585.00	Replace	Replace R	No
	BODY		CHASSIS MEMBER RR RH	1	525.38	10.00	472.84	Replace	Replace R	No
	BODY		PNL SIDE RH SPARE TYRE	1	650.00	10.00	585.00	Replace	Replace R	No
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace ✓	No BT
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace ✓	No JM
96327155	REAR		REAR BOOT ACTUATOR LOCK	1	75.00	10.00	67.50	Replace	Replace ?	No
96993921	REAR	6504578	TRIM TAIL LID	1	71.00	10.00	63.90	Replace	Replace X	No
96976171	REAR	6504635	REAR BOOT REFLECTOR	1	165.00	10.00	148.50	Replace	Replace ✓	No X
96851765	REAR	6504566	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace ✓	No CRK
96851766	REAR	6504583	LAMP BACK UP RH	1	122.00	10.00	109.80	Replace	Replace ✓	No X
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace ✓	No NEC
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace ✓	No NEC
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace ✓	No NEC
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No NEC
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No NEC
	COMMON		NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace X	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	COMMON		NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace X	No
96190751	REAR		LAMP LICENSE	2	56.00	10.00	100.80	Replace	Replace ?	No
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace ✓	No Deform
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace ?	No
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace ✓	No NEC
			TRIM REAR BOOT, LH	1	125.00	10.00	112.50	Replace	Replace ✓	No Deform
			TRIM REAR BOOT, RH	1	125.00	10.00	112.50	Replace	Replace ✓	No Deform
94503739			CLIP,TRIM	10	1.00	10.00	9.00	Replace	Replace ✓	No NEC
96932979			COVER BAORD SPARE TYRE	1	661.00	10.00	594.90	Replace	Replace ?	No
			INSULATOR SHEET	2	41.48	10.00	74.66	Replace	Replace ?	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ✓	No NEC
			JACK FOAM COVER	1	35.00	10.00	31.50	Replace	Replace ?	No
96406718			SIGN WARNING TRIANGLE	1	68.00	10.00	61.20	Replace	Replace ?	No
			PANEL TAIL LAMP, LH	1	143.40	10.00	129.06	Replace	Replace ?	No
			PANEL TAIL LAMP, RH	1	143.40	10.00	129.06	Replace	Replace ?	No
96851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace ✓	No BT
96851764	REAR	6504511	LAMP RR COMBINATION RH	1	415.00	10.00	373.50	Replace	Replace ✓	No BT
96632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	10.00	1,071.90	Replace	Replace ✓	No Deform
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No NEC
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No NEC
96633557	REAR	6504575	LINER LH REAR FENDER ( PROTECTOR )	1	201.00	10.00	180.90	Replace	Replace ✓	No CRK.
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	10.00	1,320.30	Replace	Replace R	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No NEC
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No NEC
			LINER RH REAR FENDER (PROTECTOR)	1	65.00	10.00	58.50	Replace	Replace X	No
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace ✓	No NEC
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace ✓	No NEC
<b>TOTAL MATERIALS</b>								<b>17,080.39</b>	<b>17,080.39</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>13,664.31</b>	<b>13,664.31</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									