

INSURANCE

INS. CASE OWNER:

SHAWN

CC 3 / AIG1800

2594, T 163

LKK:
IDAC:

ASSIGNMENT

Surveyor:

TRUMP

DOI:

210010

Date / Time:

26/1/18

Registered in Merimen:

26/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLW 8714J

Name of Insured:

SIM POH WEE

Insured Tel No.:

HP: 97452946

Excess Sec II :SS

D.O.A.:

27/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

220860581534

Policy No.:

1800005961

Make / Model:

SUBARU

Place of Accident:

BET LOR KHAM & BANGKOK

RD

If NO, Driver Name / Age:

Driver Tel No.:

(VA) (YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SLW 8714J



INSRS:
WSP:
Tel:
Liability:
RMKS:

performance



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time		STAGE	DATE / PIC
7/7/18	SLW 8714J	Non-Reporting ltr (1st):	
7/7/18		Non-Reporting ltr (2nd):	
7/7/18		Non-Reporting ltr (Final):	
7/7/18		Notification ltr (if non-pickup):	
7/7/18		Call OI:	051010-2000
7/7/18		After call ltr to OI:	
5/3/18		Documentation Check List:	Handler Typist
5/3/18		Notification ltr (if non-pickup):	
5/3/18		After call ltr to OI:	
5/3/18		Authorisation To Act:	
5/3/18		Release Voucher:	
5/3/18		Final Repair Bill:	
5/3/18		Car Rental Invoice:	
5/3/18		Towing Invoice:	
5/3/18		LTA / GIA:	
5/3/18		Medical Bill:	
5/3/18		PIR:	
5/3/18		Mandate/Reject Instruction:	
5/3/18		LOD:	
5/3/18		Payment Breakdown Form:	
5/3/18		Post-Repair Photos:	
5/3/18		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: P/P	SS 10,570.95 (6 days)	Reduction: 48%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 03/04/19	Confirm with: CAROLINE	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.:	27
Repair Cost: (w/gate)	SS 11,310.92		
Loss of Rental (LOR):	SS 800.00 x 8 (days)		
Loss of Use (LOU):	SS 800.00 x 8 (days)		
Loss of Income (LOI):	SS 7.45		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>			
GIA/LTA Search	SS 7.45		
Medical:	SS 7.45		
Disbursement:	SS 7.45		
Legal Cost:	SS 7.45		
Total:	SS 12,118.37	Global Sum SS:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 11,310.92	Name 1:	PERFORMANCE MOTOR LTD
Payee 2: (Strike if N.A.)	SS 800.00	Name 2:	VENKATESHVARA DO PURUSHOTHAMAN
Payee 3: (Strike if N.A.)	SS 7.45	Name 3:	

Date / Time Action / Instruction

P/P 10,570.95
CRMD: 9,619.90 (48%)

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401339W GST Reg. No. M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159942
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax 64747770

288, Tampung Arang Road
Siam Coast Centre
Singapore 438180
Tel. 63190088 (AfterSales)
Fax 63445773

313, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190529 AfterSales/
63190537/538 Motorrad
Fax 64796401 AfterSales/
64796424 Motorrad

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46033
Date Estimated : 24/02/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH8549Y	G754126	22/11/2016	420iA GC	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER TRIM STRIP (SPORT LINE)	1	120.90	120.90
REAR BUMPER CENTRE GUIDE	1	55.40	55.40
COVER	1	61.00	61.00
RR LH RETAINING STRIP FOR TRIM STRIP	1	13.25	13.25
RR RH RETAINING STRIP FOR TRIM STRIP	1	13.25	13.25
FLAP TOWING EYE PRIMED	1	42.20	42.20
REAR BUMPER PANEL PRIMED (ZWEIF/LIN	1	1,133.25	1,133.25
GAP SEAL	1	34.15	34.15
RR BUMPER LH SIDE GUIDE	1	48.10	48.10
RR BUMPER RH SIDE GUIDE	1	48.10	48.10
LETTERING 420i	1	62.55	62.55
GROMMET	2	0.75	1.50
BADGE (BMW)	1	69.50	69.50
BUMP STOP	12	3.25	39.00
RR ROOF GAP FINISHER	1	77.90	77.90
SEAL REAR WINDOW LH	1	40.10	40.10
SEAL REAR WINDOW RH	1	40.10	40.10
TRUNK LID GASKET	1	124.00	124.00
RR BUMPER LH REFLECTOR	1	35.20	35.20
RR BUMPER RH REFLECTOR	1	35.20	35.20
REAR LIGHT RH IN THE SIDE PANEL PAN	1	419.85	419.85
REAR LIGHT IN TRUNK LID RH	1	293.90	293.90
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
PDC SENSOR IMPERIAL BLUE (A89)	4	368.80	1,475.20
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
(S/L) SEAM SEAL 300ML	4	33.80	135.20

Total Parts : 7,087.85

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This parts survey is on a "Without Prejudice" basis

- No illegal modification is allowed
- Supplementary parts must be resurveyed and is subject to final approval from Insurance Company

Labour 1	13,178.00
Labour 2	0.00
Excess	0.00
Total GST @ 7%	1,418.61

Date:

Grand Total : 21,684.46

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

20,890.85

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M3-0030081-X



SUPPLEMENTARY

Estimate No. : b1 46033
Date Estimated : 24/02/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Venkateswara S/O Purushothaman
49 Brockhampton Drive

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 559097

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLH8549Y	G754126	22/11/2016	420iA GC	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR PDC HOLDER SET (PDC & PMA) *	62.95	1.00		62.95 / <i>see</i>
# PLUG BLACK D=5MM *	0.90	10.00		9.00 / <i>see</i>
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05 / <i>see</i>

Total Labour :	
Total Parts :	125.00
Total Labour & Parts :	125.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559N/ GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46033
Date Estimated : 24/02/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Venkateswara S/O Purushothaman
49 Brockhampton Drive

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 559097

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLH8549Y	G754126	22/11/2016	420iA GC	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, trunk lid and attachments include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00	
To spray paint rear bumper, boot lid and tail end panel	2537.00		2,537.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To transfer lock mechanism from old to new trunk lid include conducting checks on new tail gate central locking system for proper function	451.00		451.00	
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00	
To remove and install rear windscreen glass include conducting water leak tests	649.00		649.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
TRUNK LID	1,204.80	1.00		1,204.80
RR BUMPER CARRIER ECE	432.90	1.00		432.90
REINFORCEMENT BUMPER REAR BOTTOM	67.10	1.00		67.10
REAR BUMPER TRIM STRIP (SPORT LINE)	120.90	1.00		120.90
REAR BUMPER CENTRE GUIDE	55.40	1.00		55.40
COVER	61.00	1.00		61.00
RR LH RETAINING STRIP FOR TRIM STRI	13.25	1.00		13.25
RR RH RETAINING STRIP FOR TRIM STRI	13.25	1.00		13.25
REAR BUMPER PANEL PRIMED (ZWEIF/LIN	1,133.25	1.00		1,133.25
# REAR PDC HOLDER SET (PDC & PMA) *	62.95	1.00		62.95
LETTERING 420i	62.55	1.00		62.55

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0030081-K



FINAL REPORT

GROMMET	0.75	1.00	0.75
BADGE (BMW)	69.50	1.00	69.50
SEAL REAR WINDOW LH	40.10	1.00	40.10
SEAL REAR WINDOW RH	40.10	1.00	40.10
# PLUG BLACK D=5MM *	0.90	10.00	9.00 <i>rec</i>
REAR LIGHT IN TRUNK LID RH	293.90	1.00	293.90
DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00	20.20
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00	53.05 <i>rec</i>

SUPPLEMENTARY ITEMS

Total Labour :	6,817.00
Total Parts :	3,753.95
Total Labour & Parts :	10,570.95
Deduction for Excess :	
Total Repair Costs less Excess:	10,570.95
GST @7%:	739.97
Grand Total :	11,310.92

Vic (LKKAUTO)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Friday, 27 April, 2018 3:24 PM
To: Vic (LKKAUTO); Taufikh (LKKAUTO)
Subject: URGENT REMINDER: FINAL REPORT / SLH8549Y
Attachments: Final Report SLH8549Y.pdf; Final Report SLH8549Y_2.pdf

URGENT REMINDER

From: PBSP
Sent: Tuesday, 17 April 2018 3:16 PM
To: taufikh@lkkauto.com; vicalpeh@lkkauto.com
Subject: FINAL REPORT / SLH8549Y

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 6,817.00
Total Parts : 3,753.95
Total Labour & Parts : 10,570.95

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Print Received Message

This mail is associated with :

***SLH8549Y (3208605815SG)**
[SLV8314J]

TP

VENKATESWARA S/O PURUSHOTHAMAN

Feb 23 2018 6:00PM

[Sim Poh Whee (Shen BaoHui)]

Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 15/03/2019 15:02 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12218.37) - SLH8549Y - Claim Handler: Chan, Kian-Meng

Approved:12218.37:Dear Asher, You may try to offer 6-8 days for LOU first. Kindly settle at best.

Vic (LKKAUTO)

From: Wui, Shawnkaijye <Shawnkaijye.Wui@aig.com>
Sent: Monday, 2 July, 2018 3:36 PM
To: Vic (LKKAUTO)
Cc: Admin A
Subject: RE: <SEEK MANDATE> Your Ref: 3208605815SG_ACCIDENT INVOLVING VEHICLES SLV 8314J (OI) AND SLH 8549Y (TP) ON 23/02/2018

Dear Vic,

Please upload repair invoice, LTA search record and ATA.

At the same time, please advise me whether both rear RH/ LH fender sustained any damages as I realized surveyor offer seal for rear window LH and RH.

Besides, there is labour for replace rear windscreen at \$ 649.00. Please advise whether there is a need to carry the repair job.

Thanks and Regards,
Shawn Wui
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1959 | Fax +(65) 6835 7416

Shawnkaijye.Wui@aig.com | www.aig.com.sg

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Saturday, June 30, 2018 4:48 PM
To: Wui, Shawnkaijye
Cc: Admin A; Vic (LKKAUTO)
Subject: <SEEK MANDATE> Your Ref: 3208605815SG_ACCIDENT INVOLVING VEHICLES SLV 8314J (OI) AND SLH 8549Y (TP) ON 23/02/2018

Your Ref: 3208605815SG
Our Ref: CC3/AIG18003594/T1hb3

Dear Shawn,

ACCIDENT INVOLVING VEHICLES SLV 8314J (OI) AND SLH 8549Y (TP) ON 23/02/2018

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)

Vehicle No:	50485494	Model:	
Date of Accident:	22.2.2018		

Global Sum Settlement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	\$	21684.46	
Final Repair Cost	\$	11310.92	
Loss of Use	\$	900.00	9 days at \$100 per day
Rental (if any)	\$		days
LTA / GIA Search Fee	\$	7.45	
Others:	\$		
	\$		
Final Settlement Sum	\$	12218.37	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop: Agreed Liability _____ (%)			
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Ltd	\$	11310.92
2)	Performance Motors Ltd	\$	7.45
3)	Venkateswara S/o Purushotham	\$	900.00

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
 Survey Report; Medical Report/ Bill (if any))



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG18003594/hb3

05 MARCH 2018

SIM POH WHEE
2 JALAN LABU MERAH
#01-01
SINGAPORE 537972

Dear Sir/Madam,

ACCIDENT INVOLVING SLV 8314J AND SLH8549Y ON 23/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Bevan Lim
Case Handler
DID: 6749 4274
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, VENKATESWARA S/O PARUSUTHANAN (the third party claimant) of 49 BRICKHAMPTON
DRIVE S 559097 (address), owner of SLV 85477 (vehicle no.)
hereby authorize PERFORMANCE MOTORSPORTS ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLV 85477 that was damaged pursuant to the accident which occurred on 23/2/18
(date) along LEONG CHUAN / BEAVER 2190 (location) involving vehicle no/s
SLV 8314 ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 29 (day) of 03 (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$1310.92 (Repair Cost), S\$ 800 (Loss of rental/use), S\$ 7,45 (Disbursement), for vehicle no. SLH8549Y that was damaged pursuant to the accident which occurred on 23.2.18 (date) along LOR CHUAN (location) involving vehicle no/s SLV8314J. This is pursuant to the inspection conducted on 21.3.18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Venkateswara S/O Purushothaman ("the third party claimant") of vehicle no. SLH8549Y make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLH8549Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 03 (day) of 04 (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559N GST Reg. No M2-0020062-X

107, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64767770

288, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : B1 1252862	Page No. : 1 of 2
Date IN : 21/03/2018	Invoice Number : 1960837 / WSB
Cust. Svc. Advisor: Gary Poh Chai Hoon	Invoice Date : 03/05/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Venkateswara S/O Purushothaman
49 Brockhampton Drive

Singapore 559097

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO. / SLH8549Y	CHASSIS NO. G754126	REGN. DATE 22/11/2016	MODEL 420IA GC	MILEAGE 16915
-----------------------------	----------------------------	------------------------------	-----------------------	----------------------

--- LABOUR 1 ---

To replace rear bumper and attachments, rear boot lid and right tail lamp etc including to make good the tail end panel and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	2,550.00
To respray rear bumper, rear boot lid and tail end panel etc.	2,537.00
To carry out body cavity preservation.	100.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	451.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00
To remove and install rear windscreen glass to facilitate the repair job.	649.00
Sundries.	150.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 23.2.2018. 3RD PARTY CAR : SLV8314J.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO CONSULTANTS PTE LTD ON 21.3.2018 AT 4.20 PM. AUTHORISED REPAIR BY MR VIC ALPEH FROM LKK ON 5.3.2018 VIA E-MAIL.	
PROPOSE LOSS OF USE = \$100X9. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
LTA SEARCH FEE = \$7.45.	0.00

Total Labour 1: **6,817.00**

--- PARTS ---

	Qty	Retail Price	NETT
GROMMET	1	0.75	0.75
BADGE (BMW)	1	69.50	69.50
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 119944
Tel. 63190528 (AfterSales)
63190533/310 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1252862	Page No. : 2 of 2
Date IN : 21/03/2018	Invoice Number : 1960837 / WSB
Cust. Svc. Advisor: Gary Poh Chai Hoon	Invoice Date : 03/05/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

PLUG BLACK D=5MM	10	0.90	9.00
REAR PDC HOLDER SET (PDC & PMA)	1	62.95	62.95
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
RR LH RETAINING STRIP FOR TRIM STRI	1	13.25	13.25
RR RH RETAINING STRIP FOR TRIM STRI	1	13.25	13.25
COVER	1	61.00	61.00
TRUNK LID	1	1,204.80	1,204.80
REINFORCEMENT BUMPER REAR BOTTOM	1	67.10	67.10
REAR BUMPER TRIM STRIP (SPORT LINE)	1	120.90	120.90
REAR BUMPER CENTRE GUIDE	1	55.40	55.40
REAR BUMPER PANEL PRIMED (ZWEIF/LIN	1	1,133.25	1,133.25
LETTERING 420I	1	62.55	62.55
REAR LIGHT IN TRUNK LID RH	1	293.90	293.90
SEAL REAR WINDOW LH	1	40.10	40.10
SEAL REAR WINDOW RH	1	40.10	40.10
RR BUMPER CARRIER ECE	1	432.90	432.90
Total Parts		:	3,753.95

Labour Charges :	6,667.00	Total Labour & Parts Charges :	S\$ 10,570.95
Parts Charges :	3,753.95	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	150.00	Invoice Total Amount Exclude GST :	S\$ 10,570.95
		GST @ 7% :	S\$ 739.97
		Invoice Total Amount Include GST :	S\$ 11,310.92

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 11,310.92**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 24 Feb 2018 / 10:47:56

Receipt Date/Time : 24 Feb 2018 / 10:47:56

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180224-000309

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLV8314J				
As at 23 Feb 2018/18:15:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLV8314J			
	Enquiry Fee	7.00	0.49	7.49
	20180224104632060615			
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	xxxxxxxxxxxx5164	Credit Card:		7.45
		Visa/MasterCard		
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express


































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2018 Edit Reg		21 Mar 2018 00:00 Edit Adj Rpt	S\$10,570.95 Edit Estimates	S\$10,570.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Sim Poh Whee (Shen BaoHui), ID: S7413982E								
Main Claimant:	VENKATESWARA S/O PURUSHOTHAMAN, ID: S1690377I								
Vehicle Reg. No.:	SLH8549Y	Date of Loss:	23/02/2018 18:00 - :59 [15 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3208605815SG	Policy/Cover Note No.:	1800005961 (Comprehensive) Coverage: 18/01/2018 - 17/01/2019						
Vehicle Reg. No. (Insured):	SLV8314J	Policy No. (Claimant):	VPA/P1865462						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 07/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (15/03/2019): Alert - Adj Mandate Approved (S\$12218.37) - SLH8549Y - Claim Handler: Chan, Kian... AIG_SG_EXPRESS (24/08/2018): Alert - Adj Mandate Maintained - SLH8549Y - Claim Handler: Wui, Shawn-KJ 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH8549Y (3208605815SG)
[SLV8314J]
TP
VENKATESWARA S/O PURUSHOTHAMAN
Feb 23 2018 6:00PM
[Sim Poh Whee (Shen BaoHui)]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown													1	Edit				
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	11/05/18 14:32	Odometer Reading													1	Load JPG	<input checked="" type="checkbox"/>			
2	11/05/18 14:32	Chassis Number													1	Load JPG	<input checked="" type="checkbox"/>			
3	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
4	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
5	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
6	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
7	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
8	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
9	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
10	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
11	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
12	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
13	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
14	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
15	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
16	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
17	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
18	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
19	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
20	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
21	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
22	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
23	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
24	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
25	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
26	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
27	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
28	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
29	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
30	11/05/18 14:33	General View													1	Load JPG	<input checked="" type="checkbox"/>			
31	11/05/18 14:33	Reinspection Photos													1	Load JPG	<input checked="" type="checkbox"/>			
32	11/05/18 14:33	Reinspection Photos													1	Load JPG	<input checked="" type="checkbox"/>			
33	11/05/18 14:33	Reinspection Photos													1	Load JPG	<input checked="" type="checkbox"/>			
34	11/05/18 14:33	Reinspection Photos													1	Load JPG	<input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	11/05/18 14:33	Reinspection Photos	 Load JPG	<input checked="" type="checkbox"/>
36	11/05/18 14:33	Reinspection Photos	 Load JPG	<input checked="" type="checkbox"/>
37	11/05/18 14:33	Reinspection Photos	 Load JPG	<input checked="" type="checkbox"/>
38	11/05/18 14:33	Reinspection Photos	 Load JPG	<input checked="" type="checkbox"/>
39	11/05/18 14:33	Reinspection Photos	 Load JPG	<input checked="" type="checkbox"/>
40	11/05/18 14:33	Reinspection Photos	 Load JPG	<input checked="" type="checkbox"/>
41	11/05/18 14:33	Reinspection Photos	 Load JPG	<input checked="" type="checkbox"/>
42	11/05/18 14:33	Reinspection Photos	 Load JPG	<input checked="" type="checkbox"/>
43	11/05/18 14:33	Reinspection Photos	 Load JPG	<input checked="" type="checkbox"/>
44	14/03/19 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	14/03/19 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	14/03/19 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	14/03/19 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	14/03/19 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	14/03/19 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	14/03/19 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	14/03/19 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	14/03/19 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	14/03/19 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	14/03/19 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	14/03/19 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/18 16:00	TP ESTIMATE	 Load TIF	
2	26/02/18 16:00	TP GIA REPORT	 Load PDF	
3	06/03/18 09:45	LETTER TO OI	 Load PDF	
4	23/03/18 15:54	TP ESTIMATE- MARKED	 Load PDF	
5	05/06/18 11:14	LTA SEARCH	 Load PDF	
6	20/08/18 09:57	REPAIR INVOICE	 Load PDF	
7	14/03/19 17:27	DIAGRAMS	 Load PDF	
8	05/04/19 15:28	AUTHORISATION TO ACT FORM	 Load PDF	
9	05/04/19 15:28	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/02/18 16:29	OI Policy	 Load PDF	
2	26/02/18 16:29	OI Driving License Status	 Load JPG	<input checked="" type="checkbox"/>
3	26/02/18 16:29	OI GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLV8314J (Insd veh)	Model:	BMW 420I 2.0 CABRIOLET
	SLH8549Y (TP veh)		SPORT (F33) (A)
Date of Accident:	23/02/2018		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$	21,818.21	
Final Repair Cost	: \$	11,310.92	
Loss of Use	: \$	800.00	8.00 days at \$100.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	12,118.37	
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	: \$	11,318.37
2)	Venkateswara S/O Purushothaman	: \$	800.00
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

05 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18003594/T1HB3Q2

Date: 05/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800005961

Claimant Vehicle No: SLH8549Y Insured Vehicle No: SLV8314J

Date of Loss: 23/02/2018 Nature of Claim: TP Claim No: 3208605815SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH8549Y**
 Make & Model: BMW 420i, 2.0 Cabriolet Sport (F33) (A) Engine No: F4771558B48B20A
 Reg. Date: 22/11/2016 (Man. Year: 2016) Chassis No: WBA4D32080G754126
 Colour: Blue Odometer: 16915 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,893.85	3,903.95	3,989.90	50.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,497.00	6,667.00	5,830.00	46.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,390.85	10,570.95	9,819.90	48.16
+ GST 7.00/7.00% (S\$)	1,427.36	739.97	687.39	48.16
Nett Amount (S\$)	21,818.21	11,310.92	10,507.29	48.16
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		12,118.37		

INSPECTION

Date of Assignment: 21/03/2018

Date Inspected: 21/03/2018 Inspected At:

Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1	*REAR WINDSCREEN SOLAR FILM	Not Necessary	531.00 FS	*- FS
3	4	*VELCRO	Not Necessary	37.00 FS	*- FS
4	1	*TRUNK LID	Bent	1,204.80 FS	*1,204.80 FS
5	1	*TAIL PANEL	Not Necessary	592.25 FS	*- FS
6	1	*RR BUMPER CARRIER ECE	Bent	432.90 FS	*432.90 FS
7	1	*REINFORCEMENT BUMPER REAR BOTTOM	Distorted	67.10 FS	*67.10 FS
8	1	*REAR BUMPER TRIM STRIP (SPORT LINE)	Cut	120.90 FS	*120.90 FS
9	1	*REAR BUMPER CENTRE GUIDE	Deformed	55.40 FS	*55.40 FS
10	1	*COVER	Deformed	61.00 FS	*61.00 FS
11	1	*RR LH RETAINING STRIP FOR TRIM STRI	Necessary	13.25 FS	*13.25 FS
12	1	*RR RH RETAINING STRIP FOR TRIM STRI	Necessary	13.25 FS	*13.25 FS
13	1	*FLAP TOWING EYE PRIMED	Not Necessary	42.20 FS	*- FS
14	1	*REAR BUMPER PANEL PRIMED (ZWEIF/LIN)	Deformed	1,133.25 FS	*1,133.25 FS
15	1	*GAP SEAL	Not Necessary	34.15 FS	*- FS
16	1	*RR BUMPER LH SIDE GUIDE	Not Necessary	48.10 FS	*- FS
17	1	*RR BUMPER RH SIDE GUIDE	Not Necessary	48.10 FS	*- FS
18	1	*LETTERING 420I	Necessary	62.55 FS	*62.55 FS
19	1	*GROMMET (2 PCS)	Necessary (1 PCS ONLY)	1.50 FS	*0.75 FS
20	1	*BADGE (BMW)	Necessary	69.50 FS	*69.50 FS
21	12	*BUMP STOP	Not Necessary	39.00 FS	*- FS
22	1	*RR ROOF GAP FINISHER	Not Necessary	77.90 FS	*- FS
23	1	*SEAL REAR WINDOW LH	Necessary	40.10 FS	*40.10 FS
24	1	*SEAL REAR WINDOW RH	Necessary	40.10 FS	*40.10 FS
25	1	*TRUNK LID GASKET	Not Necessary	124.00 FS	*- FS
26	1	*RR BUMPER LH REFLECTOR	Not Necessary	35.20 FS	*- FS
27	1	*RR BUMPER RH REFLECTOR	Not Necessary	35.20 FS	*- FS
28	1	*REAR LIGHT RH IN THE SIDE PANEL PAN	Not Necessary	419.85 FS	*- FS
29	1	*REAR LIGHT IN TRUNK LID RH	Cut	293.90 FS	*293.90 FS
30	4	*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.20 FS	*20.20 FS
31	4	*PDC SENSOR IMPERIAL BLUE (A89)	Not Necessary	1,475.20 FS	*- FS
32	1	*(DG) CLEANER R1 (100ML)	Not Necessary	23.85 FS	*- FS
33	2	*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*- FS
34	1	*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
35	4	*(S/L) SEAM SEAL 300ML	Not Necessary	135.20 FS	*- FS
36	1	*REAR PDC HOLDER SET (PDC & PMA)	Necessary	62.95 FS	*62.95 FS
37	10	*PLUG BLACK D=5MM	Necessary	9.00 FS	*9.00 FS
38	1	*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 7,893.85 3,903.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER ,TAIL PANEL.BOOTLID AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT	New	5,100.00	2,550.00
2	PAINTING REAR BUMPER ,BOOTLID ,TAIL PANEL ,TRUNK FLOOR	New	5,120.00	2,537.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	451.00
6	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
7	TO REPLACE REAR WINDSCREEN GLASS	New	649.00	649.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	0.00
Gross Labour Cost (S\$)			12,497.00	6,667.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >