

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

26 FEB 2018

Estimate No. : b1 46033
Date Estimated : 24/02/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Venkateswara S/O Purushothaman
49 Brockhampton Drive**- ACCOUNT - 40000**
Cash Sales - Service
Singapore

Singapore 559097

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH8549Y	G754126	22/11/2016	420iA GC	0

DESCRIPTIONTo replace rear bumper, tail panel, bootlid and attachment
include knocking cause by the accidentRepair - 2550
Repl - 3400
5,100.00

Painting rear bumper, bootlid, tail panel, trunk floor

2537 5,120.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

To transfer lock mechanism from old to new door including
conduct checks on new door power window system for proper
function. (1 door).

451 531.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

To replace rear windscreen glass

551 649.00

To supply and install rear windscreen solar film.

451 531.00

To carry out body cavity preservation.
(For cut panel).

451? 531.00

Sundries.

? 150.00

Total Labour 1: 13,178.00

DESCRIPTIONVelcro
TRUNK LID
TAIL PANEL
RR BUMPER CARRIER ECE
REINFORCEMENT BUMPER REAR BOTTOM

QTY	PRIC	VALUE
4	9.25	37.00
1	1,204.80	1,204.80
1	592.25	592.25
1	432.90	432.90
1	67.10	67.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46033
Date Estimated : 24/02/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH8549Y	G754126	22/11/2016	420iA GC	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER TRIM STRIP (SPORT LINE)	1	120.90	120.90
REAR BUMPER CENTRE GUIDE	1	55.40	55.40
COVER	1	61.00	61.00
RR LH RETAINING STRIP FOR TRIM STRI	1	13.25	13.25
RR RH RETAINING STRIP FOR TRIM STRI	1	13.25	13.25
FLAP TOWING EYE PRIMED	1	42.20	42.20
REAR BUMPER PANEL PRIMED (ZWEIF/LIN	1	1,133.25	1,133.25
GAP SEAL	1	34.15	34.15
RR BUMPER LH SIDE GUIDE	1	48.10	48.10
RR BUMPER RH SIDE GUIDE	1	48.10	48.10
LETTERING 420I	1	62.55	62.55
GROMMET	2	0.75	1.50
BADGE (BMW)	1	69.50	69.50
BUMP STOP	12	3.25	39.00
RR ROOF GAP FINISHER	1	77.90	77.90
SEAL REAR WINDOW LH	1	40.10	40.10
SEAL REAR WINDOW RH	1	40.10	40.10
TRUNK LID GASKET	1	124.00	124.00
RR BUMPER LH REFLECTOR	1	35.20	35.20
RR BUMPER RH REFLECTOR	1	35.20	35.20
REAR LIGHT RH IN THE SIDE PANEL PAN	1	419.85	419.85
REAR LIGHT IN TRUNK LID RH	1	293.90	293.90
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
PDC SENSOR IMPERIAL BLUE (A89)	4	368.80	1,475.20
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
(S/L) SEAM SEAL 300ML	4	33.80	135.20

Total Parts : 7,087.85

Claims OD / Survey / Uninsured losses / Direct Settlement
Regn No. 21/3/18 Claim No.
Date & Time 21/3/18
Surveyor's Name Taufik Sign
Surveyor's Tel 97495749

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorised Date
RESURVEY
Surveyor's Email Taufik@lkk.com
No. of Working Days 6-8 days

• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Labour 1 : 13,178.00
Parts : 7,087.85
Labour 2 : 0.00
Acknowledged by Repairs : 0.00
Signature: Total GST @ 7% : 1,418.61
Date:

Grand Total : 21,684.46

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **