

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBF1677K180213

Estimate

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Address: Motor Claims Department

78 Shenton Way #07-16

AIG Building Singapore 079120

Date: 23-02-18

Vehicle No: GBF1677K

Model/Make: Fiat Doblo Cargo

Max 1.6 MTJ 6MT Glaze

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper	\$ 745.00	✓
2	Rear Bumper Clips 1 set	\$ 65.00	✓
3	Rear Fender 1/2	\$ 2,350.00	SN
4	Rear Wheel Hub Cap 1/2	\$ 225.00	SN 1205.~
5	Rear Oil Tank Cover	\$ 159.00	✓
6	Rear "Corporate" Advertisement Sticker	\$ 500.00	SN 4805.~
Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc		\$ 600.00	400
To putty & spray painting & including touch up paint on accident affected areas		\$ 700.00	540

Total Parts & Labour of estimate for damaged vehicle

\$ 5,344.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

not Approved
date

2/5 \$1800/2

4 dy.

26/2/18

Take photo After repair

P-748
2225-4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: