

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0243/2018/GW
Date : 26-Feb-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Sia Chee Poh
Address : Blk 267B Compassive Link
#15-55
Singapore 542267
Telephone : HP +65 81807500
Type of Claim : Third Party Claims
Policy No. : 2100500841-01
Vehicle No : **SLL 1307 D**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Feb-17
Engine No : CHZ 158654
Chassis No : WAUZZZ8V4H1028226
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Feb-18
Place of Accident : Cross Junc Of Lorong Ah Soo Blk 114

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLL 1307 D.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓	
2	To remove trunk fittings, dismantle and renew rear bumper, repair rear lid, renew damaged fittings. Reinstall all parts.	\$ 1,200.00 500	
3	To respray paint on rear bumper, rear lid.	\$ 1,500.00 1,100	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>3,172.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 1307 D.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>reborn d</i>	\$ 1,697.00	✓
2	REAR BUMPER SPOILER <i>ph m</i>	\$ 206.00	✓
3	REAR BUMPER SIDE REINFORCEMENT <i>?</i>	\$ 501.00	?
4	LED TAIL LIGHT-RH <i>ph m</i>	\$ 730.00	✓
5	AUDI EMBLEM <i>?</i>	\$ 108.00	✓
6	INSCRIPTION " A3 " <i>ph m</i>	\$ 83.00	✓
7	INSCRIPTION " TFSI " <i>?</i>	\$ 83.00	✓
8	SUNDRIES <i>?</i>	\$ 280.00	?
TOTAL SPARE PARTS CHARGES		\$ 3,688.00	
TOTAL LABOUR CHARGES		\$ 3,172.00	
GRAND TOTAL		\$ 6,860.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant