

FASTECH AUTO PTE LTD

1 Kaki Bukiy Ave 6 #01-48 Autobay
Singapore 417883

Tel No:67452063/67467158 Fax No:67458520

Tex Reg No: 20-0006262-D

SJM4547B

Not Attached
2/5 = 4250
4 Day.
26/2/18

| QTY | PARTICULAR | | AMOUNT |
|------|--------------------------------------|--------------------------|-------------------|
| 1PCS | BONNET | 22/Bent | \$1,102.00 ✓ |
| 1PCS | BONNET INNER RUBBER BEADING | neu | \$42.00 ✓ |
| 2PCS | BONNET HINGES @89.50 | 11 | \$179.00 X |
| 1PCS | BONNET INNER LOCK | YWI | \$83.60 ✓ |
| 1PCS | FRONT GRILLE | CNE | \$385.00 ✓ |
| 1PCS | FRONT BUMPER | 22/DE | \$480.60 ✓ |
| 1PCS | FRONT BUMPER CENTRE LOWER GRILLE | YWI | \$105.20 ✓ |
| 1PCS | FRONT BUMPER REINFORCEMENT | 22 | \$341.50 ✓ |
| 2PCS | FRONT BUMPER SIDE RETAINERS @36.50 | Bent | \$73.00 ✓ |
| 1SET | FRONT BUMPER CLIPS | neu | \$50.00 ✓ |
| 2PCS | HEADLAMPS @650.00 | 625.00 x 2 = 1250.00 CNE | \$1,300.00 ✓ |
| 1PCS | FRONT SUPPORT PANEL | 1 | \$958.00 X |
| 1PCS | FRONT BUMPER SPONGE | YWI | \$145.80 ✓ |
| 1PCS | AIRCON CONDENSER | Bent | \$950.00 ✓ |
| 1PCS | RADIATOR ASSY | 11 | \$885.00 X |
| 1PCS | FRONT LICENSE PLATE | Bent | \$50.00 ✓ |
| | | | \$6,830.70 |
| | | | 5058.90 |
| | | | 4047.12 |
| | TO CHECK WIRING | | \$80.00 20 |
| | TO REFILL AIR CON GAS | | \$150.00 100 |
| | TO SPRAY RUST PROOFING | | \$100.00 30 |
| | LABOUR FOR PANEL BEATING & REPLACING | | \$880.00 520 |
| | TO PUTTY AND SPRAY PAINTING | | \$1,080.00 600 |
| | TOTAL | | \$9,120.70 |

20%
↓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: