

ASS. REC. BY:

REF: CS/FCI18003619/Ttd3n2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time: 26/2/18 @ 11.46am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

EU10104

Insured:

SHC 3746B

at Workshop m/s

Weamer Automotive

Tel:

97704368

of

249 Alexandra Rd

Policy No:

Claim No:

D18001576MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 05/02/18

27/2/18 @ After 10.30am

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

3:31pm 26/2/18

Person Contacted:

Mandy

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	EU10104-x	
	SHC 3746B-CS/FCI17014616/Klgbe2	D.O.A: 26/7/17
	Part by Part #A732-J1	(Red: 2933.29 :30%)

Signature: *Angela*

REF: FCI

ASSIGNMENT

From: _____ Date: 27/02/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: EU 1010U

at Workshop m/s Wearnes

of 45 Long Kee Rd

Insured

Policy No.

Claims No.

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Mandy
10.30 am
owner waiting



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: EU1010U Yr Regn: 2016 Sep.

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Jaguar F-Pace cc 1999

Colour: Grey A/C Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SAD7AZAN9HA054391

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 253/60R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: _____ D.O.I: 27/2/18

Survey held at: Wearnes Long Kee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 19 JUN 2018

Date/Time: File Pass to?

19/6 Typist ☐: Preli. Report ☒: Final Report

Date/Time: File Return to?

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation

_____ S + RS _____

Phone

Other

TOTAL

Add Fee: ☐ Site Insp / \$

☐ Interview / \$

☐ Tech. Insp / \$

☐ Weekend / \$

Report Format: TP

Lump Sum / I.B. / \$ 9732.71

3152.45

1704.45

50

50

25

340



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003619/T1td3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-02-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3746B	Veh. Inspected	EU 1010U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001576MFSH	Excess (\$)	0.00	
Assign From	CWS (KAREN TAN)	Assign Date	26/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/02/2018	Inspection Date		
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	22-02-2018	Our Ref No. D18001576MFSH
Accident Date	05-02-2018	Claim Type. Third Party
Insured Vehicle	SHC3746B	Third Party Vehicle. EU1010U
Survey Location	BODY AND PAINT DEPT 249 ALEXANDRA ROAD	
Contact Person.	MANDY NEO	
Contact No.	62647137/ 97704368	Fax No. 0
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235270)



PRI Documents



Close X

PRI Header Details

Claim No	D18001576MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & WEARNES
Workshop Name	WEARNES AUTOMOTIVE PTE LTD (Contact Person : MANDY NEO)	Survey Location & Contact Details	BODY AND PAINT DEPT 249 ALEXANDRA ROAD Mobile: 97704368 , Phone: 62647137 , Fax: 0 EmailId: MANDY.NEO@WEARNES.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3746B	TP Vehicle No	EU1010U
PRI Recieved Date	22-02-2018 09:53:05 PM	Surveyor Appointed Date	26-02-2018 11:45:33 AM	Surveyor Accept Date	26-02-2018 0

Survey Report Upload

Surveyor Inspection Date *		Surveyor Report Date	27-02-2018	Upload Survey Report *:	Choose File
----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Identification Card

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S0570531B



Name
ONG LIM WAN
@ONG TECK MENG
王 德 明

Race
CHINESE

Date of birth
24-06-1949

Sex
M

Country/Place of birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S0570531B

Name
ONG LIM WAN

Birth Date: 24 Jun 1949


Issue Date: 08 Jul 2003



000637515K



Identification Card



5669918



WRIC No. S0570531B



Date of Issue
09-11-2016

Address
331 RIVER VALLEY ROAD
#13-01
SINGAPORE 238363

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)


	PASS DATE
Class 2B Motorcycle $\leq$ 200 CC	12 Sep 1976
Class 2A Motorcycle between 201 CC and 400 CC	12 Sep 1976
Class 2 Motorcycle $>$ 400 CC	12 Sep 1976
Class 3 Motor cars $\leq$ 3000 kg with $\leq$ 7 passengers, exclusive of the driver, and motor tractor-vehicles $\leq$ 2500 kg	22 Sep 1977

S0570531B

S / No. 90001971

7P 422A

Licence No. S0570531B



SERVICE ESTIMATE

86973 - C00001 SL: SERVICE SALES - PC

Ong Lim Wan
331 River Valley Road
#13-01

Singapore 238363

Closed by : Mandy Neo
Svc Consultant :
Remarks : Ong Lim Wan

GST Reg.No: M28920628X
Inv.No. : B&P 0 Page 1
Inv.date : 22/02/2018
WIP No. : 46607
Veh.In/Out:
*Tel.No. : Mobile: 98552233
Reg.No. : EU1010U
Reg.date : 26/09/2016
Mileage : 0
Chassis No: SADCA2AN9HA054391

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
						2400/-	
802	TO REPLACE LH FRONT DOOR, LH REAR DOOR, WINDMIRROR COVER LH FRT	0	3600.00	0	3,600.00	S	
						2200/-	
800	TO PUTTY, SPRAY FRONT LH FRONT DOOR, LH REAR DOOR	0	3300.00	0	3,300.00	S	
802	TO TRANSFER DOOR LH FRONT	0	500.00	0 X2	500.00	S	1000/-
280	TO CHECK WIRING INCLUDING RESETTING ELECTRICAL MOUDLE	0	486.00	0	486.00	S	✓
	MOULDING LH FR	1.0 EA	275.30	247.77	275.30	S	cut
	MOULDING LH Rear	1.0 EA	233.60	210.24	233.60	S	cut
	CLIP	20.0 EA	1.90		X 38.00	S	new
	DEFLECTOR SCREW XF	10.0 EA	2.60	23.40	26.00	S	new
	PANEL-DOOR LH FR	1.0 EA	1575.60	1418.04	1,575.60	S	bb
	PANEL-DOOR LH REAR	1.0 EA	1581.30	1423.17	1,581.30	S	bb
	SEAL-DOOR LH FR	1.0 EA	157.30	141.57	157.30	S	new
	SEAL-DOOR LH REAR	1.0 EA	174.80	157.32	174.80	S	new
	HINGE-DOOR LH UPPER	2.0 EA	111.20		222.40	S	X new

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X

Tanjik 97495749
wp
27/2/18 @ 1045
5 days
* Resurvey before paint.
sure lkkauto.com

SERVICE ESTIMATE

86973 - C00001 SL: SERVICE SALES - PC

Ong Lim Wan

331 River Valley Road
#13-01

Singapore 238363

Closed by : Mandy Neo

Svc Consultant :

Remarks : Ong Lim Wan

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 22/02/2018

WIP No. . : 46607

Veh.In/Out:

*Tel.No. . : Mobile: 98552233

Reg.No. . : EU1010U

Reg.date. : 26/09/2016

Mileage . : 0

Chassis No: SADCA2AN9HA054391

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	HINGE-DOOR LH LOWER	2.0 EA	111.20			222.40	S X nn
	CHECKARM FRONT	1.0 EA	83.90			83.90	S X nn
	CHECKARM REAR	1.0 EA	87.20			87.20	S X nn
	NUT AND WASHER	8.0 EA	3.50	25%		28.00	S X nn
	BOLT	4.0 EA	2.50			10.00	S X nn
	BOLT-FLANGE	12.0 EA	3.20			38.40	S X nn
	DOOR HINGE BOLT XF	8.0 EA	3.20			25.60	S X nn

Labour Total	7,886.00
Parts Total	4,779.80
Package Total	0.00

13165.80

Gross Total.	12,665.80
Net.....	12,665.80
GST @ 7.0%	886.61
Total.....	13,552.40
Paid.....	0.00
Please Pay..	13,552.40

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - F00003
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

SL: FIRST CAPITAL INSURANCE LTD

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1
 Inv.date. : 09/05/2018
 WIP No. : 52379
 Veh.In/Out: 02/04/2018 06/04/2018
 *Tel.No. :
 Reg.No. : EU1010U
 Reg.date : 26/09/2016
 Mileage : 44,802
 Chassis No: SADCA2AN9HA054391

Closed by : Mandy Neo
 Svc Consultant :
 Remarks : Ong Lim Wan

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE LH FRONT DOOR	0	2400.00	0		2,400.00	S ✓
	LH REAR DOOR , WINDMIRROR COVER						
	LH SIDE						
800	TO PUTTY , SPRAY FRONT	0	2200.00	0		2,200.00	S ✓
	LH FRONT DOOR , LH REAR DOOR						
802	TO TRANSFER DOOR ASSY LH FRT,	0	1000.00	0		1,000.00	S ✓
	LH REAR						
280	TO CHECK WIRING INCLUDING	0	486.00	0		486.00	S ✓
	RESETTING ELECTRICAL MODULE						
	MOULDING 1	1.0 EA	275.30	10		247.77	S
	MOULDING 2	1.0 EA	233.60	10		210.24	S
	PANEL-DOOR 5	1.0 EA	1575.60	10		1,418.04	S
	PANEL-DOOR 6	1.0 EA	1581.30	10		1,423.17	S
	SEAL-DOOR 7	1.0 EA	157.30	10		141.57	S
	SEAL-DOOR 8	1.0 EA	174.80	10		157.32	S
	NUT AND WASHER 13	8.0 EA	3.50	10		25.20	S
	DEFLECTOR SCREW XF 4	10.0 EA	2.60	10		23.40	S

Gross Total. 9,732.71

Labour Total 6,086.00
 Parts Total 3,646.71
 Package Total 0.00

Net..... 9,732.71
 GST @ 7.0% 681.29
 Total..... 10,414.00
 Paid..... 0.00
 Please Pay.. 10,414.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003619/T1td3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-06-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3746B	Veh. Inspected	EU 1010U
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001576MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	26/02/2018

2. Vehicle Particulars & Condition

Make & Model	JAGUAR F-PACE	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	SADCA2AN9HA054391	Colour	GREY
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/60 R18	CONTINENTAL	6 mm
L/H Front Tyre	255/60 R18	CONTINENTAL	6 mm
R/H Rear Tyre	255/60 R18	CONTINENTAL	6 mm
L/H Rear Tyre	255/60 R18	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/02/2018	Inspection Date	27/02/2018
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EU 1010U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	MOULDING LH FR (SN)	CUT	275.30	247.77
1	MOULDING LH REAR (SN)	CUT	233.60	210.24
20	CLIP (SN)	NOT NECESSARY	38.00	-
10	DEFLECTOR SCREW XF (SN)	NECESSARY	26.00	23.40
1	PANEL-DOOR LH FR (SN)	BENT	1,575.60	1,418.04
1	PANEL-DOOR LH REAR (SN)	BENT	1,581.30	1,423.17
1	SEAL-DOOR LH FR (SN)	NECESSARY	157.30	141.57
1	SEAL-DOOR LH REAR (SN)	NECESSARY	174.80	157.32
2	HINGE-DOOR LH UPPER (SN)	NOT NECESSARY	222.40	-
2	HINGE-DOOR LH LOWER (SN)	NOT NECESSARY	222.40	-
1	CHECK ARM FRONT (SN)	NOT NECESSARY	83.90	-
1	CHECK ARM REAR (SN)	NOT NECESSARY	87.20	-
8	NUT AND WASHER (SN)	NECESSARY	28.00	25.20
4	BOLT (SN)	NOT NECESSARY	10.00	-
12	BOLT-FLANGE (SN)	NOT NECESSARY	38.40	-
8	DOOR HINGE BOLT XF (SN)	NOT NECESSARY	25.60	-
			4,779.80	3,646.71
LABOUR				
TO REPLACE LH FRONT DOOR,LH REAR DOOR,WINDMIRROR COVER LH FRONT.			3,600.00	2,400.00
TO PUTTY,SPRAY FRONT LH FRONT DOOR,LH REAR DOOR.			3,300.00	2,200.00
TO TRANSFER DOOR LH FRONT.			1,000.00	1,000.00
TO CHECK WIRING INCLUDING RESETTING ELECTRICAL MODULE.			486.00	486.00
-			-	-
-			-	-
-			-	-
			8,386.00	6,086.00
GRAND TOTAL			13,165.80	9,732.71



RECOMMENDED COST OF REPAIRS			9,732.71
-----------------------------	--	--	----------

Report Ref No. CS/FC118003619/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.