

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Feb-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6199 K

1 pc	Front n/s wheel cover	X	\$	116.00
1 pc	Front n/s fender inner shield	X	\$	120.00
1 pc	n/s head lamp	X	\$	1,028.00
1 pc	Front bumper	/	\$	531.00
1 pc	Front bumper lip	X	\$	52.00
1 pc	Front bumper n/s side retainer	X	\$	16.00
1 pc	Front bumper n/s protector	X	\$	51.00
1 pc	Front bumper emblem	/	\$	44.00
1 pc	Front bumper n/s fog lamp cover	X	\$	66.00
1 pc	N/s wing mirror assy	/	\$	590.00
			\$	2,614.00
			Less 10%	\$ 261.40
			\$	2,352.60

S/NETT

1 set	Front bumper clips	/	\$	48.00
1 set	Front n/s fender inner shield clips	X	\$	28.00

Sundry		\$	50.00 20
To check wiring on headlamp		\$	60.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten repair, reshape and adjust same, etc.		\$	600.00 300
To putty and spray painting on front bumper, front n/s fender, n/s wing mirror cover		\$	550.00 40
To apply rustproofing on the repaired and replaced panels.		\$	120.00 20
			\$ 3,808.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey, before later spray painting
- The damaged parts during resurvey
- Third party claim on "Without Prejudice" basis
- No liability is allowed
- Supplier must be resurveyed and
- is subject to approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka Loh 16/04
27/2/18 1030 hrs.
3 Pgs.
4/3
After Repair ph