

ASS. REC. BY:

REF:

CS/CT18003621/Tlt b n2

Special Instruction:

Surveyor:

Mirmen

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

23022018 4:03pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJG 281A

Insured:

at Workshop m/s

Wearnes Automotive

Tel:

9129 4556

of

45 Leng Kee Road

Policy No:

DMPCSN 3011171700

Claim No:

SNM180 00990C01

Sum Insured:

Excess:

\$ 1000.00

Make of Veh:

D.O.A.

20022018

(Client's Record)

CA / REV / REP. / REV 24 HRS W

27.02.2018 @ 1:30pm

H.O.D. Endorsement:

Date/Time:

26022018 4:29pm

Person Contacted:

Michelle

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJG 281A - x

08/2

Revert via mirmen

1/3/2018

@11:29am authorise repair by Susan Teo

1/3/2018

@3:21pm email to Michelle Chng. excess \$1000

Part by part \$6546.97 (Red: 6342.93; 49%)

Date/Time

Days

Val. Yes or No

Limit Sum

Surveyed at

Wearnes

CA / REV

REP. / 24 HRS

Des of Damages Frt Rear OS NS UC Roof

Date

Person Contacted

Vehicle IN/OUT

Frt n/s

The UC Chassis frame Body Structure affected due to accident

Date/Time

Action/Instruction

RECEIVED 31 MAY 2018

Date/Time Referred



Prelim. Report

Final Report

Days Of Repair

5

Resurvey No. of Trk

1

Date/Time Referred

Date/Time

Resurvey

Add Fee

Sub Fee

Resurvey No. of Trk

OD

6546.97