

ASS. RFC. BY:

REF:

(S/MSG18003623/Kyb n2)

Special Instruction:

Surveyor:

Kannan

ASSIGNMENT (Office)

Maurice

From (Person):

Monica Chung

of

MSU

Date/Time:

23/02/2018 4:59pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKJ 1973C

Insured:

9JV 7258T

at Workshop m/s

Estaeem Performance

Tel:

6484 1221

of

81k 5033 AMK Ind Park 2 # 01-259

Policy No:

71395498 QMX

Claim No:

5504 06

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/02/2018

CA / REV / REP. / REV 24 HRS 'WPI'

H.O.D. Endorsement:

Date/Time:

26/02/2018 2:39pm

Person Contacted:

Carmen

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SKJ 1973C x

9JV 7258T x

22/2/18 @ 4.30pm revised to Monica Chung via Maurice.

C1 Rpt & Fod confirmed by email (Ref 87603.15, 79%.)

ASS. REC. BY:

REF:

MSG/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKJ 1973C Yr Regn: 02, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota A181 c.c. 1598

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 145680 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR053REE104154880

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 16/2/18

Survey held at

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 26/2/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/2 19h pass to Coroner

RECEIVED 01 JUN 2018

Date/Time, File Pass to?

19/6 19h 15m

Date/Time, File Return to?

☐ : Prel. Report☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Photos

Others

TOTAL

200

10

310

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

MER-TP

700

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003623/Kqb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 26-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJV 7258T	Veh. Inspected	SKJ 1973C
Policy No.	71595998QMX	Coverage (\$)	0.00
Claim No.	550406	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	23/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/02/2018	Inspection Date	26/02/2018
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 27 Feb 2018

Preliminary Advice

Insured Vehicle No	: SJV7258T	Accident Date	: 16/02/2018
TP Vehicle No	: SKJ1973C	Assignment Date	: 23/02/2018
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 2.00
Date of Inspection	: 26/02/2018		
Inspection At	: ESTEEM PERFORMANCE PTE LTD (HQ) BLK 5033 ANG MO KIO IND PARK 2, #01-259 SINGAPORE 569536		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,303.15
Revised Amount	:S\$	853.88
Check Items (Estimated)	:S\$	316.03
Total	:S\$	1,169.91
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Feb 2018		23 Feb 2018 16:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHONG WEI EN NICHOLAS, ID: S8613189G		
Main Claimant:	GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D		
Vehicle Reg. No.:	SKJ1973C	Date of Loss:	16/02/2018 00:00 - :59
Claim Type:	TP / 550406	Policy/Cover Note No.:	71595998QMX (Comprehensive) Coverage: 08/02/2018 - 07/02/2019
Vehicle Reg. No. (Insured):	SJV7258T	Policy No. (Claimant):	
		Excess:	
Repairer:	Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/02/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0651D
Vehicle Details	
Vehicle No.:	SKJ1973C
Vehicle to be Exported:	No
Intended De-registration Date:	27 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 A
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	1ZRX248196
Chassis No.:	MR053REE104154880
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$15,511.00
Original Registration Date:	28 Feb 2013
First Registration Date:	28 Feb 2013
Transfer Count:	0
Actual ARF Paid:	\$15,511.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2023
PARF Rebate Amount:	\$11,633.00
Intended COE Rebate Details	
COE Expiry Date:	27 Feb 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$68,000.00
COE Rebate Amount:	\$34,000.00
Total Rebate Amount:	\$45,633.00

The information contained herein is correct as at 27 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2018 18:50
Date Of Accident	16/02/2018 14:35
Exact Location Of Accident	BRADDELL FLYOVER TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKJ1973C
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66039399

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD18V00034/VPZ/R03
Cover Note Number	

Driver

Name of Driver	LEONG ZHI YONG , JEROME
NRIC No	S9331532D
Date Of Birth	10/08/1993
Occupation	OUTDOOR
Date Of Driving Pass	04/09/2012
Driving Experience	5 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97772759
Fax Number	
Contact Number	
Email Address	LEONG.JEROME@YAHOO.COM.SG

Address	3 SIN MING WALK #05-25
Postcode	575575
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER AS ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV7258T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NICHOLAS CHONG WEI EN
NRIC/Passport Number	S8613189G
Contact Number	93391902
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

* 
Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan *



Describe Circumstance of the Accident *


please refer to attached.

Declaration

We declare the foregoing particulars are true in every respect.


 
Policyholder's Signature / Date / Time

*


Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre Personnel

INCIDENT REPORT FOR DUTY POST

Location of Duty Post	Type of Business (Bank/KINs/Embassy/ Residence/Factory)	Date of Incident	Time of Incident	Weather Condition				
VICTOR VICTOR (VV)	KIN'S I VIP	16/02/18	1435	FINE				
Person(s) Involved	Particulars of Witness(es)							
SGT 93750 JEROME								
Details of Incident (Who, What, Where, When, Why, How and Other Essential Details)								
<p>On 16/2/18 at about 1435 hrs, I SGT 93750 was on duty at VV section 2 using white Toyota Ray plate no. SKJ 1973C. The car's set which I had been issued with was low on battery. As it was the only means of contacting Seccom, I decided to go back to PHD to get the charger. While driving along Bradball Road towards PIE, the traffic was slow moving. The vehicle in front of me slowed down and I followed however, the vehicle behind me bearing ray plate no. SJV 7258 T could not stop in time and crash into the rear of the vehicle I was using.</p> <p>Below is the detail of the person involved.</p> <p>Name: NICHOLAS CHONG WEI EN</p> <p>IC: 98613189G Contact: 9339 1902-</p>								
Reported by: (Rank/Svc No/Name)	Signature	Date	Time					
SGT 93750 JEROME		16/2/18	1753					

9777 2759



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SKJ 1973 C

*Not Authorized
6/1/18
Resurvey After Rain*

Parts	(a) Cost / List Price Items	\$	2,044.20
	Plus/Less 25%	\$	511.05
	Total of Cost / List	\$	1,533.15
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	1,733.15
Labour		\$	1,570.00
Total		\$	3,303.15

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Date: 26/12/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SKJ 1973 C Submit By : Carmen Lim
Make & Model : TOYOTA ALTIS Year Manufacture : 2012
Chassis No : MR053REE104154880 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sn</i>	2	\$200.00	S.N	<input checked="" type="checkbox"/>
2	Rear bumper <i>Back up</i>	1	\$498.50		<input checked="" type="checkbox"/>
3	Rear bumper clip <i>me</i>	10	\$40.00		<input checked="" type="checkbox"/>
4	Rear bumper side retainer LH <i>Sn</i>	1	\$55.30		<input checked="" type="checkbox"/>
5	Rear bumper side retainer RH <i>Sn</i>	1	\$55.30		<input checked="" type="checkbox"/>
6	Rear bumper bracket LH <i>R</i>	1	\$97.30		<input checked="" type="checkbox"/>
7	Rear bumper bracket RH <i>R</i>	1	\$97.30		<input checked="" type="checkbox"/>
8	Rear bumper sponge]	1	\$154.70	<i>Sn</i>	<input checked="" type="checkbox"/>
9	Rear bumper reinforcement]	1			
10	Tail end panel <i>R</i>	1	\$590.40		<input checked="" type="checkbox"/>
11	Tail end panel garnish <i>Sn</i>	1	\$242.70		<input checked="" type="checkbox"/>
12	Tail end panel garnish clip <i>rr</i>	8	\$28.00		<input checked="" type="checkbox"/>
13	Boot weatherstrip <i>Sn</i>	1	\$184.70		<input checked="" type="checkbox"/>
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003623/KQBN2

Date: 01/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	71595998QMX
Claimant Vehicle No :	SKJ1973C	Insured Vehicle No :	SJV7258T
Date of Loss:	16/02/2018	Nature of Claim:	TP
		Claim No:	550406

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ1973C	Engine No:	1ZR248196
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REE104154880
Reg. Date:	28/02/2013 (Man. Year: 2012)	Odometer:	145680 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,733.15	403.87	1,329.28	76.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,570.00	450.00	1,120.00	71.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,303.15	853.87	2,449.28	74.15
Approved Total (Overridden) (\$\$)		700.00		
(\$\$)	3,303.15	700.00	2,603.15	78.81
+ GST 7.00/7.00% (\$\$)	231.22	49.00	182.22	78.81
Nett Amount (\$\$)	3,534.37	749.00	2,785.37	78.81

INSPECTION

Date of Assignment: 23/02/2018
Date Inspected: 26/02/2018 Inspected At:

Esteem Performance Pte Ltd (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-259
Singapore 569536

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ1973C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Cracked	498.50 FL	*498.50 FL
2	10		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
3	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	55.30 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	55.30 FL	*- FL
5	1		*REAR BUMPER BRACKET LH	Repair	97.30 FL	*- FL
6	1		*REAR BUMPER BRACKET RH	Repair	97.30 FL	*- FL
7	1		*REAR BUMPER SPONGE }	Serviceable	154.70 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT }	Serviceable	0.00 FL	*- FL
9	1		*TAIL END PANEL	Repair	590.40 FL	*- FL
10	1		*TAIL END PANEL GARNISH	Serviceable	242.70 FL	*- FL
11	8		*TAIL END PANEL GARNISH CLIP	Not Necessary	28.00 FL	*- FL
12	1		*BOOT WEATHERSTRIP	Serviceable	184.70 FL	*- FL
13	2		*REVERSE SENSOR	Serviceable	200.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	2,244.20	538.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	511.05	134.63
Total Parts (\$\$)	1,733.15	403.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER,END PANEL)	New	600.00	200.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER,END PANEL)	New	600.00	200.00
3	TO CHECK WIRING	New	50.00	-
4	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
5	TO TUFF COAT	New	50.00	-
6	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	-
Gross Labour Cost (\$\$)			1,570.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >