

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 27 Feb 2018

**Preliminary Advice**

Insured Vehicle No	: SJR8422A	Accident Date	: 04/01/2018
TP Vehicle No	: SKG3215K	Assignment Date	: 26/02/2018
Make	: PORSCHE BOXSTER	Est. Duration of Repair	: 4.00
Date of Inspection	: 26/02/2018		
Inspection At	: STUTTGART AUTO PTE LTD (HQ) 12 SUNGEI KADUT AVE SINGAPORE 729648		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,990.36
Revised Amount	:S\$	5,050.96
Check Items (Estimated)	:S\$	1,045.98
Total	:S\$	6,096.94
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.