

* 26/02/18 - CHOOSE LKK FOR THIS CASE.
 * Appointment for survey on Feb 28, 2018 @ 11 AM-



TRANS EUROKARS PTE LTD
 NO:5 UBI CLOSE, SINGAPORE 408605
 ESTIMATE COST OF REPAIRS

EUROKARS GROUP

BOA - 18/02/18 VS SHN 7144Y

INDIA INTERNATIONAL INSURANCE P/L		NAME : Mr Choo Quee Yong		WIP : 63302	
64 CECIL STREET		ADDRESS : Block 150 Petir Road		EXCESS :	
#04-#05 IOB BUILDING		12-160		DATE: 21-Feb-18	
SINGAPORE 049711		Singapore 670150			
ATTN. : MOTOR CLAIMS		TEL : 98183156			
FAX :					
VEH NO :	SLA3411E	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6CW1071G0123376	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	26-Feb-16	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	REAR BUMPER	1	MC513-50-221EBB	915.40
2	RETAINER(LHS), REAR BUMPER	1	MC513-50-2J1C	45.30
3	RETAINER(RHS), REAR BUMPER	1	MC513-50-2H1B	45.30
4	BRACKET(LHS), REAR BUMPER	1	MC513-51-077A	5.40
5	BRACKET(RHS), REAR BUMPER	1	MC513-51-067A	5.40
6	GUARD(LHS), REFLECTOR	1	MC513-50-371	20.50
7	REFLECTOR LHS	1	MD350-51-5L0E	50.40
8	GUARD(RHS), REFLECTOR	1	MC513-50-361	20.50
9	REFLECTOR RHS	1	MD350-51-5M0E	50.40
10	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	6.00
11	RIVET, REAR BUMPER	4	MBN8F-50-355	21.60
12	GROMMET, REAR BUMPER	1	M9991-00-501	2.80
13	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	10.00
14	GROMMET, REAR BUMPER	2	MC235-50-ES1	8.80
15	REAR REINFORCEMENT	1	MC235-56-B9XC	148.00
16	PANEL, REAR END	1	MCG15-70-750B	491.10
17	TAILGATE	1	MCGY3-62-02XF	1,559.00
18	VALVE ONEWAY, TAILGATE	2	MGHP9-58-867	22.80
19	WEATHERSTRIP, TAILGATE	1	MC513-62-761C	169.00
20	TAPE PROTECTOR, TAILGATE	2	MBR5S-56-994	14.40
21	TAPE PROTECTOR, TAILGATE	2	MG043-62-864A	6.60
22	TRIM LOWER, TAILGATE	1	MC513-68-960B	411.40
23	LOCK, TAILGATE	1	MC513-62-310A	244.00
24	GARNISH, TAILGATE	1	MC513-50-810F53	426.50
25	SEAL, GARNISH	4	MGJ6A-50-818	10.00
26	CLIP, GARNISH	3	MEG21-51-SJ3	16.20
27	MAZDA, EMBLEM	1	MCGY0-51-711	43.10
28	S, EMBLEM	1	MCGY0-51-721	34.50
29	SKYACTIV, EMBLEM	1	MC597-51-771	76.10
30	MOULD, REAR WINDSCREEN	1	MC513-50-611	57.60

31	FASTENER, REAR WINDSCREEN	2	MD204-50-896A	der	\$ 5.20
32	SPACER, REAR WINDSCREEN	1	MDJ01-50-897	der	\$ 6.80
33	FASTENER, REAR WINDSCREEN	2	MC273-50-896	der	\$ 15.60
34	SPACER, REAR WINDSCREEN	4	MGJ6A-50-897	der	\$ 48.40
35	PIN STUD, REAR WINDSCREEN	1	MG21E-63-938B	der	\$ 10.50
36	PROTECTOR, REAR SPOILER	2	MC514-51-979B	der	\$ 10.40
37	PROTECTOR, REAR SPOILER	2	MC514-51-982B	der	\$ 22.80
38	PROTECTOR, REAR SPOILER	2	MC514-51-972B	der	\$ 26.80
39	CLIP, REAR SPOILER	3	MC514-51-958A	der	\$ 21.90
40	CLIP, REAR SPOILER	1	MC525-51-958A	der	\$ 8.20
41	GASKET(LHS), TAILGATE LAMP	1	MC513-51-3J8	der	\$ 90.80
42	GASKET(RHS), TAILGATE LAMP	1	MC513-51-3H8	der	\$ 90.80
43	TRIM, BOOT END	1	MC513-68-89XD	der	\$ 76.50
44	BEZEL, LOCK	1	MC513-68-894A		\$ 13.00
TOTAL PARTS					\$ 5,385.80
LESS 10%					\$ 538.58
TOTAL PARTS COST					\$ 4,847.22

Labour Description

1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1320	\$ 3,960.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.	1260	\$ 3,780.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	150	\$ 350.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	330	\$ 660.00
6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS.	✓ NETT	\$ 560.00
7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	der ✓ NETT	\$ 120.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	200	\$ 660.00
9	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	200	\$ 660.00
10	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	NETT	\$ 70.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00

12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
13	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00
			me 30	
TOTAL LABOUR			\$ -	\$ 11,770.00
TOTAL PARTS			\$ -	\$ 4,847.22
TOTAL			\$ -	\$ 16,617.22
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ -	
GST 7%			\$ -	\$ -
GRAND TOTAL			\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorized Signature

Not Authorized
 when photo taken party
 27/8/18
 Tany.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: