

ASS. REC. BY:

REF:

CS/MSH18003643 / Gtb 9v

Special Instruction:

Survivor

QA

ASSIGNMENT (Office)

From Person:

Pearllyn Kong

of

MSH

Date/Time:

26/02/2018 10:18am

Estimated Cost:

Bill to:

OIL / TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No:

SJX 977L

Insured:

at Workshop m/s

Premium

Tel:

of

55 Ubi Rd 1

Policy No:

MSD / VPCP / 17-000625-00

Claim No:

Sum Insured:

Excess:

\$ 750.00

Make of Veh:

D.O.A.

23/02/2018

(Client's Record)

CA / ~~REV~~

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJX 977L - CS / MSH 17021185 / 111123
	QOT: 02-11-17
	Sent preli thru merimen
1/3/18	Authorise repair & inform repairer to proceed & exes
6/3/18	Supplementary received; sent preli thru merimen
7/3/18	Supplementary approve



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18003643/Grb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 26-02-2018	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SJX 977L
Policy No.	MSD/VPCP/17-000625-00	Coverage (\$)	0.00
Claim No.		Excess (\$)	750.00
Assign From	MERIMEN (PEARLLYN KANG)	Assign Date	26/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/02/2018	Inspection Date	26/02/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Est Auth'd	Status
Main	23 Feb 2018		26 Feb 2018 10:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD., Co. Reg. No.: 199400399N								
Vehicle Reg. No.:	SJX977L	Date of Loss:	23/02/2018 00:00 - :59						
Claim Type:	OD	Policy/Cover Note No.:	MSD/VPCP/17-000625-00 (Comprehensive) Coverage: 28/03/2017 - 27/03/2018						
		Excess:	S\$750.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/02/2018]								
OD Investigation	Yes								
Driver/Custodian:	LIM CHOON KIAT CALVIN (39 / Male), NRIC: S7829770J, Tel: +6597522278								
Adj. Asg. Remarks:	Car in. Please survey and revert. Thank you.								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearllyn Kang Yen Lin

Date: 28 Feb 2018

Preliminary Advice

Vehicle No	: SJX977L	Accident Date	: 23/02/2018
Make	: AUDI A8 L	Policy No.	: MSD/VPCP/17-000625-00
Assignment Date	: 26/02/2018	Excess	: S\$750.00
Date of Inspection	: 26/02/2018	Est. Duration of Repair	: 7.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	45,114.00
Revised Amount	:S\$	27,336.00
Check Items (Estimated)	:S\$	7,187.00
Total	:S\$	34,523.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	340,000.00
COE / PARF Rebate	:S\$	117,119.00
Salvage Value	:S\$	
Margin for Repair	:S\$	222,881.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Print Received Message

This mail is associated with :

***SJX977L (MSC/V/18-000288)**

OD

Feb 23 2018 12:00AM

[HITACHI CAPITAL ASIA PACIFIC PTE. LTD.]

Premium Automobiles Pte Ltd

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 01/03/2018 10:53 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$27336.00) - SJX977L - Claim Handler: Pearllyn Kang Yen Lin

Approved:27336.00:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Thursday, March 01, 2018 11:19 AM
To: 'claims@premiumauto.com.sg'
Cc: SUR
Subject: SJX 977L OD MSIG DOA: 23.02.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJX 977L (excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearllyn Kang Yen Lin

Date: 06 Mar 2018

Preliminary Advice

Vehicle No	: SJX977L	Accident Date	: 23/02/2018
Make	: AUDI A8 L	Policy No.	: MSD/VPCP/17-000625-00
Assignment Date	: 26/02/2018	Excess	: S\$750.00
Date of Inspection	: 26/02/2018	Est. Duration of Repair	: 7.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	45,763.00	(Include Supplementary \$649.00)
Revised Amount	:S\$	27,985.00	
Check Items (Estimated)	:S\$	7,187.00	
Total	:S\$	35,172.00	
Lump Sum Repair	:S\$		46338

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	340,000.00
COE / PARF Rebate	:S\$	117,119.00
Salvage Value	:S\$	
Margin for Repair	:S\$	222,881.00

53 : 575

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 18 Jul 2018

Preliminary Advice

Vehicle No	: SJX977L	Accident Date	: 23/02/2018
Make	: AUDI A8 L	Policy No.	: MSD/VPCP/17-000625-00
Assignment Date	: 26/02/2018	Excess	: S\$750.00
Date of Inspection	: 26/02/2018	Est. Duration of Repair	: 7.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,338.00	(Include supplementary \$575)
Revised Amount	:S\$	33,628.50	(include supplementary + check item)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	33,628.50	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	340,000.00
COE / PARF Rebate	:S\$	117,119.00
Salvage Value	:S\$	
Margin for Repair	:S\$	222,881.00

Remarks

(x) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Print Received Message

This mail is associated with :

***SJX977L (MSC/V/18-000288)**

OD

Feb 23 2018 12:00AM

[HITACHI CAPITAL ASIA PACIFIC PTE. LTD.]

Premium Automobiles Pte Ltd

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 03/09/2018 16:00 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$33628.50) - SJX977L - Claim Handler: Eliza Ho Teng Boon

Approved:33628.50.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/02/2018 12:26
Date Of Accident	23/02/2018 00:55
Exact Location Of Accident	JUNCTION OF PUNGGOL ROAD AND PUNGGOL FIELD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX977L
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE. LTD.
Co Reg No	199400399N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67341222

Vehicle Particulars

Manufacturer	AUDI
Model	A8L D4 3.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MSD/VPCP/17-000625-00
Cover Note Number	

Driver

Name of Driver	LIM CHOON KIAT CALVIN
NRIC No	S7829770J
Date Of Birth	10/10/1978
Occupation	INDOOR
Date Of Driving Pass	29/03/1997
Driving Experience	20 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97522278
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 614 ANG MO KIO AVE 4 #07-1007
Postcode	560614
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : YEO LIK KHAI GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

THE ACCIDENT HAPPENED ON JUNCTION OF PUNGGOL FIELD AND PUNGGOL RD. IT WAS GREEN LIGHT THEN I WAS MAKING A TURN TO PUNGGOL RD AND VEHICLE B COLLIDED TO MY VEHICLE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJG9784G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Low Pooi Yee
NRIC/TIN No.: G724201517



The accident happen on Junction of Punggal field and Punggal Rd. It was green light then I making a turn to Punggal Rd and vehicle B collided to my vehicle.

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & time:

MM-



Name: Faraz
NIC/FIN No: 02041026

Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7829770J**

Name: **LIM CHOON KIAT**
(LIN JUNJIE)

Find Search results

Birth Date: 10 Oct 1978
Issue Date: 30 Jun 2003

0005116448



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7829770J**



Name

LIM CHOON KIAT CALVIN

林俊杰

Race

CHINESE

Date of birth

10-10-1978

Sex

M

Country of birth

SINGAPORE

S7829770J

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 2B Motorcycles not exceeding 200 cc	21 Aug 1995
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	29 Mar 1997

NP 428A

Licence No: S7829770J



4321734



NRIC No: S7829770J



Date of issue
15-12-2008

APT BLK 614 ANG MO KIO AVENUE 4 #07-1007
SINGAPORE 560614

NRIC No: S7829770J Date: 11/07/2011 No: 6675646

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd. (Co Reg No 200412212G)
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
 www.msig.com.sg

CERTIFICATE OF INSURANCE

Motor Vehicles (Third Party Risks And Compensation) Act (Chapter 189)
 Motor Vehicles (Third Party Risks And Compensation) Rules, 1960
 Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)

16/03/2017

Excess : \$750/-SECT I

Others Excess : Refer to your policy schedule

A0215-001

CERTIFICATE No.

MSD/VPCP/17-000625-00

1. Index Mark and Registration

Number of Vehicle

SJX977L

2. Name of Policy holder

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.

3. Effective date of the Commencement of Insurance for the purposes of the Act

28/03/2017

4. Date of Expiry of Insurance

27/03/2018

5. Persons of classes of Persons entitled to drive*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicles or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And Provided further that the Motor Vehicle is registered and licensed under the Road Traffic Act and its registration and licensing under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to Use*

1. Use for the carriage of passengers or goods in connection with the policyholder's business.

2. Use for social, domestic & pleasure purposes and business purposes of any person to whom the vehicle is hired.

The Policy does not cover:-

1. Use for racing, pace-making, reliability trial or speed-testing.

2. Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

3. Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks & Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

AUTHORIZED SIGNATURE

IMPORTANT NOTICE

This Certificate is not transferable to a new owner of the vehicle.

If for any reason the Insurance is terminated during its currency, the Certificate must be returned to the Insurer, or if the Certificate has been lost or destroyed a Statutory Declaration to that Effect has to be made. Failure to comply with this obligation is an

offence under the compulsory Insurance Legislation. This Certificate must be returned if the insurance is suspended during its currency.

If you are involved in an accident, full details must be forwarded immediately to the Company.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0399N
Vehicle Details	
Vehicle No.:	SJX977L
Vehicle to be Exported:	No
Intended De-registration Date:	27 Feb 2018
Vehicle Make:	AUDI
Vehicle Model:	A8L 3.0 TFSI QU (PI)
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	CRE004002
Chassis No.:	WAUZZZ4H0EN015204
Maximum Power Output:	228.0 kW (305 bhp)
Open Market Value:	\$74,467.00
Original Registration Date:	28 Mar 2016
First Registration Date:	28 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$106,041.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Mar 2026
PARF Rebate Amount:	\$79,530.00
Intended COE Rebate Details	
COE Expiry Date:	27 Mar 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,502.00
COE Rebate Amount:	\$37,589.00
Total Rebate Amount:	\$117,119.00

The information contained herein is correct as at 27 Feb 2018

OK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0233/2018/GW
Date	:	24-Feb-18

Vehicle IN workshop. Kindly arrange for survey.

YOUR INSURED VEH NO : SJX 977 L

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way

#23-01 SGX Centre 2

Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 27692 - Fax: 6225 7402

Owner's Name	:	Hitachi Capital Asia Pacific Pte.Ltd.
Address	:	Blk 614 Ang Mo Kio Ave 4 #07-1007 Singapore 560614
Telephone	:	HP +65 97522278
Type of Claim	:	Own Damge Claims
Policy No.	:	MSD/VPCP/17-000625-00
Vehicle No	:	SJX 977 L
Model Code	:	Audi A8L D4 3.0 TFSI Qu
Model / Year	:	Mar-16
Engine No	:	CRE 004002
Chassis No	:	WAUZZZ4H0EN015204
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Allan Wu
Accident Date	:	23-Feb-18
Place of Accident	:	JUNC Of Punggol Road and Punggol Field

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJX 977 L.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	/ 480
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans control unit. To carry out vacuum/ regas and to pressurise cooling system. Renew lhs additional cooler.	S/N \$ 1,600.00	/ 1600
3	To dismantle front bumper, lhs front fender, headlight and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Reorganise front crash management components. Reinstall all parts removed. (800)	\$ 6,000.00	2000 + 2000 5200 / 4800
4	To respray front bumper, lhs front fender and bonnet. 800 800	\$ 2,700.00	2500 2500
5	To renew lhs front rim and tyre. Carry out wheel alignment. 900	S/N \$ 280.00	240 280
6	To carry out diagnostic check.	S/N \$ 192.00	/ 192
TOTAL LABOUR CHARGES		: \$ 11,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJX 977 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER / Re	\$ 2,902.00	2902.00
2	FRONT BUMPER FIXING PARTS / MC	\$ 422.00	422.00
3	FRONT BUMPER GRILLE / X	\$ 616.00	} X
4	FRONT BUMPER CLOSING ELEMENT / A	\$ 225.00	
5	FRONT BUMPER SPOILER / X	\$ 258.00	
6	FRONT WHEEL SPOILER LEFT OUTER / X	\$ 38.00	
7	FRONT WHEEL SPOILER LEFT INNER / X	\$ 31.00	} X
8	FRONT BUMPER GRILLE-LH / Cut	\$ 454.00	
9	FRONT BUMPER SENSOR / DM	TBC	
10	FRONT FENDER-LH / bnc	\$ 1,613.00	1613.00
11	FRONT FENDER ATTACHMENT PARTS / X	\$ 246.00	X
12	FRONT FENDER BRACKET-LH /	2 \$ 47.00	46.20
13	FRONT FENDER BRACE-LH / X	\$ 212.00	212.00
14	FRONT FENDER MOUNTING BRACKET-LH /	\$ 744.00	744.00
15	RETAINING BRACKET /	\$ 15.00	14.70
16	FRONT PLASTIC WHEEL HOUSING LINER-LH / TV	\$ 265.00	264.5
17	FRONT WHEEL HOUSING LINER-LH X NN	\$ 198.00	X
18	WHEEL HOUSING LINER ATTACHMENT PARTS / MC	\$ 169.00	169.00
19	LED HEADLIGHT-LH / OA	\$ 11,536.00	11,536.00
20	HEADLIGHT POWER MODULE X NN	\$ 1,657.00	X
SUB -TOTAL SPARE PARTS		\$ 21,648.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJX 977 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	HEADLIGHT POWER MODULE FOR DIPPED BEAM	\$ 486.00	
22	HEADLIGHT POWER MODULE FOR DAY DRIVING LIGHT	\$ 486.00	
23	HEADLIGHT BRACKET	2 \$ 50.00	
24	HEADLIGHT RETAINING PLATE	\$ 19.00	
25	HEADLIGHT LIFT CYLINDER-LH	TBC	204.00
26	BONNET	\$ 5,814.00	
27	BONNET SEAL	\$ 50.00	
28	NOTICE STICKER	\$ 17.00	
29	AIR CONDITIONER STICKER	\$ 17.00	
30	AIR DUCT	\$ 35.00	
31	AIR GUIDE	\$ 22.00	21.70
32	ADDITIONAL COOLER FOR COLANT-LH	\$ 720.00	719.50
33	ADDITIONAL COOLANT RADIATOR BRACKET-LH	\$ 137.00	
34	COOLANT PUMP	\$ 1,050.00	
35	DECOUPLING ELEMENT	\$ 16.00	
36	ADDITIONAL COOLANT PUMP BRACKET	\$ 66.00	
37	COLANT CONCENTRATE	4 \$ 133.00	132.50
38	FRONT ALUMINIUM RIM-LH	\$ 824.00	824.00
39	COOLANT RADIATOR LOCK CARRIER WITH MOUNTING	\$ 972.00	972
40	MICHELIN PILOT SUPER SPORT 255/45/19-LH	S/N TBC	X
SUB-TOTAL SPARE PARTS		\$ 10,914.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJX 977 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	FRONT BUMPER TOP COVER X {NN	\$ 208.00	207.50
42	CAUTION "SIGN" X	\$ 12.00	X
43	SUNDRIES 2 / ACC.	\$ 800.00	219.80
TOTAL SPARE PARTS		:	\$ 33,582.00
TOTAL LABOUR CHARGES		:	\$ 11,252.00
GRAND TOTAL		:	\$ 44,834.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Guo Qiang - 82880282

7 Days.

before paint photos.

Excess \$750

Not Authorized.

26/2/18.

[Signature]
13/18.

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

MSIG Insurance (Singapore) Pte Ltd
No 4 Shenton Way
#23-01 SGX Centre 2
Singapore 068896

Attn: Motor Claims Dept
Tel: 6827 2762 - Fax: 6225 7402

Estimate No.	PA/OD/0233/2018/GW
Date	27-Feb-18
Service Advisor	Tony
Pages	1
Regn No	SJX 977 L
Model No	Audi A8L D4 3.0 TFSI Qu

Quantity	Description	Unit Price	Amount
<u>LABORS</u> 1	Towing vehicle from accident scenes (S/N) /	\$280	280
TOTAL		\$280	

For Premium Automobiles Pte Ltd

Tony Foong

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 2

GST Reg No. 19-9902271-W

MSIG Insurance (Singapore) Pte Ltd
No 4 Shenton Way
#23-01 SGX Centre 2
Singapore 068896

Attn: Motor Claims Dept
Tel: 6827 2762 - Fax: 6225 7402

Estimate No.	PA/OD/0233/2018/GW
Date	5-Mar-17
Service Advisor	Jeffery Tan
Pages	1
Regn No	SJX 977 L
Model No	Audi A8L D4 3.0 TFSI Qu

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Additional Air cooler guide - LHS / CRA	\$ 21.00	20.50
2	Front bumper side guide - LHS /	\$ 45.00	44.50
3	Aircond Pipe / HT	\$ 483.00	482.50
4	Headlight bracket - LHS / BT	\$ 100.00	99.20
TOTAL		\$649.00	

To remove and renew air cond pipes \$280

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 5841 1183

Supplementary Estimate 3

GST Reg No. 19-9902271-W

MSIG Insurance (Singapore) Pte Ltd
No 4 Shenton Way
#23-01 SGX Centre 2
Singapore 068896

Attn: Motor Claims Dept
Tel: 6827 2762 - Fax: 6225 7402

Estimate No. PA/OD/0233/2018/GW
Date 5-Mar-17
Service Advisor Jeffery Tan
Pages 1
Regn No SJX 977 L
Model No Audi A8L D4 3.0 TFSI Qu

Quantity	Description	Unit Price	Amount
labour			
<u>Parts</u>			
1	Coolant	\$ 295.00	\$ 295.00
2			
3			
4			
5			
MATERIALS		\$ 295.00	\$ 295.00
LABOUR		\$ -	\$ -
TOTAL		\$ 295.00	\$ 295.00

/ MEC.

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 2

GST Reg No. 19-9902271-W

MSIG Insurance (Singapore) Pte Ltd
No 4 Shenton Way
#23-01 SGX Centre 2
Singapore 068896

Attn: Motor Claims Dept
Tel: 6827 2762 - Fax: 6225 7402

Estimate No. PA/OD/0233/2018/GW
Date 05-Mar-17
Service Advisor Jeffery Tan
Pages 1
Regn No SJX 977 L
Model No Audi A8L D4 3.0 TFSI Qu

Quantity	Description	Unit Price	Amount
labour			
1	To remove and renew air cond pipes s/n	\$ 280.00	\$ 280.00
Parts			
1	Additional Air cooler guide - LHS	\$ 21.00	\$ 20.80
2	Front bumper side guide - LHS	\$ 45.00	\$ 44.30
3	Aircond Pipe	\$ 483.00	\$ 482.50
4	Headlight bracket - LHS	\$ 100.00	\$ 99.20
5	Coolant	\$ 295.00	\$ 295.00
MATERIALS		\$ 944.00	\$ 941.80
LABOUR		\$ 280.00	\$ 280.00
TOTAL		\$ 1,224.00	\$ 1,221.80

For Premium Automobiles Pte Ltd

Authorised Signature

Janice Lee (LKKAUTO)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Monday, March 05, 2018 6:19 PM
To: Janice Lee (LKKAUTO)
Cc: SUR; 'Claims Dept'
Subject: RE: SJX 977L OD MSIG DOA: 23.02.2018
Attachments: SAftersales18030518240.pdf

Dear Janice,

Kindly forward the supplementary list to Guo Qiang for his kind reference.

Resurvey photo was taken by Adrian earlier this morning.

We will need additional labour for the lock carrier replacement, "???" items and supplementary list.

He can contact me @ 8777 9608 for further clarification.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Janice Lee (LKKAUTO) [mailto:JaniceLee@lkkauto.com]
Sent: Thursday, 1 March, 2018 11:19 AM
To: claims@premiumauto.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: SJX 977L OD MSIG DOA: 23.02.2018

Dear Sir,

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0233/2018/GW
Date : 24-Feb-18

Vehicle IN workshop. Kindly arrange for survey.

YOUR INSURED VEH NO : SJX 977 L

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way

#23-01 SGX Centre 2

Singapore 068896

Hi Guo Qiang

You recommended 7 days

We took 15 days exclude 3 Sundays

19 Apr 18

Attn: Motor Claims Dept

Tel: 6827 27692 - Fax: 6225 7402

Owner's Name : Hitachi Capital Asia Pacific Pte.Ltd.
Address : Blk 614 Ang Mo Kio Ave 4
#07-1007
Singapore 560614
Telephone : HP +65 97522278
Type of Claim : Own Damage Claims
Policy No. : MSD/VPCP/17-000625-00
Vehicle No : **SJX 977 L**
Model Code : Audi A8L D4 3.0 TFSI Qu
Model / Year : Mar-16
Engine No : CRE 004002
Chassis No : WAUZZZ4H0EN015204
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 23-Feb-18
Place of Accident : JUNC Of Punggol Road and Punggol Field

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJX 977 L.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans control unit. To carry out vacuum/ regas and to pressurise cooling system. Renew lhs additional cooler.	S/N \$ 1,600.00	\$ 1,600.00
3	To dismantle front bumper, lhs front fender, headlight and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed.	\$ 6,000.00	\$ 5,200.00
4	To respray front bumper, lhs front fender and bonnet.	\$ 2,700.00	\$ 2,500.00
5	To renew lhs front rim and tyre. Carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
5a	Added labour charges - see attached dtd 27/2/18	S/N \$ 280.00	\$ 280.00
5b	Added labour charges - see attached dtd 5/3/18	S/N \$ 280.00	\$ 280.00
7	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 11,812.00	\$ 10,812.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJX 977 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,902.00	\$ 2,902.00
2	FRONT BUMPER FIXING PARTS	\$ 422.00	\$ 422.00
3	FRONT BUMPER GRILLE	\$ 616.00	
4	FRONT BUMPER CLOSING ELEMENT	\$ 225.00	
5	FRONT BUMPER SPOILER	\$ 258.00	
6	FRONT WHEEL SPOILER LEFT OUTER	\$ 38.00	
7	FRONT WHEEL SPOILER LEFT INNER	\$ 31.00	
8	FRONT BUMPER GRILLE-LH	\$ 454.00	\$ 454.00
9	FRONT BUMPER SENSOR	TBC	\$ 196.00
10	FRONT FENDER-LH	\$ 1,613.00	\$ 1,613.00
11	FRONT FENDER ATTACHMENT PARTS	\$ 246.00	
12	FRONT FENDER BRACKET-LH	2 \$ 47.00	\$ 46.20
13	FRONT FENDER BRACE-LH	\$ 212.00	\$ 212.00
14	FRONT FENDER MOUNTING BRACKET-LH	\$ 744.00	\$ 744.00
15	RETAINING BRACKET	\$ 15.00	\$ 14.70
16	FRONT PLASTIC WHEEL HOUSING LINER-LH	\$ 265.00	\$ 264.50
17	FRONT WHEEL HOUSING LINER-LH	\$ 198.00	
18	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 169.00	\$ 169.00
19	LED HEADLIGHT-LH	\$ 11,536.00	\$ 11,536.00
20	HEADLIGHT POWER MODULE	\$ 1,657.00	
SUB -TOTAL SPARE PARTS		\$ 21,648.00	\$ 18,573.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJX 977 L.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	18,573.40
21	HEADLIGHT POWER MODULE FOR DIPPED BEAM		\$ 486.00	
22	HEADLIGHT POWER MODULE FOR DAY DRIVING LIGHT		\$ 486.00	
23	HEADLIGHT BRACKET	2	\$ 50.00	
24	HEADLIGHT RETAINING PLATE		\$ 19.00	
25	HEADLIGHT LIFT CYLINDER-LH		\$ 204.00	\$ 204.00
26	BONNET		\$ 5,814.00	
27	BONNET SEAL		\$ 50.00	
28	NOTICE STICKER		\$ 17.00	
29	AIR CONDITIONER STICKER		\$ 17.00	
30	AIR DUCT		\$ 35.00	
31	AIR GUIDE		\$ 22.00	\$ 21.70
32	ADDITIONAL COOLER FOR COLANT-LH		\$ 720.00	\$ 719.50
33	ADDITIONAL COOLANT RADIATOR BRACKET-LH		\$ 137.00	
34	COOLANT PUMP		\$ 1,050.00	
35	DECOUPLING ELEMENT		\$ 16.00	
36	ADDITIONAL COOLANT PUMP BRACKET		\$ 66.00	
37	COLANT CONCENTRATE	4	\$ 133.00	\$ 132.80
38	FRONT ALUMINIUM RIM-LH		\$ 824.00	\$ 824.00
39	COOLANT RADIATOR LOCK CARRIER WITH MOUNTING		\$ 972.00	\$ 972.00
40	MICHELIN PILOT SUPER SPORT 255/45/19-LH	S/N	TBC	
SUB-TOTAL SPARE PARTS		:	\$ 11,118.00	\$ 21,447.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJX 977 L.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 21,447.40
41	FRONT BUMPER TOP COVER		\$ 208.00	\$ 207.50
42	CAUTION "SIGN"		\$ 12.00	
44	<i>Added parts - see attached</i>		\$ 944.00	\$ 941.80
45	SUNDRIES		\$ 800.00	\$ 219.80
TOTAL SPARE PARTS		:	\$ 34,730.00	\$ 22,816.50
TOTAL LABOUR CHARGES		:	\$ 11,812.00	\$ 10,812.00
GRAND TOTAL		:	\$ 46,542.00	\$ 33,628.50

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

MSIG Insurance (Singapore) Pte Ltd
No 4 Shenton Way
#23-01 SGX Centre 2
Singapore 068896

Attn: Motor Claims Dept
Tel: 6827 2762 - Fax: 6225 7402

Estimate No.	PA/OD/0233/2018/GW
Date	27-Feb-18
Service Advisor	Tony
Pages	1
Regn No	SJX 977 L
Model No	Audi A8L D4 3.0 TFSI Qu

Quantity	Description	Unit Price	Amount
<u>LABORS</u>			
1	Towing vehicle from accident scenes (S/N)	\$280	\$ 280.00
	TOTAL	\$280	\$ 280.00

For Premium Automobiles Pte Ltd

Authorised Signature

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Thursday, April 19, 2018 4:17 PM
To: Guo Qiang (LKKAUTO); Janice Lee (LKKAUTO); SUR; Carrine Leong; Nora Khai
Subject: FINAL REVISION - SJX977L - OD MSIF - SURVEYED 26 FEB 18
Attachments: PA02332018 - SJX 977 L - A8L D4 3.0 TFSI Mu FRONT+LHS (MSIG) + SUPP.xls

Hi Guo Qiang and all,

Revised estimate is attached.

Please confirm repair cost of \$33,628.50 @ 15 days of repairs exclude 3 Sundays.

your early closure is well appreciated.

Best regards - jb

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Feb 2018		26 Feb 2018 10:18 Edit Adj Rpt	\$533,628.50 Edit Estimates	\$533,628.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD., Co. Reg. No.: 199400399N								
Vehicle Reg. No.:	SJX977L	Date of Loss:	23/02/2018 00:00 - :59 [22 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / MSC/V/18-000288	Policy/Cover Note No.:	MSD/VPCP/17-000625-00 (Comprehensive) Coverage: 28/03/2017 - 27/03/2018						
		Excess:	S\$750.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 28/03/2018]								
OD Investigation	Yes								
Driver/Custodian:	LIM CHOON KIAT CALVIN (39 / Male), NRIC: S7829770J, Tel: +6597522278								
Adj Asg. Remarks:	Car in. Please survey and revert. Thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (03/09/2018): Alert - Adj Mandate Approved (\$533628.50) - SJX977L - Claim Handler: Eliza Ho Te... - MSIG_SG (06/03/2018): Alert - Adj Mandate Approved (\$27985.00) - SJX977L - Claim Handler: Pearlyn Ka... - MSIG_SG (01/03/2018): Alert - Adj Mandate Approved (\$27336.00) - SJX977L - Claim Handler: Pearlyn Ka...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJX977L (MSC/V/18-000288)

OD

Feb 23 2018 12:00AM

[HITACHI CAPITAL ASIA PACIFIC PTE. LTD.]

Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/02/18 13:00	Accident Statement	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/02/18 09:07	Adjuster Immediate Advice	 Load HTM	
2	06/03/18 11:25	Adjuster Immediate Advice	 Load HTM	
3	28/08/18 15:47	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/02/18 09:14	General View	 Load JPG	☒
2	28/02/18 09:14	General View	 Load JPG	☒
3	28/02/18 09:14	General View	 Load JPG	☒
4	28/02/18 09:14	General View	 Load JPG	☒
5	28/02/18 09:14	General View	 Load JPG	☒
6	28/02/18 09:14	General View	 Load JPG	☒
7	28/02/18 09:14	General View	 Load JPG	☒
8	28/02/18 09:14	General View	 Load JPG	☒
9	28/02/18 09:14	General View	 Load JPG	☒
10	28/02/18 09:14	General View	 Load JPG	☒
11	28/02/18 09:14	General View	 Load JPG	☒
12	28/02/18 09:14	General View	 Load JPG	☒
13	28/02/18 09:14	General View	 Load JPG	☒
14	28/02/18 09:14	General View	 Load JPG	☒
15	28/02/18 09:14	General View	 Load JPG	☒
16	28/02/18 09:14	General View	 Load JPG	☒
17	28/02/18 09:14	General View	 Load JPG	☒
18	28/02/18 09:14	General View	 Load JPG	☒
19	28/02/18 09:14	General View	 Load JPG	☒
20	28/02/18 09:14	General View	 Load JPG	☒
21	28/02/18 09:14	General View	 Load JPG	☒
22	28/02/18 09:14	General View	 Load JPG	☒
23	28/02/18 09:14	General View	 Load JPG	☒
24	28/02/18 09:14	General View	 Load JPG	☒
25	28/02/18 09:14	General View	 Load JPG	☒
26	28/02/18 09:14	General View	 Load JPG	☒
27	28/02/18 09:14	General View	 Load JPG	☒
28	28/02/18 09:14	General View	 Load JPG	☒
29	28/02/18 09:14	General View	 Load JPG	☒
30	28/02/18 09:14	General View	 Load JPG	☒
31	28/02/18 09:14	General View	 Load JPG	☒
32	28/02/18 09:14	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
33	28/02/18 09:14	General View	 Load JPG	☒
34	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
35	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
36	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
37	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
38	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
39	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
40	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
41	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
42	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
43	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
44	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
45	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
46	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
47	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
48	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
49	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
50	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
51	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
52	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
53	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
54	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
55	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
56	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
57	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
58	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
59	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
60	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
61	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
62	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
63	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
64	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
65	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
66	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
67	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
68	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
69	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
70	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
71	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
72	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
73	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
74	06/03/18 11:29	Reinspection Photo	 Load JPG	☒
75	31/08/18 09:07	Reinspection Photo	 Load JPG	☒
76	31/08/18 09:07	Reinspection Photo	 Load JPG	☒
77	31/08/18 09:07	Reinspection Photo	 Load JPG	☒
78	31/08/18 09:07	Reinspection Photo	 Load JPG	☒
79	31/08/18 09:07	Reinspection Photo	 Load JPG	☒
80	03/09/18 15:00	Reinspection Photo	 Load JPG	☒
81	03/09/18 15:00	Reinspection Photo	 Load JPG	☒
82	03/09/18 15:00	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
83	03/09/18 15:00	Reinspection Photo	 Load JPG	☒
84	03/09/18 15:00	Reinspection Photo	 Load JPG	☒
85	03/09/18 15:00	Reinspection Photo	 Load JPG	☒
86	03/09/18 15:00	Reinspection Photo	 Load JPG	☒
87	03/09/18 15:00	Reinspection Photo	 Load JPG	☒
88	03/09/18 15:00	Reinspection Photo	 Load JPG	☒
89	03/09/18 15:00	Reinspection Photo	 Load JPG	☒
90	03/09/18 15:00	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/02/18 13:59	Enquire Transfer Fee	 Load PDF	
2	23/02/18 13:59	Enquire Rebate	 Load PDF	
3	26/02/18 10:06	Premium Estimate	 Load PDF	
4	26/02/18 10:06	Email from Premium to arrange survey - Jeffrey	 Load PDF	
5	26/02/18 10:14	TP GIA Report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/02/18 09:13	SJX 977L ESTIMATE	 Load PDF	
2	28/02/18 17:53	Certificate of Insurance	 Load PDF	
3	28/02/18 17:53	Driver's NRIC & DL	 Load PDF	
4	28/02/18 17:55	SKG 9477G ESTIMATE	 Load PDF	
5	28/02/18 17:55	Singapore Accident Statement	 Load PDF	
6	06/03/18 11:28	SJX 977L SUPPLEMENTARY	 Load PDF	
7	28/08/18 15:51	SJX 977L FINALISE EST	 Load PDF	
8	10/09/18 09:23	SUPPLEMENTARY PART	 Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/02/18 13:00	Accident Statement	 Load HTM	
2	26/02/18 19:22	Addendum Sheet	 Load JPG	☒
3	26/02/18 19:32	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/02/18 12:56	Accident Photo	 Load JPG	☒
2	23/02/18 12:56	Accident Photo	 Load JPG	☒
3	23/02/18 12:56	Accident Photo	 Load JPG	☒
4	23/02/18 12:56	Accident Photo	 Load JPG	☒
5	23/02/18 12:56	Accident Photo	 Load JPG	☒
6	23/02/18 12:56	Accident Photo	 Load JPG	☒
7	23/02/18 12:56	Accident Photo	 Load JPG	☒
8	23/02/18 12:56	Accident Photo	 Load JPG	☒
9	23/02/18 12:56	Accident Photo	 Load JPG	☒
10	23/02/18 12:56	Accident Photo	 Load JPG	☒
11	23/02/18 12:56	Accident Photo	 Load JPG	☒
12	23/02/18 12:56	Accident Photo	 Load JPG	☒
13	23/02/18 12:56	Accident Photo	 Load JPG	☒
14	23/02/18 12:56	Accident Photo	 Load JPG	☒
15	23/02/18 12:56	Accident Photo	 Load JPG	☒
16	26/02/18 19:31	Accident Photo	 Load JPG	☒
17	26/02/18 19:31	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
18	26/02/18 19:31	Accident Photo	 Load JPG	☒
19	26/02/18 19:31	Accident Photo	 Load JPG	☒
20	26/02/18 19:31	Accident Photo	 Load JPG	☒
21	26/02/18 19:31	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/02/18 12:42	Sketch Plan	 Load JPG	☒
2	26/02/18 19:29	Accident Sketch Plan	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18003643/GRBQ2

Date: 10/09/2018

REFERENCE

Insured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE. LTD.

Policy No: MSD/VPCP/17-000625-00

Date of Loss: 23/02/2018

Nature of Claim: OD

Claim No: MSC/V/18-000288

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJX977L

Make & Model: AUDI A8 L, 3.0 TFSI QU (A)

Engine No: CRE004002

Reg. Date: 28/03/2016 (Man. Year: 2014)

Chassis No: WAUZZZ4H0EN015204

Colour: Black

Odometer: 32923 km

Engine Capacity: 2995 cc

Market Value/New Car Price: S\$340,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45Z R19

Rear Tyre Size: 255/45Z R19

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,923.80	22,816.50	12,107.30	34.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,812.00	10,812.00	1,000.00	8.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,735.80	33,628.50	13,107.30	28.05
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	45,985.80	32,878.50	13,107.30	28.50
+ GST 7.00/7.00% (S\$)	3,219.01	2,301.50	917.51	28.50
Nett Amount (S\$)	49,204.81	35,180.00	14,024.81	28.50

INSPECTION

Date of Assignment: 26/02/2018

Date Inspected: 26/02/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2018)
Parts: 143	AUDI A8 L 3.0 TFSI QU (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJX977L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,902.00 FS	*2,902.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Necessary	422.00 FS	*422.00 FS
3	1		*FRONT BUMPER GRILLE	Not Necessary	616.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	225.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	258.00 FS	*- FS
6	1		*FRONT WHEEL SPOILER LEFT OUTER	Not Necessary	38.00 FS	*- FS
7	1		*FRONT WHEEL SPOILER LEFT INNER	Not Necessary	31.00 FS	*- FS
8	1		*FRONT BUMPER GRILLE -LH	Cut	454.00 FS	*454.00 FS
9	1		*FRONT BUMPER SENSOR	Damaged	196.00 FS	*196.00 FS
10	1		*FRONT FENDER -LH	Buckled	1,613.00 FS	*1,613.00 FS
11	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	246.00 FS	*- FS
12	2		*FRONT FENDER BRACKET -LH	Necessary	47.00 FS	*46.20 FS
13	1		*FRONT FENDER BRACE -LH	Necessary	212.00 FS	*212.00 FS
14	1		*FRONT FENDER MOUNTING BRACKET -LH	Necessary	744.00 FS	*744.00 FS
15	1		*RETAINING BRACKET	Necessary	15.00 FS	*14.70 FS
16	1		*FRONT PLASTIC WHEEL HOUSING LINER -LH	Torn	265.00 FS	*264.50 FS
17	1		*FRONT WHEEL HOUSING LINER -LH	Not Necessary	198.00 FS	*- FS
18	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	169.00 FS	*169.00 FS
19	1		*LED HEADLIGHT -LH	Cracked	11,536.00 FS	*11,536.00 FS
20	1		*HEADLIGHT POWER MODULE	Not Necessary	1,657.00 FS	*- FS
21	1		*HEADLIGHT POWER MODULE FOR DIPPED BEAM	Not Necessary	486.00 FS	*- FS
22	1		*HEADLIGHT POWER MODULE FOR DAY DRIVING LIGHT	Not Necessary	486.00 FS	*- FS
23	2		*HEADLIGHT BRACKET	Not Necessary	50.00 FS	*- FS
24	1		*HEADLIGHT RETAINING PLATE	Not Necessary	19.00 FS	*- FS
25	1		*HEADLIGHT LIFT CYLINDER -LH	Damaged	204.00 FS	*204.00 FS
26	1		*BONNET	Repair	5,814.00 FS	*- FS
27	1		*BONNET SEAL	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*NOTICE STICKER	Not Necessary	17.00 FS	*- FS
29	1		*AIR CONDITIONER STICKER	Not Necessary	17.00 FS	*- FS
30	1		*AIR DUCT	Not Necessary	35.00 FS	*- FS
31	1		*AIR GUIDE	Deformed	22.00 FS	*21.70 FS
32	1		*ADDITIONAL COOLER FOR COLANT-LH	Bent	720.00 FS	*719.50 FS
33	1		*ADDITIONAL COOLANT RADIATOR BRACKET -LH	Not Necessary	137.00 FS	*- FS
34	1		*COOLANT PUMP	Not Necessary	1,050.00 FS	*- FS
35	1		*DECOUPLING ELEMENT	Not Necessary	16.00 FS	*- FS
36	1		*ADDITIONAL COOLANT PUMP BRACKET	Not Necessary	66.00 FS	*- FS
37	4		*COLANT CONCENTRATE	Necessary	133.00 FS	*132.80 FS
38	1		*FRONT ALUMINIUM RIM -LH	Cut	824.00 FS	*824.00 FS
39	1		*COOLANT RADIATOR LOCK CARRIER WITH MOUNTING	Cracked	972.00 FS	*972.00 FS
40	1		*MICHELIN PILOT SUPER SPORT 255/45/19-LH (NPA)	Not Necessary	0.00 FS	*- FS
41	1		*FRONT BUMPER TOP COVER	Not Necessary	208.00 FS	*207.50 FS
42	1		*CAUTION SIGN	Not Necessary	12.00 FS	*- FS
43	1		*SUNDRIES	Necessary	800.00 FS	*219.80 FS
44	1		*ADDITIONAL AIR COOLER GUIDE -LHS	Cracked	20.80 FS	*20.80 FS
45	1		*FRONT BUMPER SIDE GUIDE -LHS	Cracked	44.30 FS	*44.30 FS
46	1		*AIRCOND PIPE	Bent	482.50 FS	*482.50 FS
47	1		*HEADLIGHT BRACKET -LHS	Bent	99.20 FS	*99.20 FS
48	1		*COOLANT	Necessary	295.00 FS	*295.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 34,923.80 22,816.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND RENEW AIR COND PIPES	New	280.00	280.00
2	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS ,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
3	TO REMOVE AND TRANSFER AIRCON CONDENSER ,RADIATOR,ADDITIONAL RADIATOR ,ELECTRICAL FANS CONTROL UNIT.TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM .RENEW LHS ADDITIONAL COOLER	New	1,600.00	1,600.00
4	TO DISMANTLE FRONT BUMPER ,LHS FRONT FENDER,HEADLIGHT AND BONNET .RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION .RENEW DAMAGED PANELS .REORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,000.00	5,200.00
5	TO RESPRAY FRONT BUMPER ,LHS FRONT FENDER AND BONNET	New	2,700.00	2,500.00
6	TO RENEW LHS FRONT RIM AND TYRE .CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TOWING VEHICLE FRONT ACCIDENT SCENES	New	280.00	280.00
Gross Labour Cost (S\$)			11,812.00	10,812.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >