

INS. CASE OWNER:

Surveyor:

ADRIAN

DOI:

ASSIGNMENT

23/1/18

Date / Tin

23/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKA 9465Y

Name of Insured:

Yong Kar Moh

Insured Tel No.:

HP:

9412816

Excess Sec II :SS

D.O.A.:

21/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

12/18/18/1005/102421

Policy No.:

Make / Model:

Jaguar

Place of Accident:

C16

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

G86 791 A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Zero Gravity



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

2/3

G86 791 A, M/10080344/14; 22/1/18

SKA 9465Y

Bola 27.

File pass to typist type report

Email to LPU to seek mandate.

RECEIVED 20 APR 2018

RECEIVED 20 MAR 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No. : 27.

If NO or B 28, Ass. Lia :

Repair Cost:

SS

2500.00

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

400.00 (\$100 x 4 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 2907.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2907.45

Name 1:

Zero Gravity.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GBE 791 A Yr Regn: 2015 / Sept.Type: M.Car / M.Cycle / Bus / Van Lo / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Substar. C.C. 2953Colour white. A/C: Insured / Std / NI / NASp. Reading 83004 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JNISC2F2420857247.Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/70R15CR: 155R13C.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake.Front 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 23/02/18Survey held at Zero Gravity,Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
TP Lon Pac2013/18 Confirm LIS \$2500.00 with 4 working days.(Red: \$3627.74  
58.1)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

) \$ + RS. \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_

TOTAL

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18003644/Awa3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 26-02-2018		
		Code : LPC2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKA 9465Y	Veh. Inspected	GBE 791A	
Policy No.		Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020421	Excess (\$)	0.00	
Assign From		Assign Date	26/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	22/02/2018	Inspection Date	23/02/2018	
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**Nivitha (LKK Auto)**

---

**From:** ERIC WOO JUN KIAT <ericwoo@lonpac.com>  
**Sent:** Friday, 23 February 2018 4:52 PM  
**To:** Zero Gravity; assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Our Ref: 17/18/18/VP05/020421 GBE791A & SKA9465Y Accident day 22/02/2018  
**Attachments:** GBE791A PRI.PDF; GBE791A\_GIA REPORT.PDF

Dear Tiffany,

We will proceed to appoint Adrian Ling from LKK Auto Consultants Pte Ltd to survey GBE 791A.

Dear Catherine/Nivitha,

FYA.

Thank you.

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

3.10 pm @ 26/2/18  
vehicle in  
person @ stanley  
sur @ Adrian

---

**From:** Zero Gravity [mailto:zero\_gravity@singnet.com.sg]  
**Sent:** Friday, 23 February, 2018 4:48 PM  
**To:** ERIC WOO JUN KIAT  
**Subject:** RE: Our Ref: 17/18/18/VP05/020421 GBE791A & SKA9465Y Accident day 22/02/2018

Dear Eric

We would like to choose surveyor is No. 6 : Adrian Ling  
Please arrange surveyor as soon as possible

Kindly let us have your reply asap.

Thanks & Best regards

Have a good day!

Tiffany  
Zero Gravity  
Tel:67412845/67412170  
Fax:67412170

---

**From:** ERIC WOO JUN KIAT [mailto:ericwoo@lonpac.com]  
**Sent:** 23 February, 2018 3:35 PM  
**To:** Zero Gravity <zero\_gravity@singnet.com.sg>

Cc: MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

Subject: RE: Our Ref: 17/18/18/VP05/020421 GBE791A & SKA9465Y Accident day 22/02/2018

Dear Tiffany,

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

---

**From:** Zero Gravity [[mailto:zero\\_gravity@singnet.com.sg](mailto:zero_gravity@singnet.com.sg)]

**Sent:** Friday, 23 February, 2018 2:59 PM

**To:** MT\_Claim\_SG

**Subject:** GBE791A & SKA9465Y Accident day22/02/2018

Your Vehicle No.: SKA9465Y

Our Vehicle No.: GBE791A

Hi

Please check attachment of PRI & GIA Report.

Please provide the surveyor list to us

Kindly let us have your reply asap.

Thanks & Best regards

Have a good day!

Tiffany

Zero Gravity

Tel:67412845/67412170

Fax:67412170

Date / Time : .....23/02/2018. 2:35PM

BY FAX NO: .....E-mail.....

.....Lompae..... Insurance

Motor Claim Department

Dear Sirs/Madam,

PRE-REPAIR INSPECTION

YOUR INSURED VEHICLE REGISTRATION NO.....SKA9465Y.....

ACCIDENT ON.....22/02/2018.....BETWEEN.....GBE791A & SKA9465Y.....  
& .....

We are the repairers of motor vehicle registration  
no.....GBE791A.....

TAKE NOTICE that the aforesaid vehicle has an accident with your  
insured vehicle.

The aforesaid vehicle is available for pre-repair inspection at

**ZERO GRAVITY**

2 KAKI BUKIT AVE 2

#01-25 KAKI BUKIT AUTOHUB

SINGAPORE 417921.

Tel: 67412845

Yours faithfully,



Zero Gravity

**Mei Kwan (LKKAUTO)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Tuesday, 27 February, 2018 10:13 AM  
**To:** Mei Kwan (LKKAUTO)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Direct Settlement - Accident Involving SKA9465Y (OI : LPC - TBA) and GBE791A (TP : LKK REF - CC6/LPC18003644/Awa3) on 22/02/2018  
**Attachments:** 27022018100107.pdf  
**Categories:** HMK

Our Ref : 17/18/18/VP05/020421

Dear Mei Kwan,

We attached a copy of insured's GIA report for your attention.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Monday, 26 February, 2018 6:25 PM  
**To:** MT\_Claim\_SG  
**Cc:** GERALD POH WEE BIN; ERIC WOO JUN KIAT; ONG LI LI; Vivian Lau (LKKAUTO); Joy Irene (LKKAUTO); Admin A  
**Subject:** Direct Settlement - Accident Involving SKA9465Y (OI : LPC - TBA) and GBE791A (TP : LKK REF - CC6/LPC18003644/Awa3) on 22/02/2018

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle GBE 791A at M/s Zero Gravity.

Enclosed for your perusal is:  
- TP's GIA report

Please note that estimated cost of repair and preliminary advice is not ready yet.

We will revert to you on preliminary advice in due course.

Kindly assist to verify validity of our insured's policy and let us have a copy of insured's accident report for our necessary action.

Our case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.





# ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921  
 Tel: +65 67412845 Fax No: +65 67412170  
 Email: zero\_gravity@singnet.com.sg  
 Buss.Reg.No.: 5288887X

## QUOTATION

No : QT-000125

LONPAC INSURANCE BHD

100 BEACH ROAD

#19-00 SHAW TOWER

SINGAPORE 189702

Attention: Motor Claim Department

TEL : 62507388

FAX : 62532058

Your Ref. : SKA9465Y  
 Vehicle No. : GBE791A  
 Make & Model : NISSAN CABSTAR  
 Chasis No. : JN15C2F24Z0857247  
 Engine No. : ZD30346653K  
 Accident Date : 22/02/2018  
 Policy No. : 5082765978-01  
 Date : 23/02/2018  
 Page : 1 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	REAR TAIL GATE <i>dent</i>	1.0 PCS	1,588.50	1,588.50 ✓
2	REAR END PANEL (DECK) <i>Repair</i>	1.0 PCS	146.80	146.80 ✓
3	TAILGATE LEVEL	2.0 PCS	39.40	78.80 ✓
4	LOCK HINDGE (L/H) <i>new</i>	1.0 PCS	113.40	113.40 ✓
5	LOCK HINDGE (R/H) <i>new</i>	1.0 PCS	113.40	113.40 ✓
6	TAILGATE HINDGE	3.0 PCS	21.40	64.20 ✓
7	LAMP BRACKET (L/H/R) <i>Best</i>	1.0 PCS	80.00	80.00 ✓
8	BRACKET (STEP) <i>Best</i>	1.0 PCS	474.70	474.70 ✓
9	TOW HOOK <i>new</i>	1.0 PCS	156.40	156.40 ✓
10	REAR TAIL GATE RUBBER/BRACKET (L/H) <i>Best</i>	1.0 PCS	58.40	58.40 ✓
11	LAMP (NUMBER PLATE) <i>new</i>	1.0 PCS	90.20	90.20 ✓
12	REAR NUMBER PLATE BRACKET <i>Best</i>	1.0 PCS	60.40	60.40 ✓
13	LOCK REGULATOR (SPARE TYRE) <i>Damaged</i>	1.0 PCS	276.80	276.80 ✓
14	Discount 30 %			-990.60
15	SubTotal (L)			2,311.40
16	STICKER "NISSAN" <i>new</i>	1.0 PCS	120.40	120.40 ✓
17	LAMP (L/H/R) <i>cracked</i>	1.0 PCS	146.10	146.10 ✓
18	LAMP (R/H/R) <i>new</i>	1.0 PCS	146.10	146.10 ✓
19	Discount 10 %			-41.26
20	SubTotal (N)			371.34
21	REVERSE SENSOR <i>Damaged</i>	1.0 SET	280.00	280.00 ✓
22	REAR NUMBER PLATE <i>Best</i>	1.0 PCS	35.00	35.00 ✓
23	STICKER "70 km/h" <i>new</i>	1.0 PCS	10.00	10.00 ✓
24	STICKER "11 pax" <i>new</i>	1.0 PCS	10.00	10.00 ✓
25	ALUMINIUM PANEL (TAILGATE) <i>new</i>	1.0 PCS	450.00	450.00 ✓
26	RIM (SPARE) <i>new</i>	2.0 PCS	120.00	240.00 ✓

Virgin

253880  
1777.16

266.5

239.85



Attn: Adrian



# ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921  
 Tel: +65 67412845 Fax No: +65 67412170  
 Email: zero\_gravity@singnet.com.sg  
 Buss.Reg.No.: 5288887X

## QUOTATION

No : QT-000125

LONPAC INSURANCE BHD

100 BEACH ROAD

#19-00 SHAW TOWER

SINGAPORE 189702

Attention: Motor Claim Department

TEL : 62507388

FAX : 62532058

Your Ref. : SKA9465Y  
 Vehicle No. : GBE791A  
 Make & Model : NISSAN CABSTAR  
 Chassis No. : JN15C2F24Z0857247  
 Engine No. : ZD30346653K  
 Accident Date : 22/02/2018  
 Policy No. : 5082765978-01  
 Date : 23/02/2018  
 Page : 2 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
27	TYRE (TYRE) <i>not New</i>	275	2.0 PCS	150.00 300.00 X
28	SubTotal (S)			1,325.00
29	PANEL BEAT & REPAIR REAR DAMAGE	1.0 X	850.00	850.00 400
30	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0 X	750.00	750.00 350
31	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	820	1.0 X	50.00 50.00 30
32	TO PROVIDE UNDER TURFCODE	1.0 X	150.00	150.00 X
33	TO REMOVE REVERSE SENSOR	1.0 X	120.00	120.00 40
34	SubTotal (LABOUR)			1,920.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED TWENTY SEVEN AND CENTS  
 SEVENTY FOUR ONLY

total 3612.01  
 L/S: 25K.  
 04 Days.

E. &amp; O.E

Total	S\$	5,927.74
Discount	S\$	0.00
Net Total	S\$	5,927.74

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18003644/Awa3n2		
300 BEACH ROAD		Date : 24-04-2018		
#17-04/07 THE CONCOURSESINGAPORE 199555		Code : LPC2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKA 9465Y	Veh. Inspected	GBE 791A	
Policy No.		Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020421	Excess (\$)	0.00	
Assign From	ERIC	Assign Date	23/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN CABSTAR	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JN1SC2F24Z0857247	Colour	WHITE	
Odometer	83004	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/70 R15C	WEST LAKE	6 mm	
L/H Front Tyre	195/70 R15C	WEST LAKE	6 mm	
R/H Rear Tyre	155 R13C	WEST LAKE	6 mm	
L/H Rear Tyre	155 R13C	WEST LAKE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/02/2018	Inspection Date	23/02/2018	
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 791A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR TAIL GATE	DENTED	1,588.50	1,588.50
1	REAR END PANEL (DECK)	TO REPAIR SEE LABOUR	146.80	-
2	TAILGATE LEVEL @\$39.40	NOT NECESSARY	78.80	-
1	LOCK HINDGE (L/H)	NOT NECESSARY	113.40	-
1	LOCK HINDGE (R/H)	NOT NECESSARY	113.40	-
3	TAILGATE HINDGE @\$21.40	NOT NECESSARY	64.20	-
1	LAMP BRACKET (L/H/R)	BENT	80.00	80.00
1	BRACKET (STEP)	BENT	474.70	474.70
1	TOW HOOK	NOT NECESSARY	156.40	-
1	REAR TAIL GATE RUBBER /BRACKET (L/H)	BENT	58.40	58.40
1	LAMP (NUMBER PLATE)	NOT NECESSARY	90.20	-
1	REAR NUMBER PLATE BRACKET	BENT	60.40	60.40
1	LOCK REGULATOR (SPARE TYRE)	DAMAGED	276.80	276.80
	LESS 30% DISCOUNT		-990.60	-761.64
			2,311.40	1,777.16
<b>NETT ITEMS</b>				
1	STICKER 'NISSAN' (N)	NECESSARY	120.40	120.40
1	LAMP (L/H/R) (N)	CRACKED	146.10	146.10
1	LAMP (R/H/R) (N)	NOT NECESSARY	146.10	-
	LESS 10% DISCOUNT		-41.26	-26.65
			371.34	239.85
<b>SPECIAL NETT ITEMS</b>				
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	220.00
1	REAR NUMBER PLATE (SN)	BENT	35.00	35.00
1	STICKER '70KM/H' (SN)	NECESSARY	10.00	10.00
1	STICKER '11 PAX' (SN)	NECESSARY	10.00	10.00
1	ALUMINIUM PANEL (TAILGATE) (SN)	NOT NECESSARY	450.00	-
2	RIM (SPARE) @\$120.00 (SN)	NOT NECESSARY	240.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	TYRE (TYRE) @\$150.00 (SN)	NOT NECESSARY	300.00	-
			1,325.00	275.00
	<b>LABOUR</b>			
	PANEL BEAT & REPAIR REAR DAMGE INCLUSIVE OF THE REPAIR OF REAR END PANEL (DECK).		850.00	400.00
	TO PUTTY AND RE-SPRAY AFFECTED PORTION.		750.00	350.00
	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS.		50.00	30.00
	TO PROVIDE UNDER TURCODE.	NOT NECESSARY	150.00	-
	TO REMOVE REVERSE SENSOR .		120.00	40.00
			1,920.00	820.00
<b>GRAND TOTAL</b>			<b>5,927.74</b>	<b>3,112.01</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,500.00</b>

Report Ref No. CC4/LPC18003644/Awa3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.