

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: F3F9282M. Yr Regn: 2012 Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha. YZF C.C. 599

Colour: Blue A/C Insured / Std / NI / NA

Sp Reading: 843/6. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JYARJISS00000 A34.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70 R17.

R: 180/55 R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 23/02/18

Survey held at Hucc Meng.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPALG.

LIS - \$4800.1 (Red: \$ 4368.50 / 48%).

MV: 1AK.

PV: 1K

Nett: 13K

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Photos

Other

Report Format: _____

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18003647/Aua3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 26-02-2018		
Code : AIG				
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJT 7367Y	Veh. Inspected	FBF 9282M
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	26/02/2018
2. Vehicle Particulars & Condition				
	Make & Model	c.c 0		
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	21/02/2018	Inspection Date	23/02/2018
	Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

TP A16
Thin Thin.

FBF9282M

Yamaha YZF

JYARI1550000AH34.

Rees Number Plate. Best	25 (SW) ✓
Rees Signal Lamp x 02 LH cut	75 x 2 = 150 75
Rees Mudflap 2nd	65 ✓
Rees Mudflap Bracket Best	185 ✓
Tail lamp	190 X
Rees Exhaust Pipe. Best	1850 ✓
Rees Footrest x 02 LH cut Rt cancelled	68 x 2 = 136 ✓
Rees Footrest Bracket x 02	165 x 2 = 330 X
Front Number Plate	25 (SW) ✓
Front Windshield. LH	135 ✓
Headlamp Assy. Canceled.	580 ✓
Headlamp Garnish 1 x 02 LH cut	175 x 2 = 350 175
Front Wing Mirror LH. LH	115 ✓
Balances LH. LH	30 ✓
Clutch lever LH	58 ✓
Front Signal lamp LH. LH	68 ✓

FBA9282M.

Front Fork Oil ~~Ne~~
Front Fork X 0 2 ~~HT Best~~

Front Fork Under Bracket ~~Best~~

Steering Cone and Bearing. ~~HTL~~

Side Fairing LH. ~~At~~

Speedometer ~~HTL~~

Side Lower Cowling (white) ~~Del'd~~

Engine Cover ~~HT~~

Front Footrest LH. ~~Could~~

Rear Side Fairing LH. ~~At~~

Front Wheel Rim. ~~HTL~~

Front Brake Disc

Stickers ~~Ne~~

Panel Beating.

Spray Painting.

Wiring.

Towing.

To remove exhaust Pipe

20(SN) ~~880~~ 02 = 1760.880

185

75(SN)

255

980

295

215

70

285

450(SN)

68

100(SN) 60(SN)

850

350

550

280

250

30

75

150 80

Last 5667

km 10/5: 5100.30

SN: 205

labour 685

total 5990.30

1/5 4.8K

04Dmg

4.8K

Let the customer sign and date noting the Reparer of the following:

- To re-survey before any spray painting
- To display to customer with a long receipt
- Parts procedure
- Third party survey
- No illegal modifications or alterations
- Supplementary items

is subject to final approval from the company

Acknowledged by Reparer
Signature:
Date:



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680

Reg. No.: 254578/00M



Your Ref :

Our Ref :

Date: 07.08.2018

Attn: Motor Claims Dept

**ACCIDENT ON 21.02.2018 INVOLVING VEHICLE FBF 9282 M & SJT 7367 Y ALONG
FILTER LANE OF LOWER DELTA ROAD TO JALAN BUKIT MERAH**

With regards to the above, we are writing on behalf of the registered owner of vehicle FBF 9282 M which was involved in the above mentioned accident.

We are informed that the above accident was caused solely by the negligence of your insured vehicle SJT 7367 Y. As a result of the accident, our client's vehicle was damaged and our client had instructed us to submit his claims for loss and expenses, particulars of which are follows:

1) Repair cost	\$	4,800.00
2) Loss of use-\$150 X 14days	\$	2100.00
3) LTA search	\$	7.49
Total	\$	6,907.49

We hereby enclosed herewith the following documents for your consideration of the above claim.

a) Final Repair Bill Of FBF 9282 M

c) LTA SEARCH

b) GIA report

d) Owner / Driver NRIC & Driving License

華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP
AUTOBAY@KAKI BUKIT
1, KAKI BUKIT AVE 6 #01-34 SINGAPORE 417883
TEL: 6747 8064 6746 5519 FAX: 6743 4896

Yours faithfully,

HUA MENG SPRAY PAINTING WORKSHOP

Thin Thin (LKKAUTO)

From: Thin Thin (LKKAUTO)
Sent: Tuesday, 11 September 2018 2:31 PM
To: 'KIMLE88@HOTMAIL.COM'
Subject: ACCIDENT INVOLVING SJT 7367Y & FBF 9282M ON 21/02/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18003647/Aua3

11 SEPTEMBER 2018

LE MY DIEP

APT BLK 490 JURONG WEST AVE 1
#06-07
SINGAPORE 640490

Dear Sir/Madam,

ACCIDENT INVOLVING SJT 7367Y & FBF 9282M ON 21/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING

Case Handler

DID: 6841 2360

FAX: 6741 4108

Email: thinthin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT

I/We, Lee Lay Huat Addie ("the third party claimant") of
Blk 720 Ang Mo Kio Ave 6 #04-4122. S(8607) (address),
owner of PBF9282M (vehicle no.) hereby authorise **HUA MENG SPRAY PAINTING**
WORKSHOP ("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. PBF9282M that was damaged pursuant
to the accident which occurred on 21-02-18 (date) along Pitts Lane of corner
Delta Road to Jalan (location) involving vehicle no/s SJ173677 ("the accident").
Akai 1 Merah

I further authorize the workshop to settle my above mentioned claim in a manner that they deem
fit and the workshop is further authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 22 (day) of 02 (month) 2018 (year)

+ [Signature] 22/2/18 4.10pm

Signed by "the third party claimant"
(with company stamp if applicable)

李明噴漆廠
HUA MENG SPRAY PAINTING WORKSHO.
AUTOBAY/BUKIT
SINGAPORE 41788
TEL: 6721 1519 FAX: 6721 488

Signed by "the workshop"
(with company stamp)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **HUA MENG SPRAY PAINTING WORKSHOP** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$4,980.00** (Global Sum) for vehicle no. **FBF 9282M** that was damaged pursuant to the accident which occurred on **21/02/2018** (date) along **LOWER DELTA ROAD TO JALAN BUKIT MERAH** (location) involving vehicle no/s **SJT 7367Y**.

This is pursuant to the inspection conducted on **23/02/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **LEE LENG HUAT ADDIE** ("the third party claimant") of vehicle no. **FBF 9282M** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **FBF 9282M** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 15 (day) of 10 (month) 2018 (year)



Signed by appointed surveyor

李明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP
AUTOBAY@KAKI BUKIT
1000 Delta Avenue, #01-14 SINGAPORE 417881
TEL: 6746 5519 FAX: 6743 409

Signed by "the workshop" (with chop)

WITHOUT PREJUDICE
OUR CLIENT'S PERSONAL LIABILITY
CLAIM (PRESENT OR FUTURE) WHICH IS
EXPRESSLY RESERVED



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680

Reg. No.: 254678/00M



Your Ref : SJ1 7367Y

Our Ref : FBF 9282M

28/7/2018

Date:

VEHICLE NO : FBF 9282 M
MAKE / MODEL : YAMAHA R6S
NAME : LEE LENG HUAT ADDIE
ADDRESS : BLK 720 ANG MO KIO AVE 6
#04-4122
S 560720

FINAL REPAIR BILL FOR VEHICLE NO: FBF 9282 M

TO SUPPLY AND REPLACE PARTS, LABOUR CHARGES FOR
REPAIRING, KNOCKING, WELDING AND TO RESPRAY PAINTING
(LUMP SUM REPAIR)

\$ 4,800.00

SINGAPORE DOLLARS: FOUR THOUSAND AND EIGHT HUNDRED ONLY

Enquire Vehicle & Owner Information (Vehicle No. SJT7367Y As At 21 Feb 2018 / 12:20:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: MKR/LKE/7793/2018

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S7573517J
Owner Name: LE MY DIEP
Registered Address Type: HDB / HUDC
Registered Block/House No.: 490
Registered Street Name: JURONG WEST AVENUE 1
Registered Unit No.: # 06 - 07
Registered Building Name: -
Registered Postal Code: 640490

Current Vehicle Details

Vehicle No.: SJT7367Y
Make Description/Model: NISSAN / LATIO 1.5L AT ABS D/AIRBAG 2WD 4DR
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

ATTN: June
FBF 9282M



SINGAPORE
POLICE FORCE

Traffic Police
10-11A Avenue 8
Singapore 439891
Tel: 6733 9417 (ext. 3000)
Fax: 6733 9441 (ext. 3000)
www.police.gov.sg

Our Ref: TPI/P/15967/2018
Date: 17 July 2018

LEE LENG KIANG ERIC
BLK 720 ANG MO KIO AVENUE 6
#04-4122
SINGAPORE 560720

Dear Sir/Madam

**ROAD TRAFFIC ACCIDENT INVOLVING FBF9282M AND SJT7367Y ALONG JALAN BUKIT
MERAH ON 21 FEBRUARY 2018 AT ABOUT 1220 HRS**

I refer to the above accident.

Please be informed that we have completed our investigations which revealed that the driver of **SJT7367Y** had committed an offence of **Careless Driving under Rule 29 of the Road Traffic Rules**. Action has been initiated against the driver for the said offence.

Yours faithfully

HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE

This is a computer-generated letter. No signature is required.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2018 Edit Reg		23 Feb 2018 00:00 Edit Adj Rpt	S\$4,800.00 Edit Estimates	S\$4,800.00 View Rpt		Pending for Survey Report Cancel Case

















































Main	Reference	Claim Details	Documents	Show All																																								
<div style="border: 1px solid black; padding: 5px;"> CLAIM SUBFOLDER DETAILS [Created by adjuster] <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Insured:</td> <td colspan="3">Le My Diep, ID: S75735173</td> </tr> <tr> <td>Main Claimant:</td> <td colspan="3">LEE LENG HUAT ADDIE, ID: S73067041</td> </tr> <tr> <td>Vehicle Reg. No.:</td> <td>FBF9282M</td> <td>Date of Loss:</td> <td>21/02/2018 12:00 - :59 [72 Months and 19 Days From LTA Reg Date (Man Yr)]</td> </tr> <tr> <td>Claim Type:</td> <td>TP / 0877877652SG</td> <td>Policy/Cover Note No.:</td> <td>2100171276-08 (Comprehensive)</td> </tr> <tr> <td>Vehicle Reg. No. (Insured):</td> <td>SJT7367Y</td> <td>Policy No. (Claimant):</td> <td>5083563745-01</td> </tr> <tr> <td></td> <td></td> <td>Excess:</td> <td></td> </tr> <tr> <td>Repairer:</td> <td colspan="3">Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519</td> </tr> <tr> <td>Handling Insurer:</td> <td colspan="3">AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Mohd-Rasheed, Rashidah - 64191767] Rashidah.Mohamedrasheed@aig.com</td> </tr> <tr> <td>Claimant's Insurer:</td> <td colspan="3">NTUC Income Insurance Co-operative Ltd (HQ) - Tel:</td> </tr> <tr> <td>Adjuster:</td> <td colspan="3">LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/03/2018]</td> </tr> </table> </div>					Insured:	Le My Diep, ID: S75735173			Main Claimant:	LEE LENG HUAT ADDIE, ID: S73067041			Vehicle Reg. No.:	FBF9282M	Date of Loss:	21/02/2018 12:00 - :59 [72 Months and 19 Days From LTA Reg Date (Man Yr)]	Claim Type:	TP / 0877877652SG	Policy/Cover Note No.:	2100171276-08 (Comprehensive)	Vehicle Reg. No. (Insured):	SJT7367Y	Policy No. (Claimant):	5083563745-01			Excess:		Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519			Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Mohd-Rasheed, Rashidah - 64191767] Rashidah.Mohamedrasheed@aig.com			Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/03/2018]		
Insured:	Le My Diep, ID: S75735173																																											
Main Claimant:	LEE LENG HUAT ADDIE, ID: S73067041																																											
Vehicle Reg. No.:	FBF9282M	Date of Loss:	21/02/2018 12:00 - :59 [72 Months and 19 Days From LTA Reg Date (Man Yr)]																																									
Claim Type:	TP / 0877877652SG	Policy/Cover Note No.:	2100171276-08 (Comprehensive)																																									
Vehicle Reg. No. (Insured):	SJT7367Y	Policy No. (Claimant):	5083563745-01																																									
		Excess:																																										
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519																																											
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Mohd-Rasheed, Rashidah - 64191767] Rashidah.Mohamedrasheed@aig.com																																											
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:																																											
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/03/2018]																																											
<div style="border: 1px solid black; padding: 5px;"> ASSOCIATED MAIL RECEIVED View All Compose Case Mail <p>There are no mail for this case.</p> </div>																																												
<div style="border: 1px solid black; padding: 5px;"> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.																													
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?																																			
No results.																																												

Claim Documents

*FBF9282M (0877877652SG)
[SJT7367Y]
TP
LEE LENG HUAT ADDIE
Feb 21 2018 12:40PM
[Le My Diep]
Hua Meng Spray Painting Workshop

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1	Edit				
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
2	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
3	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
4	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
5	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
6	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
7	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
8	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
9	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
10	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
11	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
12	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
13	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
14	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
15	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
16	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
17	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
18	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
19	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
20	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
21	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
22	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
23	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
24	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
25	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
26	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
27	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
28	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
29	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
30	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
31	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
32	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
33	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			
34	11/07/18 12:29		General View												1	Load JPG	<input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
36	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
37	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
38	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
39	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
40	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
41	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
42	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
43	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
44	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
45	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
46	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
47	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
48	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
49	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
50	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
51	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
52	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
53	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
54	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
55	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
56	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
57	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
58	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
59	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
60	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
61	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
62	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
63	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
64	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
65	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
66	11/07/18 12:29	General View		<input checked="" type="checkbox"/>
67	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
68	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
69	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
70	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
71	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
72	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
73	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
74	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
75	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
76	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
77	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
78	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
79	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
80	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
81	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
82	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>
83	11/07/18 12:30	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	11/07/18 12:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 14:25	PIR RESULT.	 Load JPG	<input checked="" type="checkbox"/>
2	24/10/18 11:05	WORKSHOP INVOICE	 Load PDF	
3	24/10/18 11:05	AUTHORISATION TO ACT FORM	 Load PDF	
4	24/10/18 11:05	Release Voucher	 Load PDF	
5	24/10/18 11:05	LTA SEARCH	 Load PDF	

Letters/Correspondences			1 per page	<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
6	24/10/18 11:05	LETTER TO OI	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	27/02/18 11:08	FBF9282M	1	Load PDF	
2	27/02/18 11:08	SJT7367Y	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJT7367Y (Insd veh)	Model:	YAMAHA YZF-R6S 599CC
	FBF9282M (TP veh)		
Date of Accident:	21/02/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	10,005.00
Final Repair Cost	:	\$	4,980.00
Loss of Use	:	\$	6.00 days at \$30.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	4,980.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Hua Meng Spray Painting Workshop	:	\$ 4,980.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

24 Oct
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18003647/AUA3Q2

Date: 24/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100171276-08

Claimant Vehicle No: FBF9282M Insured Vehicle No: SJT7367Y

Date of Loss: 21/02/2018 Nature of Claim: TP Claim No: 0877877652SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBF9282M
 Make & Model: YAMAHA YZF-R6S, 599cc Engine No: J515E026542
 Reg. Date: 02/02/2012 (Man. Year: 2011) Chassis No: JYARJ155000004434
 Colour: Blue Odometer: 84316 km
 Engine Capacity: 599 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R17 Rear Tyre Size: 180/55 R17
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,060.00	5,305.30	3,754.70	41.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	945.00	685.00	260.00	27.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,005.00	5,990.30	4,014.70	40.13
Approved Total (Overridden) (S\$)		4,800.00		
Nett Amount (S\$)	10,005.00	4,800.00	5,205.00	52.02
+ Loss of Use (6.0 x S\$30.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		4,987.49		
Global Sum Settlement (S\$)		4,980.00		

INSPECTION

Date of Assignment: 23/02/2018

Date Inspected: 23/02/2018 Inspected At:

Hua Meng Spray Painting Workshop (HQ)
 No 1 Kaki Bukit Avenue 6, #01-61
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	25.00 FS	*25.00 FS
2	1		*REAR SIGNAL LAMP	N/S Cut	150.00 F	*75.00 FL
3	1		*REAR MUDFLAP	Deformed	65.00 F	*65.00 FL
4	1		*REAR MUDFLAP BRACKET	Bent	185.00 F	*185.00 FL
5	1		*TAILLAMP	Not Necessary	190.00 F	*- FL
6	1		*REAR EXHAUST PIPE	Bent	1,850.00 F	*1,850.00 FL
7	2		*REAR FOOTREST	N/S Cut / O/S Cracked	136.00 F	*136.00 FL
8	2		*REAR FOOTREST BRACKET	Not Necessary	330.00 F	*- FL
9	1		*FRONT NUMBER PLATE	Necessary	25.00 FS	*25.00 FS
10	1		*FRONT WINDSHIELD	Cut	135.00 F	*135.00 FL
11	1		*HEADLAMP ASSY	Cracked	580.00 F	*580.00 FL
12	1		*HEADLAMP GARNISH	N/S Cracked	350.00 F	*175.00 FL
13	1		*FRONT WING MIRROR LH	Cut	115.00 F	*115.00 FL
14	1		*BALANCER LH	Cut	30.00 F	*30.00 FL
15	1		*CLUTCH LEVER	Cut	58.00 F	*58.00 FL
16	1		*FRONT SIGNAL LAMP LH	Cut	68.00 F	*68.00 FL
17	1		*FRONT FORK OIL	Necessary	20.00 FS	*20.00 FS
18	1		*FRONT FORK	N/S Bent	1,760.00 F	*880.00 FL
19	1		*FRONT FORK UNDER BRACKET	Bent	195.00 F	*195.00 FL
20	1		*STEERING CONE AND BEARING	Necessary	75.00 FS	*75.00 FS
21	1		*SIDE FAIRING LH	Cut	255.00 F	*255.00 FL
22	1		*SPEEDOMETER	Not Necessary	980.00 F	*- FL
23	1		*SIDE LOWER COWLING (WHITE)	Deformed	295.00 F	*295.00 FL
24	1		*ENGINE COVER	Cut	215.00 F	*215.00 FL
25	1		*FRONT FOOTREST LH	Cracked	70.00 F	*70.00 FL
26	1		*REAR SIDE FAIRING LH	Cut	285.00 F	*285.00 FL
27	1		*FRONT WHEEL RIM	Not Necessary	450.00 FS	*- FS
28	1		*FRONT BRAKE DISC	Not Necessary	68.00 F	*- FL
29	1		*STICKERS	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,060.00	5,872.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	566.70
Total Parts (\$\$)	9,060.00	5,305.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	280.00
2	SPRAY PAINTING	New	350.00	250.00
3	WIRING	New	50.00	30.00
4	TOWING	New	45.00	45.00
5	TO REMOVE EXHAUST PIPE	New	150.00	80.00
Gross Labour Cost (S\$)			945.00	685.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >