

SMRT Vehicle Repair Estimate

Group : Buses / Taxis / Private Car

Reg. No. : SKC 9663 G

Ref. No. _____

Make / Model : MERCEDES BENZ E200K

Reg. Date : 07/12/2006

Chassis No : WDB2110412B028377

Mileage _____

Name of Driver : WONG KOK WEI

Rental/Replacement Vehicle : Yes / No

Date/Time of Accident : 03/02/2018 20:35

Surveyor is Required ? YES / NO

If Yes, VICOM / LKK / AIS / Others MSIG : _____

Vehicle is Towed Back ? YES / NO Date / Time : _____


Accident reporting date : 05/02/2018 10:25

Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others

Special Instruction to ARC, if any :

TP Claim AIG

The damages on the vehicle are as indicated in the following diagram :



Signed : _____

Date : _____

Accident Repair Job Card No : _____

Date Prepared : _____

Summary of Repair Estimates

Repair Completed : _____

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charges : \$ 900.00

\$ -

Total Spray Painting Charges : \$ 1,000.00

\$ -

Total Material Charges : \$ 7,247.10

\$ -

Other Charges : \$ 540.00

\$ -

TOTAL : \$ 9,687.10

\$ -

Lump Sum Repair, if any : _____

No. of Repair Days : [4] days

[] days

Signature : Prepared by: _____

Adjusted by: _____

QN No. _____ Invoice No. _____

Signed : _____

Date : _____

Part 1 - Labour Works

Job Scope	Quotation from ARC	
To renew damaged parts, replace and realign support panels, and aligned all parts	\$ 900.00	
Total Labour Cost	\$ 900.00	\$ -

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray affected areas	\$ 1,000.00	
Spray Painting	\$ 1,000.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page ()

Job Scope	Quotation from ARC	
Towing		
Windscreen sealant		
To tuffcoat affect areas	\$ 250.00	
To renew front/ windscreen glass		
To renew engine mountings		
To remove /refit aircon condensor, pipings, vacuum and recharge aircon gas		
To remove/refit replace dashboard		
To remove and refit interior upholstery	\$ 150.00	
To remove and replace steering column		
To remove /refit wiring check	\$ 60.00	
To remove/refit adjust brake 4 wheel		
To remove/replace exhaust silencer box and straighten centre pipe		
To remove/replace reverse sensors	\$ 80.00	
To remove/replace brake booster pump		
To remove & renew Fuel Tank		
To remove & renew canopy		
Total Other Costs	\$ 540.00	

Part 4 - Spare Parts / Material Usage

To be completed by Service Advisor, ARC							
Part Number	Parts Description	Qty	Cost Price (\$)	less 10%	Final Price (\$)	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
	BOOTLID		\$ 2,226.00	10%	\$ 2,003.40		
	BOOTLID LOGO		\$ 58.00	10%	\$ 52.20		
	BOOTLID EMBLEM E200		\$ 95.00	10%	\$ 85.50		
	BOOTLID EMBLEM KOMPRESSOR		\$ 98.00	10%	\$ 88.20		
	BOOTLID GARNISH WITH MOULDING		\$ 650.00	10%	\$ 585.00		
	REAR BUMPER		\$ 1,485.00	10%	\$ 1,336.50		
	REAR BUMPER INNER FRAME		\$ 250.00	10%	\$ 225.00		
	REAR BUMPER SIDE FRAME	2	\$ 138.00	10%	\$ 124.20		
	REAR BUMPER SIDE BRACKET	2	\$ 116.00	10%	\$ 104.40		
	REAR BUMPER LOWER BRACKET	2	\$ 36.00	10%	\$ 32.40		
	REAR BUMPER TOW COVER		\$ 79.00	10%	\$ 71.10		
	REAR BUMPER REINFORCEMENT		\$ 679.00	10%	\$ 611.10		
	REAR BUMPER MOULDING CENTER		\$ 195.00	10%	\$ 175.50		
	REAR BUMPER MOULDING SIDE	2	\$ 304.00	10%	\$ 273.60		
	REAR END PANEL OUTER		\$ 794.00	10%	\$ 714.60		
	REAR END PANEL TOP GARNISH		\$ 181.00	10%	\$ 162.90		
	REAR SPARE TYRE SCREW COVER		\$ 135.00	10%	\$ 121.50		

Special Nett Items	Parts Description	Qty	Cost Price (\$)	Discount	Final Price (\$)	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
	REAR NO PLATE	1	\$ 50.00	-	\$ 50.00		
	REAR BUMPER CLIP	10	\$ 50.00	-	\$ 50.00		
	REAR END PANEL TOP GARNISH CLIP	6	\$ 30.00	-	\$ 30.00		
	REAR REVERSE SENSOR	1 SET	\$ 350.00	-	\$ 350.00		
				-			
				-			
				-			
				-			

TOTAL MATERIALS			\$ 7,999.00	-	\$ 7,247.10		
-----------------	--	--	-------------	---	-------------	--	--

Surveyor Remark: