

Special Instruction:

45: \$ 30500.00

ASSIGNMENT (Office)

From (Person): May Onica of FCI Date/Time: 19-02-2018  
Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

*Third Parties:*

Claimant:

Surveyor:

Surveyor: PAR Automotive

Workshop: Twincar.

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SKR 6368A Insured: SHD 69506

at Workshop m/s Twincar Automotive Tel: 6842 0051

of 2 Kaki Bukit Ave 2 #01-17

Policy No: \_\_\_\_\_ Claim No: **D17002113MFSH**

Sum Insured: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 21-02-2017  
(Client's Record)

(Client's Record)

H.O.D. Enregistrement/Date:

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_

Date/Time: 3/2/15 Confirmed with            Final Fig           ,            days (Red \$            /            %; Original 15 days)

Date/Time: 28/7/18 Submit Final Fig LS 12,800, 8 days (Red \$1,100 / 58 %; Original      days)

[illegible]

**Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)**

**Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)**

RECEIVED 28 FEB 2019

**Para(3) : Nett Value**

Market Value .

Salvage Value :

Nett Value :

Inspected/  
Evaluated by:

*Fee Charged:*

Date: \_\_\_\_\_

Basic &amp; Add

Transport

## Photos

Others

Total

1) Date/Time 28-2-2024 File Pass to

2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

4) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS1/FCI18003653/vb		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-02-2018		
		Code : FCI2		
<b>1. Policy Particulars : PAPER SURVEY</b>				
Insured Veh.	SHD 6950C	Veh. Inspected	SKR 6368A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17002113MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	19/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	21/02/2017	Inspection Date	26/02/2018	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				

**From:** May Chua Hui Chin <maychua@msfirstcapital.com.sg>  
**Sent:** Monday, 19 February, 2018 11:30 AM  
**To:** SUR  
**Cc:** Catherine Chong (LKK Auto)  
**Subject:** Request paper resurvey for SHC2780H  
**Attachments:** DAMAGE ASSESSMENT SKR6368A.PDF

**OUR REF: D17002113MFSH**

Dear Sir / Madam,

Kindly assist to conduct a paper resurvey on urgent basis.

Third party LOD:

**Download Link** - Expires on 2018-03-05 00:00 GMT+0800

LOD FR TPV SKR6368A - PART (1).pdf (2.1 MB)

<https://secure.justattach.com/download.php?T=Ps85WAZIXf2AU8AfUAAZcyZv5Pww3WT2fEN6f9TVvKeNDUVdvnyLPg2fuTtNrOly0RlhOp2wPSAqKKFQDSUdIQ>

**Download Link** - Expires on 2018-03-05 00:00 GMT+0800

LOD FR TPV SKR6368A - PART (2).pdf (1.3 MB)

<https://secure.justattach.com/download.php?T=2tlinkpmQgF5UwVOoYKJZAGmTff0Wui3ka9.2d85I1uE.7MJLdD9TVPRG2BDZr8YhviHeRK4E2jmdALt62kBg>

Thank you

May Chua

Motor Claim Department

MS First Capital Insurance Ltd | 36 Robinson Road, City House #16-01 Singapore 068877 | DID : 6507 3859| Fax No. : 6507 3849 |Email: [maychua@msfirstcapital.com.sg](mailto:maychua@msfirstcapital.com.sg) |Company Regn. No. 195000106C

A Member of **MS&AD** Insurance Group

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to <http://www.msfirstcapital.com.sg> for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

First Capital Insurance Ltd  
36 Robinson Road  
#16-01 City House  
Singapore 068877



VICOM LTD  
385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555  
Facsimile (65) 6458 1040

www.vicom.com.sg  
Company Registration No: 198100320K

## DAMAGE ASSESSMENT REPORT

### GENERAL INFORMATION

VAC Ref. No.	: 504300	Claim No.	: D17002113MFSH
Accident Date	: 21/02/2017	Claim Type	: THIRD PARTY
Assignment Date	: 23/02/2017	Policy No.	:
Survey Date	: 24/02/2017		
Report Date	: 10/03/2017	Insured Veh. :	SHD6950C

### VEHICLE PARTICULARS

Vehicle No.	: SKR6368A	Chassis No.	: WAUZZZ4G2EN127297
Registration Date	: 29/12/2014	Engine No.	: CDN40654C
Make	: AUDI	Engine Cap.	: 1984CC
Model	: A6 2.0 TFSI M	Transmission	: AUTOMATIC
		Colour	: WHITE

### CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)

Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 56186		

<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	275/30ZR20	BRIDGESTONE	6
FRONT LH	275/30ZR20	BRIDGESTONE	6
REAR RH	275/30ZR20	BRIDGESTONE	6
REAR LH	275/30ZR20	BRIDGESTONE	6

### SURVEY CONDUCTED AT

TWINCAR AUTO PL  
2 K BT AVE 2 #01-17/18 K BT AUTOHUB S417921 MR ONG:84840051/ MELODY:68420051

### REMARKS

- [1]Workshop did not give repair estimate.
- [2]We have not authorised repairs. This survey was carried out on without prejudice basis.

**DAMAGE ASSESSMENT REPORT****Annex A: List of damaged parts**

#	Qty	Vehicle Parts Description	Condition
1	1	Rear Bumper	Replace
2	1	Rear Bumper Lower Cover	Replace

## DAMAGE ASSESSMENT REPORT

## Annex B: Comments

## ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained rear damage.

The damages seen during our survey were at rear bumper and surrounding areas. A fuller detailed description of the damages is in Annex A of this damage assessment report.

We enclose 60 photographs of this vehicle taken during our attendance.

The repair estimate was not available during our survey attendance.

This Vehicle has :

- a) estimated pre-accident value = S\$141,000.00
- b) estimated salvage value = S\$74,000.00
- c) economical repair value = S\$67,000.00

## REMARKS

owner/driver reported(GIA Statement)mention front portion no damage in this accident



Fock Ping Yan  
for VICOM Ltd

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks  
(Incorporated with limited liability)

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALI D-O MUNIANDY  
SEGA PARAM  
TIWARY ANURADHA  
ONG BOCK KEE  
ANG KIM NOI DIANE  
RAVENDRA KRISHNASAMY  
TAY HAO RAN  
JANICE HAN JIA LIN  
TAN YINGXIAN SELWYN

Unique Entity Number: 200721148H

✓Head Office:  
133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 058413

Branch:  
490 Toa Payoh Lorong 6  
#03-11 HOB Hub  
Singapore 310490

Branch:  
133 New Bridge Road  
#10-03 Chinatown Point  
Singapore 059413

## HEAD OFFICE:

TEL : (65) 65342811 (Hunting)  
FAX : (65) 65356802 (General)

E-MAIL: annatan@visionlawllc.com

## BRANCH

TEL : (65) 63580703  
TEL : (65) 65330868

## BRANCH

TEL : (65) 65342811 (Hunting)  
TEL : (65) 65330869

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to HEAD OFFICE for this

Our Ref : AKN-atv-Ins-T140-104276-17  
Your Ref : SHD 6950 C

Date: 20 September 2017


**FIRST CAPITAL INSURANCE LIMITED**  
36 Robinson Road  
#16-01 City House  
Singapore 068877  
Attn: Motor Claims Department

**COMFORT TRANSPORTATION PTE LTD**  
383 Sin Ming Drive  
GAS Building  
Singapore 575717

# URGENT

WITHOUT PREJUDICE  
BY HAND

**CERTIFICATE OF POSTING**  
[For your information only]



Dear Sir,

**CLAIMANT : LAW VOON YEAM**  
**ACCIDENT INVOLVING SKR 6368 A & SHD 6950 C, SHB 9925 S, SLG 1224 K & SGA 2352 H ON 21-FEB-2017 ALONG CTE TOWARDS WOODLANDS AFTER BRADDELL EXIT AT ABOUT 2200HOURS**

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on **21-FEB-2017 ALONG CTE TOWARDS WOODLANDS AFTER BRADDELL EXIT AT ABOUT 2200HOURS** involving our client's vehicle registration number **SKR 6368 A** and vehicle registration number **SHD 6950 C** driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

01.	Cost of Repair	\$32,635.00
02.	Rental fees	\$ 1,120.00
03.	Additional 9 days loss of use including pre repair	\$ 1,350.00
04.	Survey report fees	\$ 1,577.00
05.	GIA & LTA search / report fees	\$ 42.35
06.	Cost Contribution (at this stage)	\$ 2,675.00
07.	Disbursements (at this stage)	\$ 50.00
<b>TOTAL</b>		<b>\$39,449.35</b>

.../2 to be continued next page

**CONFIDENTIALITY**  
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

# VISION LAW LLC

Advocates & Solicitors

Page 2

Our Ref : AKN-atv-Ins-T140-104276-17  
Your Ref : SHD 6950 C

Date: 20 September 2017

## FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road

#16-01 City House

Singapore 068877

Attn: Motor Claims Department

## COMFORT TRANSPORTATION PTE LTD

383 Sin Ming Drive

GAS Building

Singapore 575717

---

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA report lodged by driver of SKR 6368 A;
  - (b) LTANet Search;
  - (c) Certificate of Insurance;
  - (d) Registration Card;
  - (e) Rental agreement, rental invoice & rental receipt;
  - (f) Final Repair Bill;
  - (g) Surveyor's report & invoice; and
  - (h) 151 coloured photographs depicting the damages to motor vehicle SKR 6368 A.
- (P.S:- Original photographs will be sent to insurance co. only)

The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully



(HEAD OFFICE)

Enc. (By PDX Only)

### CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/02/2017 12:14
Date Of Accident	21/02/2017 22:00
Exact Location Of Accident	CTE TWDS WOODLANDS AFT BRADDELL EXIT
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR6368A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LAW VOON YEAM
NRIC No	S7175759E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96177781
Alternative Phone No	Others-96177781
<b>Vehicle Particulars</b>	
Manufacturer	AUDI
Model	A6 2.0
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car
<b>Insurance Company</b>	
Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2100397721-02000
Cover Note Number	
<b>Driver</b>	
Name of Driver	LAW VOON YEAM
NRIC No	S7175759E
Date Of Birth	22/01/1971
Occupation	Indoor
Date Of Driving Pass	31/05/2008
Driving Experience	8 Years And 8 Months
Gender	Male
Mobile Number	(Local) +65-96177781
Fax Number	
Contact Number	Others-96177781
Email Address	NOEMAIL

Address	10 WOODGROVE DR #01-34
Postcode	738211
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	Collision- Chain Collision
Weather Conditions	Clear
Road Surface	Dry

#### Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD6950C
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	TAN ENG GUAN
NRIC/Passport Number	
Contact Number	81132903
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	
Details of Witness	
Name	
Phone Number	
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHB9925S
Vehicle Make/Model/Colour	

**Details Of Properties**

**Name of Driver**

**NRIC/Passport Number**

**Contact Number**

**Address**

**Postcode**

**Insurance Company Name**

**Nature Of Damage**

**No. Of Passenger (Including Driver)**

**Details of Witness**

**Name**

**Phone Number**

**Email Address**

**DETAILS OF OTHER VEHICLE PROPERTY 3**

**Vehicle Registration Number**

**SLG1224K**

**Vehicle Make/Model/Colour**

**Details Of Properties**

**Name of Driver**

**NRIC/Passport Number**

**Contact Number**

**Address**

**Postcode**

**Insurance Company Name**

**Nature Of Damage**

**No. Of Passenger (Including Driver)**

**Details of Witness**

**Name**

**Phone Number**

**Email Address**

**DETAILS OF OTHER VEHICLE PROPERTY 4**

**Vehicle Registration Number**

**SGA2352H**

**Vehicle Make/Model/Colour**

**Details Of Properties**

**Name of Driver**

**NRIC/Passport Number**

**Contact Number**

**Address**

**Postcode**

**Insurance Company Name**

**Nature Of Damage**

**No. Of Passenger (Including Driver)**

**Details of Witness**

**Name**

**Phone Number**




**Email Address**

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3 Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information"), and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquires by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me in bring about delivery of the same as well as on the external cover of envelopes/parcel packages) and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/ can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 Policyholder's Signature / Date & Time	 Driver's Signature (if driver is not the policyholder) / Date & Time	 Witnessed by Reporting Centre Personnel
---	---	--

Sketch Plan

LTE TONGGONG JOURNALIST OFFICE DENNIS LEE

VEHICLE A - SK123640

VEHICLE B - SH10 64500

VEHICLE C - SH10 77245

VEHICLE D - SK123456

VEHICLE E - SC020024 →



### Sketch Plan #2

### Describe Circumstances of the Accident

I WAS TRAVELLING ON THE EXTREME RIGHT LANE OF CTR TOWARDS SLE  
AFTER PASSING BY BRADDELL ROAD EXIT DUE TO THE VEHICLE INFRONT  
JAMMO BRAKE SO I TOO APPLIED BRAKE AND MANAGED TO STOP IN  
TIME BEHIND THE VEHICLE BEARING (SGA-352H) BUT AFTER A  
FEW SECONDS SUDDELY I FELT A GREAT IMPACT FROM THE REAR  
OF MY VEHICLE AND THE IMPACT THREW ME FORWARD AND CAME  
ME SUDDELY DOWN ON THE CAR INFRONT OF ME BUT NO INJURY CAME.

VEHICLE A - SKR636G A

VEHICLE 13 - SHIP GRAC

VEHICLE # - 510 99255

vehicle 2 - SLG.224R

VEHICLE R - SGA2352 M

## Declaration


We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date &  
Time


Driver's Signature (if driver is not the policy holder) Date & Time

Witnessed by Flopping Centre  
Personnel

Accident Photo



Accident Photo




Accident Photo






Accident Photo




Accident Photo



Accident Photo



Accident Photo




**Accident Photo**




Accident Photo



**Accident Photo**



Accident Photo





Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 22 Feb 2017 / 12:02:59

Receipt Date/Time : 22 Feb 2017 / 12:02:59

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-170222-000583

Previous Receipt No. :

**S/N Item Description/  
Business Transaction  
Reference No.**

<b>Amount Before GST (\$\$)</b>	<b>GST Amount (\$\$)</b>	<b>Amount After GST (\$\$)</b>
---	----------------------------------	--

Result of Insurance Enquiry - SHD6950C  
As at 21 Feb 2017/22:00:00  
Insurance Co: FIRST CAPITAL INS LTD

1 Insurance Enquiry - SHD6950C  
Enquiry Fee  
20170222120227346416

5.00	0.35	5.35
------	------	------

<b>Sub-Total</b>	5.00	0.35	5.35
------------------	------	------	------

<b>Total Before Rounding</b>	5.00	0.35	5.35
------------------------------	------	------	------

<b>Rounding Difference</b>			0.00
----------------------------	--	--	------

<b>Total Amount Payable</b>			5.35
-----------------------------	--	--	------

Paid By

xxxxxxxxxx2392	Credit Card: Visa/MasterCard	5.35
----------------	---------------------------------	------

<b>Total</b>			5.35
--------------	--	--	------

<b>Cash Change</b>			0.00
--------------------	--	--	------

<b>Tendered Amount</b>			5.35
------------------------	--	--	------

<b>Excess Refundable Amount</b>			0.00
---------------------------------	--	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

**Enquire Vehicle & Owner Information ( Vehicle No. SHD6950C As At 21 Feb 2017 / 22:00:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: T140-104276-17

**Current Owner Details**

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

**Current Vehicle Details**

Vehicle No.: SHD6950C

Make Description/Model: HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Insurance Company Name: FIRST CAPITAL INS LTD

Land Transport  Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

Last updated on 27 Aug 2017 at 01:09 AM

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

LAW VOON YEAM

10 WOODGROVE DRIVE #01-34

SINGAPORE 738211

Contact : 96177781

## TAX INVOICE

Date : 25/08/2017

Date in : 22/02/2017

Vehicle Num. : SKR6368A

Make/Model : AUDI A6 2.0 TFSI MU-2014

Chassis/Eng# : WAUZZZ4G2EN127297/CDN406540

Accident Date : 21/02/2017

Claim No : CLM13608

Reference : FEB-25/2017

Policy No. : 2100397721-02000 (28/12/2017)

LUMPSUM REPAIR BILL

AS PER SURVEYOR REPORT

EF : 0362-17-TCA DATED 10/08/2017  
BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$

30,500.00

E. & O.E. Sub S\$ : 30,500.00

Add GST ( 7 % ) S\$ : 2,135.00

Total Amount S\$ : 32,635.00



for TWINCAR AUTOMOTIVE PTE LTD



HOTLINE TEL: (65) 6419 3000  
FAX: (65) 6415-3723

## CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUTOPLUS

OWN DAMAGE EXCESS S\$800.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

CERTIFICATE NO. 2100397721-02000

SUM INSURED Market Value

INSURING WITH COE/PARF Yes

SKR6368A

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

LAW VOON YEAM

3) EFFECTIVE DATE OF THE COMMENCEMENT  
OF INSURANCE FOR THE PURPOSES OF THE ACT

29 Dec 2016

4) DATE OF EXPIRY OF INSURANCE

28 Dec 2017

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE \*  
SUBJECT TO AGE CONDITION :40 years old and above

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

### 6) LIMITATION AS TO USE \*

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

SOLE AGENT'S WORKSHOP: For new vehicles less than 3 years from initial registration, you have the option for claims-related repairs to be done at Sole Agent's workshop.

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

1. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118)
2. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only
3. Eboz - 30 Bukit Batok Cres (Tel: 66547777)
4. DPS Body & Paint (Subsidiary of C & C) - 209 Pandan Gardens (Tel: 65684501)
5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560)
6. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)
7. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892)
8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)
9. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss of Use 10 Days (1600cc) - Refer to policy wordings for details

NAMED DRIVER NA

HIRE PURCHASE COMPANY DBS BANK LTD  
/ EMPLOYER'S LOAN

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 1 Dec 2016

AIG Asia Pacific Insurance Pte. Ltd.

501851-000  
LO SOK TSING VINCY  
51 SCOTTS ROAD  
#03-23  
SINGAPORE 228241

AUTHORISED REPRESENTATIVE

ORIGINAL

SSPSLT.

# V&P Registration Confirmation Slip

Thank you for registering the following vehicle

## Vehicle Details

Vehicle No.	SKRG368A
Vehicle Type	SALOON
Vehicle Make	AUDI
Vehicle Model	A6
Chassis No.	WAUZZZ4G2EN127297
Primary Colour	WHITE
COE Expiry Date	29/12/2024
Insurance Company Name	AIG
Insurance Policy No.	2100397721
Insurance Expiry Date	28/12/2016
Road Tax Expiry Date	28/12/2016

## Owner Details

Full Name	LAW VOON YEAM
Nationality	Malaysia
Passport No.	A25803338
Passport Expiry Date	01/09/2017
Mobile Phone No.	96177781
Email	LEW@MHC-BIA.COM

Verification Code



154 3014 015745

### Various Particulars

Vehicle Scheme:	Normal
Vehicle Attachment 3:	-
Vehicle Model:	A8 2.0 TFSI MU
Engine No.:	CDN400640
Trailer Chassis No.:	-
Passenger Capacity:	4
Power Rating:	-
Maximum Laden Weight:	2145 kg
Secondary Colour:	-
Original Registration Date:	29 Dec 2014
Open Market Value:	\$36,530.00
Minimum PARF Benefit:	\$20,471.00
Additional Registration Fee Rate:	First \$20,000.00 (100%), next \$16,530.00 (140%)

Owner Name:	LAW NGON YEAM
Owner ID Type:	Malaysian NRIC
Owner ID:	710122-0-9679
Registered Address Type:	Private Residential (Condo Apt or House) / Shopping Mall or Gas Station
Registered Block/House No:	10
Registered Street Name:	WOODGROVE DRIVE
Registered Unit No.:	1011-14
Registered Building Name:	
Registered Postal Code:	735211

### Construction Details

**000000**



WIN WIN RENT-A-CAR PTE LTD

## Invoice

SKR6368A  
LAW VOON YEAM  
10 WOODGROVE DRIVE  
#01-34  
S(738211)

Invoice No : WPLIN0000872  
Invoice Date : 28/2/2017  
Due Date : 28/2/2017  
VHA No : 1234  
Referral ID : T015

Description :	Amount
Rental for 8 Day/s @ \$140 per Day	\$1,120

Vehicle No : SLC4697E

Vehicle Description : Mazda 3

Rental Period : 22/02/2017 to 01/03/2017

Total Amount Payable : \$1,120

# PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

---

Report No: 0362-17-TCA

10 August 2017

Law Voon Yeam  
10 Woodgrove Drive #01-34  
Singapore 738211

**INVOICE No.**                      **0362-17-TCA**


**Vehicle No.**                      **SKR6368A**

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$1,577 00
<b>Total amount payable</b>		<b><u>\$1,577.00</u></b>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

**PAR Automotive Consultancy**



---



# PAR Automotive Consultancy

Regn. No 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

---

Report No: 0362-17-TCA

10 August 2017

## ACCIDENT VEHICLE SURVEY REPORT

Law Voon Yeam  
10 Woodgrove Drive #01-34  
Singapore 738211

### VEHICLE INFORMATION:

Vehicle Reg No.:	SKR6368A	Odometer:	197849km
Make & Model:	Audi A6 2.0	Colour:	White
Chassis number:	WAUZZZAG2EN127297	Date of accident:	21/02/2017
Year of Regn.:	29/12/2014	Date inspected:	24/02/2017
Repairer at:	Twincar Automotive Pte Ltd	Date inspected (After Repair):	01/03/2017
	Blk 2 Kaki Bukit Ave 2 #01-17		
	Kaki Bukit Auto Hub		
	Singapore 417921		

### STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

### TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Bridgestone	6mm/Bridgestone	245/35ZR20
Rear:	5mm/Pirelli	5mm/Pirelli	275/30ZR20

### POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.

Please see details as described in the Annex for parts and labour.

### REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

## Parts and Labour Assessment

### PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
FRONT BUMPER	1	squashed	2,243.00	2,243.00
FRONT BUMPER FOGLAMP COVER L/R	2	fractured	254.30	254.30 X NN
FRONT BUMPER INNER SPONGE	1	deformed	80.55	80.55
FRONT BUMPER LOWER RUBBER MOULDING	1	deformed	204.25	204.25
FRONT BUMPER LOWER UNDER COVER	1	reuse	155.30	0.00
FRONT BUMPER NOZZLE COVER L/R	2	deformed	293.46	293.46 X NN
FRONT BUMPER NUMBER PLATE SCREW WITH COVER L/R	2	necessary	56.00	56.00
FRONT BUMPER PARKING SENSOR 'ORIGINAL'	2	shorted	857.40	857.40 428.70
FRONT BUMPER PARKING SENSOR HOLDER	2	necessary	247.40	247.40 123.70
FRONT BUMPER PARKING SENSOR RUBBER SEAL	2	necessary	24.00	24.00 12
FRONT BUMPER PARKING SENSOR WIRE HARNESS - SET	1	snaped	552.83	552.83 X NN
FRONT BUMPER REINFORCEMENT	1	bent	679.20	679.20 X NN
FRONT BUMPER REINFORCEMENT BRACKET L/R	2	bent	410.66	410.66 X NN
FRONT BUMPER SIDE RETAINER L/R	2	necessary	60.50	60.50
FRONT BUMPER TOW HOOK COVER	1	reuse	37.85	0.00
FRONT GRILLE	1	fractured	1,142.53	1,142.53
FRONT GRILLE 'LOGO' EMBLEM	1	necessary	32.82	32.82
FRONT GRILLE CHROME MOULDING	1	fractured	195.00	195.00
FRONT GRILLE CLIPS	10	necessary	65.00	65.00
FRONT HEADLAMP CLIPS L/R	2	necessary	13.00	13.00
FRONT HEADLAMP L/R	2	fractured LH	5,747.56	5,747.56 2813.78
FRONT HEADLAMP NOZZLE HOSE L/R	2	deformed	231.50	231.50 X NN
FRONT HEADLAMP NOZZLE L/R	2	fractured	451.36	451.36 X NN
REAR BOOTLID	1	buckled	2,412.48	2,412.48 X R
REAR BOOTLID '2.0' EMBLEM	1	necessary	81.48	81.48
REAR BOOTLID 'A6' EMBLEM	1	necessary	81.48	81.48
REAR BOOTLID 'LOGO' EMBLEM	1	necessary	105.50	105.50
REAR BOOTLID 'T' EMBLEM	1	necessary	55.80	55.80
REAR BOOTLID HINGES GARNISH CLIPS L/R	6	necessary	39.00	39.00 X NN
REAR BOOTLID HINGES GARNISH L/R	2	reuse	52.66	0.00
REAR BOOTLID HINGES L/R	2	repair	389.66	0.00
REAR BOOTLID INNER HANDLE	1	reuse	11.00	0.00
REAR BOOTLID INNER LOCK HANDLE SWITCH	1	reuse	157.15	0.00
REAR BOOTLID INNER UPHOLSTERY TRIM	1	reuse	658.15	0.00
REAR BOOTLID MECHANISM LOCK	1	bent	165.75	165.75
REAR BOOTLID MECHANISM LOCK GARNISH	1	warped	5.45	5.45 X NN
REAR BOOTLID NUMBER PLATE LAMP L/R	2	reuse	96.96	0.00
REAR BOOTLID OUTER LOCK HANDLE SWITCH	1	reuse	157.15	0.00
REAR BOOTLID REFLECTOR LAMP CLIPS L/R	4	necessary	26.00	26.00
REAR BOOTLID REFLECTOR LAMP GARNISH L/R	2	reuse	47.66	0.00
REAR BOOTLID REFLECTOR LAMP L/R	2	reuse	47.66	0.00
REAR BOOTLID RUBBER GUIDE STOPPER L/R	4	deformed	52.00	52.00

REAR BOOTLID WEATHERSTRIP	1	deformed	140.63	140.63	X NN
REAR BUMPER	1	squashed	2,148.23	2,148.23	
REAR BUMPER CORNER RETAINER L/R	2	necessary	85.86	85.86	
REAR BUMPER CORNER RETAINER LOCK CLIPS L/R	2	necessary	13.00	13.00	
REAR BUMPER INNER LOWER BOOTLID KICK SENSOR	1	reuse	289.33	0.00	
RR BUMPER INNER LOWER BOOTLID KICK SENSOR HOLDER	1	reuse	61.85	0.00	
RR BUMPER INNER LOWER BOOTLID KICK SENSOR MODULE	1	reuse	699.70	0.00	
REAR BUMPER LOWER DIFFUSER	1	deformed	284.83	284.83	
REAR BUMPER REINFORCEMENT	1	bent	824.43	824.43	
REAR BUMPER REVERSE SENSOR 'ORIGINAL'	2/4	shorted	857.40	857.40	428.70
REAR BUMPER REVERSE SENSOR HOLDER	2/4	necessary	247.40	247.40	123.70
REAR BUMPER REVERSE SENSOR RUBBER SEAL	2/4	necessary	24.00	24.00	12
REAR BUMPER REVERSE SENSOR WIRE HARNESS - SET	1	snapped	552.83	552.83	X NN
REAR BUMPER SIDE RETAINER L/R	2	necessary	52.66	52.66	
REAR BUMPER TOP RETAINER	1	deformed	86.35	86.35	
REAR BUMPER TOW HOOK COVER	1	reuse	46.73	0.00	
REAR END PANEL 'INNER'	1	repair	621.30	0.00	
REAR END PANEL 'OUTER'	1	buckled	424.90	424.90	X R
REAR END PANEL INNER TOP GARNISH	1	fractured	113.18	113.18	X NN
REAR END PANEL INNER TOP GARNISH CLIPS	4	necessary	26.00	26.00	
REAR END PANEL LOCK STRIKER WITH MOTOR	1	shorted	534.40	534.40	X NN
REAR TAILLAMP CLIPS L/R	2	necessary	13.00	13.00	
REAR TAILLAMP GARNISH L/R	2	deformed	78.90	78.90	
REAR TAILLAMP INNER PANEL L/R	2	repair	1,405.80	0.00	
REAR TAILLAMP L/R	2	fractured	2,128.56	2,128.56	X NN
REAR TAILLAMP LOWER BRACKET L/R	2	bent	130.00	130.00	X NN
REAR TWIN EXHAUST ALUMINIUM HEAT SHIELD L/R	2	reuse	490.00	0.00	
REAR TWIN EXHAUST BRACKET	2	repair	136.96	0.00	
REAR TWIN EXHAUST END CHROME PIPE L/R	2	distorted	1,358.40	1,358.40	800
REAR TWIN EXHAUST GASKET	2	necessary	25.00	25.00	
REAR TWIN EXHAUST RUBBER MOUNTING	4	distorted	180.00	180.00	
REAR TWIN EXHAUST SILENCER BOX L/R	2	bent	3,198.86	3,198.86	X NN
Subtotal before discount			S\$ 35,958.95	S\$ 30,396.08	
Percentage discount 0% and 0%			S\$ 0.00	S\$ 0.00	
Sub-total 1			S\$ 35,958.95	S\$ 30,396.08	
FRONT BUMPER CLIPS - SET	1	necessary	30.00	30.00	
FRONT BUMPER NUMBER PLATE	1	bent	25.00	25.00	
REAR BOOTLID INNER UPHOLSTERY TRIM CLIPS - SET	1	necessary	30.00	30.00	
REAR BOOTLID NUMBER PLATE	1	reuse	25.00	0.00	
REAR BOOTLID NUMBER PLATE HOLDER	1	reuse	50.00	0.00	
REAR BUMPER CLIPS - SET	1	necessary	30.00	30.00	
Subtotal before discount			S\$ 190.00	S\$ 115.00	
Sub-total 2			S\$ 190.00	S\$ 115.00	
Parts-total			S\$ 36,148.95	S\$ 30,511.08	

## LABOUR


To reset system after repair works	500.00	400.00	250
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	180.00	120.00	80
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	60.00	
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1,500.00	1,200.00	700
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	1,250.00	1,000.00	500
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	160.00	140.00	70
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,250.00	1,980.00	1000
To mount vehicle on to Car 'O' Liner.	400.00	400.00	X
To apply anti-rust chemical on repaired and replaced panel.	120.00	120.00	X
<b>Labour Total</b>	<b>SS 6,500.00</b>	<b>SS 5,420.00</b>	
<b>Parts &amp; Labour Total</b>	<b>SS 42,648.95</b>	<b>SS 35,931.08</b>	

Results of inspection of the accident vehicle are as shown above.

8 days

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 30,500.00  
and the recommended number of working days for the repairs is within 15 day(s).

  
B J Loi (i Eng., MIMI, AIRTE)  
Automotive Appraiser

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: D17002113MFSH

Date: 28<sup>th</sup> February 2018

Our Ref: CS1/FCI18003653/Cvbe2

**M/s First Capital Insurance Ltd**  
36 Robinson Road  
#16-01 City House  
Singapore 068877  
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SKR 6368A INSURED VEHICLE: SHD 6950C ACCIDENT DATE: 21/02/2017**

We thank you for your instruction on 19/02/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKR 6368A from M/s Par Automotive Consultancy.
- b) Singapore Accident Statement of Vehicles SKR 6368A.
- c) Colour damaged vehicle photographs of SKR 6368A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKR 6368A
Make & Model	: Audi A6 2.0
Year of Registration	: 2014
Chassis Number	: WAUZZZ4G2EN127297
2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 6368A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	SQUASHED	2,243.00	2,243.00
2	FRONT BUMPER FOGLAMP COVER L/R	NOT NECESSARY	254.30	-
1	FRONT BUMPER INNER SPONGE	DEFORMED	80.55	80.55
1	FRONT BUMPER LOWER RUBBER MOULDING	DEFORMED	204.25	204.25
1	FRONT BUMPER LOWER UNDER COVER	REUSE	155.30	-
2	FRONT BUMPER NOZZLE COVER L/R	NOT NECESSARY	293.46	-
2	FRONT BUMPER NUMBER PLATE SCREW WITH COVER L/R	NECESSARY	56.00	56.00
4	FRONT BUMPER PARKING SENSOR 'ORIGINAL'	SHORTED - 2PCS ONLY	857.40	428.70
4	FRONT BUMPER PARKING SENSOR HOLDER	NECESSARY-2PCS ONLY	247.40	123.70
4	FRONT BUMPER PARKING SENSOR RUBBER SEAL	NECESSARY-2PCS ONLY	24.00	12.00
1	SET FRONT BUMPER PARKING SENSOR WIRE HARNESS	NOT NECESSARY	552.83	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	679.20	-
2	FRONT BUMPER REINFORCEMENT BRACKET L/R	NOT NECESSARY	410.66	-
2	FRONT BUMPER SIDE RETAINER L/R	NECESSARY	60.50	60.50
1	FRONT BUMPER TOW HOOK COVER	REUSE	37.85	-
1	FRONT GRILLE	FRACTURED	1,142.53	1,142.53
1	FRONT GRILLE 'LOGO' EMBLEM	NECESSARY	32.82	32.82
1	FRONT GRILLE CHROME MOULDING	FRACTURED	195.00	195.00
10	FRONT GRILLE CLIPS	NECESSARY	65.00	65.00
2	FRONT HEADLAMP CLIPS L/R	NECESSARY	13.00	13.00
2	FRONT HEADLAMP L/R	N/S FRACTURED	5,747.56	2,873.78
2	FRONT HEADLAMP NOZZLE HOSE L/R	NOT NECESSARY	231.50	-
2	FRONT HEADLAMP NOZZLE L/R	NOT NECESSARY	451.36	-
1	REAR BOOTLID	REPAIRED SEE LABOUR	2,412.48	-
1	REAR BOOTLID '2.0' EMBLEM	NECESSARY	81.48	81.48
1	REAR BOOTLID 'A6' EMBLEM	NECESSARY	81.48	81.48
1	REAR BOOTLID 'LOGO' EMBLEM	NECESSARY	105.50	105.50

Report Ref No. CS1/FCI18003653/Cvbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOTLID 'T' EMBLEM	NECESSARY	55.80	55.80
6	REAR BOOTLID HINGES GARNISH CLIPS L/R	NOT NECESSARY	39.00	-
2	REAR BOOTLID HINGES GARNISH L/R	REUSE	52.66	-
2	REAR BOOTLID HINGES L/R	REPAIRED SEE LABOUR	389.66	-
1	REAR BOOTLID INNER HANDLE	REUSE	11.00	-
1	REAR BOOTLID INNER LOCK HANDLE SWITCH	REUSE	157.15	-
1	REAR BOOTLID INNER UPHOLSTERY TRIM	REUSE	658.15	-
1	REAR BOOTLID MECHANISM LOCK	BENT	165.75	165.75
1	REAR BOOTLID MECHANISM LOCK GARNISH	NOT NECESSARY	5.45	-
2	REAR BOOTLID NUMBER PLATE LAMP L/R	REUSE	96.96	-
1	REAR BOOTLID OUTER LOCK HANDLE SWITCH	REUSE	157.15	-
4	REAR BOOTLID REFLECTOR LAMP CLIPS L/R	NECESSARY	26.00	26.00
2	REAR BOOTLID REFLECTOR LAMP GARNISH L/R	REUSE	47.66	-
2	REAR BOOTLID REFLECTOR LAMP L/R	REUSE	47.66	-
4	REAR BOOTLID RUBBER GUIDE STOPPER L/R	DEFORMED	52.00	52.00
1	REAR BOOTLID WEATHERSTRIP	NOT NECESSARY	140.63	-
1	REAR BUMPER	SQUASHED	2,148.23	2,148.23
2	REAR BUMPER CORNER RETAINER L/R	NECESSARY	85.86	85.86
2	REAR BUMPER CORNER RETAINER LOCK CLIPS L/R	NECESSARY	13.00	13.00
1	REAR BUMPER INNER LOWER BOOTLID KICK SENSOR	REUSE	289.33	-
1	RR BUMPER LOWER BOOTLID KICK SENSOR HOLDER	REUSE	61.85	-
1	RR BUMPER INNER LOWER BOOTLID KICK SENSOR MODULE	REUSE	699.70	-
1	REAR BUMPER LOWER DIFFUSER	DEFORMED	284.83	284.83
1	REAR BUMPER REINFORCEMENT	BENT	824.43	824.43
4	REAR BUMPER REVERSE SENSOR 'ORIGINAL'	SHORTED-2PCS ONLY	857.40	428.70
4	REAR BUMPER REVERSE SENSOR HOLDER	NECESSARY-2PCS ONLY	247.40	123.70
4	REAR BUMPER REVERSE SENSOR RUBBER SEAL	NECESSARY-2PCS ONLY	24.00	12.00
1	SET REAR BUMPER REVERSE SENSOR WIRE HARNESS	NOT NECESSARY	552.83	-
2	REAR BUMPER SIDE RETAINER L/R	NECESSARY	52.66	52.66
1	REAR BUMPER TOP RETAINER	DEFORMED	86.35	86.35

Report Ref No. CS1/FCI18003653/Cvbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER TOW HOOK COVER	REUSE	46.73	-
1	REAR END PANEL 'INNER'	REPAIRED SEE LABOUR	621.30	-
1	REAR END PANEL 'OUTER'	REPAIRED SEE LABOUR	424.90	-
1	REAR END PANEL INNER TOP GARNISH	NOT NECESSARY	113.18	-
4	REAR END PANEL INNER TOP GARNISH CLIPS	NECESSARY	26.00	26.00
1	REAR END PANEL LOCK STRIKER WITH MOTOR	NOT NECESSARY	534.40	-
2	REAR TAILLAMP CLIPS L/R	NECESSARY	13.00	13.00
2	REAR TAILLAMP GARNISH L/R	DEFORMED	78.90	78.90
2	REAR TAILLAMP INNER PANEL L/R	REPAIRED SEE LABOUR	1,405.80	-
2	REAR TAILLAMP L/R	NOT NECESSARY	2,128.56	-
2	REAR TAILLAMP LOWER BRACKET L/R	NOT NECESSARY	130.00	-
2	REAR TWIN EXHAUST ALUMINIUM HEAT SHIELD L/R	REUSE	490.00	-
2	REAR TWIN EXHAUST BRACKET	REPAIRED SEE LABOUR	136.96	-
2	REAR TWIN EXHUAUST END CHROME PIPE L/R	DISTORTED	1,358.40	800.00
2	REAR TWIN EXHAUST GASKET	NECESSARY	25.00	25.00
4	REAR TWIN EXHAUST RUBBER MOUNTING	DISTORTED	180.00	180.00
2	REAR TWIN EXHAUST SILENCER BOX L/R	NOT NECESSARY	3,198.86	-
			35,958.95	13,281.50
	<b>SPECIAL NETT ITEMS</b>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT BUMPER NUMBER PLATE (SN)	BENT	25.00	25.00
1	SET REAR BOOTLID INNER UPHOLSTERY TRIM CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR BOOTLID NUMBER PLATE (SN)	REUSE	25.00	-
1	REAR BOOTLID NUMBER PLATE HOLDER (SN)	REUSE	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
			190.00	115.00
	<b>LABOUR</b>			
	TO RESET SYSTEM AFTER REPAIR WORKS.		500.00	250.00

Report Ref No. CS1/FCI18003653/Cvbe2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.		180.00	80.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)		140.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		1,500.00	700.00
	TO RE-SPRAY PAINTING ON THE FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER (L/R) AND FRONT BUMPER.		1,250.00	500.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		160.00	70.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND REALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOTLID, REAR BOOTLID HINGES L/R, REAR END PANEL 'INNER', REAR END PANEL 'OUTER', REAR TAILLAMP INNER PANEL L/R AND REAR TWIN EXHAUST BRACKET.		2,250.00	1,000.00
	TO MOUNT VEHICLE ON THE CAR 'O' LINER.	NOT NECESSARY	400.00	-
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	120.00	-
			6,500.00	2,660.00
<b>GRAND TOTAL</b>			<b>42,648.95</b>	<b>16,056.50</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>12,800.00</b>
---	--	--	------------------

Report Ref No. CS1/FCI18003653/Cvbe2

HO LEONG CHUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.