

MODERN AUTOMOTIVE PTE LTD
 BLK 3023A UBI ROAD 1 # 01-61
 SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 7B Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Asher

Quotation

DATE : 27.02.2018
 VEH NO : SJV9695B
 MODEL : Mazda 3
 D O A : 26.02.2018
 YR REF : SLJ1770J

Attn : Motor Claim Dept (Pis arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJV9695B (Mazda 3)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	947.30
2	Rear Bumper Clips <i>new</i>	1 set	30.00
3	Rear Bumper Side Holder - LH & RH <i>LH Distorted</i>	2	68.00 34.30
4	Rear Bumper Reinforcement <i>Best</i>	1	491.70
5	Rear Bumper Reflector - LH <i>cracked</i>	1	94.60
6	Rear End Panel <i>Distorted</i>	1	365.40
7	Rear End Panel Top Garnish <i>Debond.</i>	1	225.00
8	Taillamp - LH <i>smashed</i>	1	1,038.40
9	Taillamp Panel - LH <i>Distorted</i>	1	102.00
10	Bootlid Reflector - LH <i>cracked</i>	1	297.20
11	Mazda Logo <i>2</i>	1	29.20
12	Mazda Wordling <i>2</i>	1	36.70
13	3 Wordling	1	20.20
14	Speaker Panel <i>Distorted</i>	1	528.10
15	Speaker Panel Top Board <i>pre new</i>	1	295.40 X
16	Rear Fender - LH <i>Distorted</i>	1	995.10
17	Rear Fender Inner Shield - LH <i>new</i>	1	52.80
18	Rear Fender Inner Shield Clips - LH <i>new</i>	1	10.00
19	Rear Fender Inner Trim - LH <i>cracked</i>	1	190.90
20	Rear Fender Inner Trim Clips - LH <i>new</i>	1 set	30.00
21	Rear Fender Wheelhouse - LH <i>Pre</i>	1	953.30 X
22	Spare Tyre Panel Top Cover <i>new</i>	1	380.50 X
23	Rear Exhaust Pipe <i>not new</i>	1	953.80 X
24	Rear Exhaust Mounting <i>not new</i>	1	45.50 X
25	Rear Door - LH <i>Distorted.</i>	1	1,119.30
26	Rear Door Lock - LH <i>Jammed</i>	1	183.00
27	Rear Door Weatherstripe - LH <i>cut</i>	1	128.90

RE: ESTIMATE FOR ACCIDENT REPAIR SJV9695B (Mazda 3)

28	Rear Door Hinge - LH <i>Not New</i>	1	74.80 X
29	Rear Door Outer Handle - LH <i>Damaged</i>	1	259.80 ✓
30	Rear Door Inner Trim Board - LH <i>Cracked</i>	1	723.00 ✓
31	Rear Door Inner Trim Board Clips - LH <i>New</i>	1 set	30.00 ✓
32	Rear Door Glass Outer Moulding - LH <i>Bent</i>	1	75.10 ✓
33	Rear Door Glass Regulator Gear - LH <i>Damaged</i>	1	215.20 ✓
34	Front Door - LH <i>Repair</i>	1	982.40 X
35	Front Door Lock - LH <i>Not New</i>	1	183.00 X
36	Front Door Weatherstripe - LH	1	118.90 X
37	Rear Windscreen Moulding <i>New</i>	1	100.10 ✓
38	Rear Wheel Rim - LH <i>Cracked</i>	1	1,055.90 <i>(600.00)</i>
39	Rear Shock Absorber - LH <i>Bent</i>	1	325.20 ✓
40	Rear Lower Arm - LH <i>Bent</i>	1	263.50 ✓
41	Rear Knuckle Arm - LH <i>Bent</i>	1	485.70 ✓
42	Rear Wheel Hub c/w Bearing - LH <i>Damaged</i>	1	352.90 ✓
43	Rear Control Arm - LH <i>Bent</i>	1	163.80 ✓
44	Rear Stay Arm - LH	1	195.90 ✓
45	Rear Cross Member <i>Bent</i>	1	1,043.00 ✓
46	Front Bumper <i>Distorted</i>	1	966.70 ✓
47	Front Bumper Clips <i>New</i>	1 set	30.00 ✓
48	Front Bumper Side Holder - LH & RH <i>LH Damaged</i>	2	58.80 <i>2840</i>
49	Front Bumper Reinforcement <i>Bent</i>	1	382.70 ✓
50	Front Bumper Tow Cover <i>Distorted</i>	1	25.50 ✓
51	Front Bumper Logo <i>New</i>	1	34.30 ✓
52	Front Bumper Grille <i>Cracked</i>	1	216.30 ✓
53	Front Bumper Fog Lamp Cover - LH <i>Deformed</i>	1	78.50 ✓
54	Front Bumper Fog Lamp Cover Inner Garnish - LH <i>New</i>	1	35.40 X
55	Front Bumper Grille Lower Garnish - LH <i>Deformed</i>	1	39.50 ✓
56	Front Bumper Grille Upper Garnish - LH <i>Deformed</i>	1	42.10 ✓
57	Front Bumper Lower Centre Garnish	1	202.40 ✓
58	Headlamp - LH & RH <i>Both Cracked</i>	2	4,584.00 <i>2292</i>
59	Bonnet <i>Repair</i>	1	954.60 X
60	Bonnet Lock <i>New</i>	1	98.80 X
61	Bonnet Hinge <i>New</i>	1	97.00 X
62	Front Fender - LH <i>Repair</i>	1	482.10 X
63	Front Fender Inner Shield - LH <i>New</i>	1	158.10 X
64	Front Fender Inner Shield Clips - LH <i>New</i>	1 set	30.00 X
65	Front Support Panel <i>Cracked</i>	1	447.60 ✓
66	Air Con Condenser <i>New</i>	1	858.90 X
67	Radiator <i>New</i>	1	1,962.70 X
			28,041.70
	Less 20%		(5,608.34)
			\$ 22,433.36

S/NET ITEMS

1	Reverse Sensor <i>Damaged</i>	\$	280.00 <i>200</i>
---	-------------------------------	----	------------------------------

RE: ESTIMATE FOR ACCIDENT REPAIR SJV9695B (Mazda 3)

2	Rear End Panel Sealant <i>NEW</i>	\$	60.00 ✓
3	Rear Door Black Tape - LH <i>NEW</i>	\$	60.00 ✓
4	Front Door Black Tape - LH <i>NEW</i>	\$	60.00 ✓
5	Rear Windscreen Sealant <i>NEW</i>	\$	60.00 ✓
6	Rear Tyre - LH <i>Purchased</i>	\$	280.00 200
7	Front Number Plate <i>Painted</i>	\$	30.00 ✓
8	Front Number Plate Holder <i>Painted</i>	\$	30.00 ✓
Total Parts		\$	23,293.36

LABOUR CHARGE

1	To knocking & pull out front & rear portion & renew above parts	\$	3,200.00 2000
2	To putty & spray up paint works	\$	2,200.00 1800
3	To check wiring	\$	150.00 60
4	To underseal	\$	250.00 120
5	To remove upholstery	\$	150.00 80
6	To remove reverse sensor	\$	100.00 50
7	To remove exhaust pipe	\$	180.00 80
8	To transfer front & rear LH door fittings	\$	300.00 80
9	To remove rear windscreen	\$	180.00 120
10	To perform wheel alignment	\$	150.00 80
11	To dismantle rear undercarriage	\$	450.00 220
12	To remove condenser, radiator & to re-gas	\$	180.00 120
13	Towing Fees <i>5010</i>	\$	120.00 ✓
14	To remove fuel tank	\$	150.00 80
Total Labour		\$	7,760.00

Grand Total \$ 31,053.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey by independent valuer
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party suit on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

NOTE

Acknowledged by Repairer
 Signature:
 Date:

total 1910464
 h/s LSK
 18 Days

RE : ESTIMATE FOR ACCIDENT REPAIR SJV9695B (Mazda 3)

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8776E
Vehicle Details	
Vehicle No.:	SJV9695B
Vehicle to be Exported:	Yes
Intended De-registration Date:	27 Feb 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 1.6L SDN
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	Z6842464
Chassis No.:	JM6BL10Z1A0136427
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$20,031.00
Original Registration Date:	25 Feb 2010
First Registration Date:	25 Feb 2010
Transfer Count:	2
Actual ARF Paid:	\$20,031.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Feb 2020
PARF Rebate Amount:	\$11,017.00
Intended COE Rebate Details	
COE Expiry Date:	24 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,340.00
COE Rebate Amount:	\$4,060.00
Total Rebate Amount:	\$15,077.00

The information contained herein is correct as at 27 Feb 2018

OK



SELL YOUR CAR BY BIDDING
HIGHEST SELLING PRICE GUARANTEED!
OR GET \$100 CASH!



Mazda 3 Price Range Depreciation 2010 Vehicle Type 

Advanced Search

Used Car Comparison

— Comparing 4 Vehicles —

Mazda 3 1.6A

Mazda 3 1.6A SP

Mazda 3 1.6A

Mazda 3 1.6A Luxury



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

CAR DETAILS

	Mazda 3 1.6A	Mazda 3 1.6A SP	Mazda 3 1.6A	Mazda 3 1.6A Luxury
Price	\$32,800	\$29,800	\$33,000	\$30,800
Instalment	\$1,014	\$886	\$981	\$916
Registration Date	26-Mar-2010	29-Mar-2010	31-Mar-2010	29-Mar-2010
Manufactured	2009	2010	2009	2009
Mileage	118,500 km	-	108,038 km	-
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,598 cc	1,598 cc	1,598 cc	1,598 cc
Road Tax	\$742 /yr	\$742 /yr	\$742 /yr	\$742 /yr
Power	77.0 kW (103 bhp)	77.0 kW (103 bhp)	77.0 kW (103 bhp)	77.0 kW (103 bhp)
Curb Weight	1,275 kg	1,275 kg	1,275 kg	1,275 kg
Features	Powerful And Fuel Efficient 1.6L DOHC 16V VVT Engine, 4 Speed Automatic Steptronic Transmission, 2 x SRS Airbags, ABS, Keyless Entry And Push Start.	1.6L DOHC VVT Engine, 4 Speed Tiptronic Smooth Automatic Transmission, Multi Function Steering Wheel, Keyless Entry/Start.	-	Smooth, Steering C Airbags.
Accessories	Auto Headlights, Rain Sensors, Reverse Sensor, Factory Fitted Audio System, Solar Film, Electric Retractable Side Mirrors, Upholstery Leather Seats.	Sports Rims, Leather Seats, Solar Film, Reverse Sensors, Original Factory, Factory Fitted Audio Player, Retractable Side Mirrors.	-	Sports Rims, Leath Controls, Reverse ! And Boot Release.
Description	Call Now For Viewing.	Well Maintained, Supreme Condition, Trade In And In House Loan Available, Call Our Friendly Salesman To View Now!	1 Owner, Mileage 14000Km Per Year, Excellent Condition, Please Kindly Call For More Information.	Pearl White Color! Of By Previous Ow Down Payment, Up Loan, We Provide Flexible Loan And I Available, Package Warranty Complete Test Report, Check Now, Meet Our Fri An Non Obligation
COE	\$20,802	\$28,389	\$28,389	\$28,389
OMV	\$20,611	\$20,483	\$20,573	\$21,468
ARF	\$20,611	\$20,483	\$20,573	\$21,468
Depreciation	\$10,850 /yr	\$9,390 /yr	\$10,880 /yr	\$9,640 /yr
No. of Owners	2	2	1	1
Type of Vehicle	Sedan	Sedan	Sedan	Sedan
Category	PARF Car, Premium Ad Car	PARF Car	PARF Car	PARF Car
Availability	Available	Available	Available	Available

SELLER INFORMATION

Auto Mart (P) Ltd

Auto Mart (P) Ltd

Auto Mart (P) Ltd

Auto Mart (P) Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18003677/eb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 26-02-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLJ 1770J	Veh. Inspected	SJV 9695B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/02/2018	Inspection Date	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 1 March 2018 10:35 AM
To: Shu Pei (LKKAuto); Chin
Cc: Admin A; Vic (LKKAuto)
Subject: RE: TP Claim SJV9695B & SLJ1770J (AIG) ***LKK REF:CC6/AIG18003677/Aeb3

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents for us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher@sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)
Sent: Thursday, 1 March 2018 10:28 AM
To: Chin <chin@modernautomotive.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>
Subject: RE: TP Claim SJV9695B & SLJ1770J (AIG) ***LKK REF:CC6/AIG18003677/Aeb3

Dear Grace,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Asher,

For your information and necessary action please.

To check availability of the case handler , you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chin [<mailto:chin@modernautomotive.com.sg>]

Sent: Thursday, 1 March 2018 10:07 AM

To: Admin A <admin-a@lkkauto.com>

Subject: RE: TP Claim SJV9695B & SLJ1770J (AIG)

Dear Sir/ Madam

Please advise case handler for liability.

Thank you

Regards,

Grace Chin

Modern Automotive Pte Ltd

Blk 3023-A, Ubi Road I #01-61

Singapore 408717

Tel: 6748 4422

Fax: 6747 6720

From: Meei Huey [<mailto:meeihuey@modernautomotive.com.sg>]

Sent: Monday, 26 February, 2018 5:33 PM

To: admin-a@lkkauto.com

Cc: Chin <chin@modernautomotive.com.sg>

Subject: TP Claim SJV9695B & SLJ1770J (AIG)

Dear Sir/Madam

We refer to the above matter.

Kindly advise liability for our vehicle below:

Your Insured: SLJ1770J

Our Insured: SJV9695B

DOA: 26.02.2018

Do also advise on the case officer-in-charge.

Thank you.

Regards,

Mei

Modern Automotive Pte Ltd | MM Trading Enterprise

Blk 3023A Ubi Road 1 #01-61 S(408717)

Tel: 6744 4422 / 8121 3226

Fax: 6747 6720

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 31 May 2018 2:36 PM
To: 'Tan, Bennie-WZ'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: [MANDATE REQUEST] 5935621567SG, ACCIDENT ON 26/02/2018 INVOLVING SLJ 1770J (OI) & SJV 9695B (TP)

Your ref : **5935621567SG**
Our ref : CC6/AIG18003677/Aeb3

Dear Sirs,

ACCIDENT ON 26/02/2018 INVOLVING SLJ 1770J (OI) & SJV 9695B (TP)

We refer to the above matter.

The said chain collision involved 4 vehicles whereby our insured swerved into tp lane.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) maybe affected.

We seek your approval to offer repairer " **MODERN AUTOMOTIVE PTE LTD**" at **\$ 18,358.25 (all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 33,227.10	\$ 16,050.00
2. Loss of Rental (21days x \$120)	\$ 2,520.00	\$ 2,100.00 (21days x \$100)
3. LTA Search Fee	\$ 2.00	\$ 2.00
4. Medical Fee	\$ 206.25	\$ 206.25
Total	\$ 35,955.35	<u>\$ 18,358.25</u>

MARKET VALUE:	\$ 30,100
LTA REBATE:	\$ 15,077
NETT VALUE:	\$ 15,023

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

Print Received Message

This mail is associated with :

***SJV9695B (5935621567SG)
[SLJ1770J]**

TP
NG YEOW CHOI
Feb 26 2018 8:00AM
[Lim Sin Yue (Lin Xinyi)]
Modern Automotive Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 08/06/2018 18:18 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$17800.00) - SJV9695B - Claim Handler: Tan, Bennie-WZ

Approved:17800.00:***Subject to Final Repair Bill, Rental Bill & Agreement, GIA Search Bill ***Note: Medical expenses been settled by Injury Team

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Wednesday, 20 June 2018 10:51 AM
To: 'Tan, Bennie-WZ'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: RE: [MANDATE REQUEST] 5935621567SG, ACCIDENT ON 26/02/2018 INVOLVING SLJ 1770J (OI) & SJV 9695B (TP)
Attachments: EMAIL FROM TP WSP.pdf

Hi Bennie,

We refer to the above matter.

Third party disagreed with our offer and counter proposed G/S \$18,150 without medical fee.

Please kindly advise.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asher Sng (LKKAuto)
Sent: Thursday, 31 May 2018 2:36 PM
To: 'Tan, Bennie-WZ' <Bennie-WZ.Tan@aig.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Subject: [MANDATE REQUEST] 5935621567SG, ACCIDENT ON 26/02/2018 INVOLVING SLJ 1770J (OI) & SJV 9695B (TP)

Your ref : **5935621567SG**

Our ref : CC6/AIG18003677/Aeb3

Dear Sirs,

ACCIDENT ON 26/02/2018 INVOLVING SLJ 1770J (OI) & SJV 9695B (TP)

We refer to the above matter.

The said chain collision involved 4 vehicles whereby our insured swerved into tp lane.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) maybe affected.

We seek your approval to offer repairer " **MODERN AUTOMOTIVE PTE LTD**" at **\$ 18,358.25 (all-in)**.

Print Received Message

This mail is associated with :

***SJV9695B (5935621567SG)**
[SLJ1770J]

TP
NG YEOW CHOI
Feb 26 2018 8:00AM
[Lim Sin Yue (Lin Xinyi)]
Modern Automotive Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 06/08/2018 10:52 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$18000.00) - SJV9695B - Claim Handler: Tan, Bennie-WZ

Approved:18000.00:Strictly for amicable settlement and not to protract matter further, please do your utmost to negotiate settlement at best: \$18,000 (Global All-in). ***Note: Medical expenses been settled by Injury Team

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 #01 - 61
SINGAPORE 408717
GST REG. NO : 200501102H
TEL : 6748-4422/ 6745-4422 FAX : 6-747- 6720
Email: chin@modernautomotive.com.sg

Your Ref : SLJ1770J
Our Ref : SJV9695B

Date : 12.04.2018

The Claims Manager
AIG Asia Pacific Insurance Pte Ltd
AIG Building
78, Shenton Way #07-16
Singapore 079120
Tel : 6-419-300 Fax : 6-415-3727

Attn : The Motor Claim Dept

RE : ACCIDENT INVOLVING SJV9695B & SLJ1770J ON 26.02.2018
ALONG KJE AROUND THE 6.5KM MARK


We refer to the above matter.

We have been authorized by our client Mr Ng Yeow Choi to make claim against your insured vehicle No. SLJ1770J in respect of the above accident for the following :

Repair Cost	\$ 16,050.00 (Incl GST)
Loss of rental (\$120 x 21 days)	\$ 2,520.00
Search fee	\$ 2.00
Medical Fee	\$ 206.25 (Chong Geok Lan, Maria)
Total :	\$ 18,778.25

Enclosed herewith a copy each of the supporting documents for your perusal.
Kindly process the above and remit the payment to us asap

Yours faithfully



Modern Automotive Pte Ltd

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 9 March 2018 2:32 PM
To: 'ERICSTGAN@GMAIL.COM'
Subject: ACCIDENT INVOLVING SLJ 1770J AND SJV 9695B / OTHERS ON 26/02/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18003677/Aeb3

09 MAR 2018

LIM SIN YUE / GAN SHI THONG

Dear Sir/Madam,

ACCIDENT INVOLVING SLJ 1770J AND SJV 9695B / OTHERS ON 26/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORIZATION

Date: 26/2/18

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SJV9695B & SLJ1770J & SJT1941D


ON 26/2/18 ALONG KJE Around the 6.5 km
mark

This letter is to authorize **MODERN AUTOMOTIVE PTE LTD** at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, **MODERN AUTOMOTIVE PTE LTD** has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of **MODERN AUTOMOTIVE PTE LTD**.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully


.....
Signature of Owner

Ng Yeow Choj S6918776E
Name / NRIC

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, MODERN AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$18,000.00 (Global Sum) for vehicle no. SJV 9695B that was damaged pursuant to the accident which occurred on 26/02/2018 (date) along KJE AROUND THE 6.5KM MARK involving vehicle no/s SLJ 1770J.

This is pursuant to the inspection conducted on 27/02/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner NG YEOW CHOI ("the third party claimant") of vehicle no. SJV 9695B make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJV 9695B (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in ~~full and final~~ ^{property damage} settlement of ~~any~~ claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 07 (day) of August (month) 2018 (year)



LWP

Signed by appointed surveyor



Signed by "the workshop" (with chop)

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01-58 / 61 SINGAPORE 408717
TEL : 67474422, 67454422 FAX : 67476720
GST REG. NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
SINGAPORE 079120

Attention : Motor Claim Department
Contact : 6415-3727 6419-3000


Tax Invoice : TP001168

Date : 05/04/2018
Vehicle Num. : SJV 9695B
Make/Model : MAZDA 3-2010
Chassis/Eng# :
Accident Date : 26/02/2018
Claim No. :
Reference : CC6/AIG18003677/Aeb3
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR : ACCIDENT REPAIR (LUMPSUM)		15,000.00
		Labour Total S\$:		15,000.00

Total S\$:	15,000.00
GST @ 7% S\$:	1,050.00
Amount Due S\$:	16,050.00

=====


MODERN AUTOMOTIVE PTE LTD



DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1
SINGAPORE 798125
TEL: 6383 2661 FAX: 6484 2836
REG. NO. 430058/00D

No. 19218

Date, 22/2/18

OFFICIAL RECEIPT

Received from Ng Yeow Chai

the sum of Dollars Two thousand five hundred twenty

only only
being Payment Of S\$ 4897E (1/3/18 - 22/3/18)

DAWN ENTERPRISES

\$ 2520/2
Cash/Cheque No.



SJV 9695 B



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

N^o 34594

[Signature]
DATE 1/3/18

RENTAL AGREEMENT

HIRER'S PARTICULARS

Name Ng Yeow Choi
Address Blk 256, Compassvale Road, #07-676
Sipore 540256
I/C or Passport No. 6918776E Country _____
Occupation _____
Date of Birth _____ Age _____
Driving Licence No. _____ Date Passed _____
Tel: (HP) 97491456 (Residence) _____

DRIVER'S PARTICULARS

Name _____
Address _____
I/C or Passport No. _____ Country _____
Occupation _____
Date of Birth _____ Age _____
Driving Licence No. _____ Date Passed _____
Tel: (Office) _____ (Residence) _____

IMPORTANT NOTES:			CHARGES	
1. No insurance coverage if the driver is below 24 yrs old or less than 2 years driving licence. 2. This vehicle is licensed to carry ⁰⁴ passengers only. 3. Hirer is liable to pay first \$ <u>2000</u> all excess all claims any accident plus loss of earning while damaged vehicle is under repair. 4. For usage in Malaysia subject to higher excess all claims of \$55,000.00 and different rental rate. 5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs. 6. No refund will be given for vehicle returns early. 7. No refund will be given for petrol left in vehicle. 8. Hirer is liable to pay all parking fee and traffic summonses. 9. Vehicles to be return during office hour only. 10. No Service on Public Holiday and Sunday.			21 Day at \$ <u>20.00</u> per days	\$ <u>2520.00</u>
			Day at \$ _____ per week	
			Day at \$ _____ per month	
			TOTAL AMOUNT	\$ <u>2520.00</u>
			AMOUNT PAID	\$ <u>2520.00</u>
			BALANCE DUE	
			Days Extension From _____ To _____	
			Amount Deposit (refundable) \$ _____	
SCHEDULE SKH 4897E MODEL T/A/H/1				
Date	Time	Mileage		
<u>1/3/18</u>	<u>5:15pm</u>			
<u>22/3/18</u>				
FROM <u>1/3/18</u>			TO <u>22/3/18</u>	

I've have read and understood the terms and conditions above and hereby agreed to abide

[Signature]
Hirer's Signature

Driver/Gurantor's Signature

[Signature]
DAWN ENTERPRISES



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-029760
Date of Request: 26/02/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-58
Singapore 408717

Dear Sir/Madam,

Enquiry Date 26/02/2018
Enquiry By Ho Meei Huey
TP Vehicle No. SLJ1770J
Accident Date 26/02/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLJ1770J	AIG Asia Pacific Insurance Pte. Ltd.	22/10/2017-21/10/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-029760
Date of Request: 26/02/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-58
Singapore 408717

Dear Sir/Madam,

Enquiry Date 26/02/2018
Enquiry By Ho Meel Huey
TP Vehicle No. SLJ1770J
Accident Date 26/02/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Feb 2018 Edit Reg		27 Feb 2018 00:00 Edit Adj Rpt	S\$15,000.00 Edit Estimates	S\$15,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Lim Sin Yue (Lin Xinyi), ID: S7806190A								
Main Claimant:	NG YEOW CHOI, ID: S6918776E								
Vehicle Reg. No.:	SJV9695B	Date of Loss:	26/02/2018 08:00 - :59 [96 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5935621567SG	Policy/Cover Note No.:	2100491650 (Comprehensive) Coverage: 22/10/2017 - 21/10/2018						
Vehicle Reg. No. [Insured]:	SLJ1770J	Policy No. (Claimant):	5095461194						
Excess:									
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • AIG_SG_EXPRESS (06/08/2018): Alert - Adj Mandate Approved (S\$18000.00) - SJV9695B - Claim Handler: Tan, Benni... • AIG_SG_EXPRESS (08/07/2018): Alert - Adj Mandate Maintained - SJV9695B - Claim Handler: Tan, Bennie-WZ • AIG_SG_EXPRESS (29/06/2018): Alert - Adj Mandate Maintained - SJV9695B - Claim Handler: Tan, Bennie-WZ • AIG_SG_EXPRESS (08/06/2018): Alert - Adj Mandate Approved (S\$17800.00) - SJV9695B - Claim Handler: Tan, Benni... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV9695B (59356215675G)
 [SLJ1770J]
 TP
 NG YEOW CHOI
 Feb 26 2018 8:00AM
 [Lim Sin Yue (Lin Xinyi)]
 Modern Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>	
Letters/Correspondences														1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit			
Assessment Reports														1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print			
1	27/02/18 13:09	Accident Statement <small>From: SC - Reg. No: SLJ1770J, Claimant: LIM SIN YUE</small>											Load HTM			
Photos/Images														3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
2	11/04/18 01:26	Chassis Number											Load JPG	<input checked="" type="checkbox"/>		
3	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
4	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
5	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
6	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
7	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
8	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
9	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
10	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
11	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
12	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
13	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
14	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
15	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
16	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
17	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
18	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
19	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
20	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
21	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
22	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
23	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
24	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
25	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
26	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
27	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
28	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
29	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		
30	11/04/18 01:26	General View											Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
32	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
33	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
34	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
38	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
46	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
47	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
48	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
49	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
50	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
51	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
52	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
53	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
54	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
55	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
56	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
57	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
58	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
59	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
60	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
61	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
62	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
63	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
64	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
65	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
66	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
67	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
68	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
69	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
70	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
71	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
72	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
73	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
74	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
75	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
76	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
77	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
78	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
79	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
80	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
82	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
83	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
84	11/04/18 01:26	General View	 Load JPG	<input checked="" type="checkbox"/>
85	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	11/04/18 01:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
131	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
132	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
133	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
134	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
135	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
136	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
137	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
138	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
139	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
140	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
141	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
142	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
143	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
144	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
145	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
146	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
147	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
148	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
149	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
150	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
151	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
152	11/04/18 01:27	Reinspection Photo		<input checked="" type="checkbox"/>
153	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
154	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
155	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
156	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
157	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
158	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
159	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
160	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
161	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
162	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
163	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
164	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
165	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
166	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
167	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
168	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
169	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
170	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
171	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
172	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
173	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
174	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
175	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
176	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
177	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
178	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
179	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
180	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
181	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
182	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
183	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
184	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
185	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
186	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
187	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
188	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
189	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
190	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
191	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
192	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
193	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
194	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
195	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
196	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
197	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
198	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
199	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
200	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
201	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
202	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
203	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
204	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
205	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
206	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
207	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
208	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
209	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
210	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
211	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
212	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
213	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
214	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
215	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
216	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
217	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
218	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
219	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
220	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
221	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
222	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
223	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
224	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
225	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
226	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
227	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
228	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>
229	11/04/18 01:28	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/18 19:55	TP GIA REPORT	Load PDF	
2	09/03/18 14:41	LETTER TO OI	Load PDF	
3	21/05/18 12:01	RENTAL RECEIPT	Load PDF	
4	21/05/18 12:01	MEDICAL FEE	Load PDF	
5	21/05/18 12:01	GIA SEARCH	Load PDF	
6	31/05/18 14:35	LTA PARF COE Rebate Details	Load PDF	
7	20/06/18 10:49	EMAIL FROM TP WSP	Load PDF	
8	14/08/18 14:16	WORKSHOP INVOICE	Load PDF	
9	14/08/18 14:16	AUTHORISATION TO ACT FORM	Load PDF	
10	14/08/18 14:16	Release Voucher	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLJ1770J (Insd veh)	Model:	MAZDA 3 1.6 L (A)
	SJV9695B (TP veh)		
Date of Accident:	26/02/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	33,227.10
Final Repair Cost	:	\$	18,000.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	21 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	18,000.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100____(%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____(%)		Assessed Liability (*): _____ 100____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Modern Automotive Pte Ltd	:	\$ 18,000.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

14 Aug
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18003677/AEB3Q2

Date: 14/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100491650
 Claimant Vehicle No: SJV9695B Insured Vehicle No: SLJ1770J
 Date of Loss: 26/02/2018 Nature of Claim: TP Claim No: 5935621567SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV9695B**
 Make & Model: MAZDA 3, 1.6 L (A) Engine No: Z8842464
 Reg. Date: 25/02/2010 (Man. Year: 2009) Chassis No: JM6BL10Z1A0136427
 Colour: Red Odometer: 65651 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	23,293.36	14,094.64	9,198.72	39.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,760.00	5,010.00	2,750.00	35.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,053.36	19,104.64	11,948.72	38.48
Approved Total (Overridden) (S\$)		15,000.00		
(S\$)	31,053.36	15,000.00	16,053.36	51.70
+ GST 7.00/7.00% (S\$)	2,173.74	1,050.00	1,123.74	51.70
Nett Amount (S\$)	33,227.10	16,050.00	17,177.10	51.70
+ Car Rental (21.0 x S\$100.00/day) (S\$)		2,100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		18,152.00		
Global Sum Settlement (S\$)		18,000.00		

INSPECTION

Date of Assignment: 27/02/2018
 Date Inspected: 27/02/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 18.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	947.30 FL	*947.30 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	1		*REAR BUMPER SIDE HOLDER-LH & RH	N/S Distorted	68.60 FL	*34.30 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	491.70 FL	*491.70 FL
5	1		*REAR BUMPER REFLECTOR -LH	Cracked	94.60 FL	*94.60 FL
6	1		*REAR END PANEL	Distorted	365.40 FL	*365.40 FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	225.00 FL	*225.00 FL
8	1		*TAILLAMP -LH	Smashed	1,038.40 FL	*1,038.40 FL
9	1		*TAILLAMP PANEL -LH	Distorted	102.00 FL	*102.00 FL
10	1		*BOOTLID REFLECTOR -LH	Cracked	297.20 FL	*297.20 FL
11	1		*MAZDA LOGO	Necessary	29.20 FL	*29.20 FL
12	1		*MAZDA WORDING	Necessary	36.70 FL	*36.70 FL
13	1		*3 WORDING	Necessary	20.20 FL	*20.20 FL
14	1		*SPEAKER PANEL	Distorted	528.10 FL	*528.10 FL
15	1		*SPEAKER PANEL TOP BOARD	Not Necessary	295.40 FL	*- FL
16	1		*REAR FENDER -LH	Distorted	995.10 FL	*995.10 FL
17	1		*REAR FENDER INNER SHIELD -LH	Torn	52.80 FL	*52.80 FL
18	1		*REAR FENDER INNER SHIELD CLIPS-LH	Necessary	10.00 FL	*10.00 FL
19	1		*REAR FENDER INNER TRIM -LH	Crumpled	190.90 FL	*190.90 FL
20	1		*SET REAR FENDER INNER TRIM CLIPS -LH	Necessary	30.00 FL	*30.00 FL
21	1		*REAR FENDER WHEELHOUSE -LH	Repair	953.30 FL	*- FL
22	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	380.50 FL	*- FL
23	1		*REAR EXHAUST PIPE	Not Necessary	953.80 FL	*- FL
24	1		*REAR EXHAUST MOUNTING	Not Necessary	45.50 FL	*- FL
25	1		*REAR DOOR -LH	Distorted	1,119.30 FL	*1,119.30 FL
26	1		*REAR DOOR LOCK -LH	Jammed	183.00 FL	*183.00 FL
27	1		*REAR DOOR WEATHERSTRIPE-LH	Cut	128.90 FL	*128.90 FL
28	1		*REAR DOOR HINGE -LH	Not Necessary	74.60 FL	*- FL
29	1		*REAR DOOR OUTER HANDLE -LH	Damaged	259.80 FL	*259.80 FL
30	1		*REAR DOOR INNER TRIM BOARD -LH	Cracked	723.00 FL	*723.00 FL
31	1		*SET REAR DOOR INNER TRIM BOARD CLIPS -LH	Necessary	30.00 FL	*30.00 FL
32	1		*REAR DOOR GLASS OUTER MOULDING -LH	Deformed	75.10 FL	*75.10 FL
33	1		*REAR DOOR GLASS REGULATOR GEAR-LH	Damaged	215.20 FL	*215.20 FL
34	1		*FRONT DOOR -LH	Repair	982.40 FL	*- FL
35	1		*FRONT DOOR LOCK -LH	Not Necessary	183.00 FL	*- FL
36	1		*FRONT DOOR WEATHERSTRIP -LH	Not Necessary	118.90 FL	*- FL
37	1		*REAR WINDSCREEN MOULDING	Necessary	100.10 FL	*100.10 FL
38	1		*REAR WHEEL RIM -LH	Cut	844.72 FS	*680.00 FS
39	1		*REAR SHOCK ABSORBER -LH	Bent	326.20 FL	*326.20 FL
40	1		*REAR LOWER ARM -LH	Bent	263.50 FL	*263.50 FL
41	1		*REAR KNUCKLE ARM -LH	Bent	485.70 FL	*485.70 FL
42	1		*REAR WHEEL HUB C/W BEARING-LH	Damaged	352.90 FL	*352.90 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR CONTROL ARM-LH	Bent	163.80 FL	*163.80 FL
44	1		*REAR STAY ARM-LH	Bent	195.90 FL	*195.90 FL
45	1		*REAR CROSS MEMBER	Bent	1,043.00 FL	*1,043.00 FL
46	1		*FRONT BUMPER	Distorted	966.70 FL	*966.70 FL
47	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
48	1		*FRONT BUMPER SIDE HOLDER -LH & RH	N/S Damaged	56.80 FL	*28,40 FL
49	1		*FRONT BUMPER REINFORCEMENT	Bent	382.70 FL	*382.70 FL
50	1		*FRONT BUMPER TOW COVER	Distorted	25.50 FL	*25.50 FL
51	1		*FRONT BUMPER LOGO	Necessary	34.30 FL	*34.30 FL
52	1		*FRONT BUMPER GRILLE	Cracked	216.30 FL	*216.30 FL
53	1		*FRONT BUMPER FOG LAMP COVER -LH	Deformed	76.50 FL	*76.50 FL
54	1		*FRONT BUMPER FOG LAMP COVER INNER GARNISH -LH	Not Necessary	35.40 FL	*- FL
55	1		*FRONT BUMPER GRILLE LOWER GARNISH -LH	Deformed	39.50 FL	*39.50 FL
56	1		*FRONT BUMPER GRILLE UPPER GARNISH -LH	Deformed	42.10 FL	*42.10 FL
57	1		*FRONT BUMPER LOWER CENTRE GARNISH	Deformed	202.40 FL	*202.40 FL
58	1		*HEADLAMP -LH & RH	N/S Cracked	4,584.00 FL	*2,292.00 FL
59	1		*BONNET	Repair	954.60 FL	*- FL
60	1		*BONNET LOCK	Not Necessary	96.60 FL	*- FL
61	1		*BONNET HINGE	Not Necessary	97.00 FL	*- FL
62	1		*FRONT FENDER -LH	Repair	482.10 FL	*- FL
63	1		*FRONT FENDER INNER SHIELD -LH	Not Necessary	158.10 FL	*- FL
64	1		*SET FRONT FENDER INNER SHIELD CLIPS -LH	Not Necessary	30.00 FL	*- FL
65	1		*FRONT SUPPORT PANEL	Cracked	447.60 FL	*447.60 FL
66	1		*AIR CON CONDENSER	Not Necessary	858.90 FL	*- FL
67	1		*RADIATOR	Not Necessary	1,962.70 FL	*- FL
68	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
69	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
70	1		*REAR DOOR BLACK TAPE-LH	Necessary	60.00 FS	*60.00 FS
71	1		*FRONT DOOR BLACK TAPE-LH	Not Necessary	60.00 FS	*- FS
72	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
73	1		*REAR TYRE -LH	Punctured	280.00 FS	*200.00 FS
74	1		*FRONT NUMBER PLATE	Cracked	30.00 FS	*30.00 FS
75	1		*FRONT NUMBER PLATE HOLDER	Cracked	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,690.52	17,288.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,397.16	3,193.66
Total Parts (\$\$)	23,293.36	14,094.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT FRONT & REAR PORTION & RENEW ABOVE PARTS	New	3,200.00	2,000.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	2,200.00	1,800.00
3	TO CHECK WIRING	New	150.00	60.00
4	TO UNDERSEAL	New	250.00	120.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE EXHAUST PIPE	New	180.00	80.00
8	TO TRANSFER FRONT & REAR LH DOOR FITTINGS	New	300.00	80.00
9	TO REMOVE REAR WINDSCREEN	New	180.00	120.00
10	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
11	TO DISMANTLE REAR UNDERCARRIAGE	New	450.00	220.00
12	TO REMOVE CONDENSER ,RADIATOR & TO RE-GAS	New	180.00	120.00
13	TOWING FEES	New	120.00	120.00
14	TO REMOVE FUEL TANK	New	150.00	80.00
Gross Labour Cost (S\$)			7,760.00	5,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >