OPTIMA WERKZ PTE LTD

Tel: +65 6472 1313 Fax: +65 6472 2112 Head office : 6 Kung Chong Road Singapore 159143 Branch office: 9A Serangoon North Ave 5 Singapore 554500 Tel: +65 6484 9919 Fax: +65 6481 1011

Co. Reg. No. 201212455W

Date:

05 March 2018

Vehicle No:

SLQ7585B

Model: Chassis: MERCEDES BENZ CLA 180 WDD1173422N492324

Third Party Insurer:

Third Party Veh No: Date of Accident:

SJH8800U

AIG

04/02/2018

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR BUMPER		M \$1,120.00
1	REAR BUMPER LOWER DIFFUSER		Rc \$279.00
1	REAR BUMPER CHROME MOULDING		M \$155.00
10	REAR BUMPER CLIP	\$9.00	ルル \$90.00
10	REAR BUMPER RIVET	\$9.00	~~ \$90.00
1	REAR BUMPER EXHAUST END CHROME PIPE RH		\$286.00
1	REAR BUMPER EXHAUST END CHROME PIPE BRACKET RH		\$66.00
		SUB TOTAL	\$2,086.00
		Less 10%	-\$208.60
		PARTS TOTAL	\$1,877.40

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

\$750.00 2001

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$350.00 2501

TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD

NA \$280.00 X

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR

NA \$80.00 X

TO CHECK WIRING WITH TEST

12 \$60.00 X

LABOUR TOTAL

\$1,520.00

WINSON

TOTAL

\$3,397.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Not Norhashed Runny After Paint 2 days