

ASS. REC. BY:

REF: CS3/SMO18003690/8d3524 Special Instruction:

Surveyor: Sebastian

ASSIGNMENT (Office)

From (Person): Grace Teo of SMO Date/Time: 26/2/18 @ 10:25am

Estimated Cost: _____ Bill to: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FBD 3246 T Insured: SKR 723 Yat Workshop m/s Lian Chin Heng Tel: 8200 8888of Blk 22, Woodlands Link # 01-35Policy No: _____ Claim No: CMTD1704570 / GPL

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15/12/17
(Client's Record)CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement: _____Date/Time: 10:51am @ 26/2/18 Person Contacted: Jason Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate
	FBD 3246 T-X
	SKR 723 Y - CC4 / III 15009350 / Rna 3s2 D.O.A: 2/6/15

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

\$3,200 - \$5,500

Veh No.

F-3032467

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha

C.C.

Colour

Orange / White

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 70/90-17 Diamond Star

R: 80/90-17M Bridgestone

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

26/4/18 @ 5:13pm

Survey held at

Lian, Chin Heng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation.

) \$ + RS. \$

: Photos

: Others

Report Format:

PRE

Lump Sum / I.B.I. (\$

TOTAL

RECEIVED 06 APR 2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO18003690/Sd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 27-02-2018



Code : SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKR 723Y	Veh. Inspected	FBD 3246T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704570/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	27/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/12/2017	Inspection Date	26/02/2018
Survey held at	LIAN CHIN HENG MOTOR & CARRIAGE PTE LTD BLK 22 WOODLANDS LINK #01-35 SINGAPORE 738734		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 26 February 2018 10:25 AM
To: Daniel Poon & Co.; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Gnoh, Pau Loong
Subject: CMTD1704570/GPL - PRI - ACCIDENT INVOLVING SKR723Y & FBD3246T on 15.12.2017
Attachments: LCHM.pdf

Our Reference : CMTD1704570/GPL
Your Reference: DP.sl.isk.10355.18.LCH

We refer to your email reply dated 26/02/2018.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO CONSULTANTS** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Daniel Poon & Co. [mailto:law@dpco.com.sg]
Sent: Monday, February 26, 2018 9:13 AM

To: Teo, Grace
Cc: Gnoh, Pau Loong
Subject: RE: CMTD1704570/GPL - PRI - ACCIDENT INVOLVING SKR723Y & FBD3246T on 15.12.2017

Dear Sir/s,

We refer to your E-mail dated 23 February 2018.

We will not be appointing any of your appointed surveyor as a single joint expert.

Kindly note that in the event that you are not agreeable to our list of appointed surveyor attached with our fax dated 23 February 2018, kindly contact the workshop to arrange a pre-repair inspection.

Yours faithfully,

Daniel C. K. Poon
Advocate & Solicitor

DANIEL POON & CO.

Advocates & Solicitors
Commissioners for Oaths
Notary Public

133 New Bridge Road
#11-02 Chinatown Point
Singapore 059413
Tel: +65 6227 2469
Fax: +65 6225 2579
E-mail: law@dpcos.com.sg

Note: We do not accept service of Court documents via email

This email is confidential. If you are not the intended recipient, please inform us and then delete it from your system; you should not copy, disclose, or distribute its contents to anyone nor act in reliance on this email, as this is prohibited and may be unlawful.

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Friday, 23 February, 2018 2:49 PM
To: law@dpcos.com.sg
Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>
Subject: CMTD1704570/GPL - PRI - ACCIDENT INVOLVING SKR723Y & FBD3246T on 15.12.2017

Our Reference : CMTD1704570/GPL
Your Reference: DP.sl.isk.10355.18.LCH

Date: 23rd February 2018

Without Prejudice
EMAIL ONLY

Attention:
M/S DANIEL POON & CO

Dear Sirs,

ACCIDENT INVOLVING SKR723Y & FBD3246T on 15.12.2017

We refer to your Notice of Accident dated 23/02/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy



This email has been checked for viruses by Avast antivirus software.
www.avast.com

**Daniel Poon & Co.**

Advocates & Solicitors
Commissioners for Oaths
Notary Public

Daniel Poon Choon Kow
LL. B. (Hons), LL.M

133 New Bridge Road
#11-02 Chinatown Point
Singapore 059413
Tel: +65 6227-2469
Fax: +65 6228-2579
Email: law@dpco.com.sg
(UEN: 53130838C)

Our Ref: DP.sl.isk.10355.18.LCH
Your Ref: -----
Please quote our reference number when replying

Date: 23 FEBRUARY 2018

M/S SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623
ATTN: IRENE HENRY

FAX (6221-3147) ONLY

DEAR SIRs,

PRE-REPAIR INSPECTION

**YOUR INSURED VEHICLE REGISTRATION NO: SKR 723Y
ACCIDENT ON 15 DECEMBER 2017 INVOLVING FBD 3246T AND SKR 723Y
ALONG AYE TOWARDS CTE**

We are instructed to notify you of a road traffic accident on 15th December 2017 at about 11:50 along AYE towards CTE involving our client's vehicle registration number FBD 3246T and vehicle registration number SKR 723Y driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair inspection of the vehicle, by the attached list of ten (10) surveyor which our client deemed suitable to be appointed.

If the aforesaid is not agreeable, kindly therefore instruct your appointed surveyor for a pre-repair inspection of our client's vehicle at by making a prior appointment with the repairer stated below:-

M/S LIAN CHIN HENG MOTOR & CARRIAGE
BLK 22 WOODLANDS LINK
#01-35
SINGAPORE 738734
ATTN: JASON LIAN (8200-8888)



... 2/-

CMTD 1 704570 / GPL



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO18003690/Sd3s2	
50 RAFFLES PLACE #05-01/06		Date: 06-04-2018	
SINGAPORE LAND TOWERS SINGAPORE 048623		Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SKR 723Y	Veh. Inspected	FBD 3246T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704570/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	26/02/2018
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	ORANGE / WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70/90-17	DIAMOND STAR	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17M	BRIDGESTONE	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.			
5. General Information			
Accident Date	15/12/2017	Inspect Date / Time	26/02/2018 (05:13 PM)
Survey held at	LIAN CHIN HENG MOTOR & CARRIAGE PTE LTD BLK 22 WOODLANDS LINK #01-35 SINGAPORE 738734		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,800-\$5,500			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

Report Ref No. CS3/SMO18003690/Sd3s2

Inspected By



YEANG WAI KEEN

Automotive Assessor



K.K. LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.