

22/03/2018

ASS. REC. BY:

REF: CS/FCI 18003693/4td3

Special Instruction:

Surveyor:  
CWS

March

ASSIGNMENT (Office)

From (Person):

Sreeni Jer

of

FCI

Date/Time:

23/2/18 @ 7:32pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL 2650R

Insured:

SHA 46694

at Workshop m/s

Tan Tim Motor

Tel:

6858 5151

of

51 Defutene 10

Policy No:

Claim No:

D1800/603MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/2/18

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

10:33am 26/2/18

Person Contacted:

Caymen

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SL 2650R - CS/GAI 18003627/Klv d3

D.O.A. 23/2/18

SHA 46694 - CS/GAI 18003627/Klv d3

D.O.A. 23/2/18



**MOTOR SURVEY ASSIGNMENT**

Date	23-02-2018	Our Ref No. D18001603MFSH
Accident Date	23-02-2018	Claim Type. Third Party
Insured Vehicle	SHA4669U	Third Party Vehicle. SLJ2650R
Survey Location	51 DEFU LANE 10	
Contact Person.	CAYMEN	
Contact No.	68585151/ 0	Fax No. 68580877
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	TAN LIM MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003693/Utd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-02-2018	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHA 4669U	Veh. Inspected	SLJ 2650R
Policy No.		Coverage (\$)	0.00
Claim No.	D18001603MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	27/02/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	23/02/2018	Inspection Date	26/02/2018
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/02/2018 10:15
Date Of Accident	23/02/2018 06:55
Exact Location Of Accident	TAMPINES AVENUE 8 X TAMPINES AVENUE 5
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ2650R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE TONG SOON
NRIC No	S1327033C
Email Address	LEE_TONG_SOON@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96252359
Alternative Phone No	OFFICE-96252359

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER 2.0-2.0 PREMIUM AT AIRBAG 2WD (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVP000003152-00-000
Cover Note Number	

### Driver

Name of Driver	LEE CHUN LING, CHERYL
NRIC No	S9019299Z
Date Of Birth	05/06/1990
Occupation	INDOOR
Date Of Driving Pass	24/06/2009
Driving Experience	8 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97461718
Fax Number	
Contact Number	
Email Address	LCL_CHERYL@HOTMAIL.COM

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHD3393E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SKD7808P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 23/07/18 @ 10:55h

Driver's Signature

(If driver is not the policyholder)

Date & Time: 23/07/18 @ 10:55h

Reporting Centre Personnel's Signature

Name: Shanon

NRIC/FIN No.: S72675024

@ARMC SketchPlanForm\_V8



**SINGAPORE  
POLICE FORCE**



Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

3 of 4  
Report No. T/20180223/2017

**CONTINUATION OF REPORT**

<b>Driver:</b>			
Name	LEE CHUN LING, CHERYL	ID No.	S9019299Z
Related Vehicle	SLJ2650R (Car)	Contact No.	97461718
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 23/02/18, at about 0657hrs, I was at the cross junction from Tampines Avenue 8 turning right into Tampines Ave 5. I noticed that there was a taxi, SHA4669U, in the opposite direction turning left. However, he stopped as there was pedestrians crossing. While I was turning right, the taxi (which was turning left), cut into my lane. As such, in order to avoid collision, I swerved to my right. This resulted in my vehicle crashing into the center divider and going over to the opposite lane, crashing into a taxi, SHD3393E. While I was exchanging particulars with the taxi driver which I collided with, I was approached by an Audi driver that the fragments from the center divider railing scratched slightly on his vehicle. However, from what I can see, there were no fragments around the area.

I would like to state that traffic police and ambulance was at scene. However, no one was conveyed and there were no visible injuries on anyone. I have handed over the SD card for my inbuilt vehicle camera to the traffic police which attended to my case. I was also given a case card by the traffic police. Vide: G/20180223/0064. IO: Lim Hong Lee, O: 65476438.





**SINGAPORE  
POLICE FORCE**



T/20180223/2017

4 of 4

Report No. T/20180223/2017

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 JONATHAN LIM XIONG HAI 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 23/02/2018 09:29
Officer In Charge Of Case: TP / AEIT / Sgt 2 YEO KIA HUAT Contact No.: 65476325	Classification Of Case: 
Authentication Stamp NP158	<div data-bbox="682 1769 1160 1957" data-label="Image"> </div>

## Enquire Transfer Fee

### Vehicle Details

Vehicle No.: SLJ2650R

Vehicle Type: P11 - Passenger Station Wagon/Jeep/Land Rover

Vehicle Attachment 1: With Sun Roof

Vehicle Scheme: Normal

Vehicle Make: TOYOTA

Vehicle Model: HARRIER 2.0 PREMIUM AT AIRBAG 2WD 5DR

Chassis No.: ZSU600085953

Propellant: Petrol

Engine No.: 3ZRB851770

Engine Capacity: 1986 cc

Maximum Power Output: 111.0 kW ( 148 bhp )

Maximum Laden Weight: 1885 kg

Unladen Weight: 1610 kg

Year Of Manufacture: 2016

Original Registration Date: 01 Dec 2016

Lifespan Expiry Date: -

COE Category: B - Car above 1600cc or 97kW (130bhp)

Quota Premium: \$53,001.00

COE Expiry Date: 30 Nov 2026

Road Tax Expiry Date: 30 Nov 2018

PARF Eligibility Expiry Date: 30 Nov 2026

Inspection Due Date: 30 Nov 2019

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7033C
Vehicle Details	
Vehicle No.:	SLJ2650R
Vehicle to be Exported:	No
Intended De-registration Date:	26 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.0 PREMIUM AT AIRBAG 2WD 5DR
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	3ZRB851770
Chassis No.:	ZSU600085953
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$33,647.00
Original Registration Date:	01 Dec 2016
First Registration Date:	01 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$34,106.00 17053
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Nov 2026
PARF Rebate Amount:	\$25,579.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$46,434.00
Total Rebate Amount:	\$72,013.00

The information contained herein is correct as at 26 Feb 2018

OK



## Start With AdWords Today

Our Specialists Are Here To Answer Your Questions & Get You Started With AdWords.

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

308 SW 1.2A PureTech Allure



Low Mileage, Great Condition, 1 Owner, Warranty Till 2020, Accident Free, Direct Owner StartAd

Browse by Category 







+ Back ( 1 2 ) Next +

Sort by Date Posted 20 results/page 

30 vehicles

Toyota Harrier

Advanced Search  Submit 

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Toyota Harrier		Any	Any	2016	Any	Any	Any	Available
	Toyota Harrier	2.0A Premium Panoramic	\$125,000	\$13,170 /yr	05-Feb-2016	1,986 cc	15,000 km	SUV	Available
Posted: 26-Feb-2018 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota									
	Toyota Harrier	2.0A G's Panoramic	\$119,800	\$12,680 /yr	29-Jan-2016	1,986 cc	23,000 km	SUV	Available
Warranty Till Jan 2019, Sleek Black Paintwork, Immaculate Interior Condition, Comes With Exclusive Harrier Alpine Head Unit Worth \$3000. Low Mileage Done At 10,000KM Per Year. Contact Us For More Deta...									
Auto Zoom Enterprise Pte Ltd									
Posted: 25-Feb-2018 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota									
	Toyota Harrier	2.0A Elegance	\$119,800	\$13,260 /yr	12-Apr-2016	1,986 cc	28,398 km	SUV	Available
Please Call For More Info And Viewing! 100% Accident Free! Low Mileage At 28398km Only! Must View! Must Buy! Very Well Kept And Maintenance. Reluctant Sale! Superb Excellent Condition! Viewing Strongl...									
Benefit Auto Enterprise Pte Ltd									
Posted: 25-Feb-2018 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota									
	Toyota Harrier	2.0A Premium Panoramic	\$123,800	\$13,780 /yr	05-Feb-2016	1,986 cc	27,000 km	SUV	Available
Look No Further! With This 1 Owner Modellista Unit That Gives You Both Comfort With A Body Kit That Gives You A Sporty Look! Elegant Black On Black With Red Trimmings. A Deal Not Be Missed! Free 1 Yea...									
Don Motoring									
Posted: 24-Feb-2018 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota									
Car Buying	Car Selling	Car Aftermarket	Buying a pre-owned car, but Unsure of its Condition? Get STA Car Evaluation						
Car Ownership	On The Move	Lifestyle							
	Toyota Harrier	2.0A Premium Panoramic	\$129,800	\$13,090 /yr	30-Sep-2016	1,986 cc	16,600 km	SUV	Available
Elegant White SUV, Almost Brand New, Accident Free, One Owner Only, Low Mileage Done, Low Maintenance Cost, Very Well Maintained, Flexible In-house Loan Packages Available.									
Prime Motor & Leasing									
Posted: 24-Feb-2018 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota									
	Toyota Harrier	2.0A Premium Panoramic	\$120,800	\$13,180 /yr	29-Mar-2016	1,986 cc	16,300 km	SUV	Available
Elegant Silver SUV, Premium Model With High Specifications, One Owner Only, Low Mileage Done, Low Maintenance Cost, Very Well Maintained, Flexible In House Loan Packages Available.									
Prime Motor & Leasing									

Compare

7/p \$18922.25 contd. 12/4/18



TAN LIM MOTOR PTE LTD

First Capital Insured's Veh No : SHA4669U

Date of Accident : 23 February 2018

51 Defu Lane 10 Singapore 539216

Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Lee Tong Soon

Date : 22 March 2018

Not Attached  
Hh  
yuhphd. Bkhu pany  
7/2/18  
26/2/18

Estimate To Repair SLJ2650R - Toyota HARRIER 2.0 PREMIUM AT AIRBAG

Chassis No : ZSU600085953

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	2 ps	Front fender o/s @ \$1446.00 1200x2=2400 o/s/bul	\$ 2,892.00 ✓
02	<del>2 ps</del> 1	Front fender inner liner <del>front @ \$425.00</del> o/s	\$ 425.00 ✓
03	<del>2 ps</del> 1	Front Fender inner liner rear <del>@ \$425.00</del> n/s	\$ 425.00 ✓ Gps
04	12 ps	Front fender inner liner clips @ \$12.00 3.50 3.50x6 = 21	\$ 144.00 ✓
05	1 pc	Front fender air guide rear o/s	\$ 55.00 X
06	3 ps	Front fender air guide rear clips @ \$50.00	\$ 150.00 X
07	1 pc	Front Fender top garnish o/s	\$ 167.00 X
08	3 ps	Front fender top garnish clips @ \$6.00	\$ 18.00 X
09	1 pc	windshield washer tank	\$ 155.00 ✓
10	1 pc	Windshield washer tank filler neck	\$ 15.00 X
11	2 ps	Head-lamp @ \$3300.00 o/s one	\$ 6,600.00 3300 ✓ 1 pc
12	1 pc	Head-lamp panel o/s	\$ 195.00 X
13	2 ps	Head-lamp lower bracket @ \$125.00 o/s back	\$ 250.00 125 ✓ 1 pc
14	1 pc	Front bumper	\$ 1,465.00 ✓
15	1 pc	Front bumper reinforcement	\$ 425.00 ✓
16	1 pc	Front bumper cover absorber foam	\$ 135.00 ✓
17	2 ps	Front bumper side absorber foam @ \$37.00	\$ 74.00 ✓
18	1 pc	Front bumper lower cover air guide	\$ 250.00 ✓
19	2 ps	front bumper spot lamp @ \$335.00 o/s cr	\$ 670.00 335 ✓ 1 pc
20	2 ps	front bumper spot lamp garnish @ \$125.00 o/s fw	\$ 250.00 125 ✓ 1 pc
21	2 ps	front bumper side retainer @ \$120.00 o/s bul	\$ 240.00 120 ✓ 1 pc
22	2 ps	front bumper air guide upper @ \$42.00	\$ 84.00 X
23	4 ps	front bumper air guide clips @ \$6.00	\$ 24.00 X
24	2 ps	front bumper tow cover @ \$40.00	\$ 80.00 ✓
25	1 pc	front bumper lower spoiler garnish	\$ 325.00 ✓
26	2 ps	front bumper air guide lower @ \$74.00	\$ 148.00 ✓
27	4 ps	front bumper air guide lower clips @ \$6.00	\$ 24.00 ✓
28	1 pc	front bumper under lower cover	\$ 155.00 ✓
29	1 pc	front bumper under lower splashshield cover	\$ 245.00 ✓
30	10 ps	front bumper clips @ \$4.00	\$ 40.00 ✓
31	1 pc	radiator grille assy	\$ 545.00 ✓
32	1 pc	radiator grille logo badge	\$ 98.00 ✓
33	1 pc	radiator grille brace panel	\$ 225.00 X
34	2 ps	front wheel rim @ \$2177.00 do/lu7 1000x2=2000	\$ 4,354.00 2000 ✓
35	2 ps	front wheel knuckle @ \$495.00 o/s bul	\$ 990.00 495 ✓ 1 pc
36	2 ps	front wheel bearing with hub @ \$539.00 o/s bul	\$ 1,078.00 539 ✓ 1 pc
37	2 ps	front lower arm @ \$600.00 o/s bul	\$ 1,200.00 600 ✓ 1 pc
38	2 ps	front shock absorber @ \$433.00 o/s bul	\$ 866.00 433 ✓ 1 pc
39	2 ps	front shock absorber top mount @ \$197.00 n/s	\$ 394.00 X

13,807



陳林摩打私人有限公司  
TAN LIM MOTOR PTE LTD

First Capital Insured's Veh No : SHA4669U

Date of Accident : 23 February 2018

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Lee Tong Soon

Date : 22 March 2018

Estimate To Repair SLJ2650R - Toyota HARRIER 2.0 PREMIUM AT AIRBAG

Chassis No : ZSU600085953

S/No	Quantity	Description	Amount	
		<u>LIST ITEMS</u>		
40	1 pc	steering rack and pinion assy <i>sub/bm</i>	\$ 1,750.00	✓
41	2 pc	front anti-roll bar link @ \$155.00 <i>o/s sub</i>	\$ 310.00	155 <i>PC</i>
42	1 pc	driver shaft o/s <i>n1</i>	\$ 1,367.00	α
43	2 ps	driver shaft oil seal @ \$19.00 <i>n1</i>	\$ 38.00	α
44	1 pc	drive shaft n/s <i>n1</i>	\$ 1,186.00	α
45	1 pc	engine suspension cross-member rear <i>DO/beat</i>	\$ 2,410.00	✓
46	1 pc	engine suspension cross-member sub front <i>n1</i>	\$ 892.00	X
47	1 pc	engine mount rear <i>n1</i>	\$ 315.00	α
48	1 pc	engine mount o/s <i>n1</i>	\$ 366.00	α
49	1 pc	gearbox mount n/s <i>n1</i>	\$ 282.00	α
50	1 pc	engine lower splashshield cover <i>Torn</i>	\$ 369.00	✓
51	1 pc	radiator assy <i>n1</i>	\$ 2,065.00	X
52	1 pc	radiator coolant <i>n1</i>	\$ 70.00	X
53	1 pc	radiator lower cross-member <i>n1</i>	\$ 220.45	X
54	1 pc	radiator lower garnish cover <i>n1</i>	\$ 150.00	α
55	1 pc	air-con condensor <i>n1</i>	\$ 1,465.00	X
		Less 25 %	\$ 39,131.05	
			\$ 9,782.76	18191
			\$ 29,348.29	
		<u>SPECIAL NETT ITEMS</u>		
56	1 pc	front license plate <i>n1</i>	\$ 50.00	X
57	2 ps	front wheel tyre @ \$600.00 <i>n1</i>	\$ 1,200.00	X
			\$ 1,250.00	
		<u>LABOUR &amp; MISC. CHARGES</u>		
01		Towing charges.	\$ 130.00	60
02		To check electrical lighting concerned.	\$ 60.00	30
03		To rust-proofing of the affected areas.	\$ 200.00	90
04		To apply paint protection system (PPS) maintain and enhancement of shines on paintwork.	\$ 11 650.00	X
05		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 220.00	100
06		To transfer of front wheel tyre, rim and on wheel balancing.	\$ 100.00	80
07		To check steering geometry and computer wheel alignment.	\$ 150.00	
08		To drop front and rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 1,300.00	380
09		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,500.00	800



陳林聯峰私人有限公司  
**TAN LIM MOTOR PTE LTD**

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
**GST Regn. No. : M2-8922054-2**

First Capital Insured's Veh No : SHA4669U  
Date of Accident : 23 February 2018

Mr Lee Tong Soon

Date : 22 March 2018

Estimate To Repair SLJ2650R - Toyota HARRIER 2.0 PREMIUM AT AIRBAG  
Chassis No : ZSU600085953

S/No	Quantity	Description	Amount
10		<u>LABOUR &amp; MISC. CHARGES</u>	
		Putty and spray painting of the affected portion.	\$ 1,800.00
			\$ 6,110.00
		Total	\$ 36,708.29
			37347.29

1100  
2640



陳林摩打私人有限公司  
TAN LIM MOTOR PTE LTD

First Capital Insured's Veh No : SHA4669U

Date of Accident : 23 February 2018

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Lee Tong Soon

Date : 22 March 2018

Supplementary To Repair SLJ2650R - Toyota HARRIER 2.0 PREMIUM AT AIRBAG

Chassis No : ZSU600085953

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	steering tie-rod end <i>sent</i>	\$ 195.00
02	1 pc	front lower arm ball joint <i>sent</i>	\$ 217.00
03	1 pc	front bumper top beam <i>sent</i>	\$ 315.00
04	1 pc	r/s front bumper beam <i>sent</i>	\$ 125.00
			\$ 852.00
		Less 25 %	\$ 213.00
			\$ 639.00
		Total	\$ 639.00
		<i>Parts</i>	
		<i>Part Supp</i>	
		<i>Labour</i>	
		<i>P-19043</i>	
		<i>25%</i>	
		<i>14282.25</i>	
		<i>S.N+ 2000</i>	
		<i>1chm-2640</i>	
		<i>18922.25</i>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





陳林摩摩私人有限公司  
TAN LIM MOTOR PTE LTD

First Capital Insured's Veh No : SHA4669U

Date of Accident : 23 February 2018

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

Mr Lee Tong Soon

Date : 23 February 2018

Estimate To Repair SLJ2650R - Toyota HARRIER 2.0 PREMIUM AT AIRBAG  
Chassis No : ZSU600085953

S/No	Quantity	Description	Amount
<b>LIST ITEMS</b>			
01	2 ps	Front fender @ \$0.00 <i>20/Sec</i>	\$ 0.00
02	2 ps	Front fender inner liner front @ \$0.00 <i>To.1 ✓</i>	\$ 0.00
03	2 ps	Front Fender inner liner rear @ \$0.00 <i>11X</i>	\$ 0.00
04	12 ps	Front fender inner liner clips @ \$0.00 <i>ner ✓</i>	\$ 0.00
05	1 pc	Front fender air guide rear o/s <i>11X</i>	\$ 0.00
06	3 ps	Front fender air guide rear clips @ \$0.00 <i>11X</i>	\$ 0.00
07	1 pc	Front Fender top garnish o/s <i>11X</i>	\$ 0.00
08	3 ps	Front fender top garnish clips @ \$0.00 <i>11X</i>	\$ 0.00
09	1 pc	windshield washer tank <i>De ✓</i>	\$ 0.00
10	1 pc	Windshield washer tank filler neck <i>?</i>	\$ 0.00
11	2 ps	Head-lamp @ \$0.00 <i>O/S one 11C</i>	\$ 0.00
12	1 pc	Head-lamp panel o/s <i>12X</i>	\$ 0.00
13	2 ps	Head-lamp lower bracket @ \$0.00 <i>?</i>	\$ 0.00
14	1 pc	Front bumper <i>D.S ✓</i>	\$ 0.00
15	1 pc	Front bumper reinforcement <i>20 ✓</i>	\$ 0.00
16	1 pc	Front bumper cover absorber foam <i>To.1 ✓</i>	\$ 0.00
17	2 ps	Front bumper side absorber foam @ \$0.00 <i>O/S To.1 12C</i>	\$ 0.00
18	1 pc	Front bumper lower cover air guide <i>To.1 ✓</i>	\$ 0.00
19	2 ps	front bumper spot lamp @ \$0.00 <i>O/S one 4C</i>	\$ 0.00
20	2 ps	front bumper spot lamp garnish @ \$0.00 <i>?</i>	\$ 0.00
21	2 ps	front bumper side retainer @ \$0.00 <i>21 ✓</i>	\$ 0.00
22	2 ps	front bumper air guide upper @ \$0.00 <i>?</i>	\$ 0.00
23	4 ps	front bumper air guide clips @ \$0.00 <i>?</i>	\$ 0.00
24	2 ps	front bumper tow cover @ \$0.00 <i>To.1 ✓</i>	\$ 0.00
25	1 pc	front bumper lower spoiler garnish <i>D.S ✓</i>	\$ 0.00
26	2 ps	front bumper air guide lower @ \$0.00 <i>To.1 ✓</i>	\$ 0.00
27	4 ps	front bumper air guide lower clips @ \$0.00 <i>ner ✓</i>	\$ 0.00
28	1 pc	front bumper under lower cover <i>To.1 ✓</i>	\$ 0.00
29	1 pc	front bumper under lower splashshield cover <i>To.1 ✓</i>	\$ 0.00
30	10 ps	front bumper clips @ \$0.00 <i>ner ✓</i>	\$ 0.00
31	1 pc	front license plate <i>11X</i>	\$ 0.00
32	1 pc	radiator grille assy <i>11X</i>	\$ 0.00
33	1 pc	radiator grille logo badge <i>11X</i>	\$ 0.00
34	1 pc	radiator grille brace panel <i>11X</i>	\$ 0.00
35	2 ps	front wheel rim @ \$0.00 <i>O/S one ✓</i>	\$ 0.00
36	2 ps	front wheel knuckle @ \$0.00 <i>?</i>	\$ 0.00
37	2 ps	front wheel bearing with hub @ \$0.00 <i>?</i>	\$ 0.00
38	2 ps	front lower arm @ \$0.00 <i>?</i>	\$ 0.00
39	2 ps	front shock absorber @ \$0.00 <i>?</i>	\$ 0.00



陳林摩哆私人有限公司  
**TAN LIM MOTOR PTE LTD**

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

First Capital Insured's Veh No : SHA4669U

Date of Accident : 23 February 2018

Mr Lee Tong Soon

Date : 23 February 2018

Estimate To Repair SLJ2650R - Toyota HARRIER 2.0 PREMIUM AT AIRBAG

Chassis No : ZSU600085953

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
40	2 ps	front shock absorber top mount @ \$00 <sup>21X</sup>	\$ 0.00
41	1 pc	steering rack and pinion assy	\$ 0.00
42	2 pc	front anti-roll bar link @ \$00 ?	\$ 0.00
43	1 pc	driver shaft o/s <sup>11X</sup>	\$ 0.00
44	2 ps	driver shaft oil seal @ \$00 <sup>11X</sup>	\$ 0.00
45	1 pc	drive shaft n/s <sup>11X</sup>	\$ 0.00
46	1 pc	engine suspension cross-member rear ?	\$ 0.00
47	1 pc	engine suspension cross-member sub front ?	\$ 0.00
48	1 pc	engine mount rear ?	\$ 0.00
49	1 pc	engine mount o/s ?	\$ 0.00
50	1 pc	gearbox mount n/s ?	\$ 0.00
51	1 pc	engine lower splashshield cover ?	\$ 0.00
52	1 pc	radiator assy <sup>11X</sup>	\$ 0.00
53	1 pc	radiator coolant ?	\$ 0.00
54	1 pc	radiator lower cross-member ?	\$ 0.00
55	1 pc	radiator lower garnish cover ?	\$ 0.00
56	1 pc	air-con condensor ?	\$ 0.00
			\$ 0.00
		Less 10 %	\$ 0.00
			\$ 0.00
		<u>SPECIAL NETT ITEMS</u> ?	
57	2 ps	front wheel tyre @ \$600.00	\$ 1,200.00
			\$ 1,200.00
		<u>LABOUR &amp; MISC. CHARGES</u>	
01		Towing charges.	\$ 130.00
02		To check electrical lighting concerned.	\$ 60.00
03		To rust-proofing of the affected areas.	\$ 200.00
04		To apply paint protection system (PPS) maintain and enhancement of shines on paintwork.	\$ 650.00
05		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 220.00
06		To transfer of front wheel tyre, rim and on wheel balancing.	\$ 100.00
07		To check steering geometry and computer wheel alignment.	\$ 150.00
08		To drop front and rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 1,300.00
09		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,500.00

60  
30  
80  
?  
100  
20  
380  
700  
700



陳林摩哆私人有限公司  
**TAN LIM MOTOR PTE LTD**

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

First Capital Insured's Veh No : SHA4669U

Date of Accident : 23 February 2018

Mr Lee Tong Soon

Date : 23 February 2018

Estimate To Repair SLJ2650R - Toyota HARRIER 2.0 PREMIUM AT AIRBAG  
Chassis No : ZSU600085953

S/No	Quantity	Description	Amount
10		<b>LABOUR &amp; MISC. CHARGES</b>	
		Putty and spray painting of the affected portion.	\$ 1,800.00
			\$ 6,110.00
		<b>Total</b>	<b>\$ 7,310.00</b>
<div><p>LKR Auto &amp; Air Systems hence notify the repairer of the following:</p><ul style="list-style-type: none"><li>• To inspect before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Putty procedure subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modifications is allowed</li><li>• Supplementary detail must be resurveyed and is subject to final approval from Insurance Company</li></ul><p>Acknowledged by Repairer Signature: Date:</p></div>			

1100




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003693/Utd3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-04-2018		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 4669U	Veh. Inspected	SLJ 2650R	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001603MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	23/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600085953	Colour	BLACK	
Odometer	18623	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	BRIDGESTONE	7 mm	
L/H Front Tyre	235/55 R18	BRIDGESTONE	7 mm	
R/H Rear Tyre	235/55 R18	BRIDGESTONE	7 mm	
L/H Rear Tyre	235/55 R18	BRIDGESTONE	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S & O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/02/2018	Inspection Date	26/02/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 2650R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
2	FRONT FENDER O/S @\$1446.00	DENTED / BUCKLED	2,892.00	2,400.00
1	FRONT FENDER INNER LINER O/S	TORN	425.00	425.00
1	FRONT FENDER INNER LINER N/S	TORN	425.00	425.00
12	FRONT FENDER INNER LINER CLIPS @\$12.00	NECESSARY (6 PCS ONLY)	144.00	21.00
1	FRONT FENDER AIR GUIDE REAR O/S	NOT NECESSARY	55.00	-
3	FRONT FENDER AIR GUIDE REAR CLIPS @\$50.00	NOT NECESSARY	150.00	-
1	FRONT FENDER TOP GARNISH O/S	NOT NECESSARY	167.00	-
3	FRONT FENDER TOP GARNISH CLIPS @\$6.00	NOT NECESSARY	18.00	-
1	WINDSHIELD WASHER TANK	DEFORMED	155.00	155.00
1	WINDSHIELD WASHER TANK FILLER NECK	NOT NECESSARY	15.00	-
2	HEAD-LAMP @\$3300.00	O/S CRACKED	6,600.00	3,300.00
1	HEAD-LAMP PANEL O/S	NOT NECESSARY	195.00	-
2	HEAD-LAMP LOWER BRACKET @\$125.00	O/S BENT	250.00	125.00
1	FRONT BUMPER	DISTORTED	1,465.00	1,465.00
1	FRONT BUMPER REINFORCEMENT	DENTED	425.00	425.00
1	FRONT BUMPER COVER ABSORBER FOAM	TORN	135.00	135.00
2	FRONT BUMPER SIDE ABSORBER FOAM @\$37.00	TORN	74.00	74.00
1	FRONT BUMPER LOWER COVER AIR GUIDE	TWISTED	250.00	250.00
2	FRONT BUMPER SPOT LAMP @\$335.00	O/S CRACKED	670.00	335.00
2	FRONT BUMPER SPOT LAMP GARNISH @\$125.00	O/S TWISTED	250.00	125.00
2	FRONT BUMPER SIDE RETAINER @\$120.00	O/S BENT	240.00	120.00
2	FRONT BUMPER AIR GUIDE UPPER @\$42.00	NOT NECESSARY	84.00	-
4	FRONT BUMPER AIR GUIDE CLIPS @\$6.00	NOT NECESSARY	24.00	-
2	FRONT BUMPER TOW COVER @\$40.00	TORN	80.00	80.00
1	FRONT BUMPER LOWER SPOILER GARNISH	DISTORTED	325.00	325.00
2	FRONT BUMPER AIR GUIDE LOWER @\$74.00	TORN	148.00	148.00
4	FRONT BUMPER AIR GUIDE LOWER CLIPS @\$6.00	NECESSARY	24.00	24.00
1	FRONT BUMPER UNDER LOWER COVER	TORN	155.00	155.00
1	FRONT BUMPER UNDER LOWER SPLASHIELD COVER	TORN	245.00	245.00

Report Ref No. CS/FCI18003693/Utd3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	FRONT BUMPER CLIPS @\$4.00	NECESSARY	40.00	40.00
1	RADIATOR GRILLE ASSY	CRACKED	545.00	545.00
1	RADIATOR GRILLE LOGO BADGE	NECESSARY	98.00	98.00
1	RADIATOR GRILLE BRACE PANEL	NOT NECESSARY	225.00	-
2	FRONT WHEEL KNUCKLE @\$495.00	O/S BENT	990.00	495.00
2	FRONT WHEEL BEARING WITH HUB @\$539.00	O/S BENT	1,078.00	539.00
2	FRONT LOWER ARM @\$800.00	O/S BENT	1,200.00	600.00
2	FRONT SHOCK ABSORBER @\$433.00	O/S BENT	866.00	433.00
2	FRONT SHOCK ABSORBER TOP MOUNT @\$197.00	NOT NECESSARY	394.00	-
1	STEERING RACK AND PINION ASSY	BENT / JAMMED	1,750.00	1,750.00
2	FRONT ANTI-ROLL BAR LINK @\$155.00	O/S BENT	310.00	155.00
1	DRIVE SHAFT O/S	NOT NECESSARY	1,367.00	-
2	DRIVE SHAFT OIL SEAL @\$19.00	NOT NECESSARY	38.00	-
1	DRIVE SHAFT N/S	NOT NECESSARY	1,186.00	-
1	ENGINE SUSPENSION CROSS-MEMBER REAR	DENTED / BENT	2,410.00	2,410.00
1	ENGINE SUSPENSION CROSS-MEMBER SUB FRONT	NOT NECESSARY	892.00	-
1	ENGINE MOUNT REAR	NOT NECESSARY	315.00	-
1	ENGINE MOUNT O/S	NOT NECESSARY	366.00	-
1	GEARBOX MOUNT N/S	NOT NECESSARY	282.00	-
1	ENGINE LOWER SPLASHIELD COVER	TORN	369.00	369.00
1	RADIATOR ASSY	NOT NECESSARY	2,065.00	-
1	RADIATOR COOLANT	NOT NECESSARY	70.00	-
1	RADIATOR LOWER CROSS -MEMBER	NOT NECESSARY	220.45	-
1	RADIATOR LOWER GARNISH COVER	NOT NECESSARY	150.60	-
1	AIR-CON CONDENSOR	NOT NECESSARY	1,465.00	-
1	STEERING TIE-ROD END (ADDITIONAL)	BENT	195.00	195.00
1	FRONT LOWER ARM BALL JOINT (ADDITIONAL)	BENT	217.00	217.00
1	FRONT BUMPER TOP BEAM (ADDITIONAL)	BENT	315.00	315.00
1	N/S FRONT BUMPER BEAM (ADDITIONAL)	BENT	125.00	125.00
	LESS 25% DISCOUNT		-8,907.26	-4,760.75
			26,721.79	14,282.25
2	FRONT WHEEL RIM @\$2177.00 (SN)	DENTED / CUT	4,354.00	2,000.00

Report Ref No. CS/FCI18003693/Utd3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-1,088.50	-
			3,265.50	2,000.00
	<b>SPECIAL NETT ITEMS</b>			
1	FRONT LICENSE PLATE (SN)	NOT NECESSARY	50.00	-
2	FRONT WHEEL TYRE @\$600.00 (SN)	NOT NECESSARY	1,200.00	-
			1,250.00	-
	<b>LABOUR</b>			
	TOWING CHARGES.		130.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	30.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		200.00	90.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT OF SHINES ON PAINTWORK.	NOT NECESSARY	650.00	-
	TO DISMANTLE AIR-CON ASSY ,REMOVE AND RENEWAL OF PARTS ,VACUUM AND CHARGE-IN GAS.		220.00	100.00
	TO TRANSFER OF FRONT WHEEL TYRE ,RIM AND ON WHEEL BALANCING .}		100.00	80.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT .}		150.00	-
	TO DROP FRONT AND REAR AXLE AND SUSPENSION ASSY ,REMOVE AND RENEWAL OF NECESSARY PARTS .TO CONDUCT FINAL CHECKING AND TESTING.		1,300.00	380.00
	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.		1,500.00	800.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,800.00	1,100.00
			6,110.00	2,640.00
<b>GRAND TOTAL</b>			<b>37,347.29</b>	<b>18,922.25</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>18,922.25</b>

Report Ref No. CS/FC18003693/Utd3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.