

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 1778H

DATE 26/2/2018 11:50

MAKE :

MODEL : HYUNDAI i40

AIG-LKK

Jumani

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?			\$ 49.00	
	Rear Bumper Clips ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover ✕			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 380.00	
	Spray Painting Charge			\$ 200.00	180
	Wiring Charge			\$ 50.00	✕
	R/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 750.00	
	ESTIMATE TOTAL			\$ 2,461.58	
16/2/18 16/11/18 26/2/18 1430 hr. 2 days 4/3 After Repair photo					
LKK Auto Consultants hence not fy the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					