

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 4114D

DATE 26/2/2018

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 538.80
	Front Bumper Bracket Top (RH)			\$ 22.40
	Front Bumper Protector (RH) <i>x repair</i>			\$ 29.20
	Headlamp (RH)			\$ 797.90
	Front Fender (RH)			\$ 593.00
	Front Fender Shield (RH) <i>x</i>			\$ 86.00
	Front Fender Retainer <i>x</i>			\$ 9.20
	Front Door Protector (RH) <i>x repair</i>			\$ 74.90
	Front Wheel Hub Cap (RH)			\$ 145.00
	SUB TOTAL			\$ 2,296.40
	LESS 20%			\$ 459.28
	DISCOUNTED TOTAL			\$ 1,837.12
	Frt Door Color Comfort Logo (RH)			\$ 75.00 Nett
				\$ 75.00
	Labour Charge			
	Panel Beating			\$ 500.00 540
	Spray Painting Charge			\$ 600.00 20
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 60
	Frt Wheel Alignment			\$ 80.00 50
	<i>Tax Fee</i>			80.00
	TOTAL LABOUR			\$ 1,340.00
	ESTIMATE TOTAL			\$ 3,252.12
	<i>Kalvin LKK</i>			
	<i>26/2/18 1500hrs</i>			
	<i>20.75</i>			
	<i>45</i>			
	<i>After Repair LK</i>			
	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			