

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5320H -**AAD1802-205***Not Authored
1/1 Sep @ 3200h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5320H - JHOW

VF1ABL15AUC276865

RENAULT

LATITUDE

20.02.2018

*AM***PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>mgm</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
3	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.22 X
4	1	BUMPER RETAINER FRT LH	\$	<i>DII</i> 151.41 ✓
5	1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 151.41 X
6	1	BUMPER SUPPORT FRT LH	\$	<i>Sn</i> 123.88
7	1	BUMPER SUPPORT FRT RH	\$	<i>Sn</i> 123.88
8	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
9	1	RADAIOR GRILLE	\$	<i>Sn</i> 1,707.78
10	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36
11	1	RADAIOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
12	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90
13	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 } X
14	1	AIR CLEANER LOWER	\$	<i>Sn</i> 352.64
15	1	AIR CLEANER HOSE	\$	<i>Sn</i> 76.14
16	1	STEERING PUMP ELECTRIC	\$	<i>Sn</i> 2,306.90
17	1	AUTO COMPUTER	\$	<i>Sn</i> 5,032.17
18	1	STEERING PINION RACK	\$	<i>Sn</i> 4,413.11
19	1	LOWER ARM LH	\$	<i>Sn</i> 685.76
20	1	KUNCKLE ARM LH	\$	<i>Sn</i> 846.98
21	1	KUNCKLE HUB+BEARING LH	\$	<i>Sn</i> 497.69
22	1	ABSORBER FRT LH	\$	<i>Sn</i> 360.54
23	1	BONNET	\$	<i>R</i> 1,941.63
24	1	HEADLAMP LH	\$	<i>mgm</i> 1,184.43 ✓
25	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
26	1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83 ✓
27	1	FENDER INSULATOR LH	\$	<i>Sn</i> 130.84 X
28	1	WHEEL HOUSING PANEL FRT LH	\$	<i>R</i> 5,173.47 X
29	1	WHEELARCH FRT LH	\$	<i>Sn</i> 278.84 X
30	1	DOOR MIRROR LH	\$	<i>Sn</i> 1,483.40 X
31	1	DOOR MIRROR GLASS LH	\$	<i>Sn</i> 148.20 X
32	1	DOOR MIRROR BACK COVER LH	\$	<i>Sn</i> 218.46 X
33	1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66 X
34	1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-205

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5320H -

35	1	DOOR HINGE LOWER LH	\$	<i>nr</i>	300.55	} X
36	1	DOOR GRAB HANDLE FRT LH	\$	<i>sn</i>	210.96	
37	1	DOOR HANDLE OUTER FRT LH	\$	<i>sn</i>	258.12	
38	1	DOOR HANDLE CAP FRT LH	\$	<i>sn</i>	26.44	
39	1	DOOR HANDLE SEAL FRT LH	\$	<i>sn</i>	7.89	
40	1	DOOR HANDLE COVER FRT LH	\$	<i>sn</i>	13.22	
41	1	DOOR HANDLE MODULE FRT LH	\$	<i>sn</i>	133.60	
42	1	DOOR MOULDING FRT LH	\$	<i>sn</i>	176.82	

TOTAL	\$	37,419.58
10%	\$	3,741.96
	\$	33,677.62

Specical Nett

1	1SET	FRONT BUMPER CLIP	\$	<i>nr</i>	66.00	} X
2	1SET	WHEELARCH CLIP LH	\$	<i>nr</i>	66.00	
3	1	TOW COVER FRT	\$	<i>sn</i>	14.50	
4	1	CAP HUB LH FRT	\$	<i>sn</i>	35.00	
5	1	RIM LH FRT	\$	<i>sn</i>	385.00	
6	1	TYRE LH FRT	\$	<i>sn</i>	330.00	
7	1SET	BUMPER SUPPORT FRT CLIP LH	\$	<i>nr</i>	9.80	
8	1SET	BUMEPR RETAINER FRT CLIP LH	\$	<i>nr</i>	12.50	
9	1	DOOR STICKER "Trans-cab"	\$	<i>nr</i>	80.00	
10	1	DOOR STICKER "Classic"	\$	<i>nr</i>	30.00	

TOTAL	\$	1,028.80
TOTAL PARTS	\$	34,706.42

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,200.00 *4000*

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

Putty and spray painting of the affected portion.

\$ 4,500.00 *4400*

To check steering geometry and computer wheel alignment

\$ *nr* 220.00 X

Towing Fees

\$ *nr* 120.00 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-205

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5320H -

To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To rust-proofing of the affected areas.	\$	170.00 307
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00 X

TOTAL	\$	10,920.00
Over All Total	\$	45,626.42

(PARTS BY PARTS) Repair Days**15 Days**

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: