

SMRT Accident Vehicle Repair Estimates

RIG L117

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB383P
 Ref. No : TAX/02/18/2143
 Reg. Date : 09/04/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : HOONG KENG HENG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 23/02/2018 08:00:00 PM
 Accident Reported Date / Time : 24/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094754
 Special Instruction to ARC, if any :
 SLG1585T - AIG LKK
 Prepared Date : 24/02/2018 10:11:01 AM



Sebastian.
 26/2/18.
 - Lump Sum Repair.
 - Question mark Item Photo.
 - Photo After Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U705741027 Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 507.00	0.00
Total Spray Painting Charges	: 756.00	0.00
Total Material Charges	: 1,306.49	1,306.49
Other Charges	: 360.00	0.00
TOTAL	: 2,929.49	0.00
Lum Sum Total	: 2,950.00	0.00
No. of Repair Days	: 5.00	0.00
Prepared / Adjusted By	:	3 days
Arc / Surveyor Sign Off Date	: 26/02/2018 01:54:12 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/02/2018 01:52:19 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

Section 2 - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	507.00	0.00 507 200
Total Labour	507.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
Total Spray Painting & Panel Beating	756.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	360.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
81561-47170		6505461	TAIL LAMP LH	1	548.40	10.00	493.56	Replace	Replace	No
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
TOTAL MATERIALS								1,633.11	1,633.11	
TOTAL MATERIALS(Discounted)								1,306.49	1,306.49	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									