



FALCON-AIR

AHMAD AL-MAHIR BIN ABU BAKAR
BLK710 CLEMENTI WEST ST 2 #10-259
SINGAPORE 120710

Attention : Motor Claim Department

Contact : 81187955

Estimate : ES003121

Date : 26/02/2018

Vehicle Num. : SKG1518A

Make/Model : MAZDA 5

Chassis/Eng# : JM6CW1OF1CO111092

Accident Date : 23/02/2018

Claim No. :

Reference : TP NTUC VS III

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAILGATE		1,447.60 <i>bt</i>
2.	1	TAILGATE GLASS MOULDING		58.45 <i>ne</i>
3.	1	TAILGATE LOGO		65.50 <i>ne</i>
4.	1	TAILGATE EMBLEM MAZDA 5		75.00 <i>ne</i>
5.	1	REAR BUMPER		915.40 <i>ora</i>
6.	1	REAR END PANEL		465.00 <i>?</i>
7.	1	TAILGATE PULL HANDLE		25.00 <i>ora</i>
8.	1	REAR BUMPER SIDE RETAINER <i>LH-RH-ne</i>		35.00
List TotalS\$:				3,086.95
20.00% Discount S\$:				617.39
				<u>2,469.56</u>
SPECIAL NETT ITEMS :				
1.	1	REVERSE SENSOR		200.00 <i>ne</i>
2.	1	REAR NUMBER PLATE		45.00 <i>bt</i>
Special Nett Total S\$:				<u>245.00</u>
LABOUR :				
TO TRANSFER TAILGATE PARTS/MECHANISM				50.00 <i>40</i>

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

AHMAD AL-MAHIR BIN ABU BAKAR
BLK710 CLEMENTI WEST ST 2 #10-259
SINGAPORE 120710

Attention : Motor Claim Department

Contact : 81187955

Estimate : ES003121

Date : 26/02/2018
Vehicle Num. : SKG1518A
Make/Model : MAZDA 5
Chassis/Eng# : JM6CW1OF1CO111092
Accident Date : 23/02/2018
Claim No. :
Reference : TP NTUC VS III
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REMOVE/REFIX REAR WINDSCREEN GLASS	120.00	✓
		TO REMOVE/REFIX REVERSE SENSOR & CHECK WIRING	80.00	40
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS	850.00	700
		TO CUT/OUT REWELD REAR END PANEL, REPAIR REAR CHASSIS		
		RH REAR FENDER INCLUDES KNOCKING & REPLACEMENT OF PARTS	650.00	550
		Labour Total S\$:	1,750.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
wp
28/2/18 @ 1140
5 days
Resurvey before paint
H/S sur@lkkauto.com



E. & O.E.

Total S\$: 4,464.56

for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

[a subsidiary of Falcon-Air Holdings Pte Ltd]

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg