

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, SINGAPORE 575644.

TEL: 456 9830 • FAX: 455 3986 Business Regn No: 269436/00J

24, Feb 2018

India International Insurance PL 64 Cecil street #04/#05/#06-02 **IOB** Building S 049711

Not Norhanks Many & 1700/ Mehny Athe Paint Gaza

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle No: SH6763A Accident involving vehicle No: SJP3496E/SH6763A

DOA: 13/02/2018 AT Cecil Street

Dear officer incharge

Re: estimate cost of repair for vehicle No: SJP3496E

To supply—

Description	Qty	Amount
Front door,Rh	1	Pellman 898.00 -
Front door outer protector,Rh	1	Ref 122.50 ←
Rear door	1	7 881.20 X
Rear door outer protector	1	nu 122.50 L
Rear rim,Rh	1	// 200.00 X
	Parts	2,224.20
	Parts less 25%	556.05
AND DESIGNATION OF THE PERSON		1,668.15
10 market 10 mm		

To remove/transfer 2 door board, power window mechanism, door glass to new door. To remove damaged parts and attachments.

250.00 601

700.00 5001

850.00 FZ01

Repair/reshape rear fender, lower panel and all dented areas

To replace/replace above parts into position.

To spray paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: