



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC6/III18003712/Ueb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 27-02-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6484E	Veh. Inspected	SLL 7695T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	27/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/02/2018	Inspection Date		
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Print Received Message

This mail is associated with :

***SLL7695T (MCT18020131)**
[SH6484E]

TP

GRAB RENTALS PTE LTD

Feb 3 2018 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Pegasus Engineering & Trading Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 13/03/2018 10:34 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SLL7695T - Claim Handler: NATALIE LEE

Approved:0.00:Dear Asher, Please proceed to reject TP claim.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Wednesday, 21 March 2018 4:45 PM
To: Pegasus Engineering
Cc: Vic (LKKAuto)
Subject: ACCIDENT INVOLVING SLL 7695T AND SH 6484E ON 03/02/2018
Attachments: OI SKETCH PLAN.pdf; Video - Accident (5).MP4

Your Ref: SLL 7695T
Our Ref: CC6/III18003712/Ueb3

Without Prejudice

Hi Sir/Mdm,

We refer to the above matter.

ACCIDENT INVOLVING SLL 7695T AND SH 6484E ON 03/02/2018

We attached here with a copy of our insured's accident statement and video for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client changed lane into our insured lane and hit our insured vehicle.

We are of the opinion that liability is not in your client's favor.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2018 Edit Reg		27 Feb 2018 00:00 Edit Adj Rpt	S\$829.20 Edit Estimates	S\$829.20 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLL7695T	Date of Loss:	03/02/2018 00:00 - :59
Claim Type:	TP / MCT18020131	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SH6484E	Policy No. (Claimant):	A29069766MKF
		Excess:	
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 16/03/2018]		
Driver/Custodian (Insured):	MOHAMAD SHAH BIN IBRAHIM (), NRIC: S1485904G		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (13/03/2018): Alert - Adj Mandate Approved (S\$0.00) - SLL7695T - Claim Handler: NATALIE LEE

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SLL7695T (MCT18020131)**
[SH6484E]

TP

GRAB RENTALS PTE LTD
Feb 3 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Pegasus Engineering & Trading Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Video			1 per page ▼	✓
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	13/03/18 08:49	Video - Accident	Load MP4	
Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/03/18 16:47	Chassis Number	Load JPG	✓
2	21/03/18 16:47	General View	Load JPG	✓
3	21/03/18 16:47	Odometer Reading	Load JPG	✓
4	21/03/18 16:47	General View	Load JPG	✓
5	21/03/18 16:47	General View	Load JPG	✓
6	21/03/18 16:47	General View	Load JPG	✓
7	21/03/18 16:47	General View	Load JPG	✓
8	21/03/18 16:47	General View	Load JPG	✓
9	21/03/18 16:47	General View	Load JPG	✓
10	21/03/18 16:47	General View	Load JPG	✓
11	21/03/18 16:47	General View	Load JPG	✓
12	21/03/18 16:47	General View	Load JPG	✓
13	21/03/18 16:47	General View	Load JPG	✓
14	21/03/18 16:47	General View	Load JPG	✓
15	21/03/18 16:47	General View	Load JPG	✓
16	21/03/18 16:47	General View	Load JPG	✓
17	21/03/18 16:47	General View	Load JPG	✓
18	21/03/18 16:47	General View	Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/03/18 17:54	TP ESTIMATE- MARKED	Load PDF	
2	07/03/18 17:54	TP GIA REPORT	Load PDF	
3	21/03/18 16:46	EMAIL WSP TO REJECT TP CLAIM	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	08/03/18 08:54	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18003712/UEB3S2
Date: 26/03/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No:
Claimant Vehicle No: SLL7695T Insured Vehicle No: SH6484E
Date of Loss: 03/02/2018 Nature of Claim: TP Claim No: MCT18020131

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL7695T
Make & Model: MAZDA 3, 1.5 SEDAN L SP.6EAT (A) Engine No: P520432882
Reg. Date: 09/03/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0145514
Colour: Grey Odometer: 75007 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R15 Rear Tyre Size: 205/60R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,168.80	99.20	1,069.60	91.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,040.00	730.00	310.00	29.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,208.80	829.20	1,379.60	62.46
+ GST 7.00/7.00% (S\$)	154.62	58.04	96.58	62.46
Nett Amount (S\$)	2,363.42	887.24	1,476.18	62.46

INSPECTION

Date of Assignment: 27/02/2018
Date Inspected: 27/02/2018 Inspected At: Pegasus Engineering & Trading Pte Ltd (HQ)
51 DEFU LANE 10
Singapore 539216
Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2018)
Parts:	143	MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL7695T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER N/S	Repair	334.00 FL	*- FL
2	1		*FRONT FENDER INNER LINER N/S	Not Necessary	130.00 FL	*- FL
3	4		*FRONT FENDER INNER LINER CLIPS	Not Necessary	18.00 FL	*- FL
4	1		*FRONT BUMPER	Repair	825.00 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER N/S	Not Necessary	12.00 FL	*- FL
6	4		*FRONT BUMPER CLIPS	Not Necessary	18.00 FL	*- FL
7	1		*FRONT WHEEL HUB CAP N/S	Cut	124.00 FL	*124.00 FL
Sub Total (S\$)						1,461.00 124.00
- List Item Discount on L Items 20.00/20.00% (S\$)						292.20 24.80
Total Parts (S\$)						1,168.80 99.20

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	60.00	20.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	80.00	60.00
3	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	500.00	250.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	400.00	400.00
Gross Labour Cost (\$\$)			1,040.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >