

PEGASUS
ENGINEERING & TRADING PTE LTD
 GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
 C/O 51 DEFU LANE 10
 539216

Officer in Charge : ALVIN LOW WAI LUN
 Tel :
 Email :

Customer :

GRAB RENTALS PTE LTD
 18 SIN MING LANE
 #01-08 MIDVIEW CITY
 SINGAPORE 573960

Attn :
 Tel :
 Fax :

Quotation No : QO18/02-1082	Quotation Date : 12/02/2018	Terms : 30 DAYS
Vehicle No : SLL7695T	Chassis No : JM6BN22A8H0145514	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: III ; TP VEHICLE NUMBER: SH6484E ; DATE OF ACCIDENT: 03.02.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	FRONT FENDER N/S	1	334.0000	334.00
2	FRONT FENDER INNER LINER N/S	1	130.0000	130.00
3	FRONT FENDER INNER LINER CLIPS	4	4.5000	18.00
4	FRONT BUMPER	1	825.0000	825.00
5	FRONT BUMPER SIDE RETAINER N/S	1	12.0000	12.00
6	FRONT BUMPER CLIPS	4	4.5000	18.00
7	FRONT WHEEL HUB CAP N/S	1	124.0000	124.00
8	LESS 20% ITEMS 1-7	1	-292.2000	-292.20
9	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	60.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	1	80.0000	80.00
11	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	500.0000	500.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		400.0000	400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Sub Total 2,208.80
 GST(7.00%) 154.62
 Total (SGD) 2,363.42

not follow
 who should others repair
 27/2/18
 98.2
 p/p \$829.20