

INS. CASE OWNER:

CC 4/LPC1800 3720, 1, w63n2

LKK:
IDAC:

Surveyor:

Tunlich

DOI:

ASSIGNMENT

2/2/18

Date / Time:

22/2/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKF 3214T

Name of Insured:

YANG LEE MING

Insured Tel No.:

HP:

Excess Sec II : \$

D.O.A.:

2/2/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TOM SON LING SANDY

Driver Tel No.:

(V/L YES / NO)

Claim No.:

15/18/18/1051020422

Policy No.:

2120005016059

Make / Model:

MINI

Place of Accident:

TUNGH TOWN HALL / AYE

Mme

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SDU 87770



INSRS:

WSP:

Tel:

Liability:

RMKS:

chc



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
26/2/18	SDU 87770 - 4	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
11/3/18	Bola 27. Head to Rear.	Documentation Check List: Handler	Typist
13/3/18	Email workshop liability clear.	Notification ltr (if non-pickup)	
13/4/18	File pass to typist type report	After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
6/6/18	Email to LPC to seek mandate	Final Repair Bill:	
7/6/18	Email from LPC approve mandate	Car Rental Invoice:	
		Towing Invoice	
		LTA / GIA :	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	
PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost: \$		Confirm by:	
(days) Reduction: %		Email <input type="checkbox"/> Call <input type="checkbox"/>	
FINAL SETTLEMENT Date/Time: 18/6/18		Confirm with: Amanda	
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27.		Email <input type="checkbox"/> Call <input type="checkbox"/>	
Repair Cost: \$ 4730.02		If NO or B 28, Ass. Ltd:	
Loss of Rental (LOR): \$ 545.70 (3 days) x 170 = 630		COPY SENT 2/6/18	
Loss of Use (LOU): \$ (\$ x days)			
Loss of Income (LOI): \$ (\$ x days)			
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]			
GIA/LTA Search \$ 2.00			
Medical: \$ -		1) Claim status: Normal/Reject/Private Settle	
Disbursement: \$ - (e.g. Tow/ Independent)		2) Report Format:	
Legal Cost \$ -		3) Survey fee:	
Total: \$ 5277.72		Global Sum \$:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1: \$ 5277.72		Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 2: (Strike if N.A.) \$		Name 1: Cycle & Carriage Industries Pte Ltd.	
Payee 3: (Strike if N.A.) \$		Name 2:	
		Name 3:	

SYNOPSIS

Taufik

REF:

LPC

ASSIGNMENT

From:

Date:

21/03/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SDU 8333D

at Workshop m/s

Cycle & Carriage
188 panden loop

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Morning
YIK

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

2-B.2 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Wp

Vehicle: IN / OUT

Date:

Person Contacted:

YIK

Date / Time

Action / Instruction

13/4/18

Confirm 2-B.2 \$4420.58 with 3 working days

Veh No:

SDU8333D

Yr Regn:

2018 Feb.

Type:

M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Meyden Suz E250

C.C. 1991

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

2918

T/Radio: Insured / Std / NI / NA

Eng/No:

WDD 213045 2A37 6366

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 275/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

4

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

21/3/18 21220

Survey held at

C&C Panden Loop

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) S + RS 100

2) Photos

3) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

TOTAL

(Red - \$1222.78
20%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18003720/wb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 27-02-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKF 3214T	Veh. Inspected	SDU 8333D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/02/2018	Inspection Date	
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18003720/T1wb3

Date: 26.03.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SDU8333D


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.03.2018 at the premises of M/s Cycle & Carriage Industries Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,643.36
Revised Estimate Amount	: S\$	4,420.58
"Check" Items Amount	: S\$	832.78
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

Catherine Chong (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Friday, 23 February, 2018 2:20 PM
To: Yik Chan Hoe; assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: RE: Our Ref: 17/18/18/VP05/020422 Accident involving motor vehicle nos. SDU 8333 D & SKF 3214 T // Propose for Direct Settlement
Attachments: img-222182045-0001.pdf

Dear Chan Hoe,

We will be appoint LKK Auto Consultants Pte Ltd to survey SDU 8333D.

Dear Catherine/Navitha,

FYA.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

-----Original Message-----

From: Yik Chan Hoe [mailto:chanhoe.yik@cyclecarriage.com.sg]
Sent: Thursday, 22 February, 2018 6:26 PM
To: MT_Claim_SG
Subject: Accident involving motor vehicle nos. SDU 8333 D & SKF 3214 T // Propose for Direct Settlement

To: Lonpac Ins
Attn: Motor Claims Dept

RE: Accident involving motor vehicle nos. SDU 8333 D & SKF 3214 T along Jurong Town Hall road junction, Accident date: 22/02/2018

Dear Officer In-Charge,

This email is with regards to the above accident which has been reported by our customer. We have since been instructed by him/her (motor vehicle number SDU 8333 D), to submit a claim on his/her behalf as we are the authorised repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number SKF 3214 T) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

I can be reached at chanhoe.yik@cyclecarriage.com.sg

26/02/2018 @ 4:08pm
Yik veh not in

Thanks & Regards,

Yik Chan Hoe

Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd

Pandan Loop Service Center

Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.



Mercedes-Benz

Survey delayed
by LKR.Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDU8333D

Teo Tai Hin (zhang Taixing)

68 Pavilion Rise
Singapore 658061

WIP No

21488

Reg No/Reg Date

SDU8333D / 05/02/2018

Date In/Mileage

/ 0

Chassis No

WDD2130452A376366

Engine No

27492031303180

Make/Model

MB/MB E 250 2.0 SEDAN (W213) "AVANTGARDE

Colour/Trim

028 890 Cavansit B1/ 042 214 Leather - J

Account No	Terms	Date/Time Printed	CSE	Operator			
WCV33980	CRDVCH	22/02/2018/ 18:19	YK	395 / Yik Chan Hoe			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M. BPNSUN

POLICY NO/ACC DATE : 180008582 // 22/02/2018
DRIVE IN/EXCESS : 22/02/2018 // TP VEH NO SKF3214T LONPAC
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW
BODY PANELS WITH REFINISH.

A BPIRES

RESPRAY REAR BUMPER

A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO
STANDARD SETTINGS.

M REAR BUMPER UNDER BRACKET

M REAR BUMPER LOWER CHROME MOULDING

M REAR BUMPER LOWER

M REAR BUMPER

M REAR CROSS MEMBER

1.00	69.87	00.00
1.00	301.99	00.00
1.00	260.25	00.00
1.00	1918.34	00.00
1.00	762.91	00.00

960 1200.00

600 750.00

0.10 ✓ 380.00

NP? 69.87
ent 301.99
de 260.25
de 1918.34
NP? 762.91

ESTIMATE

Tanjin 974 95749
'wp'
21/3/18 @ 1220
3 days
surv @ lkr auto
Resurvey check items
Resurvey before paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1277
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

Nett	5,643.36
7% GST on	5643.36
	395.04
Total Payable	6,038.40

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18003720/T1wb3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 28-06-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKF 3214T	Veh. Inspected	SDU 8333D
Policy No.	Z17VP05016059	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020422	Excess (\$)	0.00
Assign From	ERIC	Assign Date	23/02/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E250	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WDD2130452A376366	Colour	BLUE
Odometer	2918	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/40 R18	PIRELLI	6 mm
L/H Front Tyre	275/40 R18	PIRELLI	6 mm
R/H Rear Tyre	275/40 R18	PIRELLI	6 mm
L/H Rear Tyre	275/40 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/02/2018	Inspection Date	21/03/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDU 8333D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER UNDER BRACKET (SN)	NOT NECESSARY	69.87	-
1	REAR BUMPER LOWER CHROME MOULDING (SN)	CUT	301.99	301.99
1	REAR BUMPER LOWER (SN)	DEFORMED	260.25	260.25
1	REAR BUMPER (SN)	DEFORMED	1,918.34	1,918.34
1	REAR CROSS MEMBER (SN)	NOT NECESSARY	762.91	-
			3,313.36	2,480.58
LABOUR				
	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.		1,200.00	960.00
	RESPRAY REAR BUMPER.		750.00	600.00
	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
			2,330.00	1,940.00
GRAND TOTAL			5,643.36	4,420.58
RECOMMENDED COST OF REPAIRS				4,420.58

Report Ref No. CC4/LPC18003720/T1wb3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.