



Mercedes-Benz

*Survey delayed
by LKK.*

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDU8333D

Teo Tai Hin (zhang Taixing)

68 Pavilion Rise
Singapore 658061

Vehicle & Document Information

WIP No	21488
Reg No/Reg Date	SDU8333D / 05/02/2018
Date In/Mileage	/ 0
Chassis No	WDD2130452A376366
Engine No	27492031303180
Make/Model	MB/MB E 250 2.0 SEDAN (W213) "AVANTGARDE
Colour/Trim	028 890 Cavansit B1/ 042 214 Leather - J

Account No	Terms	Date/Time Printed	CSE	Operator
WCV33980	CRDVCH	22/02/2018/ 18:19	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 180008582 // 22/02/2018 DRIVE IN/EXCESS : 22/02/2018 // TP VEH NO SKF3214T LONPAC DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				960 1200.00
A BPIRES RESPRAY REAR BUMPER				600 750.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			0.10	✓ 380.00
M REAR BUMPER UNDER BRACKET	1.00	69.87	00.00	? 69.87
M REAR BUMPER LOWER CHROME MOULDING	1.00	301.99	00.00	ent 301.99
M REAR BUMPER LOWER	1.00	260.25	00.00	de ✓ 260.25
M REAR BUMPER	1.00	1918.34	00.00	de ✓ 1918.34
M REAR CROSS MEMBER	1.00	762.91	00.00	? 762.91

ESTIMATE

*Tanjin 974 95749
'wp'
21/3/18 1220
3 days
sw@lkk auto
Resurvey check items
Resurvey before paint*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Confirmed & accepted by approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Authorized signatory and company stamp

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

	Nett	5,643.36
7% GST on	5643.36	395.04
Total Payable		6,038.40

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg