

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5623J - CHINA TAIPING

AAD1802-230

*Not Authorized
61 Sep 8 1630h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5623J - JHOW

VF1ABL15AUC280289

RENAULT

LATITUDE

23.02.2018

CHINA TAIPING**PART****LIST**

1	1	BUMPER COVER FRT	\$	Bu 1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	Sh 181.75	X
3	1	BUMPER ABSORBER FRT	\$	Sh 394.68	✓
4	1	BUMPER RETAINER FRT LH	\$	Dis 151.41	✓
5	1	BUMPER SUPPORT FRT	\$	Sh 123.88	
6	1	BUMPER RETAINER FRT RH	\$	Sh 150.77	
7	1	BUMPER SUPPORT FRT	\$	Sh 123.88	
8	1	BUMPER UNDERTRAY FRT	\$	Sh 472.83	
9	1	BUMPER GRILLE LOWER FRT	\$	Sh 266.80	
10	1	BUMPER FOG LAMP GRILLE LH	\$	Sh 207.21	
11	1	BUMPER FOG LAMP GRILLE RH	\$	Sh 207.21	
12	1	BUMPER BEAM FRT	\$	N 914.08	
13	1	TOW COVER FRT	\$	Sh 28.61	
14	1	RADAIOR GRILLE	\$	Sh 1,707.78	
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	N 225.36	
16	1	RADAIOR GRILLE FRAME	\$	Sh 1,353.75	X
17	1	FRAME FULL SUPPORT PANEL	\$	Sh 615.90	
18	1	FRAME FULL SUPPORT BRACKET	\$	N 89.79	
19	1	FRONT BRACE PANEL	\$	N 177.22	
20	1	HORN	\$	Sh 314.17	
21	1	HORN BRACKET	\$	N 40.45	
22	1	HEADLAMP LH	\$	Sh 1,184.43	
23	1	HEADLAMP RH	\$	Sh 1,184.43	
24	1	HEADLAMP PANEL FRT LH	\$	N 152.15	
25	1	HEADLAMP PANEL FRT RH	\$	N 152.15	
26	1	BONNET	\$	N 1,941.63	
27	1	BONNET INSULATOR	\$	Sh 405.73	
28	1	BONNET STRUT LH	\$	Sh 88.61	
29	1	BONNET STRUT RH	\$	Sh 88.61	
30	1	BONNET HINGE LH	\$	N 348.31	
31	1	BONNET HINGE RH	\$	N 348.31	
32	1	BONNET LOCK	\$	N 305.48	
33	1	BONNET CABLE	\$	Sh 119.19	
34	1	BONNET CABLE COVER	\$	Sh 161.03	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-230

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5623J - CHINA TAIPING

35	1	BONNET SEAL OUTER	\$	<i>Sn</i>	92.36	}	<i>X</i>
36	1	FENDER PANEL FRT LH	\$	<i>K</i>	783.83		
37	1	FENDER PANEL FRT RH	\$	<i>K</i>	783.83		
38	1	WHEELARCH FRT LH	\$	<i>Sn</i>	278.84		
39	1	WHEELARCH FRT RH	\$	<i>Sn</i>	278.84		
40	1	FENDER BRACKET LOWER LH	\$	<i>Sn</i>	15.79		
41	1	FENDER BRACKET LOWER RH	\$	<i>Sn</i>	15.79		
42	1	FENDER INSULATOR LH	\$	<i>Sn</i>	130.84		
43	1	FENDER INSULATOR RH	\$	<i>Sn</i>	130.84		
44	1	ROTARY SWITCH	\$	<i>Sn</i>	1,253.11		

TOTAL	\$	19,251.08
10%	\$	1,925.11
	\$	17,325.98

Specical Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	nn	52.00	X
2	1SET	BUMPER CLIP FRT	\$	nn	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	}
4	1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
7	1	TOW COVER FRT	\$	Sn	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	Sn	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
13	1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	
14	1SET	WHEELARCH CLIP FRT RH	\$	nn	29.40	
15	1	CAP HUB LH FRT	\$	Sn	35.00	
16	1	RIM LH FRT	\$	Sn	385.00	
17	1	TYRE LH FRT	\$	Sn	330.00	}
18	1	CAP HUB RH FRT	\$	Sn	35.00	
19	1	RIM RH FRT	\$	Sn	385.00	
20	1	TYRE RH FRT	\$	Sn	330.00	
21	1SET	Front licence plate with holder	\$	nn	80.00	45nn
22	1	DOOR STICKER "6555-3333"LH	\$	nn	80.00	X
23	1	DOOR STICKER "6555-3333"RH	\$	nn	80.00	X

TOTAL	\$	2,182.40
TOTAL PARTS	\$	19,508.38

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5623J - CHINA TAIPING**AAD1802-230**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2501 2,800.00
Towing Fees.	\$	nn 120.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
Putty and spray painting of the affected portion.	\$	3,000.00 8901
To rust-proofing of the affected areas.	\$	nn 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	" 170.00 102
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X

TOTAL	\$	7,580.00
Over All Total	\$	27,088.38

Repair Days**10 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: