

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

(TZ)

12-Feb-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8916 A

1 pc	Front o/s wheel cover <i>X repair</i>	\$	116.00
1 pc	Front o/s fender <i>X repair</i>	\$	384.00
1 pc	Front o/s fender inner shield <i>X</i>	\$	120.00
1 pc	Front bumper <i>X repair</i>	\$	531.00
1 pc	Front bumper emblem <i>X</i>	\$	44.00
1 pc	Front bumper o/s side retainer <i>X</i>	\$	16.00
		\$	1,211.00
Less 10%		\$	121.10
		\$	1,089.90

S/NETT

1 set	Front o/s fender inner shield clips <i>X</i>	\$	28.00
1 set	Front bumper clips <i>X</i>	\$	48.00
1 pc	Front o/s fender sticker <i>X</i>	\$	30.00
Sundry		\$	50.00 20
To check wheel alignment		\$	80.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same		\$	650.00 200
To putty and spray painting on front bumper, front o/s fender		\$	500.00 260
To apply rustproofing on the repaired and replaced panels.		\$	120.00 X
		\$	2,495.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Ka hua (1001)
26/2/18 1330h
3 Day
4/5
After Repair

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: