

610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

ASSESSMENT FOR REPAIR: HONDA NC700XD - FBH7128D

Engine No.: RC61E5208346

[illegible]

1 pc	Left rear footrest ✕	\$115.00
1 pc	Left footrest holder ✕	\$375.00
1 pc	Right rear footrest ✕	\$115.00
1 pc	Right footrest holder ✕ ?	\$375.00
1 pc	Left side cover ✕	\$295.00
1 pc	Right side cover ✕ ✕	\$295.00
1 pc	Rear tail cover assy upper ✕	\$335.00
1 pc	Rear tail cover assy lower R	\$325.00
1 pc	Rear left signal ✕	\$165.00
1 pc	Rear right signal ✕	\$165.00
1 pc	Exhaust comp ✓ wtf	\$1,880.00
		\$15,010.00
	Less discount 10%	\$1,501.00
		<u>\$13,509.00</u>

Special nett items

1 pc	Front sport rim ?	\$995.00
1 pc	ERP IU ✕	\$157.00
1 pc	Box bracket ✕	\$265.00
1 pc	Top case ✓ wtf	\$495.00

1)	Towing charges	\$100.00 60
2)	Replace, realign and adjust above damaged parts	\$800.00 300
3)	Balancing front wheel rim	\$180.00 80
4)	To remove/refit, replace (if damage) check and straighten front fork tubes	\$180.00 100
5)	Reset Meter	\$120.00 80
6)	To knock, straighten chassis & body balancing	\$450.00 200
7)	Spray painting	\$500.00 300

Total Estimate

\$17,751.00

Note: The above estimate is subjected to the prevailing GST of 7%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Bike Production Pte Ltd

Sebastian.

2018/3/18

- Part by part repair.
- Question mark Item Photo
- Photo Before Paint

Excess : \$ 750

Revert

90036121

sebastianyeang@lkkauto.com