FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay Singapore 417883 Tel No:67452063/67467158 Fax No:67458520 Not Alloral
when

d/s=9000

947.

VEH: SKA6825L

		ANACHINIT
QTY	PARTICULAR	AMOUNT POINT
1PCS	BOOTLID	m/su(\$685.10
1PCS	BOOTLID REAR LOGO	400.00
1PCS	BOOTLID 'CITY' EMBLEM	ΨΟΟ.ΔΟ /
1PCS	BOOTLID 'I-VTEC' EMBLEM	ne \$36.50
1PCS	BOOTLID OUTER HANDLE 28f.60	c na \$366.20
1PCS	BOOTLID INNER LOCK /92.33	Yn \$245.30
1PCS	BOOTLID LOCK STRIKER	11 \$66.80 X
2PCS	BOOTLID HINGES @\$101.00	11 \$202.00 X
1PCS	BOOTLID WEATHERSTRIP	Twi \$166.30
1PCS	BOOTLID KEY CYCLINDER	Pge \$245.30 -
1PCS	REAR BUMPER	\$585.20
2PCS	REAR BUMPER SIDE HOLDERS @\$25.50	34 \$51.00 -
1SET	REAR BUMPER CLIPS	Ner \$39.00/
1PCS	REAR EXHAUST	\$688.20 \[\alpha \]
2PCS	REAR EXHAUST MOUNTINGS @\$45.00	11 \$90.00 ×
1PCS	REAR END PANEL	3-60 \$445.10
1PCS	REAR END PANEL TOP GARNISH	Twi \$221.30
1PCS	REAR FLOOR PANEL	1,066.30 X
1PCS	REAR FLOOR PANEL TOP BOARD /FY.SV	71-1 \$428.30
2PCS	TAILLAMPS @\$382.30	C~ \$764.60
2PCS	TAILLAMP HOUSING PANELS @\$285.20	015 BD \$570.40 WC
2PCS	REAR FENDERS @\$843.59	\$1,687.18
2PCS	REAR FENDER INNER TRIMS @\$262.50	u - \$525.00 >
1PCS	REAR WINDSCREEN MOULDING	11 \$82.30 ×
1PCS	BONNET 645-120	10/10 \$866.20
1PCS	BONNET RUBBER 66.50	ny \$83.40
1PCS	BONNET LOCK / 25.00	1~1 \$268.30
2PCS	BONNET HINGES @\$85.00	11 \$170.000
1PCS	FRONT BUMPER (-)) · 0 /	20/ne \$645.20
2PCS	FRONT BUMPER SIDE RETAINERS @\$30.50	Bef \$61.00
1SET	FRONT BUMPER CLIPS	u \$50.00
1PCS	FRONT BUMPER REINFORCEMENT 273.20	Bul \$345.20
2PCS	FRONT BUMPER BRACKETS @\$68.50	\$137.00
1PCS	RADIATOR GRILLE	CM \$389.20
1PCS	RADIATOR GRILLE 'H' LOGO	NU \$35.50/
or assert		400.004

29/0

2PCS 1PCS 1PCS 1PCS 2PCS	HEADLAMPS @\$845.20 FRONT SUPPORT PANEL AIRCON CONDENSER RADIATOR ASSY RADIATOR FAN MOTOR FRONT FENDERS @\$645.00 S.NETT	85.10 KZ = 970.20	9125.71	201 201 11 11	\$1,690.40 \$663.50 \$923.40 \$1,088.20 \$ \$455.20 \$ \$1,290.00 \$ 18,493.08
1SET 1PCS 1PCS 1SET 1PCS 1BOL	REAR BUMPER REVERSE SE REAR LICENCE PLATE W/HO REAR END PANEL SEALANT REAR FLOOR PANEL INSULA FRONT LICENCE PLATE W/H RADIATOR COOLANT	ATOR		sull suf M 11 3ul	\$280.00 200 \$50.00 40 \$50.00 \times \$280.00 \times \$50.00 \times \$50.00 \times
	TO CHECK WIRING TO DISMENTLE & REPLACING TO TRANSFER BOOTLID MEG TO DISMENTLE & REFIX SEA TO DISMENTLE & REFIX REA TO DISMENTLE & REFIX REA TO DISMENTLE & REFIX PETI TO SPRAY RUST PROOFING TO REFILL AIR CON GAS LABOUR FOR PANEL BEATING TO PUTTY & SPRAY PAINTING	CHANISM T,CUSHION UPHOLSTER' R EXHAUST R WINDSCREEN ROL TANK G & REPLACING PARTS	Y		\$80.00 30 \$80.00 50 \$100.00 60 \$150.00 fo \$150.00 x \$100.00 x \$100.00 x \$150.00 / 00 \$150.00 / 00 2,800.00 / 600
		Т	OTAL	\$2	5,643.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

(1310-28

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: