

22/03/2002

ASS. REC. BY:

REF: CS/EAT/18003755/Kad3m2

Special Instruction:

Surveyor: Kenneth**ASSIGNMENT (Office)**From (Person): Siti Atwikah

of

EATDate/Time: 26/2/18 @ 5:06pm

Estimated Cost:

Bill to:

OD TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 952L

Insured:

GX 354U

at Workshop m/s

Trans-Cab

Tel:

6786 6666

of

No. 2 AMK St-63

Policy No:

Claim No:

DS MCV 1800369 / SL / SQ

Sum Insured:

Excess:

Make of Veh:

D.O.A. 22/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

9:05am @ 27/2/18

Person Contacted:

CandyVehicle IN / OUT

Date/Time	Action/Instruction
	(<u>Estimate</u>
	<u>SHD 952L-X</u>
	<u>GX 354U-X</u>
<u>01/3/18 @ 9.48am</u>	<u>revised to Siti by email.</u>
	<u>Final fig @ 5137.67, 2 1/2 days (Red @ 37278.40, 88%)</u>

EGJ

27/2/18

SHD 952L

07 17

SHD 952L
Trans-cab
No. 2 Amk St-63

Permit A
M. White 1st
74180

VIFIABLISAUC 283507

215/80R4



Remarks: The van had commenced its
repair at the time of inspection

On or After: 27/2 Consistent? Yes or No
On or Before: 1-B1 Consistent? Yes or No
On or After: 27/2 Consistent? Yes or No
On or Before: 1-B1 Consistent? Yes or No

On or After: 27/2 Consistent? Yes or No

Date: 27/2/18 Person Contacted: TP

Date: 28/2 Action: File pass to Coroner

RECEIVED 20 JUN 2018

On or After: 27/2 Consistent? Yes or No
On or Before: 1-B1 Consistent? Yes or No

Days Of Report: 27/2
Reference No. of TFD: 27/2

On or After: 27/2 Consistent? Yes or No
On or Before: 1-B1 Consistent? Yes or No

On or After: 27/2 Consistent? Yes or No

On or After: 27/2 Consistent? Yes or No
On or Before: 1-B1 Consistent? Yes or No



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18003755/Kqd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 27-02-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GX 354U	Veh. Inspected	SHD 952L
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCV1800369/SL/sa	Excess (\$)	0.00
Assign From	SITI ATHIKAH	Assign Date	27/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	22/02/2018	Inspection Date	27/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

ERGO

Date: 23.02.2018
Our Reference: GX354U/SE/sa
Your Reference: SHD952L

Sent via Fax

or

Email

candy.kong@transcab.com.sg

To: TRANS-CAB SERVICES PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SHD 952L
Insured's Vehicle: GX 354U
Date Of Accident: 22.02.2018


We acknowledge receipt of your request for PRS on: 23.02.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	LKK	LKK Auto Consultants Pte Ltd
JPK	JP Knights Pte Ltd	PS	Priority Services
		VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input checked="" type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>We are therefore not in a position to discuss on liability at this juncture.</u>

Prepared by:		Siti	6829 9170	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Nivitha (LKK Auto)

From: Siti A Thikah AB Rahman <siti.rahman@ergo.com.sg>
Sent: Monday, 26 February 2018 5:06 PM
To: Catherine Chong (LKK Auto) (admin-d@lkkauto.com)
Subject: OI: GX 354U | TP: SHD 952L | LKK | DOA: 22.02.2018 - PRS | OUR REF: DSMCV1800369/SL/sa
Attachments: ARRANGE FOR SURVEY SHD952L (402 KB); PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company LKK Auto Consultants Pte Ltd to be the "Single Joint Expert".

Please conduct this survey request on without prejudice basis and to try finalise with the repairer on the repairs. (Note: Our insured has yet to lodge the accident report to us).

Please fill up the necessary on ERGO PRS Form and return to us together on your update of the survey status.

Attached are the necessary documents for your further actions.

Kindly acknowledge receipt of this email.

NOTE: Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Warmest regards
Siti A'thikah
Claims Department
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9170
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

From: Siti A Thikah AB Rahman
Sent: Monday, 26 February, 2018 5:03 PM
To: 'Candy Kong'
Cc: ERGO Insurance Pte. Ltd. (Claims Department)
Subject: RE: GX 354U | TP: SHD 952L | DOA: 22.02.2018 - OUR REF:GX354U/SL/sa

WITHOUT PREJUDICE

Dear Candy,

We shall arrange our surveyor from LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Thank you.

Warmest regards

Siti A'thikah
Claims Department
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9170
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

-----Original Message-----

From: Candy Kong [<mailto:candy.kong@transcab.com.sg>]
Sent: Monday, 26 February, 2018 4:58 PM
To: Siti A Thikah AB Rahman
Cc: ERGO Insurance Pte. Ltd. (Claims Department)
Subject: GX 354U | TP: SHD 952L | DOA: 22.02.2018 - OUR REF:GX354U/SL/sa

Hi SITi,

PLS ARRANGE LKK AUTO CONSULTANTS PTE LTD TO SURVEY.

Thks & Rdgs
Candy Kong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

-----Original Message-----

From: Siti A Thikah AB Rahman [<mailto:siti.rahman@ergo.com.sg>]
Sent: Monday, 26 February, 2018 4:48 PM
To: Candy Kong <candy.kong@transcab.com.sg>
Cc: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Subject: RE: GX 354U | TP: SHD 952L | DOA: 22.02.2018 - OUR REF:GX354U/SL/sa

WITHOUT PREJUDICE

Dear Candy,

Please refer to both of our emails for your reply.

Thank you.

Warmest regards
Siti A'thikah
Claims Department

ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9170
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment-----Original Message-----

From: Candy Kong [mailto:candy.kong@transcab.com.sg]

Sent: Monday, 26 February, 2018 4:44 PM

To: ERGO Insurance Pte. Ltd. (Claims Department)

Subject: ARRANGE FOR SURVEY SHD952L

Dear all,

Resend.

Pls arrange to survey urgently

Thks & Rdgs
Candy Kong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

-----Original Message-----

From: Candy Kong [mailto:candy.kong@transcab.com.sg]

Sent: Friday, 23 February, 2018 10:45 AM
To: 'claims@ergo.com.sg' <claims@ergo.com.sg>
Subject: ARRANGE FOR SURVEY SHD952L

Dear all,

Please arrange for survey as below :

GX354U - 22.02.2018 at 0655Hrs - SHD952L Lunch time : 12pm - 1pm.
Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs
Candy Kong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 1 March 2018 9:48 AM
To: 'Siti A Thikah AB Rahman'
Cc: assignments; SUR
Subject: RE: GX 354U | TP: SHD 952L | LKK | DOA: 22.02.2018 - PRS | OUR REF: DSMCV1800369/SL/sa
Attachments: CSEGI18003755Kqd3.pdf

Dear Siti,

Enclosed herewith preliminary advice of SHD 952L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 27 February 2018 1:20 PM
To: 'Siti A Thikah AB Rahman' <siti.rahman@ergo.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: GX 354U | TP: SHD 952L | LKK | DOA: 22.02.2018 - PRS | OUR REF: DSMCV1800369/SL/sa

Dear Siti,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Siti A Thikah AB Rahman [<mailto:siti.rahman@ergo.com.sg>]
Sent: Monday, 26 February, 2018 5:06 PM
To: Catherine Chong (LKK Auto) (admin-d@lkkauto.com) <admin-d@lkkauto.com>
Subject: OI: GX 354U | TP: SHD 952L | LKK | DOA: 22.02.2018 - PRS | OUR REF: DSMCV1800369/SL/sa

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company LKK Auto Consultants Pte Ltd to be the "Single Joint Expert".

Please conduct this survey request on without prejudice basis and to try finalise with the repairer on the repairs.
(Note: Our insured has yet to lodge the accident report to us).

Please fill up the necessary on ERGO PRS Form and return to us together on your update of the survey status.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMCV1800369/SL/sa

Date: 01st March 2018

Our Ref: CS/EG18003755/Kqd3

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SHD 952L


We thank you for the instruction on 26/02/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/02/2018 at the premises of M/s TRANS-CAB and have the following to report:-

Workshop Estimate Amount	: S\$ <u>42,416.07</u>
Revised Estimate Amount	: S\$ <u>5,137.67</u>
"Check" Items Amount	: S\$ <u>699.77</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 2.5 days.

We have NOT authorise repair.

Yours faithfully

KENNETH KONG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD952L
Vehicle to be Exported:	Yes
Intended De-registration Date:	22 Feb 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003254
Chassis No.:	VF1ABL15AUC283507
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	03 Jul 2017
First Registration Date:	03 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jul 2025
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	

COE Expiry Date:	02 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$38,560.00
COE Rebate Amount:	\$30,848.00
Total Rebate Amount:	\$45,846.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Feb 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 952L**AAD1802-218***Not Authorised
Recovery By part*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 952L

VF1ABL15AUC283507

RENAULT

LATITUDE

22.2.2018

ERGO**PART****LIST**

- | | |
|----|--------------------------------|
| 1 | 1 BUMPER COVER REAR |
| 2 | 1 BUMPER LOWER REAR |
| 3 | 1 BUMPER BRACKET CTR REAR |
| 4 | 1 BUMEP R BRACKET SIDE RH REAR |
| 5 | 1 BUMEP R RETAINER RH REAR |
| 6 | 1 BUMPER REFLECTOR RH |
| 7 | 1 BUMEP R BRACKET SIDE LH REAR |
| 8 | 1 BUMEP R RETAINER LH REAR |
| 9 | 1 BUMPER REFLECTOR LH |
| 10 | 1 BUMPER BEAM REAR |
| 11 | 1 BUMPER BEAM BRACKET LH REAR |
| 12 | 1 BUMPER BEAM BRACKET RH REAR |
| 13 | 1 BOOT REAR |
| 14 | 1 BOOT FINISHER |
| 15 | 1 BOOT WHEATERSTRIP |
| 16 | 1 BOOT REFLECTOR LAMP LH |
| 17 | 1 BOOT REFLECTOR LAMP RH |
| 18 | 1 BOOT BADGE 'RENAULT' |
| 19 | 1 BOOT BADGE |
| 20 | 1 BOOT INNER TRIM |
| 21 | 1 BOOT SWITCH |
| 22 | 1 BOOT LOCK |
| 23 | 1 BOOT LOCK CATCH |
| 24 | 2 LICENCE PLATE LAMP |
| 25 | 2 BOOT RUBBER PLUG |
| 26 | 1 TAILLAMP RH |
| 27 | 1 TAILLAMP PANEL RH |
| 28 | 1 TAILLAMP LH |
| 29 | 1 TAILLAMP PANEL LH |
| 30 | 1 OUTER PANEL REAR (End Panel) |

\$	<i>B</i> 1,108.46 ✓
\$	<i>SL</i> 768.84 X
\$	<i>SL</i> 113.47 X
\$	<i>SL</i> 135.97 X
\$	<i>SL</i> 44.99 X
\$	<i>SL</i> 43.61 X
\$	<i>SL</i> 135.97 ✓
\$	<i>SL</i> 44.99 X
\$	<i>SL</i> 43.61 X
\$	<i>R</i> 777.52 X
\$	<i>R</i> 225.95 X
\$	<i>R</i> 225.95 X
\$	<i>B</i> 2,872.68 ✓
\$	<i>SL</i> 470.06 X
\$	<i>SL</i> 323.05 ✓
\$	<i>SL</i> 493.35 ✓
\$	<i>SL</i> 493.35 X
\$	<i>R</i> 225.36 ✓
\$	<i>R</i> 225.36 ✓
\$	<i>SL</i> 586.45
\$	<i>SL</i> 168.13
\$	<i>R</i> 202.67
\$	<i>R</i> 74.40
\$	<i>SL</i> 50.52 } X
\$	<i>SL</i> 221.81
\$	<i>SL</i> 552.55
\$	<i>R</i> 986.70
\$	<i>SL</i> 552.55
\$	<i>R</i> 986.70
\$	<i>R</i> 1,471.77

Trans-cab Auto Services Pte Ltd**AAD1802-218**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 952L

31	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sm 404.56 X
32	1 EXHAUST REAR	\$	R 7,489.05 X
33	1 EXHAUST CAP REAR	\$	R 230.49 X

TOTAL	\$	22,750.91
10%	\$	3,586.89
	\$	32,282.05

Special Nett

1	1SET PARKING AID	\$	Sm 700.00 X
2	1SET REAR BUMPER CLIP	\$	nn 66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	nn 33.00 —
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn 10.00
5	1SET BUMPER RETAINER RH CLIP RR	\$	nn 20.00
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn 10.00
7	1SET BUMPER RETAINER CLIP LH RR	\$	nn 20.00
8	1SET BUMPER LOWER REAR RIVET	\$	nn 22.00
9	1SET BUMPER LOWER REAR CLIP	\$	nn 66.00
10	1 EXHAUST MOUNTING REAR	\$	Sm 17.82
11	1SET BOOT FINISHER CLIP	\$	nn 24.20
12	1 BOOT STICKER "Trans-cab"	\$	nn 30.00 —
13	1 BOOT STICKER "6555-3333"	\$	nn 30.00 —
14	1 BOOT INNER TRIM CLIP	\$	nn 45.00 X

TOTAL \$ 1,094.02**TOTAL PARTS \$ 33,376.07****LABOUR**

Putty And Spray Painting Of The Affected Portion.

\$ 3,500.00 4801

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 3,200.00 4001

To Rust-Proofing Of The Affected Areas.

\$ 170.00 301

Trans-cab Auto Services Pte Ltd**AAD1802-218**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 952L

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	~ X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	~ X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	~ X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	~ X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	~ X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	~ X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	~ X
To check steering geometry and computer wheel alignment	\$	220.00	~ X

TOTAL \$ 9,040.00**Over All Total \$ 42,416.07**

30609.82

PART BY PART

LKK Auto Cons	Repair Days	10-DAYS
the Repairer of the following:		
• To resurvey before/after spray painting		
• To display damaged part(s) during resurvey		
• Parts prices are subject to confirmation		
• Third party survey is on a "Without Prejudice" basis		
• No illegal modification(s) is allowed		
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
Acknowledged by Repairer:		
Signature:		
Date:		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18003755/Kqd3n2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 21-06-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GX 354U	Veh. Inspected	SHD 952L
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCV1800369/SL/sa	Excess (\$)	0.00
Assign From	SITI ATHIKAH	Assign Date	26/02/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VF1ABL15AUC283507	Colour	METALLIC WHITE / RED
Odometer	74190	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GOODYEAR	8 mm
L/H Front Tyre	215/60 R16	GOODYEAR	8 mm
R/H Rear Tyre	215/60 R16	GOODYEAR	8 mm
L/H Rear Tyre	215/60 R16	GOODYEAR	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/02/2018	Inspection Date	27/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2.500 Working Days
-------------------------------------	--------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 952L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-

Report Ref No. CS/EG18003755/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-2,275.09	-443.19
			20,475.80	3,988.67
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
			1,094.02	159.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,500.00	440.00

Report Ref No. CS/EGI18003755/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR,BUMPER BEAM BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR,BOOT LOCK,BOOT LOCK CATCH,TAILLAMP PANEL RH,TAILLAMP PANEL LH,OUTER PANEL REAR (END PANEL),EXHAUST REAR AND EXHAUST CAP REAR.		3,200.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			9,040.00	990.00
GRAND TOTAL			30,609.82	5,137.67
RECOMMENDED COST OF REPAIRS				5,137.67

Report Ref No. CS/EG18003755/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.