

ASS. REC. BY:

REF: CS/EGJ18003757/ Yads<sup>02</sup>

Special Instruction:

Surveyor: Marcel

**ASSIGNMENT (Office)**

From (Person): Yee pei Li

of EGI

Date/Time: 27/2/18 @ 11:32am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKK 8933S

Insured: SGB 9932H

at Workshop m/s Trans Eurocars

Tel: G3958784

of 5 ubi close

Policy No:

Claim No: SGB 9932H / SE / p1

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 23/2/18

28/2/18 @ 11am

CA / REV / REP. / REV 24 HRS <sup>lup</sup>

H.O.D. Endorsement:

Date/Time: 11:49am @ 27/2/18

Person Contacted: Jess

Vehicle IN / OUT

Date/Time	Action/Instruction ( ) Estimate
	SKK 8933S - x
	SGB 9932H - x
<u>02/3/18 @ 2:09pm</u>	<u>revised to Steve Lim by email.</u>

REF: PGI

ASSIGNMENT

From: \_\_\_\_\_ Date: 28/02/2018

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKK 89335

at Workshop no: Trans Eurokars

of: 5 Ubi Close

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Jess

Veh No: SKK 89335 Yr Regn: J 17

Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or  CA

Make: Mazda 6 CC: 1998

Colour: Grey A/C: Insured / Std / NI / NA

So. Reading: 4753 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM 66L1071J0129740

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Mod:  NI / S/Rim / STD A/Rim or

Tyre Size F: 225/55R17

R: \_\_\_\_\_

Make of Veh: Jess

11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

ID/C Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GR/FR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front	6	Rear	6
R. Bal.	mm	R. Bal.	mm
L. Bal.	mm	L. Bal.	mm
D.O.A.	23/2/18	D.O.I.	28/2/18

Survey held at: \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

21/4/18 confirmed final by \$ 3891.86 with customer.  
(Ref \$ 2622.05, 40%)

RECEIVED 24 APR 2018

Date/Time File Pass to?  : Preli. Report

21/4/18  : Final Report

Date/Time File Return to? \_\_\_\_\_

Report Format: TP

Lump Sum / I.B.I. \$ 3891.86

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:  Site Insp \$ \_\_\_\_\_

Interview \$ \_\_\_\_\_

Tech Insp \$ \_\_\_\_\_

Weekend \$ \_\_\_\_\_

TOTAL: 250




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18003757/Uqd3	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 27-02-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGB 9932H	Veh. Inspected	SKK 8933S
Policy No.		Coverage (\$)	0.00
Claim No.	SGB 9932H/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	27/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/02/2018	Inspection Date	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Tuesday, 27 February 2018 11:32 AM  
**To:** admin-d@lkkauto.com  
**Subject:** OI : SGB9932H / TP : SKK8933S/LKK / DOA : 23/02/2018  
**Attachments:** SGB9932H - SAS.pdf; SKK8933S - SAS.pdf; SKK8933S - ESTIMATE.pdf; SKK8933S - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **TRANS EUROKARS PTE LTD,**

ADDRESS : 5 UBI CLOSE  
SINGAPORE 408605

PERSON TO CONTACT : JESS FRANCIS @ 6395 8784

ERGO OFFICER-IN-CHARGE : STEVE LIM

***Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact yo ur office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are estimates, our insured's and third party's SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

### **Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Date: 27.02.2018  
 Our Reference: SGB 9932H/SE/pl  
 Your Reference: SKK 8933S  
 To: TRANS EUROKARS PTE LTD

Sent via Fax   
 or   
 Email  jess.francis@eurokars.com.sg

**Pre-Repair Survey (PRS) Acknowledgement**

Vehicle For Inspection: SKK 8933S  
 Insured's Vehicle: SGB 9932H  
 Date Of Accident: 23.02.2018


We acknowledge receipt of your request for PRS on: 27.02.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

**LKK AUTO CONSULTANTS**

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- Your request for inspection does not have your client's GIA report, kindly forward a copy.
- We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- Our Insured's driver has not reported the accident to us todate.
- Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				<b>FAX : 6829 9247</b>

**Assessor use only:**  
 Assignment Date: \_\_\_\_\_  
 Assignment Time: \_\_\_\_\_

**Workshop use only:**  
**Assessor attended workshop on:**  
 Date: \_\_\_\_\_  
 Time: \_\_\_\_\_  
 Inspector: \_\_\_\_\_

Remarks:

Vehicle not available at the appointed date and time.  
 Kindly acknowledge our Assessor presence for the above job .

\_\_\_\_\_  
 Workshop Acknowledgement & Stamp.  
 Note: Our Inspection is on a without admission to liability basis.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, 2 March 2018 2:07 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.); assignments; 'Steve Lim'  
**Cc:** SUR  
**Subject:** RE: SGB9932H / TP : SKK8933S/LKK / DOA : 23/02/2018  
**Attachments:** CSEGI18003757Uqd3.pdf

Dear Steve,

Enclosed herewith preliminary advice of SKK 8933S.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sjewsc@lkkauto.com](mailto:sjewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 27 February 2018 2:18 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <[Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SGB9932H / TP : SKK8933S/LKK / DOA : 23/02/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 28/02/2018.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Tuesday, 27 February 2018 11:32 AM  
**To:** [admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)  
**Subject:** OI : SGB9932H / TP : SKK8933S/LKK / DOA : 23/02/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **TRANS EUROKARS PTE LTD**,

ADDRESS : 5 UBI CLOSE



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SGB 9932H/SE/pl

Date: 02<sup>nd</sup> March 2018

Our Ref: CS/EGI8003757/Uqd3

The Motor Claims Department  
ERGO Insurance

Attn: Pei Li

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SKK 8933S**


We thank you for the instruction on 27/02/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/02/2018 at the premises of M/s TRANS EUROKARS and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,513.91</u>
Revised Estimate Amount	: S\$ <u>3,430.52</u>
"Check" Items Amount	: S\$ <u>482.67</u>
Lump Sum Repair Estimate Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 4 days.

We have NOT authorize repair.

Yours faithfully

CHUA KANG SENG  
Licensed Appraiser

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3205B
Vehicle Details	
Vehicle No.:	SKK89335
Vehicle to be Exported:	No
Intended De-registration Date:	28 Feb 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 SEDAN 2.0 AT STANDARD EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	PE20981572
Chassis No.:	JM6GL1071J0129740
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$19,935.00
Original Registration Date:	23 Aug 2017
First Registration Date:	23 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$19,935.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Aug 2027
PARF Rebate Amount:	\$14,951.00
Intended COE Rebate Details	
COE Expiry Date:	22 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$50,895.00
<b>Total Rebate Amount:</b>	<b>\$65,846.00</b>

The information contained herein is correct as at 28 Feb 2018

OK



# Arrange LKK AND CONSULTANTS FOR THIS CASE.



**TRANS EUROKARS PTE LTD**  
**NO:5 UBI CLOSE, SINGAPORE 408605**



**ESTIMATE COST OF REPAIRS**

to Arrange survey to LKK AND on Feb 28 @ 4 pm.

<b>ERGO Insurance Pte. Ltd.</b> 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985  ATTN.: MOTOR CLAIMS FAX:		<b>NAME:</b> Mr Ong Beng Lee Ken  <b>ADDRESS:</b> 2a Brighton Crescent Singapore 559220  <b>TEL:</b> 97468687	<b>WIP:</b> 64504  <b>EXCESS:</b>  <b>DATE:</b> 27-Feb-18
---	--	--	---

<b>VEH NO:</b>	<b>SKK89335</b>	<b>DATE IN:</b>		<b>CONTACT PERSON:</b>	JESS 6395 7874
<b>CHASSIS NO:</b>	JM6GL1071J0129740	<b>MILEAGE:</b>		<b>TYPE OF CLAIM:</b>	THIRD PARTY CLAIM
<b>MODEL:</b>	MAZDA6 2L	<b>DATE REG.:</b>	23-Aug-17	<b>POLICY NO.:</b>	

**NATURE OF WORKS**

**Parts Description**

NO	QTY	REVISED	PRICES		
1	REAR BUMPER	1	MGJR9-50-221ABB	20/10.1	\$ 1,172.80
2	RETAINER(LHS), REAR BUMPER	1	MGJR9-50-2J1	ru	\$ 39.00
3	RETAINER(RHS), REAR BUMPER	1	MGJR9-50-2H1	ru	\$ 39.00
4	BRACKET CENTER, REAR BUMPER	1	MKD53-50-251	ru	\$ 5.10
5	REFLECTOR LHS	1	MD350-51-5L0E	11	\$ 50.40
6	REFLECTOR RHS	1	MD350-51-5M0E	11	\$ 50.40
7	COVER(LHS), TOWING	1	MG4YL-50-EL1 27	m.s	\$ 23.70
8	COVER(RHS), TOWING	1	MGJR9-50-EK1 27	11	\$ 23.70
9	REAR REINFORCEMENT	1	MGHK1-50-260	DD	\$ 512.60
10	FASTENER, REAR BUMPER	6	MB45A-56-146A	ru	\$ 16.80
11	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	ru	\$ 10.00
12	GROMMET, REAR BUMPER	1	M9991-00-501	ru	\$ 2.80
13	CLIP, REAR BUMPER	4	MC274-50-133	ru	\$ 14.00
14	GASKET(LHS), TAILLAMP	1	MGHK1-51-163	ru	\$ 27.70
15	GASKET(RHS), TAILLAMP	1	MGHK1-51-153	ru	\$ 27.70
16	FASTENER, TAILLAMP	2	MKD53-51-146B	ru	\$ 7.80
17	FASTENER, TAILLAMP	2	MGHP9-51-146	ru	\$ 6.60
18	GROMMET, TAILLAMP	2	MGJ6A-51-14Y	ru	\$ 29.80
			<b>TOTAL PARTS</b>		\$ 2,059.90
			<b>LESS 10%</b>		\$ 205.99
			<b>TOTAL PARTS COST</b>		\$ 1,853.91

**Labour Description**

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 1,800.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	990	\$ 1,500.00

3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	200	\$ 660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 4,660.00
TOTAL PARTS	\$ -	\$ 1,853.91
TOTAL	\$ -	\$ 6,513.91
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

**REMARKS:**

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

**TRANS EUROKARS PTE LTD**

Authorized Signature

Not Authorised  
LKK  
take photo below party.  
Hdy.  
28/2/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
			<b>TOTAL LABOUR</b>	<b>\$ 2,150.00</b>
			<b>TOTAL PARTS</b>	<b>\$ 1,741.86</b>
			<b>TOTAL</b>	<b>\$ 3,891.86</b>
			<b>LESS EXCESS</b>	<b>\$ -</b>
			<b>TOTAL AFTER EXCESS</b>	<b>\$ 3,891.86</b>
			<b>GST 7%</b>	<b>\$ 272.43</b>
			<b>GRAND TOTAL</b>	<b>\$ 4,164.29</b>

**REMARKS:**

**4 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)**




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18003757/Uqd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 26-04-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGB 9932H	Veh. Inspected	SKK 8933S
Policy No.		Coverage (\$)	0.00
Claim No.	SGB 9932H/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	27/02/2018
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 6 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6GL1071J0129740	Colour	GREY
Odometer	4753	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R17	TOYO	6 mm
L/H Front Tyre	225/55 R17	TOYO	6 mm
R/H Rear Tyre	225/55 R17	TOYO	6 mm
L/H Rear Tyre	225/55 R17	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/02/2018	Inspection Date	28/02/2018
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 8933S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DENTED / TORN	1,172.80	1,172.80
1	RETAINER (LHS) REAR BUMPER	NECESSARY	39.00	39.00
1	RETAINER (RHS) REAR BUMPER	NECESSARY	39.00	39.00
1	BRACKET CENTER,REAR BUMPER	NECESSARY	5.10	5.10
1	REFLECTOR LHS	NOT NECESSARY	50.40	-
1	REFLECTOR RHS	NOT NECESSARY	50.40	-
1	COVER (LHS) TOWING	MISSING	23.70	23.70
1	COVER (RHS) TOWING	NOT NECESSARY	23.70	-
1	REAR REINFORCEMENT	DENTED	512.60	512.60
6	FASTENER,REAR BUMPER	NECESSARY	16.80	16.80
4	GROMMET,REAR BUMPER	NECESSARY	10.00	10.00
1	GROMMET,REAR BUMPER	NECESSARY	2.80	2.80
4	CLIP,REAR BUMPER	NECESSARY	14.00	14.00
1	GASKET (LHS) TAILLAMP	NECESSARY	27.70	27.70
1	GASKET (RHS) TAILLAMP	NECESSARY	27.70	27.70
2	FASTENER, TAILLAMP	NECESSARY	7.80	7.80
2	FASTENER, TAILLAMP	NECESSARY	6.60	6.60
2	GROMMET, TAILLAMP	NECESSARY	29.80	29.80
	LESS 10% DISCOUNT		-205.99	-193.54
			1,853.91	1,741.86
<b>SPECIAL NETT ITEMS</b>				
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			100.00	30.00
<b>LABOUR</b>				
	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		1,800.00	660.00
	TO RESPRAY REAR BUMPER AND REINFORCEMENT.		1,500.00	990.00
	TO TRANSFER REVERSE SENSORS.		660.00	200.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00

Report Ref No. CS/EGI18003757/Uqd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	150.00
			4,560.00	2,120.00
<b>GRAND TOTAL</b>			<b>6,513.91</b>	<b>3,891.86</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,891.86</b>

Report Ref No. CS/EGI18003757/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.