



樹發汽車修理廠 SHU FATT AUTO WORKS

9-71

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
2nd March 2018
TP

GBD 8420 Z NISSAN CABSTAR

			S\$		
Spare Parts	1	Left frt headlight.	493.40	Nett	
	1	Left frt headlight lower panel.	85.00	Nett	
	-- 1	Left frt quarter panel.	299.80	Nett	
	1	Left frt door.	1496.50	Nett	
	1	Left frt door signal light.	48.50	Nett	
	1	Left frt door lower hinge.	76.10	Nett	
	1	Left frt step garnish.	159.30	Nett	
	1	Frt bumper.	945.10	Nett	
	1	Left frt bumper brackets.	76.50	Nett	
	1	Set left frt step garnish clips.	64.00	Snet	
	1	Set frt bumper clips.	44.00	Snet	
	1	Left frt door sticker.	30.00	Snet	

			3818.20		
			Less 25%	920.05	

			2898.15		
Labour	To knock, straighten frt inner panel, frt lower panel, frt side panel, left frt door pillar, left frt inner top panel, left door arch panel, left door arch inner panel, frt bumper inner panel, renew frt light, frt quarter panel, frt door, frt bumper and assembly.		900.00		
	To respray damaged parts.		750.00		
	To remove, replace left frt door glass, regulator, motor, inner lock, outer lock, inner handle, outer handle, garnishes, rubbers, mouldings and assembly.		150.00		
	To remove seats, upholstery, garnishes, carpets to facilitate repairs and assembly.		80.00		

				4778.15	

JN1SC2F24Z0857113

7

(re)