



樹發汽車修理廠 SHU FATT AUTO WORKS

9-71

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
2nd March 2018
TF

GBD 8420 Z NISSAN CABSTAR

Spare Parts			S\$	
1	Left frt headlight.		493.40	Nett ?
1	Left frt headlight lower panel.		85.00	Nett Rx
1	Left frt quarter panel.		299.80	Nett 16✓
1	Left frt door.		1496.50	Nett 66✓
1	Left frt door signal light.		48.50	Nett cut✓
1	Left frt door lower hinge.		76.10	Nett Rx
1	Left frt step garnish.		159.30	Nett x
1	Frt bumper.		945.10	Nett cut✓
1	Left frt bumper brackets.		76.50	Nett ?
1	Set left frt step garnish clips.		64.00	Snet x
1	Set frt bumper clips.		44.00	Snet net✓
1	Left frt door sticker.		30.00	Snet net✓
			3818.20	
			Less 25%	920.05
			2898.15	
Labour	To knock, straighten frt inner panel, frt lower panel, frt side panel, left frt door pillar, left frt inner top panel, left door arch panel, left door arch inner panel, frt bumper inner panel, renew frt light, frt quarter panel, frt door, frt bumper and assembly		900.00	600
	To respray damaged parts.		750.00	450
	To remove, replace left frt door glass, regulator, motor, inner lock, outer lock, inner handle, outer handle, garnishes, rubbers, mouldings and assembly.		150.00	60
	To remove seats, upholstery, garnishes, carpets to facilitate repairs and assembly.		80.00	40
			4778.15	

JN1SC2F24Z0857113

Tan Jiah 97495749.
WP
5 days
Lumpsum
Resoung after repair.
sur@lakanato.com.

(16)