

Special Instructions:

Date/Time: 27/2/18 @ 9.23am

Bill to:

5. ubi close

Claim No: C1000137

Discussion

D.O.A. 20/2/18

H.O.D. Endorsement

Vehicle IN/OUT

385.14

286



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI18003761/Gqd3		
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 27-02-2018		
		Code : AGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKX 3563R	Veh. Inspected	SKT 5662X	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10001371	Excess (\$)	0.00	
Assign From	JULIE MANGUBAT	Assign Date	27/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/02/2018	Inspection Date		
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 6 April 2018 10:28 AM
To: Shu Pei (LKKAUTO); catherinechua@eurokars.com.sg; Guo Qiang (LKKAUTO)
Cc: vion.lim@eurokars.com.sg; CS A Team; Admin A; SUR
Subject: RE: SKT5662X - FINALISATION OF COR

Dear Catherine,

Confirm final fig \$3,585.14 before GST and 3 repair days.

Kindly send the relevant documents to insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)
Sent: Wednesday, 4 April 2018 4:28 PM
To: catherinechua@eurokars.com.sg; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: vion.lim@eurokars.com.sg; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FW: SKT5662X - FINALISATION OF COR

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/AGI18003761/Gqd3	Shiau Chan / Guo Qiang

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg [mailto:catherinechua@eurokars.com.sg]
Sent: Wednesday, 4 April 2018 3:33 PM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Cc: vion.lim@eurokars.com.sg; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: SKT5662X - FINALISATION OF COR

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SKT5662X
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	MAZDA
Vehicle Model :	MAZDA3 4-DOOR SEDAN 1.5L SP6EAT
Chassis No. :	JM6BM42A8G0311621
Propellant :	Petrol
Engine No. :	P520287498
Engine Capacity :	1496 cc
Maximum Power Output :	88.0 kW (118 bhp)
Maximum Laden Weight :	1835 kg
Unladen Weight :	1321 kg
Year Of Manufacture :	2015
Original Registration Date :	15 Jun 2015
Lifespan Expiry Date :	-
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium :	\$66,590.00
COE Expiry Date :	14 Jun 2025
Road Tax Expiry Date :	14 Jun 2018
PARF Eligibility Expiry Date :	14 Jun 2025
Inspection Due Date :	14 Jun 2018
Intended Transfer Date :	06 Mar 2018
CO2 Emission :	135.00 (g/km)
CEV/VES Rebate Utilised Amount :	\$10,000.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.	
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.	
Amount Payable	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2018 14:35
Date Of Accident	20/02/2018 20:55
Exact Location Of Accident	RIVERVALE LINK & BUANGKOK DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT5662X
Insured/Policyholder	
Name Of Registered Owner	TEO ENG TIONG
NRIC No	S7332415G
Email Address	TEOENGTIONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98524893
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 SEDAN L SP.6EAT (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	TEO ENG TIONG
NRIC No	S7332415G
Date Of Birth	11/09/1973
Occupation	INDOOR
Date Of Driving Pass	15/12/1994
Driving Experience	23 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98524893
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	TEOENGTIONG@GMAIL.COM

Address	11 SENGKANG EAST AVENUE #16-03
Postcode	544804
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX3536R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MAK SENG HONG
NRIC/Passport Number	S1700066G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 21/2/18 10:00

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Trans Eurokars Pte Ltd
5th Floor
Singapore 408605
Tel: 6743 1003 / 6749 4333
Fax: 6743 0000
Reporting Centre's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ACCIDENT DATE: 20/2/2018	LICENSE PLATE NO: SKT5662X
ACCIDENT TIME: 8.59pm.	CONTACT NUMBER: 98524893
LOCATION: Junction of Rivervale Link and Buangkok Dr	EMAIL: teoengtiong@gmail.com
<p>At about 8.58pm, I was driving along Rivervale Link and stopped at the traffic traffic light when when I was about to turn left into Buangkok Dr towards KPE. When the traffic light turns green, I made a left turn but I moved my car forward trying to make a left turn but stopped at the traffic light as there is a bicyclist crossing the road. After After a second, a car behind (SKX3563R) hit the rear of my car, causing the damage to the car. No one was injured during the accident.</p>	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY.	
PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
PLEASE STATE: <input type="checkbox"/> CLAIM OWN POLICY <input checked="" type="checkbox"/> CLAIM THIRD PARTY <input type="checkbox"/> REPORTING ONLY	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 20/2/18 10am.

DIARMC (S)001/2018/001_03

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Teo Eng Tiong Pte Ltd

511/1, Chong

Singapore 486605

Tel: 64700000/6757494333

Fax: 67500000

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



Auto & General Insurance (S) Pte Ltd		NAME :	Mr Teo Eng Tiong	WIP :	63821
190 Clemenceau Avenue		ADDRESS :	11 Sengkang East Avenue	EXCESS :	
#03-01 Singapore			#16-03	DATE:	22-Feb-18
Shopping Centre 239924			Singapore 544804		
ATTN :	MOTOR CLAIMS	TEL :	98524893		
FAX :					

VEH NO :	SKT5662X	DATE IN :		CONTACT PERSON :	VION 6395 7877
CHASSIS NO :	JM6BM42A8G0311621	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3 1.5L	DATE REG.:	15-Jun-15	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO		QTY		REVISED	PRICES
1	REAR BUMPER / <i>Re</i>	1	MBPD8-50-221ABB		\$ 1,074.80
2	RETAINER(LHS), REAR BUMPER <i>X</i>	1	MBHN1-50-2J1A		\$ 36.10
3	RETAINER(RHS), REAR BUMPER <i>X</i>	1	MBHN1-50-2H1A		\$ 36.10
4	BRACKET(LHS), REAR BUMPER <i>X</i>	1	MBHN9-51-077B		\$ 45.60
5	BRACKET(RHS), REAR BUMPER <i>X</i>	1	MBHN9-51-067B		\$ 45.60
6	BRACKET LOWER, REAR BUMPER <i>X</i>	1	MBHR2-50-251A		\$ 23.70
7	BRACKET CENTER, REAR BUMPER <i>X</i>	1	MKD53-50-251		\$ 5.10
8	REFLECTOR LHS <i>X</i>	1	MD350-51-5L0E		\$ 50.40
9	REFLECTOR RHS <i>X</i>	1	MD350-51-5M0E		\$ 50.40
10	COVER(LHS), TOWING <i>X</i>	1	MBHN1-50-EL1 BB		\$ 15.70
11	COVER(RHS), TOWING <i>X</i>	1	MBHN1-50-EK1 BB		\$ 16.20
12	SENSOR,ULTRASONIC <i>X</i>	4	MKD47-67-UC1 62		\$ 775.60
13	RETAINER, SENSOR / <i>acc</i>	4	MKD47-67-UC5A62		\$ 69.20
14	TAPE PROTECTOR, SENSOR / <i>acc</i>	3	MG51D-50-EM1A		\$ 24.30
15	REINFORCEMENT REAR / <i>BT</i>	1	MB45A-50-260		\$ 537.30
16	FASTENER, REAR BUMPER / <i>acc</i>	4	MB45A-56-146A		\$ 11.20
17	CLIP, REAR BUMPER / <i>acc</i>	2	MGJ21-50-049		\$ 6.40
18	RIVET, REAR BUMPER / <i>acc</i>	4	MB8M4-50-355		\$ 16.80
19	GROMMET, REAR BUMPER / <i>acc</i>	1	M9991-00-501		\$ 2.80
20	GROMMET, REAR BUMPER / <i>acc</i>	4	MBHN1-50-021A		\$ 10.00
21	GASKET(LHS), TAILLAMP / <i>acc</i>	1	MBHN1-51-163		\$ 20.90
22	GASKET(RHS), TAILLAMP / <i>acc</i>	1	MBHN1-51-153		\$ 20.90
23	FASTENER, TAILLAMP <i>X</i>	2	MKD53-51-146B		\$ 7.80
24	GROMMET, TAILLAMP <i>X</i>	2	MGJ6A-51-14Y		\$ 29.80
			TOTAL PARTS		\$ 2,932.70
			LESS 10%		\$ 293.27
			TOTAL PARTS COST		\$ 2,639.43

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 1,800.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	630	\$ 1,500.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	330	\$ 660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES. <i>See</i>	20	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 4,660.00
TOTAL PARTS	\$ -	\$ 2,639.43
TOTAL	\$ -	\$ 7,299.43
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

3 Days.

before paint photo's.

Gmo Q: ng - 82880282

05/3/18.

[Signature]
7/3/18

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____ Date: _____</p>
--



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



Auto & General Insurance (S) Pte Ltd 190 Clemenceau Avenue #03-01 Singapore Shopping Centre 239924 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Teo Eng Tiong ADDRESS : 11 Sengkang East Avenue #16-03 Singapore 544804 TEL : 98524893		WIP : 63821 EXCESS : DATE: 22-Feb-18	
VEH NO :	SKT5662X	DATE IN :		CONTACT PERSON :	VION 6395 7877
CHASSIS NO :	JM6BM42A8G0311621	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3 1.5L	DATE REG.:	15-Jun-15	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	1	MBPD8-50-221ABB	\$ 1,074.80	\$ 1,074.80	
2	1	MBHN1-50-2J1A		\$ 36.10	
3	1	MBHN1-50-2H1A		\$ 36.10	
4	1	MBHN9-51-077B		\$ 45.60	
5	1	MBHN9-51-067B		\$ 45.60	
6	1	MBHR2-50-251A		\$ 23.70	
7	1	MKD53-50-251		\$ 5.10	
8	1	MD350-51-5L0E		\$ 50.40	
9	1	MD350-51-5M0E		\$ 50.40	
10	1	MBHN1-50-EL1 BB		\$ 15.70	
11	1	MBHN1-50-EK1 BB		\$ 16.20	
12	4	MKD47-67-UC1 6Z		\$ 775.60	
13	4	MKD47-67-UCSA62	\$ 69.20	\$ 69.20	
14	3	MG51D-50-EM1A	\$ 24.30	\$ 24.30	
15	1	MB45A-50-260	\$ 537.30	\$ 537.30	
16	4	MB45A-56-146A	\$ 11.20	\$ 11.20	
17	2	MGJ21-50-049	\$ 6.40	\$ 6.40	
18	4	MBBM4-50-355	\$ 16.80	\$ 16.80	
19	1	M9991-00-501	\$ 2.80	\$ 2.80	
20	4	MBHN1-50-021A	\$ 10.00	\$ 10.00	
21	1	MBHN1-51-163	\$ 20.90	\$ 20.90	
22	1	MBHN1-51-153	\$ 20.90	\$ 20.90	
23	2	MKD53-51-146B		\$ 7.80	
24	2	MGJ6A-51-14Y		\$ 29.80	
TOTAL PARTS			\$ 1,794.60	\$ 2,932.70	
LESS 10%			\$ 179.46	\$ 293.27	
TOTAL PARTS COST			\$ 1,615.14	\$ 2,639.43	
Labour Description					

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT, REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 1,800.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	\$ 630.00	\$ 1,500.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
TOTAL LABOUR			\$ 1,970.00	\$ 4,660.00
TOTAL PARTS			\$ 1,615.14	\$ 2,639.43
TOTAL			\$ 3,585.14	\$ 7,299.43
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 3,585.14	
GST 7%			\$ 250.96	\$ -
GRAND TOTAL			\$ 3,836.10	\$ -

REMARKS: SKT5662X

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18003761/Gqd3q2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 09-04-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 3563R	Veh. Inspected	SKT 5662X
Policy No.		Coverage (\$)	0.00
Claim No.	C10001371	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	27/02/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6BM42A8G0311621	Colour	RED
Odometer	72423	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/02/2018	Inspection Date	05/03/2018
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 5662X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,074.80	1,074.80
1	RETAINER (LHS),REAR BUMPER	NOT NECESSARY	36.10	-
1	RETAINER (RHS),REAR BUMPER	NOT NECESSARY	36.10	-
1	BRACKET (LHS),REAR BUMPER	NOT NECESSARY	45.60	-
1	BRACKET (RHS),REAR BUMPER	NOT NECESSARY	45.60	-
1	BRACKET LOWER ,REAR BUMPER	NOT NECESSARY	23.70	-
1	BRACKET CENTER ,REAR BUMPER	NOT NECESSARY	5.10	-
1	REFLECTOR LHS	NOT NECESSARY	50.40	-
1	REFLECTOR RHS	NOT NECESSARY	50.40	-
1	COVER (LHS),TOWING	NOT NECESSARY	15.70	-
1	COVER (RHS),TOWING	NOT NECESSARY	16.20	-
4	SENSOR ,ULTRASONIC	NOT NECESSARY	775.60	-
4	RETAINER ,SENSOR	NECESSARY	69.20	69.20
3	TAPE PROTECTOR ,SENSOR	NECESSARY	24.30	24.30
1	REINFORCEMENT REAR	BENT	537.30	537.30
4	FASTENER ,REAR BUMPER	NECESSARY	11.20	11.20
2	CLIP ,REAR BUMPER	NECESSARY	6.40	6.40
4	RIVET ,REAR BUMPER	NECESSARY	16.80	16.80
1	GROMMET ,REAR BUMPER	NECESSARY	2.80	2.80
4	GROMMET ,REAR BUMPER	NECESSARY	10.00	10.00
1	GASKET (LHS),TAILLAMP	NECESSARY	20.90	20.90
1	GASKET (RHS),TAILLAMP	NECESSARY	20.90	20.90
2	FASTENER ,TAILLAMP	NOT NECESSARY	7.80	-
2	GROMMET ,TAILLAMP	NOT NECESSARY	29.80	-
	LESS 10% DISCOUNT		-293.27	-179.46
			2,639.43	1,615.14
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
<u>LABOUR</u>				
	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT ,REPAIR ALL AREAS AFFECTED BY THE ACCIDENT .		1,800.00	660.00

Report Ref No. CS/AGI18003761/Gqd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT		1,500.00	630.00
	TO TRANSFER REVERSE SENSORS.		660.00	330.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			4,560.00	1,950.00
GRAND TOTAL			7,299.43	3,585.14
RECOMMENDED COST OF REPAIRS				3,585.14

Report Ref No. CS/AGI18003761/Gqd3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.