

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : ☐ Own Damage  
☒ 3rd Party  
☐ Windscreen

Ins Company : AXA INS  
Excess :  
Date of Accident : 20.02.2018  
Suggested Days of Repair : 6 DAY

Vehicle No. : SLK7829E  
Make & Model : HYUNDAI / ELANTRA AD 1.6 GL  
Year of Manufacture : 2016  
Chassis No. : KMHD841CMHU332376  
Engine No. : G4FGGU014533  
Policy No. :  
Time of Accident : 18.45 P.M.  
In-house Vehicle Assessor

**Repair Estimates**

Parts (a) Cost / List Price Items \$1,382.00  
Plus/Less -30 % \$(414.60)  
(b) Nett Price Items  
Less %  
(c) Special Nett Items \$1,050.00  
Total Parts Cost (Appendix A) \$2,017.40  
Labour (Appendix B) \$1,910.00  
Total Repair Cost \$3,927.40

The above total will be subjected to 7% G.S.T.

Name : Wong Chee Wei  
Signature :  
Contact No : 68676919  
HP : 97239882

**LKK Auto Consultants hence, notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Tan Jit 97495749  
Company : LKK  
Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 3 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : [Signature] Date: 14/3/18

*Resurvey before print  
sure/submit.com*

## COMFORTDELGRO ENGINEERING PTE LTD

45 Pandna Road S (609286)

Tel: 68676919 Fax: 62626950

Appendix A

**Spare Parts**

Vehicle No. : **SLK7829E** Submit By : **Wong Chee Wei**  
 Make & Model : **HYUNDAI ELANTRA AD 1.6 GLS AT** Year Manufacture : **2016**  
 Chassis No. : **KMHD841CMHU332376** Engine No. : **G4FGGU014533**

**TP****S/Order** : \_\_\_\_\_

S/No	Part Description	Qty	Cost	Nett	List	S- Nett	Disposition By
			Price	Price	Price	Price	
1	REAR BUMPER	1 PC			\$459.00	de	
2	REAR BUMPER CLIP	10 PC			\$35.00	we	
3	REAR BUMPER SIDE RETAINER RH	1 PC			\$65.00	X	
4	REAR BUMPER SIDE RETAINER LH	1 PC			\$65.00	X	
5	REAR BUMPER BRACKET RH	1 PC			\$55.00	?	
6	REAR BUMPER BRACKET LH	1 PC			\$55.00	?	
7	REAR BUMPER REINFORCEMENT	1 PC			\$303.00	?	
8	REAR BUMPER SPONGE	1 PC				?	
9	REAR END PANEL	1 PC			\$285.00	Ry	
10	REAR END PANEL GARNISH	1 PC			\$60.00	X	
11	REVERSE SENSOR SET	1 SET				\$200.00	new
12	REAR LOWER SPOILLE	1				\$850.00	R
13		5					
14		1					
15		1					
16		1					
17		1					
18		1					
19		1					
20		1					
21		1					
22		1					
23		1					
24		1					
25		1					
26		1					
27		1					
28		1					
29		1					
30		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

## Appendix B

## Labour

[illegible]

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*