

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKC5578X (AXA)

Date : 27-02-2018

Accident Date : 25-02-2018

Our Ref : SKB7907Y /CHAN

ROS LI MOHAMED YUSOF
C/O ALAN'S UNITED AUTO PTE LTD
BLK 7 SIN MING IND. EST. SECTOR C
01-76
SINGAPORE 575642

3RD Accident

Not Insured

ESTIMATE COST OF REPAIR FOR BMW320I SKB7907Y

1 PC	REAR BUMPER FASCIA	Per \$1,182.00 ✓
1 PC	REAR BUMPER TOW COVER	Per \$19.30 X
2 PCS	REAR BUMPER PARKING SENSOR @ \$231.10	Per \$462.20 X
2 PCS	PARKING SENSOR O RING @ \$4.95	\$9.90 ✓
4 PCS	PARKING SENSOR HOLDER @ \$62.50	\$250.00 ✓
1 PC	REAR BUMPER REINFORCEMENT	\$413.90 ✓
1 PC	REAR BUMPER INNER PARTS	\$50.85 ✓
		<u>\$2,388.15</u>
	LESS 10%	<u>\$238.82</u>
		<u>\$2,149.33</u>

\$2,149.33

TO PUTTY AND SPRAY REPLACED PARTS

\$350.00 254

TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING,
ALIGN, REFIX AND TO RENEW ABOVE PARTS

\$400.00 2201

TO REMOVE & REWIRE PARKING SENSOR WIRE

\$40.00 ✓
\$2,939.33

Singapore Dollars Two Thousand Nine Hundred And Thirty Three Only

LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Receiver

Signature:

Date: