

CONNECT 3

7 Old Toh Tuck Road Singapore 597648
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

QT18/PC5329P/TPC-164

AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower
Singapore 068811

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC5329P

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	Front bumper RH <i>Repair x</i>	1	1,850.00	1,850.00
2.	Front RH small compartment cover <i>Repair x</i>	1	1,450.00	1,450.00
3.	Spray painting <i>500</i>	1	700.00	700.00
4.	Labour charges <i>200.</i>	1	500.00	500.00
	<i>700.</i>		SUB-TOTAL	S\$4,500.00

Thank you.

Yours faithfully,



Winnie Chai
HP: 9850-9666



2 Days.

part by part.

After repair photos.

Guo Qiang - 82880282

Guo Qiang @ lkkauto.com

01/3/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: