

(08/11/13)

Surveyor: Kevin

REF: NS/INC18003769 / Kimber

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SKZ 5012R

Policy No. 5077 302138-02 260118 - 290119

Claims No. MT10983442-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SHC 8134J Yr Regn: 28 Apr 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 240 C.C. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 297500 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 1CA HLB 414AH 40 87891

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 / 60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 22/2/8 D.O.I. 23/2/8

Survey held at CP&E (67 my)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC 8134J - X <span style="float: right;">INC</span>
	SKZ 5012R - X <span style="float: right;">PIR</span>
<u>28/2/8</u>	<u>Costs PIP \$945.48 / 2 Pys</u>
	<u>Red: \$1516.10, 62%</u>
RECEIVED 02 MAR 2018	

Date/Time, File Pass to?

: Preli. Report

: Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

1) Import

Date/Time, File Return to?

2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee: 160

Transportation: \_\_\_\_\_

S + RS, SI \_\_\_\_\_

Photos 35

Others \_\_\_\_\_

TOTAL 195

Report Format: TP

Lump sum / I.B.I. (\$) 945.48