

22/03/2002

ASS. REC. BY:

REF: CS/MSG18 003772/R1rd3

Special Instruction:

Sub/Vendor:

Merimen

ASSIGNMENT (Office)

From (Person):

Pearllyn King

of

MSG

Date/Time:

26/2/18 @ 5:31pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJG 7777R

Insured:

at Workshop m/s

Performance

Tel:

01165112

of

303 Alexandra Rd

Policy No:

27665710 SMP

Claim No:

549730

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

14/02/2018

28/2/2018

CA (REV)

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:45am @ 27/2/18

Person Contacted:

Mr. chuan

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SJG 7777R - X

Sent preli thru merimen, seek mandate

Mandate approve; informed repairer to proceed.

meimen

REF: ms26

60673

# ASSIGNMENT

From: Date: 28/02/2018

Estimated Cost:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 93G 7777 R

at Workshop this: Performance

of: 303 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$ 500.00

(Client's Record)

Make of Veh: Chua

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 10SK

IDAC Accident Rpt: Consistent? : Yes or No

GLA / PR. Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 53G 7777 R

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

Make: B.M.W 320i

Colour: BLACK

Sp. Reading: 33829

Eng No:

D No: WBA3B16020NS50439

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / B/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: 1"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: R. Bal. 6 mm

L. Bal. 6 mm

D.O.A. 14/02/18

Survey held at: Performance

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Confirm \$ 3121.85, - 3 days

Red: \$ 5875.50, 65%.

RECEIVED 27 JUN 2018

Date/Time File Pass to: ☐ : Prel. Report

typist ☒ : Final Report

Date/Time File Return to:

3

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transporter:

3 + 35.00

Phone:

Car:

Report Format: TP

Lump Sum I.B. 3121.85

Add Fee: ☐ Site Insp: \$

☐ Interview: \$

☐ Technician: \$

☐ Weekend: \$

FILE



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003772/R1rd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 27-02-2018

Code : MSG



## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJG 7777R
Policy No.	27665710SMP	Coverage (\$)	0.00
Claim No.	549730	Excess (\$)	500.00
Assign From	MERIMEN (PEARLYYN KANG)	Assign Date	27/02/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	14/02/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Code	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Trns Auth'd	Status
Main	14 Feb 2018		26 Feb 2018 17:31 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS

**[Created by insurer]**

Insured:	LIM OON HOCK, ID: S1436067J, Tel: +6596181770, Email: LIMOH60@YAHOO.COM		
Vehicle Reg. No.:	SJG7777R	Date of Loss:	14/02/2018 09:00 - :59
Claim Type:	OD / 549730	Policy/Cover Note No.:	27665710SMP (Comprehensive) Coverage: 19/02/2017 - 18/02/2018
		Excess:	S\$500.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Imm.Advice due 27/02/2018]</b>		
Driver/Custodian:	LIM OON HOCK (57 / Male), NRIC: S1436067J, Tel: +6596181770		
Adj Asg. Remarks:	Survey after 2pm tmr. Please survey and revert. Thank you.		

#### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pearllyn Kang Yen Lin

Date: 01 Mar 2018

## Preliminary Advice

Vehicle No	: SJG7777R	Accident Date	: 14/02/2018
Make	: BMW 320I	Policy No.	: 27665710SMP
Assignment Date	: 26/02/2018	Excess	: S\$500.00
Date of Inspection	: 28/02/2018	Est. Duration of Repair	: 3.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,997.35
Revised Amount	:S\$	3,369.25
Check Items (Estimated)	:S\$	3,151.10
Total	:S\$	6,520.35
Lump Sum Repair	:S\$	

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	74,610.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,390.00

### Remarks

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.

## Print Received Message

This mail is associated with :

**\*SJG7777R (549730)**

OD

Feb 14 2018 9:00AM

[LIM OON HOCK]

Performance Motors Limited

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 01/03/2018 11:58 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$3369.25) - SJG7777R - Claim Handler: Pearlyn Kang Yen Lin

Approved:3369.25:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.

**Janice Lee (LKKAUTO)**

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Thursday, March 01, 2018 3:21 PM  
**To:** 'chua.kee.sin@simedarby.com.sg'; 'PBSP'  
**Cc:** SUR  
**Subject:** SJG 7777R MSIG OD DOA: 14.02.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJG 7777R (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6067J
Vehicle Details	
Vehicle No.:	SJG7777R
Vehicle to be Exported:	No
Intended De-registration Date:	01 Mar 2018
Vehicle Make:	B.M.W.
Vehicle Model:	320i SEDAN AT D/AB 4DR ABS HID
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	B2070582N20B20B
Chassis No.:	WBA3B16020NS50439
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$35,862.00
Original Registration Date:	19 Feb 2014
First Registration Date:	19 Feb 2014
Transfer Count:	0
Actual ARF Paid:	\$32,207.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Feb 2024
PARF Rebate Amount:	\$24,155.00
Intended COE Rebate Details	
COE Expiry Date:	18 Feb 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$89,001.00
COE Rebate Amount:	\$50,455.00
<b>Total Rebate Amount:</b>	<b>\$74,610.00</b>

The information contained herein is correct as at 01 Mar 2018

OK



BMW Dealer

# Performance Motors Limited

A member of the Sime Darby Group

REG/CS/PAY/FA

14 FEB 2018



## FACSIMILE MESSAGE

DATE 14/02/2018TIME 16:06hrTO MSG InsuranceFAX NO. 62257402ATTENTION Motor Claim DeptNO. OF PAGES 9 pages

(INCLUSIVE OF THIS PAGE)

CC

Your Ref:

Our Ref:

Date:

Subject:

ATTENTION

FAX NO.

FROM

FAX NO.

TEL NO. 91165200

If this fax is not received in order, please do call us. Thank you

Attached is the repair estimate for MSG 7777R  
(Vehicle Regn. No)

The vehicle is presently **IN / Not IN** our workshop.

☒ This is an Own Damage Claim.

Please arrange for a surveyor to inspect the vehicle.

☐ This is a 3rd Party Claim.

If we do not hear from you within the next 24 hours, exclude Saturday and Sunday, we shall proceed with our survey and repair the vehicle.

CC

FAX:

27/02/2018 Survey & repair

Kindly Arrange Survey thank  
You Happy New Year.

Performance Motors  
Limited  
1800-Call-BMW  
(1800-2255-2689)

www.pml.com.sg

303 Alexandra Road  
Sime Darby  
Performance Centre  
Singapore 159941  
Tel Sales 6319 0100  
Tel AfterSales  
6319 0111  
Fax 6474 7770

315 Alexandra Road  
Sime Darby  
Business Centre  
Singapore 159944  
Tel Sales 6319 0511  
Tel AfterSales  
6319 0527  
Fax 6479 0524

896 Dunoon Road  
#01-01  
Sime Darby Centre  
Singapore 589472  
Tel Sales 6319 0500  
Tel AfterSales  
6319 0553  
Fax 6459 1709

290  
Kampung Arang Rd  
East Coast Centre  
Singapore 438180  
Tel AfterSales  
6319 0886  
Fax 6344 1332

Registered office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159942

Co. Reg. No.  
197401559W



MSIG Insurance (Singapore) Pte. Ltd.  
4 Sheilton Way #21-01 SGX Centre 2 Singapore 068807  
Tel: (65) 6827 7888 Fax: (65) 6827 7800  
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

## MOTOR INSURANCE COVER NOTE

Cover Note No. 10117529

The Insured named in the Schedule below having proposed for insurance in respect of the Motor Vehicle described in the Schedule below the risk is hereby HELD COVERED in the terms of the Company's usual form of Policy applicable thereto for the period as stated below unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

### SCHEDULE

**Agent No.** : 212165  
**Name of Insured** : LIM OON HOCK  
**Make and Description of Vehicle** : BMW 320I SEDAN AT D/AB 4DR ABS HID  
**Vehicle Registration No.** : SJG7777R  
**Year of Manufacture** : 2013  
**Engine No.** : B2070582N20B20B  
**Chassis No.** : WBA3B16020NS50439  
**Capacity** : 1,997 Cubic Capacity  
**Cover Type** : Comprehensive  
**Sum Insured (SGD)** : Market Value  
**Period of Insurance** : 19/02/2018 to 18/02/2019  
**Excess (SGD)** : 500

I/We hereby certify that this Cover Note is issued in accordance with the Provisions of the Motor Vehicles (Third Party Risks & Compensation) Act (Cap. 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Not valid unless countersigned by the  
Company's Authorised Representative



Sime Darby Insurance Brokers (Singapore) Pte. Ltd.

MSIG Insurance (Singapore) Pte. Ltd.  
Authorised Insurers

Katherine Yeo  
Senior Vice President, Brokers

**Date of Issue :** 05/02/2018

This Cover Note is valid for 30 days from the date of issue.

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S1436067J



Name

LIM OON HOCK

林恩福

Race

CHINESE

Date of birth

16-10-1960

Sex

M

Country of birth

SINGAPORE

S1436067J

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S1436067J

Name

LIM OON HOCK

Birth Date: 16 Oct 1960

Issue Date: 27 Dec 2002



4802747

NRIC No S1436067J



Date of issue

06-11-2012

Address

36 LENGKONG EMPAT  
SINGAPORE 417625

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

06 Jun 1978

NP 42SA



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/02/2018 15:47
Date Of Accident	14/02/2018 09:00
Exact Location Of Accident	38 LENGKONG EMPAT S(417625)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG7777R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM OON HOCK
NRIC No	S1436067J
Email Address	LIMOH60@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96181770
Alternative Phone No	OFFICE-62853911

### Vehicle Particulars

Manufacturer	BMW
Model	320
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 27665710 SMP
Cover Note Number	

### Driver

Name of Driver	LIM OON HOCK
NRIC No	S1436067J
Date Of Birth	16/10/1960
Occupation	INDOOR
Date Of Driving Pass	06/06/1978
Driving Experience	39 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96181770
Fax Number	
Contact Number	OFFICE-62853911
Email Address	LIMOH60@YAHOO.COM

Address	38 LENGKONG EMPAT (S)417625
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

18/5/2018  
1155 hr

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I reverse the car out of the car  
pouch, and the left front bumper grazed  
against it wall and pulled out the front bumper,  
also the head lamp (left) was scratched.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

14/2/18  
1155 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

14/2/18 @ 1146 AM

**Performance Motors Limited**

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Tanjong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : **b1 45939**  
Date Estimated : **14/02/2018**  
Prepared By : **Chua Kee Sin**

Page No. : 1 of 2

**- ESTIMATE REPAIR FOR -**

**LIM OON HOCK**  
**38 LENGKONG EMPAT**

SINGAPORE 417625

**- ACCOUNT - 66**

**MSIG Insurance (S) Pte Ltd**  
**4 Shenton Way**  
**#21-01 SGX Centre 2**  
**Singapore 068807**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJG7777R	NS50439	19/02/2014	320iA/4	0

DESCRIPTIONVALUE

Replace front bumper and remove attachment etc include knock on accident dent

~~850~~ 1,780.00

Spray painting front bumper and left front fender

~~934~~ 1,923.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

~~150~~ 177.00

To replace left headlight including program and conduct tests for proper function.

~~XAN 451~~ 531.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

~~AN X~~ 531.00

Sundries. *me*

~~80~~ 150.00

Total Labour 1: **5,012.00**

DESCRIPTIONQTY PRICVALUE

HEX HEAD SCREW  
HEX HEAD SCREW WITH WASHERS  
SHEET METAL NUT SELF-LOCKING  
FRT LH TOP SUPPORT SIDE PANEL  
FRT RH TOP SUPPORT SIDE PANEL  
PARTIALLY OPEN GRID LH  
LH SUPPORT FOGLAMP  
FRT LH BOTTOM MOUNTING SIDE PANEL  
FRT RH BOTTOM MOUNTING SIDE PANEL  
FRT BUMPER TRIM PRIMED (SRA)  
FRT LH GRILLE (BASIS)  
GROMMET  
Securing clip  
FRT LH WHEEL HOUSING COVER  
LH COVER BOTTOM  
DEFLECTOR LIP LH  
PLAQUE 82MM

2 0.55  
2 1.00  
2 1.00  
1 18.00  
1 18.00  
1 68.30  
1 37.60  
1 18.00  
1 18.00  
1 982.75  
1 96.40  
2 0.75  
2 0.45  
1 86.65  
1 115.60  
1 36.80  
1 69.50

~~XAN~~ 1.10  
~~XAN~~ 2.00  
~~CR~~ 2.00  
~~AN~~ 18.00  
~~CR~~ 18.00  
~~AN~~ 68.30  
~~CR~~ 37.60  
~~AN~~ 18.00  
~~AN~~ 18.00  
~~SCA~~ 982.75  
~~AN~~ 96.40  
~~XAN~~ 1.50  
~~XAN~~ 0.90  
~~AN~~ 86.65  
~~AN~~ 115.60  
~~AN~~ 36.80  
~~AN~~ 69.50



## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401539M GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

200, Tampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/330 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 45939  
Date Estimated : 14/02/2018  
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJG7777R	NS50439	19/02/2014	320ia/4	0

## DESCRIPTION

LH HEADLIGHT (XENON)  
LH FOG LIGHT

QTY	PRIC	VALUE
1	2,135.85	2,135.85
1	276.40	276.40
Total Parts		3,985.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date&amp;Time 28/02/18 @ 1355 Excess \$500

Surveyor's Name RANU Sign \_\_\_\_\_

Surveyor's Tel 90010068 Authorised Yes/No ☒ Revert

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes/No ☒ PML Yes/No ☒

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 3 days

Resurvey by paint

1/3/18

Labour 1	: 8917.35	5,012.00
Parts	: 3,985.35	3,985.35
Labour 2	: 0.00	0.00
Excess	: 0.00	0.00
Total GST @ 7%	: 629.81	629.81
Grand Total	: 9,627.16	9,627.16

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

**Janice Lee (LKKAUTO)**

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Friday, April 13, 2018 6:09 PM  
**To:** Rasul (LKKAUTO); SUR  
**Subject:** FINAL REPORT / SJG7777R  
**Attachments:** Final Report SJG7777R.pdf

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00  
Total Parts : 1,107.85  
Total Labour & Parts : 3,121.85

Repair days: 3

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020061-X



## FINAL REPORT

Estimate No. : b1 45939  
Date Estimated : 14/02/2018  
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -  
LIM OON HOCK  
38 LENGKONG EMPAT

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

SINGAPORE 417625

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SJG7777R	NS50439	19/02/2014	320iA/4	0	
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, LH foglamp support include knocking out dents caused by the accident		850.00		850.00	
To spray paint front bumper		934.00		934.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.		150.00		150.00	
Sundries.		80.00		80.00	
DESCRIPTION		UNIT PRICE	QTY	DISC. %	NETT
FRT LH TOP SUPPORT SIDE PANEL		18.00	1.00		18.00
LH SUPPORT FOGLAMP		37.60	1.00		37.60
FRT BUMPER TRIM PRIMED (SRA)		982.75	1.00		982.75
PLAQUE 82MM		69.50	1.00		69.50

### # SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,107.85
Total Labour & Parts :	3,121.85
Deduction for Excess :	500.00
Total Repair Costs less Excess:	2,621.85
GST @7%:	183.53
Grand Total :	2,805.38











































## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2018		26 Feb 2018 17:31 <a href="#">Edit Adj Rpt</a>	<b>\$53,121.85</b> <a href="#">Edit Estimates</a>	<b>\$53,121.85</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured:	LIM OON HOCK, ID: S1436067J, Tel: +6596181770, Email: LIMOH60@YAHOO.COM								
Vehicle Reg. No.:	SJG7777R	Date of Loss:	14/02/2018 09:00 - :59 [47 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 549730	Policy/Cover Note No.:	27665710SMP (Comprehensive) Coverage: 19/02/2017 - 18/02/2018						
		Excess:	\$500.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 28/03/2018]								
Driver/Custodian:	LIM OON HOCK (57 / Male), NRIC: S1436067J, Tel: +6596181770								
Adj Asg. Remarks:	Survey after 2pm tmr. Please survey and revert. Thank you.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (01/03/2018): Alert - Adj Mandate Approved (\$53369.25) - SJG7777R - Claim Handler: Pearlyn Ka...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJG7777R (549730)  
OD  
Feb 14 2018 9:00AM  
[LIM OON HOCK]  
Performance Motors Limited

Upload Documents   Upload Photos   Compose New Letter			View <span>View in Browser</span>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	14/02/18 15:59	Accident Statement	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/18 10:46	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
2	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
3	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
4	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
5	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
6	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
7	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
8	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
9	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
10	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
11	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
12	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
13	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
14	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
15	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
16	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
17	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
18	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
19	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
20	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
21	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
22	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
23	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
24	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
25	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
26	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
27	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
28	01/03/18 10:59	General View	 Load JPG	<input checked="" type="checkbox"/>
29	27/06/18 15:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	27/06/18 15:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	27/06/18 15:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	27/06/18 15:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	27/06/18 15:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	27/06/18 15:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	27/06/18 15:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	27/06/18 15:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	27/06/18 15:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	27/06/18 15:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	27/06/18 15:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	27/06/18 15:56	Reinspection Photo	 Load JPG	<input type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
					<input checked="" type="checkbox"/>
41	27/06/18 15:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	27/06/18 15:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	27/06/18 15:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
44	27/06/18 15:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
45	27/06/18 15:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
46	27/06/18 15:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
47	27/06/18 15:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
48	27/06/18 15:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	14/02/18 16:45	Enquire Transfer Fee		Load PDF	
2	14/02/18 16:45	Enquire Rebate		Load PDF	
3	14/02/18 16:57	PML Estimate + DL + IC		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/03/18 10:58	SJG 7777R ESTIMATE		Load PDF	

## Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	14/02/18 15:59	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	14/02/18 15:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	14/02/18 15:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	14/02/18 15:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	14/02/18 15:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	14/02/18 15:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	14/02/18 15:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	14/02/18 15:56	Sketch Plan		Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG18003772/R1RD3Q2

Date: 28/06/2018

### REFERENCE

Insured/Claimant:	LIM OON HOCK	Policy No:	27665710SMP	
Date of Loss:	14/02/2018	Nature of Claim:	OD	Claim No: 549730

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJG7777R</b>		Engine No:	B2070582N20B20B
Make & Model:	BMW 320i, 2.0 (A)		Chassis No:	WBA3B16020NS50439
Reg. Date:	19/02/2014 (Man. Year: 2013)		Odometer:	33829 km
Colour:	Black			
Engine Capacity:	1997 cc			
Market Value/New Car Price:	S\$105,000.00			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,135.35	1,187.85	2,947.50	71.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,862.00	1,934.00	2,928.00	60.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,997.35</b>	<b>3,121.85</b>	<b>5,875.50</b>	<b>65.30</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>8,497.35</b>	<b>2,621.85</b>	<b>5,875.50</b>	<b>69.15</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>594.81</b>	<b>183.53</b>	<b>411.28</b>	<b>69.14</b>
<b>Nett Amount (S\$)</b>	<b>9,092.16</b>	<b>2,805.38</b>	<b>6,286.78</b>	<b>69.15</b>

### INSPECTION

Date of Assignment: 26/02/2018

Date Inspected: 28/02/2018 Inspected At:

Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 28 Jun 2018)	
<b>Parts:</b>	N/A	BMW 320i 2.0 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJG7777R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	2		*HEX HEAD SCREW	Not Necessary	1.10 FS	*- FS
3	2		*HEX HEAD SCREW WITH WASHERS	Not Necessary	2.00 FS	*- FS
4	2		*SHEET METAL NUT SELF-LOCKING	Not Necessary	2.00 FS	*- FS
5	1		*FRT LH TOP SUPPORT SIDE PANEL	Cracked	18.00 FS	*18.00 FS
6	1		*FRT RH TOP SUPPORT SIDE PANEL	Not Necessary	18.00 FS	*- FS
7	1		*PARTIALLY OPEN GRID LH	Not Necessary	68.30 FS	*- FS
8	1		*LH SUPPORT FOGLAMP	Cracked	37.60 FS	*37.60 FS
9	1		*FRT LH BOTTOM MOUNTING SIDE PANEL	Not Necessary	18.00 FS	*- FS
10	1		*FRT RH BOTTOM MOUNTING SIDE PANEL	Not Necessary	18.00 FS	*- FS
11	1		*FRT BUMPER TRIM PRIMED (SRA)	Scratched	982.75 FS	*982.75 FS
12	1		*FRT LH GRILLE (BASIS)	Not Necessary	96.40 FS	*- FS
13	2		*GROMMET	Not Necessary	1.50 FS	*- FS
14	2		*SECURNG CLIP	Not Necessary	0.90 FS	*- FS
15	1		*FRT LH WHEEL HOUSING COVER	Not Necessary	86.65 FS	*- FS
16	1		*LH COVER BOTTOM	Not Necessary	115.60 FS	*- FS
17	1		*DEFLECTOR LIP LH	Not Necessary	36.80 FS	*- FS
18	1		*PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
19	1		*LH HEADLIGHT (XENON)	Serviceable	2,135.85 FS	*- FS
20	1		*LH FOG LIGHT	Serviceable	276.40 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)      4,135.35      1,187.85**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE FRONT BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	1,700.00	850.00
2	SPRAY PAINTING FRONT BUMPER AND LEFT FRONT FENDER	New	1,923.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
4	TO REPLACE LEFT RADIATOR INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	531.00	0.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TOBMW SPECIFICATION	New	531.00	0.00
Gross Labour Cost (\$\$)			4,862.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >