

22/03/2003

ASS. REC. BY:

REF: CS/MSG18003775/TI 1d3⁵⁷

Special Instructions:

SURVEYOR

ASSIGNMENT (Office)

Merimen

From (Person):

Clark Milah Yeo

of

MSG

Date/Time:

26/2/18 1:44pm

Estimated Cost:

Bill to:

① TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV181P

Insured:

at Workshop m/s

Cycle & Carriage Industries
188 Pandan Loop

Tel:

91817717

of

Policy No:

A288511240MY

Claim No:

550484

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A.

25/2/2018

(Client's Record)

28/02/2018

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:05am 27/2/18

Person Contacted:

Eric

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKV181P-X
1/3/18	Report via merimen
1/3/18	16:28pm - authorise - by Ng Chen How
1/3/18	6:14pm - Sent email to Eric authorise repair
2/3/18	Seek mandate Supplementary
9/3-10/4	approval from Ng chen how supplementary

Tanpin

REF: ms47

Memorandum

ASSIGNMENT

Date 28/02/2018

SKV 181P

2015 Nov

Estimated Cost

TP / WS / TP RES / OD RES / EVA / INV / MY

Inspect Vehicle No

SKV 181P

at Workshop no

Cycle & Carriage
188 Pandan Loop

Insured

Policy No

Claims No

Sum Insured

Excess

\$ 500.00

(Client's Record)

Make of Veh

Eric

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS	OS

Ball or Market Value

\$140K

DAO Accident Report

Consistent? : Yes or No

GIA / PP / Seen

Consistent? : Yes or No

Est. Repairs

days

Res: Yes or No

Lump Sum

%

3 Val: Yes or No

OA / REP / 24 HRS

Date

Person Contacted

Vehicle: IN / OUT

Eric

Type

M/Cycle Bus Van Lorry Taxi Prime Mover

Truck / Trailer or

Make

Mercedes Benz C180

1595

Colour

Black

Insured / Std / Nil / NA

Se Reading

51158

T Read Insured / Std / Nil / NA

Eng No

C No

WDD 2050 40 2R114 669

Gen Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

275/50R17

R:

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

C

Rear

C

R.Bal

mm

R.Bal

mm

L.Bal

mm

L.Bal

mm

D.O.A

D.O.A

Survey held at

CFC Pandan Loop

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

Front/s, u/c

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

Part by Part \$25,517.59 (Red: 2293.42; 8%)

RECEIVED 8-8 MAR 2019

7/3/2019

Date Time File Pass

☐ Preli. Report
☒ Final Report

Days Of Repair: 6

Resurvey No. of Tric: 1

Survey Fee

Reported

Survey Fee

Reported

Survey Fee

Reported

Add Fee:

☐ Site load
☐ Interfer
☐ Test
☐ Wash

Site load

Interfer

Test

Wash

Report Format

OD

Lump Sum: LB 1-5

25,517.59

300
10




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18003775/T1td3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 27-02-2018	
			Code : MSG	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SKV 181P
Policy No. A28851124QMY		Coverage (\$)		0.00
Claim No. 550484		Excess (\$)		500.00
Assign From MERIMEN (CLARAH MILAH YEO)		Assign Date		27/02/2018
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 25/02/2018		Inspection Date		
Survey held at		CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2018		26 Feb 2018 13:44 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	MAK POH FATT, ID: S15967091, Tel: +6593839889, Email: NOEMAIL		
Vehicle Reg. No.:	SKV181P	Date of Loss:	25/02/2018 06:00 - :59
Claim Type:	OD / 550484	Policy/Cover Note No.:	A28851124QMY (Comprehensive) Coverage: 11/11/2017 - 10/11/2018
		Excess:	S\$500.00
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/02/2018]		
Driver/Custodian:	MAK POH FATT (54 / Male), NRIC: S15967091, Tel: +6593839889		
Adj Asg. Remarks:	Please revert. Thanks.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

3/1/2018

Adjuster Immediate Advice

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 01 Mar 2018

Preliminary Advice

Vehicle No	: SKV181P	Accident Date	: 25/02/2018
Make	: MERCEDES-BENZ C180	Policy No.	: A28851124QMY
Assignment Date	: 26/02/2018	Excess	: S\$500.00
Date of Inspection	: 28/02/2018	Est. Duration of Repair	: 6.00
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and undercarriage parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,242.57
Revised Amount	:S\$	5,369.10
Check Items (Estimated)	:S\$	6,833.47
Total	:S\$	12,202.57

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	75,075.00
Salvage Value	:S\$	
Margin for Repair	:S\$	64,925.00

Remarks

- (x) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

3/1/2018

Adjuster Immediate Advice

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 01 Mar 2018

Preliminary Advice

Vehicle No	: SKV181P	Accident Date	: 25/02/2018
Make	: MERCEDES-BENZ C180	Policy No.	: A28851124QMY
Assignment Date	: 26/02/2018	Excess	: S\$500.00
Date of Inspection	: 28/02/2018	Est. Duration of Repair	: 6.00
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and undercarriage parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,242.57
Revised Amount	:S\$	5,369.10
Check Items (Estimated)	:S\$	6,833.47
Total	:S\$	12,202.57
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	75,075.00
Salvage Value	:S\$	
Margin for Repair	:S\$	64,925.00

Remarks

- (x) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 1 March 2018 6:14 PM
To: 'Eric Lee Ming Hui'; SUR
Subject: RE: SKV181P (MSIG OD)

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKV 181P (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Before paint and after paint required.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Eric Lee Ming Hui [mailto:eric.lee@cyclecarriage.com.sg]
Sent: Thursday, 1 March 2018 8:42 AM
To: SUR <sur@lkkauto.com>
Subject: SKV181P (MSIG OD)

Dear LKK Officer,

Please advise if the repair for SKV181P has been authorized?

Thank you.

Your Sincerely,

Eric Lee Ming Hui
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 9181 7717 | DID: 6771 4336 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

View Received Message

This mail is associated with :

***SKV181P (550484)**

OD

Feb 25 2018 6:00AM

[MAK POH FATT]

Cycle & Carriage Industries Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 01/03/2018 16:28 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5369.10) - SKV181P - Claim Handler: Clara Milah Yeo

Approved:5369.10.

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/02/2018 10:08
Date Of Accident	25/02/2018 06:30
Exact Location Of Accident	ALONG RIVERINA CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV181P
Insured/Policyholder	
Name Of Registered Owner	MAK POH FATT
NRIC No	S1596709I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93839889
Alternative Phone No	OFFICE-93839889

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28851124QMY
Cover Note Number	

Driver

Name of Driver	MAK POH FATT
NRIC No	S1596709I
Date Of Birth	09/05/1963
Occupation	INDOOR
Date Of Driving Pass	21/05/1984
Driving Experience	33 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93839889
Fax Number	
Contact Number	OFFICE-93839889
EMail Address	NOEMAIL

Address	89 RIVERINA VIEW
Postcode	518438
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG WHEN I MISJUDGE THE DISTANCE AND ACCIDENTALLY HIT ONTO THE CAR B (SJJ702L) WHICH WAS PARKED STATIONARY AT THE ROADSIDE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ702L
Vehicle Make/Model/Colour	AUDI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Eric Lee Ming Hui
DID : 6771 4336 HP : 9181 7717
Email : eric.lee@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's
Name:
NRIC/FIN No.:

SKETCH PLAN



A = SKV 181 P

B = SJJ 702 L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I WAS DRIVING ALONG WHEN I MISJUDGE THE DISTANCE & ACCIDENTALLY HIT ON TO VEH B(SJJ702L) WHICH WAS PARKED STATIONARY AT THE ROADSIDE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Eric Lee Ming Hui
DID : 6771 4336 HP : 9181 7717
Email : eric.lee@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Reporting Centre Personnel's
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6709I
Vehicle Details	
Vehicle No.:	SKV181P
Vehicle to be Exported:	No
Intended De-registration Date:	01 Mar 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180 AVANTGARDE (R17 LED)
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	27491030462272
Chassis No.:	WDD2050402R114669
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$35,294.00
Original Registration Date:	11 Nov 2015
First Registration Date:	11 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$36,412.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Nov 2025
PARF Rebate Amount:	\$27,309.00
Intended COE Rebate Details	
COE Expiry Date:	10 Nov 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10

QP Paid:	\$62,101.00
COE Rebate Amount:	\$47,766.00
Total Rebate Amount:	\$75,075.00

The information contained herein is correct as at 01 Mar 2018

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

mercedes benz c180

Price Range

Depreciation

2015

Vehicle Type

Home » Used Cars » Dennis-Link » Mercedes-Benz C-Class C180 Avantgarde

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Car Rental

For Private &
Commercial Vehicles
Rental From
\$50/Day

Rent

Mercedes-Benz C-Class C180 Avantgarde

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price	\$142,888	
Depreciation	\$15,790 /yr View models with similar depreciation	?
Reg Date	27-Nov-2015 (7yrs 8mths 25days COE left)	
Manufactured	2015	?
Mileage	13,398 km (5.9k /yr)	
Transmission	Auto	
Engine Cap	1,595 cc	
Road Tax	\$740 /yr	?
Power	115.0 kW (154 bhp) View specs of the Mercedes-Benz C-Class Saloon (2014)	
Curb Weight	1,425 kg	?
Features	1.6L 4 Cylinder Inline Turbocharged Engine Producing 154 Bhp And 250 NM Of Torque, 7G-Tronic With Paddle Shifter, Keyless Go, ECO Mode, Cruise Control	
Accessories	Factory Audio With Aux/USB Interface, Sports Rims, Bluetooth Telephone, Parktronic, Reverse Camera, Agility Select, Electric Tailgate, Leather Seats.	
Description	C&C Unit, 1 Owner, Low Mileage Of 13398km, Excellent Condition, C&C Warranty Till Nov 2018. Please Call For Appointment Viewing!	
COE	\$65,501	?
OMV	\$38,684	?
ARF	\$41,158	?
Dereg Value	\$81,600 as of today (change)	?
No. of Owners	1	?
Type of Veh	Luxury Sedan	



Seller Informat

Company

Address

Location

Compare

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

ESTIMATE FOR SKV181P

Acknowledged by Repairer

Signature:
Mak Poh Fatt

Date:
89 Riverina View
Singapore 518438



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Vehicle & Document Information

WIP No 21567
Reg No/Reg Date SKV181P / 11/11/2015
Date In/Mileage / 0
Chassis No WDD2050402R114669
Engine No 27491030462272
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 021 197 Obsidian Bl/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator				
WCV21174	CRDVCH	26/02/2018/ 10:49	EL	350 / Eric Lee Ming Hui				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN								
POLICY NO/ACC DATE : A28851124QMY // 25-2-18								
TOW IN/EXCESS : 25-2-18 // \$500								
DATE IN/DATE SURVEY :								
BY/AUTHORIZED ON :								
S BPNTOW								✓ 140.00
ACCIDENT TOWING FROM NO 89 RIVERINA VIEW TO PLSC								
USING KING DOLLEY AND SUNDAY CHARGE.								
WO: 143623								
A BPILAB							0.10	✓ 380.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO								
IDENTIFICATION STANDARD.-NETT								1200 1800.00
A BPIRES								1440 2880.00
RESpray FRONT BUMPER, RH/ FRONT FENDER.								
A BPILAB								photo 1920 2880.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPILAB								✓ 540.00
REMOVE FRONT CARRIAGE ASSY FROM FRAME, IMPACT.REPLACE AND ASSEMBLE								
WHEEL BASE & ADJUST TO VEHICLE.								✓ 60.00
A BPILAB								
TO INSPECT & CONDUCT WHEEL ALIGNMENT.-NETT								
S BPNSUB								
TRANSFER RH/ FRONT RIM AND BALANCING TYRE.-NETT								
PURCHASE ORDER NO:								
M RIGHT FRONT FENDER					1.00	881.86	00.00	bt ✓ 881.86
M RH/ FRONT WHEEL HOUSE COVERING					1.00	118.22	00.00	de ✓ 118.22
M RH/ FRONT SPRING LINK					1.00	592.02	00.00	bt ✓ 592.02
M RH/ FRONT CONTROL ARM					1.00	792.13	00.00	bt ✓ 792.13
M RH/ FRONT STEERING KNUCKLE					1.00	1208.64	00.00	bt ✓ 1208.64
M RH/ FRONT STRUT ROD					1.00	577.59	00.00	bt ✓ 577.59
M RH/ FRONT SHOCK-ABSORBER STRUT					1.00	700.54	00.00	bt ✓ 700.54
M RH/ FRONT TORSION BAR LINKAGE					1.00	82.55	00.00	bt ✓ 82.55
M RH/ FRONT DISK WHEEL					1.00	609.02	00.00	cut ✓ 609.02

Confirmed & accepted by

Eric Lee Ming Hui

DID: 6771 4336 HP: 9181 7717

Email: eric.lee@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Nett 14,242.57
7% GST on 14242.57 996.98

Total Payable 15,239.55

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV181P

Mr Mak Poh Fatt

89 Riverina View
Singapore 518438

*Mobile: 93839889

Vehicle & Document Information

WIP No 21567
Reg No/Reg Date SKV181P / 11/11/2015
Date In/Mileage 06/03/2018/ 51158
Chassis No WDD2050402R114669
Engine No 27491030462272
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 021 197 Obsidian Bl/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	
CSM00128	Cash	23/04/2018/ 17:58		350 / Eric Lee Ming Hui	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACCE DATE : 028891124QMY / 25-2-18 TOW IN/EXCESS : 25-2-18 // \$500 DATE IN/DATE SURVEY: 28-2-18 // 1200 // TAUFIKH - LKK BY/AUTHORIZED ON : Denise Tay - LKK // 1-3-18 // 1815					
S BPNTOW ACCIDENT TOWING FROM NO 89 RIVERINA VIEW TO PLSC USING KING DOLLEY AND SUNDAY CHARGE. WO: 143623					140.00
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT		0.10			380.00
A BPIRES RESPRAY FRONT BUMPER, RH/ FRONT FENDER.					1200.00
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.					1440.00
A BPILAB REMOVE FRONT CARRIAGE ASSY FROM FRAME. IMPACT.REPLACE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE.					1920.00
A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT					540.00
A BPILAB STRAIGHTEN, REMOVE & REPLACE FRONT WHEEL HOUSE SUPPORT ASSY FROM FRAME IMPACT					3840.00
A BPILAB REMOVE ENGINE ASSY WITH COOLING SYSTEM, ELECTRONIC WIRE SYSTEM- FOR NECESSARY REPAIR.					1920.00
A BPILAB DISASSEMBLE AND RE-INSTALL ABS PUMP FOR NECESSARY REPAIR.					960.00
A BPILAB PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT		0.07			1000.00
S BPNSUB MERC WHEEL RIM.					609.02

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Finalization

Finalization

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 6388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV181P

Mr Mak Poh Fatt

89 Riverina View
Singapore 518438

*Mobile: 93839889

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

21567

SKV181P / 11/11/2015

06/03/2018/ 51158

WDD2050402R144669

27491030462272

MB/MB C 180 SEDAN (W205) "AVANTGARDE / A

021 197 Obsidian Bl/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator		
CSM00128	Cash	23/04/2018/ 17:58		350 / Eric Lee Ming Hui		
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
DO: 8006						
X BP/EXC						
INSURANCE EXCESS						
X	RIGHT FRONT FENDER	1.00	881.86	00.00		881.86
X	RH/ FRONT WHEEL HOUSE COVERING	1.00	118.22	00.00		118.22
X	RH/ FRONT SPRING LINK	1.00	592.02	00.00		592.02
X	RH/ FRONT CONTROL ARM	1.00	792.13	00.00		792.13
X	RH/ FRONT STEERING KNUCKLE	1.00	1208.64	00.00		1208.64
X	RH/ FRONT STRUT ROD	1.00	577.59	00.00		577.59
X	SHOCK-ABSORBER STRUT	1.00	700.54	00.00		700.54
X	RIGHT TOP WHEEL HOUSE	1.00	1435.99	00.00		1435.99
X	TOP RH LONGITUDINAL MEMBER	1.00	457.94	00.00		457.94
X	RIGHT STRUT	1.00	244.77	00.00		244.77
X	TS TWO-COMPONENT ADHESIVE	1.00	755.31	00.00		755.31
X	INTEGRAL CARRIER	1.00	2085.67	00.00		2085.67
X	WHEEL BEARING	1.00	524.09	00.00		524.09
X	NUT-A-WASHER ASSEMBLY	2.00	10.17	00.00		20.34
X	FEED LINE	1.00	157.38	00.00		157.38
X	DRAIN VALVE	1.00	45.27	00.00		45.27
X	SEAM SEAL	1.00	97.68	00.00		97.68
X	RIVET	25.00	2.29	00.00		57.25
X	BLIND RIVET	25.00	1.27	00.00		31.75
X	WHEEL HOUSE COVERING	1.00	120.19	00.00		120.19
X	CROSS MEMBER	1.00	127.88	00.00		127.88
X	RIVET	14.00	2.29	00.00		32.06
X	RIVET	6.00	5.18	00.00		31.08
X	RIVET	2.00	3.53	00.00		7.06
X	RIVET	30.00	2.29	00.00		68.70
X	RIVET	20.00	5.18	00.00		103.60
X	SEAM SEAL	1.00	97.68	00.00		97.68
X	RADIATOR ANTIFREEZE	2.00	46.49	00.00		92.98
X	PLASTIC NUT	6.00	1.11	00.00		6.66
X	EXPANSION RIVET	4.00	1.02	00.00		4.08

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

-500.00

Finalization

Finalization

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV181P

Mr Mak Poh Fatt
89 Riverina View
Singapore 518438

*Mobile: 93839889

Vehicle & Document Information

WIP No **21567**
Reg No/Reg Date **SKV181P / 11/11/2015**
Date In/Mileage **06/03/2018/ 51158**
Chassis No **WDD2050402R104669**
Engine No **27491030462272**
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**
Colour/Trim **021 197 Obsidian Bl/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	23/04/2018/ 17:58		350 / Eric Lee Ming Hui

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RIVET	6.00	4.42	00.00	26.52
X BRACKET	1.00	65.64	00.00	65.64

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Finalization

Confirmed & accepted by

Nett **25,017.59**
7% GST on **25017.59** **1751.23**
Total Payable 26,768.82

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV181P

Mak Poh Fatt

89 Riverina View
Singapore 518438

Vehicle & Document Information

WIP No **21567**
Reg No/Reg Date **SKV181P / 11/11/2015**
Date In/Mileage **06/03/2018/ 51158**
Chassis No **WDD2050402R104669**
Engine No **27491030462272**
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**
Colour/Trim **021 197 Obsidian Bl/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator
WCV21174	CRDVCH	06/03/2018/ 10:56	EL	350 / Eric Lee Ming Hui

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A BPILAB STRAIGHTEN, REMOVE & REPLACE FRONT WHEEL HOUSE SUPPORT ASSY FROM FRAME IMPACT				3840.00 ✓
A BPILAB REMOVE ENGINE ASSY WITH COOLING SYSTEM, ELECTRONIC WIRE SYSTEM- FOR NECESSARY REPAIR.				1920.00 ✓
A BPILAB DISASSEMBLE AND RE-INSTALL ABS PUMP FOR NECESSARY REPAIR.				960.00
M RIGHT TOP WHEEL HOUSE	1.00	1435.99	00.00	1435.99
M TOP RH LONGITUDINAL MEMBER	1.00	457.94	00.00	457.94
M RIGHT STRUT	1.00	244.77	00.00	244.77
M RIGHT REINFORCEMENT	1.00	150.87	00.00	150.87
M TS TWO-COMPONENT ADHESIVE	1.00	755.31	00.00	755.31

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett 9,764.88**
683.54

Total Payable 10,448.42

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV181P

Mr Mak Poh Fatt .

89 Riverina View
Singapore 518438

*Mobile: 93839889

Vehicle & Document Information

WIP No **21567**
Reg No/Reg Date **SKV181P / 11/11/2015**
Date In/Mileage **06/03/2018 / 51158**
Chassis No **WDD2050402R144669**
Engine No **27491030462272**
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**
Colour/Trim **021 197 Obsidian Bl/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator	
CSM00128	Cash	23/04/2018/ 17:58		350 / Eric Lee Ming Hui	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
A BPILAB STRAIGHTEN, REMOVE & REPLACE FRONT WHEEL HOUSE SUPPORT ASSY FROM FRAME IMPACT					3840.00 ✓
A BPILAB REMOVE ENGINE ASSY WITH COOLING SYSTEM, ELECTRONIC WIRE SYSTEM- FOR NECESSARY REPAIR.					1920.00 ✓
A BPILAB DISASSEMBLE AND RE-INSTALL ABS PUMP FOR NECESSARY REPAIR.					960.00 ✓
A BPILAB PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT				0.07	1000.00
X	RIGHT TOP WHEEL HOUSE	1.00	1435.99	00.00	1435.99 ✓
X	TOP RH LONGITUDINAL MEMBER	1.00	457.94	00.00	457.94 ✓
X	RIGHT STRUT	1.00	244.77	00.00	244.77 ✓
X	TS TWO-COMPONENT ADHESIVE	1.00	755.31	00.00	755.31 ✓
X	INTEGRAL CARRIER	1.00	2085.67	00.00	bt ✓ 2085.67
X	WHEEL BEARING	1.00	524.09	00.00	bt ✓ 524.09
X	NUT-A-WASHER ASSEMBLY	2.00	10.17	00.00	ner ✓ 20.34
X	FEED LINE	1.00	157.38	00.00	dis ✓ 157.38
X	DRAIN VALVE	1.00	45.27	00.00	dis ✓ 45.27
X	SEAM SEAL	1.00	97.68	00.00	ner ✓ 97.68
X	RIVET	25.00	2.29	00.00	ner ✓ 57.25
X	BLIND RIVET	25.00	1.27	00.00	ner ✓ 31.75
X	WHEEL HOUSE COVERING	1.00	120.19	00.00	dis ✓ 120.19
X	CROSS MEMBER	1.00	127.88	00.00	bt ✓ 127.88
X	RIVET	14.00	2.29	00.00	ner ✓ 32.06
X	RIVET	6.00	5.18	00.00	ner ✓ 31.08
X	RIVET	2.00	3.53	00.00	ner ✓ 7.06
X	RIVET	30.00	2.29	00.00	ner ✓ 68.70
X	RIVET	20.00	5.18	00.00	ner ✓ 103.60
X	SEAM SEAL	1.00	97.68	00.00	ner ✓ 97.68
X	RADIATOR ANTIFREEZE	2.00	46.49	00.00	ner ✓ 92.98
X	PLASTIC NUT	6.00	1.11	00.00	ner ✓ 6.66
X	EXPANSION RIVET	4.00	1.02	00.00	ner ✓ 4.08

ESTIMATE

SUPPLEMENTARY

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV181P

Mr Mak Poh Fatt

89 Riverina View
Singapore 518438

*Mobile: 93839889

Vehicle & Document Information

WIP No **21567**
Reg No/Reg Date **SKV181P / 11/11/2015**
Date In/Mileage **06/03/2018/ 51158**
Chassis No **WDD2050402R104669**
Engine No **27491030462272**
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**
Colour/Trim **021 197 Obsidian Bl/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	23/04/2018/ 17:58		350 / Eric Lee Ming Hui

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RIVET	6.00	4.42	00.00	26.52
X BRACKET	1.00	65.64	00.00	65.64

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

Nett **14,417.57**
7% GST on **14417.57** **1009.23**
Total Payable 15,426.80

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Feb 2018		26 Feb 2018 13:44 Edit Adj Rpt	S\$25,517.59 Edit Estimates	S\$25,517.59 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MAK POH FATT, ID: S15967091, Tel: +6593839889, Email: NOEMAIL		
Vehicle Reg. No.:	SKV181P	Date of Loss:	25/02/2018 06:00 - :59 [27 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 550484	Policy/Cover Note No.:	A28851124QMY (Comprehensive) Coverage: 11/11/2017 - 10/11/2018
		Excess:	S\$500.00
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 28/03/2018]		
Driver/Custodian:	MAK POH FATT (54 / Male), NRIC: S15967091, Tel: +6593839889 Email: NOEMAIL		
Adj Asg. Remarks:	Please revert. Thanks.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (07/03/2019): Alert - Adj Mandate Approved (S\$25517.59) - SKV181P - Claim Handler: Clara Milah...
- MSIG_SG (09/03/2018): Alert - Adj Mandate Approved (S\$15133.80) - SKV181P - Claim Handler: Clara Milah...
- MSIG_SG (01/03/2018): Alert - Adj Mandate Approved (S\$5369.10) - SKV181P - Claim Handler: Clara Milah ...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents





***SKV181P (550484)**
OD
Feb 25 2018 6:00AM
[MAK POH FATT]
Cycle & Carriage Industries Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports









































1 per page ☒

No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	26/02/18 10:15	Accident Statement	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/18 15:29	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
2	08/03/18 17:40	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
3	16/01/19 14:06	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>

Photos/Images

3 per page ☒


No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/03/18 15:19	General View		Load JPG	
2	01/03/18 15:19	General View		Load JPG	
3	01/03/18 15:19	General View		Load JPG	
4	01/03/18 15:19	General View		Load JPG	
5	01/03/18 15:19	General View		Load JPG	
6	01/03/18 15:19	General View		Load JPG	
7	01/03/18 15:19	General View		Load JPG	
8	01/03/18 15:19	General View		Load JPG	
9	01/03/18 15:19	General View		Load JPG	
10	01/03/18 15:19	General View		Load JPG	
11	01/03/18 15:19	General View		Load JPG	
12	01/03/18 15:19	General View		Load JPG	
13	01/03/18 15:19	General View		Load JPG	
14	01/03/18 15:19	General View		Load JPG	
15	01/03/18 15:19	General View		Load JPG	
16	01/03/18 15:19	General View		Load JPG	
17	01/03/18 15:19	General View		Load JPG	
18	01/03/18 15:19	General View		Load JPG	
19	01/03/18 15:19	General View		Load JPG	
20	01/03/18 15:19	General View		Load JPG	
21	01/03/18 15:19	General View		Load JPG	
22	01/03/18 15:19	General View		Load JPG	
23	01/03/18 15:19	General View		Load JPG	
24	01/03/18 15:19	General View		Load JPG	
25	01/03/18 15:19	General View		Load JPG	
26	01/03/18 15:19	General View		Load JPG	
27	01/03/18 15:19	General View		Load JPG	
28	01/03/18 15:19	General View		Load JPG	
29	01/03/18 15:19	General View		Load JPG	
30	01/03/18 15:19	General View		Load JPG	












Assessment Reports			1 per page	
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
31	01/03/18 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
32	01/03/18 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
33	01/03/18 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
34	01/03/18 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
35	01/03/18 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
36	01/03/18 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
37	01/03/18 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
38	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	08/03/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/02/18 13:22	Repair Estimate	 Load PDF	
2	26/02/18 13:22	Email from w/shop to request for survey	 Load PDF	
3	11/05/18 17:09	Signed DV	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/18 15:31	estimate	 Load PDF	
2	08/03/18 17:34	SUPPLEMENTARY	 Load PDF	
3	16/01/19 14:08	SUPPLEMENTARY	 Load PDF	
4	16/01/19 14:11	ESTIMATE MARKED	 Load PDF	
5	12/03/19 09:42	SUPPLEMENTARY	 Load PDF	





Linked Accident Report Documents

View

Assessment Reports			1 per page	
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	26/02/18 10:15	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	26/02/18 10:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	26/02/18 10:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	26/02/18 10:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	26/02/18 10:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	26/02/18 10:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	26/02/18 10:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	26/02/18 10:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	26/02/18 10:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	26/02/18 10:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	26/02/18 10:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	26/02/18 10:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	26/02/18 10:12	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	26/02/18 10:12	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	26/02/18 10:12	Sketch Plan #3	 Load JPG	<input checked="" type="checkbox"/>
4	26/02/18 10:12	Sketch Plan #4	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18003775/T1TD3S2

Date: 12/03/2019

REFERENCE

Insured/Claimant:	MAK POH FATT	Policy No:	A28851124QMY	
Date of Loss:	25/02/2018	Nature of Claim:	OD	Claim No: 550484

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV181P	Engine No:	27491030462272
Make & Model:	MERCEDES-BENZ C180, 1.6 AVANT GARDE (A)	Chassis No:	WDD2050402R114669
Reg. Date:	11/11/2015 (Man. Year: 2015)	Odometer:	51158 km
Colour:	Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/50R17	Rear Tyre Size:	275/50R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,260.14	11,568.57	691.57	5.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,009.02	13,949.02	3,060.00	17.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,269.16	25,517.59	3,751.57	12.82
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	28,769.16	25,017.59	3,751.57	13.04
+ GST 7.00/7.00% (S\$)	2,013.84	1,751.23	262.61	13.04
Nett Amount (S\$)	30,783.00	26,768.82	4,014.18	13.04

INSPECTION

Date of Assignment:	26/02/2018	
Date Inspected:	28/02/2018	Inspected At: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Mar 2019)

Parts: 143 MERCEDES-BENZ C180 1.6 AVANT GARDE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV181P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT FRONT FENDER	Bent	881.86 FS	*881.86 FS
2	1		*RH/FRONT WHEEL HOUSE COVERING	Deformed	118.22 FS	*118.22 FS
3	1		*RH / FRONT SPRING LINK	Bent	592.02 FS	*592.02 FS
4	1		*RH / FRONT CONTROL ARM	Bent	792.13 FS	*792.13 FS
5	1		*RH / FRONT STEERING KNUCKLE	Bent	1,208.64 FS	*1,208.64 FS
6	1		*RH / FRONT STRUT ROD	Bent	577.59 FS	*577.59 FS
7	1		*RH / FRONT SHOCK-ABSORBER STRUT	Bent	700.54 FS	*700.54 FS
8	1		*RH / FRONT TORSION BAR LINKAGE	Not Necessary	82.55 FS	*- FS
9	1		*RH / FRONT DISK WHEEL	Not Necessary	609.02 FS	*- FS
10	1		*INTEGRAL CARRIER	Bent	2,085.67 FS	*2,085.67 FS
11	1		*WHEEL BEARING	Bent	524.09 FS	*524.09 FS
12	2		*NUT-A-WASHER ASSEMBLY	Necessary	20.34 FS	*20.34 FS
13	1		*FEED LINE	Distorted	157.38 FS	*157.38 FS
14	1		*DRAIN VALVE	Distorted	45.27 FS	*45.27 FS
15	1		*SEAM SEAL	Necessary	97.68 FS	*97.68 FS
16	1		*RIVET	Necessary	57.25 FS	*57.25 FS
			25pcs			
17	1		*BLIND RIVET	Necessary	31.75 FS	*31.75 FS
			25pcs			
18	1		*WHEEL HOUSE COVERING	Necessary	120.19 FS	*120.19 FS
19	1		*CROSS MEMBER	Bent	127.88 FS	*127.88 FS
20	14		*RIVET	Necessary	32.06 FS	*32.06 FS
21	6		*RIVET	Necessary	31.08 FS	*31.08 FS
22	2		*RIVET	Necessary	7.06 FS	*7.06 FS
23	1		*RIVET	Necessary	68.70 FS	*68.70 FS
			30pcs			
24	20		*RIVET	Necessary	103.60 FS	*103.60 FS
25	1		*SEAM SEAL	Necessary	97.68 FS	*97.68 FS
26	2		*RADIATOR ANTIFREEZE	Necessary	92.98 FS	*92.98 FS
27	6		*PLASTIC NUT	Necessary	6.66 FS	*6.66 FS
28	4		*EXPANSION RIVET	Necessary	4.08 FS	*4.08 FS
29	6		*RIVET	Necessary	26.52 FS	*26.52 FS
30	1		*BRACKET	Necessary	65.64 FS	*65.64 FS
31	1		*RIGHT TOP WHEEL HOUSE	Bent	1,435.99 FS	*1,435.99 FS
32	1		*TOP RH LONGITUDINAL MEMBER	Bent	457.94 FS	*457.94 FS
33	1		*RIGHT STRUT	Bent	244.77 FS	*244.77 FS
34	1		*TS TWO-COMPONENT ADHESIVE	Necessary	755.31 FS	*755.31 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 12,260.14 11,568.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ACCIDENT TOWING FROM NO 89 RIVERINA VIEW TO PLSC USING KING DOLLEY AND SUNDAY CHARGE.	New	140.00	140.00
2	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.	New	380.00	380.00
3	RESPRAY FRONT BUMPER, RH / FRONT FENDER.	New	1,800.00	1,200.00
4	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.	New	2,880.00	1,440.00
5	REMOVE FRONT CARRIAGE ASSY FROM FRAME, IMPACT. REPLACE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE.	New	2,880.00	1,920.00
6	TO INSPECT & CONDUCT WHEEL ALIGNMENT.	New	540.00	540.00
7	TRANSFER RH / FRONT RIM AND BALANCING TYRE.	New	60.00	0.00
8	PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT.	New	609.02	609.02
9	STRAIGHTEN, REMOVE & REPLACE WHEEL HOUSE SUPPORT ASSY FROM FRAME IMPACT.	New	3,840.00	3,840.00
10	REMOVE ENGINE ASSY WITH COOLING SYSTEM, ELECTRONIC WIRE SYSTEM - FOR NECESSARY REPAIR.	New	1,920.00	1,920.00
11	DISASSEMBLE AND RE-INSTALL ABS PUMP FOR NECESSARY REPAIR.	New	960.00	960.00
12	PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT.	New	1,000.00	1,000.00
Gross Labour Cost (\$\$)			17,009.02	13,949.02

Report was unsubmitted during this print-out.

< END OF ESTIMATES >